

## Summary Report for Sub Contractor

**Project Name :** Zano

**IssueTo Name :** Naim Caulker (Naim)

**Date :** 20/10/2015

**Inspections :** 1

**Page :** 1 of 1

**Report Filtered by :**

**Location Name:** Building      **Sub Location:** Level 01

**Status:** Open

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
1245144 1933928	Defect	Building > Level 01 > Apartments > 107 > Bath	Caulk	nimaih	11/09/15	Superintendent	2015-09-21	Open				