

Summary Report for Sub Contractor

Project Name : The Albert

IssueTo Name : Aluline (Baci)

Date : 22/10/2015

Inspections : 1

Page : 1 of 1

Report Filtered by :

Status:

Open

Issue To:

Aluline

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
12461437 956059	Defect	Building B > Level 02 > Apartments > B209 > Terrace	Glass splintered on edge	arcallengari	27/07/15	Builder	2015-08-13	Open				