

Property Inspection Photos

Job No: BAA 242022

Property Address: 10 Riddle Street Bentleigh VIC 3204

For: John Smith

Date: 24 July 202

Contents

Unsafe Stairs	2
Entry and Backdoor Damages	4
Bathroom and Shower Damages	8
Bedroom Damages.....	17
External Windows Damages	19
Hallway Damages.....	25
Roofs and Corrosion Damages.....	26
Sunroom Damages.....	33
Downpipes	41
Kitchen Damages	43
Laundry Damages.....	48
Loungeroom Damages	50
Master Bedroom Damages	51
Retaining Wall Damages	53
Flashing and Chimney Damages	58

Unsafe Stairs



Unsafe Stairs to Loft (1)



Unsafe Stairs to Loft (2)


Entry and Backdoor Damages



Entry Roof Deteriorating Concrete



Entry Door Gaps - No Seals



Backdoor Frame and Ceiling Rot



Backdoor Frame Rot

Bathroom and Shower Damages



Bathroom Gap in Tilework



Bathroom Lino Lifting



Bathroom Sink Cracked Tiles and No Sealant



Bathroom Sink Tiles No Sealant



Bathroom Tiles Falling Off (1)



Bathroom Tiles Falling Off (2)



Plastic Sheet Used to Cover Shower Wall Where Tiles Have Fallen Off



Shower Frame Tiles Falling Off



Shower Tiles Taped to Wall



Cracked Shower Base

Bedroom Damages



Bedroom Ceiling Water Damage



Bedroom Damp (1)



Bedroom Damp (2)

External Windows Damages



External Bedroom Window Frame Gaps - No Seal



External Bedroom Window Gap - No Seals



External Dining Room Window Gap - No Seal



External Laundry Window Rot & Gaps - No Seal



External Loungeroom Window Rot (1)



External Loungeroom Window Rot (2)

Hallway Damages



Hallway Cupboard Missing Floorboards



Hallway Cupboard Water Damage

Roofs and Corrosion Damages



Corroded Carport Roof



Carport Roof - No Fall Barrier (1)



Carport Roof - No Fall Barrier (2)



Corroded Loft Roof Sheets



Hole In Corroded Carport Roof



Asbestos Roof Sheet – Loft 1




Asbestos Roof Sheet - Loft 2




Corroded Oil Heater Storage Tank

Sunroom Damages



Sunroom Roof Water Damage (1)



Sunroom Rotten Window Frames



Sunroom Water Damage



Sunroom Water Damage (2)



Sunroom Water Damage (3)



Sunroom Water Damage (4)



External Sunroom Framing Rot



Corroded Sunroom Roof & Rotten Frame

Downpipes



Downpipe - DIY Diversion to Garden



Downpipe Not Connected

Kitchen Damages



Kitchen Cupboard - Warped and Will Not Close (1)



Kitchen Cupboard - Warped and Will Not Close (2)



Kitchen Internal Brickwork Damage



Kitchen No Rangehood



Kitchen Roof Water Damage

Laundry Damages



Laundry Roof Damage



Laundry Wall and Roof Damage

Loungeroom Damages



Loungeroom Door Cracked Glass



Loungeroom Roof Water Damage

Master Bedroom Damages



Master Bedroom Carpet Rot



Master Bedroom Ceiling Water Damage



Master Bedroom Wall Damage

Retaining Wall Damages



Rear Retaining Wall Crack



Rear Retaining Wall Leaning and Not Straight



Retaining Wall - Lean towards street



Retaining Wall Large Crack



Retaining Wall Small Crack

Flashing and Chimney Damages



Rusted Flashing and Rotten Timber



Damaged Tiles, Flashing and Chimney Brickwork