

Verbale di Intervento

Minute of Intervention

Ciente /Client:

Ragione Sociale / Company name: A-PLUS AUTOMATION USA INC
Indirizzo / Address: 31874 NORTHWESTERN HWY.
CAP / ZIP: 48334
Città / City: FARMINGTON HILLS
Paese / Country: US
P.IVA / VAT Id.:

Il nostro tecnico, Sig.

Our Technician, Mr.

Manucci Stefano

è intervenuto presso la Vs.
Sede per:

has intervened at your premises
for:

☐ Installare / To Install ☐ Collaudare / To Test ☐ Verificare / To Check ☐ Riparare / To Repair ☒ To Suggest

Macchine / Dispositivi:

Machines / Devices:

Modello / Model: A5

S/N: 1600326

Year: 0

Descrizione dell'intervento

Description of Intervention

Servizio iniziato alle / Service began 11/15/2022 5:11 PM
Servizio terminato alle / Service ended on. 11/15/2022 5:14 PM

Attività svolte: / Activities:

Customer contacted and given directions to verify screen connection.

Al termine dell'intervento, **il cliente** dichiara:

1. Che le funzioni delle macchine/dispositivi sono tutte operative;
2. Che il funzionamento delle stesse è regolare;
3. Che le protezioni di sicurezza sono operative;
4. Che in vista di quanto sopra evidenziato, nulla osta al saldo di quanto dovuto secondo gli accordi presi.

At the end of the intervention, **the customer** declares:

1. That the functions of the machines / devices are all working;
2. That the operation of the same is regular;
3. That security guards are operational;
4. That in view of the above, nothing shall prevent the payment of the amount due in accordance with the agreements.

Replaced and/or Mounted Parts

Notes and/or reserves (tick in the absence of comments)

This image shows a single sheet of white paper with horizontal blue lines, resembling notebook paper. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

11/15/2022

Stamp & Signature