Berita Acara Serah Terima Unit

Unit Handover Report: the unit below has been repaired and is Ready For Use (RFU).

Work Order	WO-202609-0021
Unit	DT 117 (DT-017) · Dump Truck
Driver / Operator	Hendra Wijaya
PIC Mechanic	Agus Prasetyo
Repair Category	Preventive Maintenance
Problem Reported	Service 500 hours
Repair Period	28/09/26, 10:18 – 29/09/26, 04:07
Result	**Unit Ready For Use (RFU)**

Repair steps

#	Step	PIC	Start	Finish	Duration
1	Unit Breakdown	Agus Prasetyo	28/09/26, 10:18	28/09/26, 10:56	37m
2	Service Request Remarks: Checked OK	Agus Prasetyo	28/09/26, 10:56	28/09/26, 11:33	37m
3	Inspection Activity	Agus Prasetyo	28/09/26, 11:42	28/09/26, 12:49	1h 8m
4	Inspection Report Readiness	Agus Prasetyo	28/09/26, 12:49	28/09/26, 13:57	1h 8m
5	Spareparts Request	Agus Prasetyo	28/09/26, 14:23	28/09/26, 18:12	3h 49m
6	Supply Spareparts Remarks: Part replaced	Agus Prasetyo	28/09/26, 18:12	28/09/26, 22:00	3h 49m
7	Repair Process Remove faulty component · Install / repair component	Agus Prasetyo	28/09/26, 22:34	28/09/26, 23:26	52m
8	Ground Test	Agus Prasetyo	28/09/26, 23:52	29/09/26, 01:35	1h 43m
9	RFU (Ready For Use)	Agus Prasetyo	29/09/26, 01:50	29/09/26, 04:07	2h 16m

Handed over by (Mechanic)	Checked by (Admin Plant)	Received by (Driver / Operator)
Agus Prasetyo	**Admin Plant**	**Hendra Wijaya**