Berita Acara Serah Terima Unit

Unit Handover Report: the unit below has been repaired and is Ready For Use (RFU).

Work Order	WO-202609-0018
Unit	DT 105 (DT-005) · Dump Truck
Driver / Operator	Yusuf Maulana
PIC Mechanic	Rudi Hartono
Repair Category	Preventive Maintenance
Problem Reported	Service 500 hours
Repair Period	24/09/26, 14:55 – 25/09/26, 03:00
Result	**Unit Ready For Use (RFU)**

Repair steps

#	Step	PIC	Start	Finish	Duration
1	Unit Breakdown	Rudi Hartono	24/09/26, 14:55	24/09/26, 15:25	30m
2	Service Request Remarks: Checked OK	Rudi Hartono	24/09/26, 15:25	24/09/26, 15:56	30m
3	Inspection Activity	Rudi Hartono	24/09/26, 16:27	24/09/26, 17:36	1h 9m
4	Inspection Report Readiness	Rudi Hartono	24/09/26, 17:36	24/09/26, 18:46	1h 9m
5	Spareparts Request	Rudi Hartono	24/09/26, 18:51	24/09/26, 21:33	2h 41m
6	Supply Spareparts	Rudi Hartono	24/09/26, 21:33	25/09/26, 00:14	2h 41m
7	Repair Process Remove faulty component · Install / repair component	Rudi Hartono	25/09/26, 00:42	25/09/26, 01:12	30m
8	Ground Test	Rudi Hartono	25/09/26, 01:35	25/09/26, 02:07	32m
9	RFU (Ready For Use) Remarks: Checked OK	Rudi Hartono	25/09/26, 02:26	25/09/26, 03:00	34m

Handed over by (Mechanic)	Checked by (Admin Plant)	Received by (Driver / Operator)
Rudi Hartono	**Admin Plant**	**Yusuf Maulana**