

COVER

Revision	Description	Date	Drawn	Checked
V10A	Initial	2017-04-22	xxx1zjxxx	

Schematics Index:


- 01 COEVR
- 02 RELAY

Schematics Block:

- 1、继电器模块

BUG

- 01 48脚画错



NO.2,
XinYe Road,
GaoXinXiqu,
Chengdu,
Sichuan,China.

SICHUAN HUIYUAN OPTICAL COMMUNICATIONS CO.,LTD

Title

RELAY_TEST_V10A

SizeA3

Document01COVER

RevV10A

DateWednesday, May 03, 2017

Sheet1of2

Designed byxxx1zjxxx

Checked by?

Approved by?

