

ID #: 1002 **Effective:** 2/5/2014 **Expires:** 2/5/2015

Equipment:	OSI 400,000 BTU Oven
Performed by:	Team
Frequency:	Meter Based
Description:	Gearbox and Roller Maintenance
Criteria:	Any non-conformance to the expected "like new" and/or "as designed" standard for a piece of equipment, device, component, or operating condition is to be corrected to an acceptable standard and maintained.
Notes:	This document is an example of the LINK360 Maintenance Procedure Full Form. This form is ideal for procedures written for multiple people or areas of expertise and provides additional fields in each procedure step.
If questions, contact:	Shift supervisor

3 Steps

Estimated time: 4 hours





#	Icon	Description	Images
1		Performed by: Operator Action: Shut down equipment per standard shutdown procedure.	
2	 16	Performed by: Lubricator Action: Change the oil in the print station gearbox Supplies: Lubrication gun (16) Notes: Remove the cover in the lower right corner to access the gearbox. Recheck after 1 hour. Benchmark: Oil level = 32 mL Results:	Control box 



PM Procedure

Runtime Maintenance



ID #: 1002 Effective: 2/5/2014 Expires: 2/5/2015

#	Icon	Description	Images
3		Performed by: Mechanic Action: Reverse the rollers. Supplies: 15/16" socket Notes: Install roller supports before loosening connectors. Results:	Rollers 

Procedure Change Notification:

Contact your supervisor if you have any questions or concerns about the accuracy or effectiveness of this procedure.