

Car Damage Analyzer

Vehicle damage assessment Gemma3n analysis

Complete AI analysis finished!

Upload & Analyze



Image uploaded successfully!



5 damage areas detected

Gemma3n AI Analysis Report

GENERAL ASSESSMENT
The vehicle has a dent on the front bumper and multiple scratches on the front bumper.

DAMAGE TYPES IDENTIFIED
dent scratch

LOCATION & SIZE ASSESSMENT
Front bumper
Size: moderate, minor

Repair Recommendations

Recommended Action: Repair the dent. Inspect and address the scratches.	Estimated Time: 2–3 hours of labor
---	--

