realme TV Product Quality Report								
Customer Name:	Mangesh kadam			Work Order No.:	IN-SA210828	30566		
Customer Address:	Maharashtra Sati	hhaqyaday	nagar swamii	Invoice Date:	16/11/2020			
Model:	Maharashtra Sati bhagyaday nagar swami TV 43 - TV 43		TV S.No.:	01CFTV436200920855				
City:	Ratnagiri	Pin Code:	415604	State:	MAHARASHT			
Fault details:	Vertical Bar line on display			Installation Date:				
Order ID:	1H28-33672RGSC01-6187426			Who opened TV box:				
Customer Email ID:		Sold by(shop name):				& ELECTRONICS		
Retailer contact number	8600666111			retailer email ID:				
Service Center & NSP:				RGSC01	•			
TV Box image	TV	TV Box image			TV Box image			
https://drive.google.com/c	https://drive.go	ogle.com,	open?id=1 <u>S</u> /	https://drive.go	oogle.com/o	pen?id=1S1QyhD\		
TV Front images	TVI	Front images						
https://drive.google.com/c	https://drive.go	ogle.com,	open?id=1Y/					
TV Back images	TV	TV Back images			TV Back images			

	Highlighted damage side in case of transit damage case	
Seri	ial number should be arly readable	
_	, roddasio	