Customer Name: RAVINDRA KAN Contact No 9890975717 Work Order No.: IN-SA2109210497 Maharashtra 1420, SHREE SAI GANESH Invoice Date: NA NAGAR, PADAWE WADI, MIRIOLE, Invoice Date: NA NAGAR, PADAWE WADI, MIRIOLE, Invoice Date: NA NA NA NA NA NA NA N	realme TV Product Quality Report						
Customer Address: NAGAR, PADAWE WADI, MIRJOLE, NATTHACIDID DATHACIDI Model: REALME, LED TV, HOME APPLIANCES / LE TV S.No.: O1CFTV436200815365 City: Ratnagiri Pin Code: 415612 State: MAHARASHTRA Fault details: Vartical lines on panels Order ID: 7172 Who opened TV box: Customer Email ID: NA Sold by(shop name): NA Service Center & NSP: NA TV Box image TV Box image TV Front images NA SIDE STATE COMMENT OF THE PROPERTY OF THE	Customer Name:	RAVINDRA KAN	Contact No.	9890975717	Work Order No.:	IN-SA2109210497	
Model: REALME, LED TV, HOME APPLIANCES / LETV S.No.: 01CFTV436200815365	Customer Address:	Maharashtra 1420, SHREE SAI GANESH NAGAR, PADAWE WADI, MIRJOLE,			Invoice Date:	NA	
Fault details: Vartical lines on panels Installation Date: NA Order ID: 7172 Who opened TV box: Engineer Customer Email ID: NA Sold by(shop name): NA Retailer contact number NA retailer email ID: NA Service Center & NSP: NA TV Box image TV Box image TV Box image TV Front images TV Front images	Model:	REALME, LED TV, HOME APPLIANCES / LET			TV S.No.:	01CFTV436200815365	
Order ID: 7172 Who opened TV box: Engineer Customer Email ID: NA Sold by(shop name): NA Retailer contact number NA retailer email ID: NA Service Center & NSP: NA TV Box image TV Box image TV Box image TV Front images TV Front images	City:	Ratnagiri	Pin Code:	415612	State:	MAHARASHTRA	
Customer Email ID: NA Retailer contact number NA Sold by(shop name): NA Retailer contact number NA Service Center & NSP: TV Box image TV Box image TV Front images TV Front images TV Front images	Fault details:	Vartical lines or	n panels		Installation Date:	NA	
Retailer contact number NA retailer email ID: NA Service Center & NSP: NA TV Box image TV Box image TV Box image TV Front images TV Front images	Order ID:	7172			Who opened TV box:	Engineer	
Service Center & NSP: NA TV Box image TV Box image TV Front images TV Front images TV Front images	Customer Email ID:		NA			NA	
TV Box image TV Box image TV Front images TV Front images	Retailer contact number	NA			retailer email ID:	NA	
TV Front images TV Front images	Service Center & NSP:	NA			•		
	TV Box image	TV Box image			TV Box image		
TV Back Images TV Back Images TV Back Images					TVP		
	IV Dack IIIIages	I V Dack IIIIages			I v Datk IIIIages		
Approved for DOA			Approve	d for DOA			