


EWR D&I ANNOTATION



FAN-000001L092001DP96-2881

Artemis # : 000001L092001DP96

Record Created Date :

Printed Date : 06/21/2010

Description : DI09-096. SEQ ID 96. 2009 Q2. DRIVER OF A 2007 COBALT REAR ENDED ANOTHER VEHICLE WHILE ON AN ARIZONA ROAD. RIGHT FRONT END DAMAGE. OWNER ALLEGES AIR BAGS SHOULD HAVE DEPLOYED. NO POLICE REPORT GIVEN. SPEED OF VEHICLE NOT GIVEN. NO RESPONSE FROM GM. *RM



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

December 16, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-096

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 2nd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 3, 7, 15, 39, 63, 78, 81, 82, 85, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 98, 100, 101, 103, 105, 106, 107, 108, 109, 110, 131, 137, 145, 146, 148, 149, 158, 167, 168, 178, 209, 216, 219, 231, 243, 253, 254, 255, 256, 257, 258, 259, 261, 263, 264, 266, 270, 271, 276, 281, 282, 288, 289, 290, 291, 292, 293, 297, 299, 300, 311, 312, 327, 338, 339, 341, 343, 344, 345, 346, 348, 349, 351, 352, 354, 370, 382, 390, 391	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new

requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

12660

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **January 22, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,



Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

11 February 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-096

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated December 16th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 2nd quarter of 2009.

GM's response is comprised of 88 disks for the incidents that are the subject of DI09-096.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 3 18605620-675350 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 3 18605620-675350_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI09-096
3 18605620-675350
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 3 18605620-675350 **_01_001** - is the first document responsive to Inquiry no. 1.
- 3 18605620-675350 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

<i>(88 Vehicles from the Light Vehicle Template)</i>		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
3	5GAER23D69J [REDACTED]	NISM
7	UNKNOWN	NISM
15	5GADS13S142 [REDACTED]	NISM
39	1G6DU57V090 [REDACTED]	LIT
63	UNKNOWN	NISM
78	1G1AL52F957 [REDACTED]	NISM
81	1G1AK52F257 [REDACTED]	NISM
82	1G1AK55F167 [REDACTED]	NISM
85	1G1AK15F467 [REDACTED]	NISM
87	1G1AK55F267 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
88	1G1AM15B367	NISM
89	1G1AL15FX67	NISM
90	1G1AK15F367	NISM
91	1G1AL58F977	NISM
92	1G1AK15F077	NISM
93	1G1AK55F577	NISM
94	1G1AK15F477	NISM
95	1G1AK55F577	LIT
96	1G1AK15F077	NISM
98	1G1AK58FX77	NISM
100	1G1AK55FX77	NISM
101	1G1AK15F477	NISM
103	1G1AK18F887	NISM
105	1G1AL58F287	NISM
106	1G1AK18F187	NISM
107	1G1AL58F987	NISM
108	1G1AK58F987	NISM
109	1G1AL58F987	NISM
110	1G1AT58H097	NISM
131	3GNDA23P76S	NISM
137	3GNDA13D48S	NISM
145	2G1WF52E049	NISM
146	2G1WF52E249	NISM
148	2G1WH52K049	NISM
149	2G1WH52K049	NISM
158	2G1WT58N279	NISM
167	2G1WT57K791	NISM
168	2G1WC57M591	NISM
178	1G1ZG57B39F	NISM
209	1GCEK24009Z	NISM
216	1GCHK29K57E	NISM
219	1GBJC34K78E	NISM
231	1GNFC16047J	NISM
243	1GNFK33059R	NISM
253	1GNDS13S642	NISM
254	1GNDT13S052	NISM
255	1GNDT13S052	NISM
256	1GNDS13SX52	NISM
257	1GNDT13S852	NISM
258	1GNDT13S052	NISM
259	1GNDT13S352	NISM
251	1GNDT13S662	NISM
263	1GNDT13S682	NISM
264	1GNDT13S882	NISM
266	1GNDS33S892	NISM
270	1GNES16S866	NISM
271	1GNEV23D29S	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
276	1GNDU03E64D [REDACTED]	NISM
281	1GKEV23D59J [REDACTED]	NISM
282	1GKEV23D99J [REDACTED]	NISM
288	UNKNOWN	NISM
289	1GKDS13S442 [REDACTED]	NISM
290	1GKDT13S442 [REDACTED]	NISM
291	1GKDT13S552 [REDACTED]	NISM
292	1GKDS13S962 [REDACTED]	NISM
293	1GKDS13S462 [REDACTED]	NISM
297	1GKET16S956 [REDACTED]	NISM
299	1GKES12S046 [REDACTED]	NISM
300	1GKES12S956 [REDACTED]	NISM
311	3GTEC13C48G [REDACTED]	NISM
312	3GTEK13378G [REDACTED]	NISM
327	5GTDN136568 [REDACTED]	NISM
338	1G2ZF55B264 [REDACTED]	NISM
339	1G2ZF55B064 [REDACTED]	NISM
341	1G2ZG558364 [REDACTED]	NISM
343	1G2ZH18N374 [REDACTED]	NISM
344	1G2ZG58B574 [REDACTED]	NISM
345	1G2ZH57N584 [REDACTED]	NISM
346	1G2ZG57B384 [REDACTED]	NISM
348	1G2ZH57N684 [REDACTED]	NISM
349	1G2ZF57B584 [REDACTED]	NISM
351	1G2ZJ57B494 [REDACTED]	NISM
352	1G2ZH36N994 [REDACTED]	NISM
354	6G2EC57Y19L [REDACTED]	NISM
370	2G2WP552881 [REDACTED]	NISM
382	5S3ET13S662 [REDACTED]	NISM
390	5GZER13737J [REDACTED]	NISM
391	5GZEV23748J [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing

responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read "G. Kent", written in a cursive style.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 88 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a legal document cover sheet titled "CIVIL CASE COVER SHEET" for the case "CARDONA V. CHEVROLET". The document is filed in the "SUPERIOR COURT FOR THE STATE OF CALIFORNIA, INDIO COUNTY". The cover sheet includes various checkboxes for case type, complexity, and other legal details. Annotations on the right side of the image point to specific features:

- Step 7: Next File (Image)**: Points to the "Next Image" button in the right-hand menu.
- Step 7: Next page**: Points to the "Next page" button in the right-hand menu.
- Step 8: Scale Image**: Points to the "Scale" section in the right-hand menu, which includes options for "fit", "Scale to fit", "Scale 50%", "Scale 100%", and "Scale 200%".
- Step 7: Image Properties**: Points to the "Image Properties" button at the bottom of the right-hand menu.

The cover sheet itself contains the following information:

ATTORNEY OR PARTY-RELATED ATTORNEY FIRM, FIRM AND ADDRESS:
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 381 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 TELEPHONE NO. 909-469-5127 FAX NO. 909-469-5126
 ATTORNEY FOR: PLAINTIFF'S

FILED AND OF COURT: JUDGE, CLERK, AND SHARED COURT, IF ANY
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COUNTY

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET
☐ Limited ☒ Unlimited

Complex Case Designation
☐ Counter ☐ Joinder
 Filed with first appearance by defendant
 (Cal. Rules of Court, rule 1811)

PLEASE COMPLETE ALL FIVE (5) ITEMS BELOW

1. Check one box below for the case type that best describes this case:

☒ Auto Tort (22)
☐ Other PIP/DWI (Personal Injury/Property Damage/Wrongful Death) Tort
☐ Assault (24)
☐ Product liability (24)
☐ Medical malpractice (45)
☐ Other PIP/DWI (23)
☐ Non-PIP/DWI (Other) Tort
☐ Business tort/unfair business practice (37)
☐ Child rights (e.g., discrimination, false arrest) (55)
☐ Defamation (e.g., slander, RAD) (13)
☐ Fraud (18)
☐ Intellectual property (19)
☐ Professional negligence (e.g., legal malpractice) (25)
☐ Other non-PIP/DWI tort (26)
☐ Employment
☐ Wrongful termination (36)

☐ Contract
☐ Breach of contract/warranty (46)
☐ Collection (e.g., money owed, open book account) (39)
☐ Insurance coverage (14)
☐ Other contract (37)
☐ Real Property
☐ Eminent domain/tortious condemnation (14)
☐ Wrongful eviction (33)
☐ Other real property (e.g., quiet title) (28)
☐ Unlawful Detainer
☐ Commercial (31)
☐ Residential (32)
☐ Drugs (34)
☐ Juvenile Delinquency
☐ Asset forfeiture (26)
☐ Petition for arbitration award (11)

☐ Will of decedent (32)
☐ Other probate matter (37)
☐ Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 188a-1812)
☐ Antitrust/Trade regulation (33)
☐ Construction defect (10)
☐ Claims insurance monies tort (33)

2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring nonpartisan judicial management:
 a. ☒ Large number of separately represented parties b. ☐ Large number of issues that will be time-consuming to resolve
 c. ☒ Substantial amount of documentary evidence d. ☐ Substantial post-trial issues
 e. ☐ Substantial issues of law or fact f. ☐ Substantial issues of law or fact

3. Type of remedies sought (check all that apply):
 a. ☒ Monetary b. ☐ Nonmonetary, declaratory or injunctive relief c. ☐ Other

4. Number of causes of action (specify): FIVE

5. This case ☐ is ☒ is not a class action suit.

Date: JULY 3, 2003

ERIC D. PARIS, ESQ., S/B# 147836
 (Print or print name)

NOTICE
 Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (except under the Probate, Family, or Welfare and Institutions Codes) (Cal. Rules of Court, rule 1811).
 File this cover sheet in addition to any cover sheet required by local court rule.
 If this case is complex under rule 1800 at seq. of the California Rules of Court, you must also file a notice of complexity.
 Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

From adopted by Monterey County Superior Court of California
 902.220 (Rev. January 1, 2006)

CIVIL CASE COVER SHEET

Right-hand menu:
 Next Image
 Previous Image
 Next page Ctrl+PgDn
 Previous page Ctrl+PgUp
 Full screen image Ctrl+F11
 Slide show F10
 fit Scale to fit
 1:2 Scale 50% F5
 1:1 Scale 100% F6
 2:1 Scale 200% F7
 Rotate left Ctrl+Alt+L
 Rotate right Ctrl+Alt+R
 Rotate by 180°
 Copy to clipboard
 Copy file to... Ctrl+C
 Move file to... Ctrl+X
 Rename file... F2
 Delete file... Del
 EXIF Image Information...
 Preferences... Ctrl+H

DI09-096
96 278516356 – 669524
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Injury
Address	City Tucson	Involved Dir	O'Reilly Chevrolet, Inc.	Safety	Yes
State AZ ZipCd	Con Acct	Source	Phone	Updated	4/7/2009 12:59:42 PM
Serial #/VIN 1G1AK15F077	Model Year 2007	Priority	Medium License # CHEVROL	Owner	MLCAKTE
Make Chevrolet	Warr. Start 11/30/2007	Status	Open	Opened	4/6/2009 06:10:30 PM
Model Cobalt	Mileage 17000	Sub-Status	Satisfied	Closed	
Abstract (ESIS) Non Deployment					
Customer Description	This is a BRC PAR Case. Do not assume case. Forward any inquiries to Teresa Mlcak ext: 41345				

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	Other Veh	People in Veh	Road Surface	Road Cond	Fire Report	Police Report
Owner	4/4/2009 01:00:00 PM	Y	1	1	Asphalt	Dry	None	2009018119
Driver Last Name	Driver First Name	DOB	Height	Weight	Disabilities			
			5'6"		none			
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Nichols	Gary	(520) 682-2088	State Farm Insurance					
Incident Loc	Oracle Rd, Tucson AZ	Incident Desc	the car in front of my daughter braked hard and my daughter hit the back of the car and the airbags didn't deploy					
Component	airbags	Damage Desc	whole right front of the car is damaged					
Vehicle Loc	Barnets towing 1514 S Freeway Frontage Rd Tucson AZ	Add'l Info						
Emergency Svc Names	Royal Metro Fire Department	Maint Loc	goodyear store					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	none
Vehicle Speed	45	Weather Condition	Prop Owner	none	Property Type	none	Prop Est Repair Cost	\$0.00
Last Service Date		Loc Last Service	Property Location	none	Prop Damage Description	none	Inspected By	
Veh Est Repair Cost	\$0.00	Spec Equip Installer	none		Inspection Date/Time			
Primary Veh Use	Personal	Inspection Type						
Veh Damage Description	whole front end of the vehicle is damaged			Explain Other				

Service Request Detail

PAR Injuries

Last Name: [REDACTED] First Name: [REDACTED] DOB: [REDACTED] Location: [REDACTED] Phone #: [REDACTED] Seating Pos: [REDACTED] Restraint Type: [REDACTED]
Occupant of Owner's Vehicle Driver Seatbelt
Injury Description: [REDACTED] Medical Ref: [REDACTED] Treatment Location: [REDACTED] Treated By: [REDACTED]
she hit her head, bruised up and neck problems. Northwest Hospital Dr. Burton Bentley II
Street Address: [REDACTED] City: [REDACTED] State: [REDACTED] Zip Code: [REDACTED]

Activities

Created: 4/8/2009 03:41:37 PM Created By: RODRIGOS Assigned To: ESISBIQU Activity Type: Escalation Activity Sub-Type: ESIS - Injuries Status: In Progress Completed: [REDACTED] Description: Assigned to ESIS

Contact Last Name: [REDACTED] Contact First Name: [REDACTED] Account: [REDACTED] BAC Code: [REDACTED]

Comments: [REDACTED]

Injuries

Confidential Comments: [REDACTED]

Created: 4/8/2009 09:58:32 AM Created By: KINZERTH Assigned To: RODRIGOS Activity Type: Notify CRM Activity Sub-Type: [REDACTED] Status: Done Completed: 4/8/2009 03:41:36 PM Description: ESIS - Injuries

Contact Last Name: [REDACTED] Contact First Name: [REDACTED] Account: [REDACTED] BAC Code: [REDACTED]

Comments: [REDACTED]

Received And Assigned to ESIS

■ Jose Rodriguez ATX PAR

Confidential Comments: [REDACTED]

Created: 4/8/2009 06:46:23 PM Created By: MLCARTE Assigned To: KINZERTH Activity Type: BRC PAR Activity Sub-Type: ESIS - Injuries Status: Done Completed: 4/8/2009 09:56:31 AM Description: ESIS - Injury

Contact Last Name: [REDACTED] Contact First Name: [REDACTED] Account: [REDACTED] BAC Code: [REDACTED]

Comments: [REDACTED]

Received and assigned for ESIS escalation

Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments: [REDACTED]

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 06:24:15 PM	RODRIGOS	MLCAKTE	Notify CRM		Done	4/7/2009 06:48:22 PM	fy...

Contact Last Name	Contact First Name	Account	BAC Code

Comments: returned.

Injury screen is not complete.

Jose Rodriguez ATX PAR

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 03:31:41 PM	MLCAKTE	MLCAKTE	Inbound Call Dealer	Voice Mail Received	Done	4/7/2009 03:33:41 PM	O'Reilly Chevrolet @ (520) 747-8000 Scott Veroni-SM

Contact Last Name	Contact First Name	Account	BAC Code

Comments: Just returning your call, as for the cust and his vehicle, we have never seen this vehicle for anything airbag related before. If you have any other questions feel free to give me a call back

Teresa Meak ATX PAR

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 01:13:46 PM	KINZERTH	RODRIGOS	Notify CRM		Done	4/7/2009 06:24:14 PM	ESIS - Injuries

Contact Last Name	Contact First Name	Account	BAC Code

Comments: returned.

Injury screen is not complete.

Jose Rodriguez ATX PAR

Confidential Comments:

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 01:03:45 PM	MLCAKTE	KINZERTH	BRC PAR		Done	4/7/2009 01:13:45 PM	ESIS-Injury

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Received and assigned for ESIS escalation

Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 12:53:11 PM	MLCAKTE	MLCAKTE	Ownership Changed	Ownership Escalated to BRC	Done	4/7/2009 12:53:11 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 10:39:20 AM	KINZERTH	MLCAKTE	Ownership Changed		Done	4/7/2009 10:39:20 AM	Service Request Ownership has changed FROM: LAPIRAMA TO: MLCAKTE

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 10:38:41 AM	KINZERTH	MLCAKTE	BRC PAR	Initial Contact- AVM	Done	4/7/2009 12:36:01 PM	Called DVM Carreon Manual 80509 58785

Contact Last Name	Contact First Name	Account	BAC Code

Comments: CRS adv. calling concerning cust last name spelled. This is to adv you that his file has been reclassified in your area, cust concern is Non deployment of the airbags in a collision. The vehicle is a 2007 Chevrolet Cobalt and the involved dealer is O RIELLY CHEVROLET.

You are not required to respond to this msg, however if you do have any questions or concerns regarding this file, pls feel free to give me a call at 1-866-790-5700 x41345 and you can reference SR# 71-714902657

TeresaMicak.ATX.PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 10:38:31 AM	KINZERTH	MLCAKTE	BRC PAR	Initial Contact- Dealer	Done	4/7/2009 12:38:20 PM	Called O'Reilly Chevrolet @ (520) 747-8000 Scott Veroni-SM

Contact Last Name	Contact First Name	Account	BAC Code

Comments: Crs adv. calling in regards to cust and vehicle. Are there any known product concerns that relate to the customer's allegation, please give me a call back at number and ext

TeresaMicak/ATX/PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 10:38:22 AM	KINZERTH	MLCAKTE	BRC PAR		Initial Contact- Phone	Done	4/7/2009 12:52:24 PM
Contact Last Name	Contact First Name	Account	BAC Code				

Crs adv: would like to go over the information given to the previous agent and ask just a couple more quick questions. Do you have a moment to speak with me?

Cust sts: ok

Crs adv: went over pre par and par detail form with cust.

cust sts: my daughter was driving about 40-45 mph when the vehicle in front of her braked hard and she ran into the back of them. It caused the front end to be smashed up pretty good and my daughter hit her head and is having neck pain. right now I dont have any work and we cant afford these medical bills.

crs adv: are you looking for compensation for the medical bills that resulted from the accident?

cust sts: yes I would hope that GM would cover the medical

crs adv: what I will do is send this file up to the central claims office because they handle the medical claims we receive it will take about 7-10 days before they receive the file and after that someone will be in contact with you

cust sts: thank you

TeresaMlcak/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 10:38:13 AM	KINZERTH	MLCAKTE	BRC PAR	Acknowledgement	Done	4/7/2009 12:39:13 PM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments
Do you have a few moments to speak with me?

cust sts: yes

*Continued in Initial activity

TeresaMlcak/ATX/PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 10:38:04 AM	KINZERTH	MLCAKTE	Notify CRM		Done	4/7/2009 11:16:45 AM	File Assigned

Contact Last Name	Contact First Name	Account Number	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 10:37:56 AM	KINZERTH	MLCAKTE	Research		Done	4/7/2009 12:32:36 PM	Research VIN

Contact Last Name	Contact First Name	Account Number	BAC Code

Comments

CRS Performed VIN Scan:

GMVIS: Found no open recalls

VIN: Found no duplicate file

SVC History: No service history related to allegation

Teresa Micak ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 10:37:33 AM	KINZERTH	MLCAKTE	BRC PAR	Case Assigned	Done	4/7/2009 11:16:40 AM	Assigned to Teresa Micak x41345

Contact Last Name	Contact First Name	Account Number	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 08:32:20 AM	KINZERTH	LAPIRAMA	SR Opened		Done	4/7/2009 08:32:20 AM	SR in Status of Closed has been Re-Opened by KINZERTH

Contact Last Name	Contact First Name	Account Number	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/7/2009 08:32:19 AM	KINZERTH	LAPIRAMA	SR Closed - Satisfied		Done	4/7/2009 08:32:19 AM	Service Request has been Closed Satisfied.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/6/2009 08:29:56 PM	LAPIRAMA	KINZERTH	Escalation	Initiate PAR	Done	4/7/2009 08:32:16 AM	Assigning activity to PAR QUEUE

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days

Martin Joseph/CAC Tier1/MNL/LvL1

Received and assigned in PAR
Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/6/2009 06:11:15 PM	LAPIRAMA	LAPIRAMA	Inbound Call Customer	Complex Request	Done	4/6/2009 06:31:47 PM	Alleged product allegation-Airbags did not deploy

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Customer states:
-airbags didn't deploy

Customer seeks:
-have the concern looked into

CRS advised customer that their information will be forwarded to the Product Allegation Department within the BRC

Martin Joseph/CAC Tier1/MNL/LvL1

Confidential Comments

UCC Information

UCC Code	UCC Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front

GM Vehicle Inquiry System Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK15F077
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AK37 -2007 COBALT 2-DOOR LS COUPE	Warranty Start Date :	11/30/2007				
BARS Order Type :	70 - RETAIL - STOCK						
Delivering Dealer :	O RIELLY CHEVROLET, INC. PO BOX 12828 TUCSON , AZ 85732-2828 (520) 747-8000	Selling Source :	13 - CHEVROLET				
		Site Code :	39222				
		Business Associate Code :	114654				
Service Contract :	Yes	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns
--

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information
--

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	11/30/2007	40 miles	11/30/2010	36040 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	11/30/2007	40 miles	11/30/2013	100040 miles
48/48000 GM CERTIFIED USED LIMITED WARRANTY	11/30/2007	40 miles	11/30/2011	48040 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	11/30/2007	40 miles	11/30/2015	80040 miles
60/100000 POWERTRAIN COVERAGE LIMITED WARRANTY	11/30/2007	40 miles	11/30/2012	100040 miles
36/36000 FEDERAL EMISSION	11/30/2007	40 miles	11/30/2010	36040 miles

<http://198.208.187.167/gmvis/main/Summary?languageSelected=EN&VIN=1G1AK15F077...> 4/9/2009

GM Vehicle Inquiry System

Claim History

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information - Service Contract - Warranty Block - Branded Title

[Help](#)

VIN :	1G1AK15F077
-------	-------------

CLAIM HISTORY

Repair Order Date :		06/20/2007		Repair Order Number :		A82459		Odometer Reading :		0 miles	
Served By :		O RIELLY CHEVROLET, INC. PO BOX 12828 TUCSON, AZ 85732-2828 (520) 747-8000				Selling Source :		13 - CHEVROLET			
						Site Code :		39222			
						Business Associate Code :		114654			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
06/26/2007	807	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A		N/A	N/A	\$ 108.15	N

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 1998-2005 General Motors Corporation. All Rights Reserved.

<http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=1G1AK15F...> 4/9/2009

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
06/20/2007	A82459	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Vehicle Build

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN	1G1AK15F077
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AK37 -2007 COBALT 2-DOOR LS COUPE		
Gross Vehicle Weight Rating :	1672 kg (3687 lb)	Order Number :	MCCZON
Build Date :	06/20/2007	Build Plant :	177A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AL0 - SENSOR INDICATOR INFLATABLE RESTRAINT, FRT PASS/CHILD PRESENCE DETECTOR
AR9 - DELUXE FRONT BUCKET SEAT	AT8 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING
C67 - ELECT. FRONT AIR CONDITIONER	DC8 - MIRROR, O/S MANUAL FLDG, BLK
D36 - MIRROR L/S R/V TILT	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FE9 - FEDERAL EMISSIONS	FY1 - TRANS/AXLE 3.63 RATIO
IPB - INTERIOR TRIM DESIGN	J41 - BRAKE, FRONT DISC/REAR DRUM
K64 - 115 AMP GENERATOR	LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO
L61 - ENGINE, 2.2L DOHC 4V ECOTEC	MN5 - 4 SPEED AUTO TRANSMISSION
MX0 - TRANSMISSION, 4 SPD AUTOMATIC	NT7 - FEDERAL EMISSION TIER 2
N45 - 3 SPOKE STEERING WHEEL	PG1 - 15" STEEL WHEEL
QTU - P195/60R15 TOURING BW TIRES	R6K
R6P - PREMIUM PAINT	R9N - HEATED LEATHER APPOINTED FRONT BUCKET SEATS
R9X - XM TRACKING CODE	SLM - STOCK ORDERS
UQ4 - BASE SPEAKER SYSTEM	US8 - AM/FM STEREO, CD PLAYER & MP3 PLAYER (REPLACES STD/OPT RADIO)
VT7 - OWNERS MANUAL ENGLISH	V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA
ILS - ILS BASE PACKAGE	ISZ - OPTION PACKAGE DISCOUNT

<http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=1G1AK15F...> 4/9/2009

14B - GRAY	14I - GRAY
50U - SUMMIT WHITE	6AR - FRONT SPRING
7AR - FRONT SPRING	8AA - REAR SPRING
9AA - REAR SPRING	

© 1998-2005 General Motors Corporation. All Rights Reserved.