


EWR D&I ANNOTATION



FAN-000001L093001DP115-4740

Artemis # : 000001L093001DP115

Record Created Date : 09/13/2010

Printed Date : 09/13/2010

Description :

DI10-006 SEQ ID 115. 2009 Q3. NO POLICE REPORT WAS GIVEN. THE CUSTOMER COMPLAINT SAYS THE DRIVER OF A 2006 CHEVY COBALT WAS TRAVELING ON THE HIGHWAY AT ABOUT 50MPH WHEN AN ACCIDENT OCCURRED IN FRONT OF HER. CUSTOMER THEN ENDED UP HITTING ONE OF THE VEHICLES FROM BEHIND AND ALLEGES AIR BAGS SHOULD HAVE DEPLOYED. THE VEHICLE IS TOTALED BY INSURANCE. GM REPRESENTATIVE STATES THAT THE VEHICLE WAS STRUCK OUTSIDE THE SENSOR AREA AND THE VELOCITY CHANGE WAS NOT SIGNIFICANT FOR AIR BAGS TO DEPLOY. VEHICLE ONLY SHOWED AROUND A 5MPH SPEED CHANGE. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

July 6, 2010

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-006

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 6, 12, 13, 14, 15, 16, 17, 46, 47, 50, 60, 61, 93, 103, 105, 106, 115, 119, 129, 132, 135, 147, 161, 171, 185, 186, 187, 188, 189, 190, 192, 193, 194, 215, 231, 239, 242, 271, 278, 281, 297, 321, 326, 342, 344, 349, 350, 352, 355, 375, 384, 386, 450, 451, 452, 462, 467, 471, 478, 495	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **August 6, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly legible.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

AUG 18 2010

August 17, 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-006

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated July 6th, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2009.

GM's response is comprised of 62 disks for the incidents that are the subject of DI10-006.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 6 48649735-678866 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 6 48649735-678866_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-006
6 48649735-678866
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

6 48649735-678866 **_01_001** - is the first document responsive to Inquiry no. 1.
6 48649735-678866 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI10-006, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

<i>(60 Vehicles from the Light Vehicle Template)</i>		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
6	5GAER23D19J [REDACTED]	NISM
12	1G4HD57267U [REDACTED]	NISM
13	1G4HD57287U [REDACTED]	NISM
14	1G4HE57Y48U [REDACTED]	NISM
15	1G4HD57278U [REDACTED]	NISM
16	1G4HD57218U [REDACTED]	NISM
17	1G4HD57248U [REDACTED]	NISM
46	1G6DT57V380 [REDACTED]	NISM
47	1G6DF577880 [REDACTED]	NISM
50	1G6DS57V890 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
60	1G6KD57Y17U [REDACTED]	NISM
61	1G6KD57947U [REDACTED]	NISM
93	KL1TJ58Y05B [REDACTED]	NISM
103	KL1TD66E09B [REDACTED]	NISM
105	KL1TD56E19B [REDACTED]	NISM
106	2G1FC1EV0A9 [REDACTED]	NISM
115	1G1AK55F267 [REDACTED]	PAR
119	1G1AK15F967 [REDACTED]	NISM
129	1G1AK55F677 [REDACTED]	NISM
132	1G1AK58F887 [REDACTED]	NISM
135	1G1AM58B187 [REDACTED]	NISM
147	1G1YY26W185 [REDACTED]	LIT
161	2CNFLGEYXA6 [REDACTED]	NISM
171	3GNDA13D57S [REDACTED]	NISM
185	2G1WF52E349 [REDACTED]	NISM
186	2G1WF52E659 [REDACTED]	NISM
187	2G1WH52K359 [REDACTED]	NISM
188	2G1WF52E859 [REDACTED]	NISM
189	2G1WF52E659 [REDACTED]	NISM
190	2G1WF52E359 [REDACTED]	NISM
192	2G1WC581469 [REDACTED]	NISM
193	2G1WB58K669 [REDACTED]	NISM
194	2G1WB58K069 [REDACTED]	NISM
215	2G1WB5ENXA1 [REDACTED]	NISM
231	1G1ZG57BX84 [REDACTED]	NISM
239	1G1ZH57B69F [REDACTED]	NISM
242	1G1ZK57749F [REDACTED]	NISM
271	2GCEK19T541 [REDACTED]	NISM
278	1GCEK19C47Z [REDACTED]	NISM
281	2GCEK19J171 [REDACTED]	NISM
297	1GCHK73K79F [REDACTED]	NISM
321	1GNEC13T75R [REDACTED]	LIT
326	2CNBJ13C036 [REDACTED]	NISM
342	1GNDD13S142 [REDACTED]	NISM
344	1GNDD13S042 [REDACTED]	NISM
349	1GNDD13S852 [REDACTED]	NISM
350	1GNDD13S352 [REDACTED]	NISM
352	1GNDD13S362 [REDACTED]	NISM
355	1GNDS13SX62 [REDACTED]	NISM
375	1GNDV23178D [REDACTED]	PAR
384	1GKER137X8J [REDACTED]	NISM
386	1GTDS43E888 [REDACTED]	LIT
450	1G2AL18H797 [REDACTED]	NISM
451	1G2AS18H197 [REDACTED]	NISM
452	1G2AS18H297 [REDACTED]	NISM
462	1G2ZH57N784 [REDACTED]	NISM
467	1G2ZG57N994 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
471	1G2ZM577194 [REDACTED]	PAR
478	2G2WP552061 [REDACTED]	LIT
495	1G8ZS57B49F [REDACTED]	NISM

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**


Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 62 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a legal case cover sheet for 'CARDONA V. CHEVROLET' filed in the Superior Court for the State of California, Indio County. The case is a Civil Case Cover Sheet, specifically a 'Complex Case Designation' case. The cover sheet includes sections for 'Check one box below for the case type that best describes this case', 'Type of remedies sought', and 'Number of causes of action (specify)'. The cover sheet is annotated with various callouts and arrows pointing to specific features:

- Step 7: Next File (Image)**: Points to the 'Next Image' button in the right-hand menu.
- Step 7: Next Page**: Points to the 'Next page' button in the right-hand menu.
- Step 8: Scale Image**: Points to the 'Scale 100%' option in the right-hand menu.
- Step 7: Image Properties**: Points to the 'Image Properties' button in the right-hand menu.

The cover sheet also includes a 'NOTICE' section at the bottom, which states that the cover sheet must be filed with the first paper filed in the action or proceeding, and that it must be filed in addition to any cover sheet required by local court rule. The cover sheet is dated July 3, 2003, and is filed by Eric D. Paris, Esq., S/B# 147836.

DI10-006
115 284088600-71-756557677
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Activity

SR No.	(b) (6)	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Collision
Address		City	Elkton	Involved Dir		Safety	Yes
State	MD	Postal Cd		Source	White Mail	Updated	10/9/2009 12:36:39 PM
Serial #/VIN	1G1AK55F267	Model Year	2006	Priority	Medium	License #	CHEVROL
Make	Chevrolet	Warr. Start	04/07/2006	Status	Closed	Owner	MLCAKTE
Model	Cobalt	Mileage	58,000	Sub-Status	Dissatisfied	Opened	9/9/2009 08:10:27 AM
Abstract	(Inspection) Non Deployment						
Customer	DO NOT ADVISE ON THIS FILE FOR ANY REASON!						
Description	This is a BRC PAR Case. Do not assume case. Forward any inquiries to Teresa Mlcak ext: 41345						
Closed	10/9/2009 12:35:49 PM						

GMPP Details

GMPP Term	GMPP Mileage	GMPP Retail Cost
-----------	--------------	------------------

Component Coverage

Component Coverage	Expiration Mileage	Expiration Date
--------------------	--------------------	-----------------

Certificate Details

Certificate Number	Amount	Expiration Date
--------------------	--------	-----------------

Pre-Authorization Basics

Service Dealer	BAC Code	Div. Dealer Code	Repair Order #
----------------	----------	------------------	----------------

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/9/2009 12:35:49 PM	MORALECR	MLCAKTE	SR Closed - Dissatisfied		Done	10/9/2009 12:35:49 PM	Service Request has been Closed
Contact Last Name	Contact First Name	Account	BAC Code				Dissatisfied.
Comments							

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/9/2009 12:35:07 PM	MORALECR	MORALECR	BRC PAR	Close-No Offer to Repair/Rep	Done	10/9/2009 12:35:17 PM	See business case
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/9/2009 12:32:02 PM	MORALECR	MORALECR	Outbound Call Customer	Made Contact	Done	10/9/2009 12:35:06 PM	
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

CRS advsd the air bags operated as designed. CRS advsd that the vehicle was struck outside the sensor area and that the velocity change was not significant enough for the air bags to deploy.

Cust sts that she has no questions.

CRS advsd would be closing file.

Crystal Morales/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/9/2009 12:30:57 PM	MORALECR	MORALECR	BRC PAR	Business Case	Done	10/9/2009 12:31:49 PM	No repairs. Operated as designed
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Veh shows: -5.42 mph changed at 50 ms.

Crystal Morales/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/7/2009 06:13:14 PM	GARCIAJR	GARCIAJR	BRC PAR	Inspection Received	Done	10/7/2009 06:13:35 PM	recvd EAA inspection
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/7/2009 01:29:58 PM	MERCADTO	MLCAKTE	Scheduled Follow-up		Done	10/9/2009 12:27:24 PM	Inspection
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Check for inspection and attach

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/5/2009 04:58:32 PM	MERCADTO	MERCADTO	Scheduled Follow-up		Done	10/7/2009 01:29:56 PM	Inspection
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Check for inspection report and contact customer to advise of any new info

10/7

1-3pm est

Tonie Mercado/PAR/ATX

Inspection not yet received

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/5/2009 12:22:47 PM	MERCADTO	MERCADTO	Outbound Call Customer		Done	10/5/2009 12:27:20 PM	
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Crs Adv: I was calling on behalf of OCRS She will be out of the office all this week. I will be handling the file while she is out. I am still awaiting the inspection report. I haven't yet received it but as soon as I do I will give you a call with that information

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/2/2009 06:18:10 PM	MLCAKTE	MLCAKTE	Manager Review	Case Assessment	Done	10/2/2009 06:19:18 PM	Notes for case
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Vehicle has been totalled by the insurance company all results are for informational purposes only

if the inspection comes in please attach and deliver.

TeresaMlcak.ATX.pAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2009 05:46:55 PM	MLCAKTE	MLCAKTE	Scheduled Follow-up		Done	10/5/2009 04:58:30 PM	Check for inspection results
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/29/2009 10:55:19 AM	MLCAKTE	MLCAKTE	BRC PAR		Done	9/29/2009 10:55:32 AM	Inspection Sent
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/29/2009 10:42:06 AM	MLCAKTE	MLCAKTE	Scheduled Follow-up		Done	10/1/2009 05:46:42 PM	Check for inspection results
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/29/2009 10:40:18 AM	MLCAKTE	MLCAKTE	PAR Case Assessment	Collision	Done	9/29/2009 10:42:04 AM	Assessment
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

driving down rt 40 at about 50 when the first vehicle pulled out and hit the second vehicle and she hit the second from behind

Vehicle has been totalled Inspection is for informational purposes only.

Crs to send inspector

TeresaMlcak.ATX.PAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/29/2009 10:38:33 AM	MLCAKTE	MLCAKTE	BRC PAR	Inspection- EAA- Airbag	Done	9/29/2009 10:40:17 AM	Vehicle Location
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Co-Part

2251 Old Westminster Pike
Sinkburg MD, 21048

410-871-9080

Stock# 17177409

TeresaMlcak.ATX.PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/28/2009 06:11:28 PM	MLCAKTE	MLCAKTE	Scheduled Follow-up		Done	9/29/2009 10:38:32 AM	Send Inspection request
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/28/2009 01:27:48 PM	MLCAKTE	MLCAKTE	Scheduled Follow-up		Done	9/28/2009 06:11:26 PM	Send Inspection request
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/28/2009 01:25:30 PM	MLCAKTE	MLCAKTE	Inbound Call Third Party	Other	Done	9/28/2009 01:27:41 PM	Tom Wilcox 877-889-6406 ext: 7723 Claim #
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

I got your message regarding the cust and the vehicle. I called the salvage yard and gave permission to have your inspector take a look any other questions feel free to give me a call

Teresamlcak.ATX.PAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/25/2009 04:45:52 PM	MLCAKTE	MLCAKTE	Outbound Call Third Party	Left Message	Done	9/25/2009 04:50:01 PM	Tom Wilcox
Contact Last Name		Contact First Name		Account		BAC Code	877-889-6406 ext: 7723
							Claim #

Comments

If you could please contact the vehicle location and ok the inspection and let me know when this is done at number and ext

TeresaMlcak.ATX.PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/24/2009 06:01:55 PM	MLCAKTE	MLCAKTE	Scheduled Follow-up		Done	9/25/2009 04:45:42 PM	contact insurance
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/24/2009 01:51:40 PM	MLCAKTE	MLCAKTE	Scheduled Follow-up		Done	9/24/2009 06:01:53 PM	contact insurance
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/24/2009 11:48:15 AM	MLCAKTE	MLCAKTE	Outbound Call Third Party	Left Message	Done	9/24/2009 01:51:32 PM	Tom Wilcox
Contact Last Name		Contact First Name		Account		BAC Code	877-889-6406 ext: 7723
							Claim #

Comments

Crs adv: the cust has requested that we do an inspection of the airbag system on the vehicle and the salvage lot needs your authorization to allow us to do that. if you could please give me a call back at number and ext

TeresaMlcak.ATX.PAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/24/2009 11:42:35 AM	MLCAKTE	MLCAKTE	Outbound Call Third Party	Made Contact	Done	9/24/2009 11:47:11 AM	Co-part
Contact Last Name		Contact First Name		Account	BAC Code		410-871-9080

Comments

Crs adv: calling in regards to the vehicle. is there a stock number associated with it?

Co: # 17177409

Crs adv: We would like to do an inspection on the vehicles airbag system, would that be possible?

Co: you will need authorization from the insurance company before we can allow that

Crs adv: thank you

TeresaMlcak.ATX.PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/24/2009 11:36:37 AM	MLCAKTE	MLCAKTE	Outbound Call Customer	Made Contact	Done	9/24/2009 11:42:03 AM	
Contact Last Name		Contact First Name		Account	BAC Code		

Comments

Crs adv: calling to see if you have located the vehicle.

Cust sts:

Co-part

2251 Old Westminster Pike
Sinkburg MD, 21048

410-871-9080

and they said call them and they will talk to the insurance company

crs adv: ok i will get this going and you should here from the inspector in a few days.

TeresaMlcak.ATX.PAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/21/2009 06:31:11 PM	MLCAKTE	MLCAKTE	Scheduled Outbound Call	Cust	Done	9/24/2009 11:36:35 AM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

follow up to see if she was able to get the location of the vehicle

Co-part

2251 Old Westminster Pike
Sinkburg MD, 21048

410-871-9080

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/21/2009 06:31:00 PM	MLCAKTE	MLCAKTE	Ownership Changed	Ownership Escalated to BRC	Done	9/21/2009 06:31:00 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/21/2009 06:22:01 PM	MLCAKTE	MLCAKTE	Outbound Call Customer	Made Contact	Done	9/21/2009 06:23:15 PM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

see initial contact

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:17:41 AM	KINZERTH	MLCAKTE	Ownership Changed		Done	9/18/2009 10:17:41 AM	Service Request Ownership has changed FROM: BOADOJE TO: MLCATE
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:17:20 AM	KINZERTH	MLCAKTE	BRC PAR	Initial Contact- AVM	Done	9/22/2009 04:53:47 PM	Called FDVM Grant Troy Troy 914055 8130
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS adv: calling concerning cust [REDACTED] last name spelled [REDACTED] This is to adv you that her file has been recieved in your area, cust concern is Non deployment of the airbags in a collision
The vehicle is a 2006 Chevrolet Cobalt and there is no involved dealer at this time

You are not required to respond to this msg, however if you do have any questions or concerns regarding this file, pls feel free to give me a call at 1-866-790-5700 x41345 and you can reference SR# 71-756557677

TeresaMlcak.ATX.PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:17:11 AM	KINZERTH	MLCAKTE	BRC PAR	Initial Contact- Dealer	Done	9/22/2009 04:44:29 PM	Called WILLIAMS CHEVROLET-OLDSMOBILE (410) 398-4500
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Speaking to the SM: Eric

Crs adv: calling in regards to cust and vehicle.

Srv: ok

Crs adv: Are there any known product concerns that relate to the customer's allegation?

Srv: none

Crs adv: Thank you

Srv: welcome

TeresaMlcak/ATX/PAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:16:59 AM	KINZERTH	MLCAKTE	BRC PAR	Initial Contact- Phone	Done	9/22/2009 04:41:26 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs adv: would like to go over the information given to the previous agent and ask just a couple more quick questions. Do you have a moment to speak with me?

Cust sts: ok

Crs adv: went over pre par and par detail form with cust

Cust sts: driving down rt 40 at about 50 when the first vehicle pulled out and hit the second vehicle and she hit the second from behind. and her airbags didnt deploy. the vehicle was totalled by the insurance company and they have already taken it and i just wanted to call and ask why.

crs adv: in these situations we normally send an inspector to look at the vehicle to see what we can find but if the insurance has totalled the vehicle anything we find would be for informational purposes only and since they have taken possession of the vehicle I will need you to contact them and find out where they have taken the vehicle and I will need a physical address and phone number for the salvage yard and the adjuster will need to contact the salvage yard and give permission for us to look at the vehicle

Cust sts: ok i will call them and get that info

TeresaMlcak.ATX.PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:16:52 AM	KINZERTH	MLCAKTE	BRC PAR	Acknowledgement	Done	9/18/2009 05:34:00 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS adv: Calling to inform cust that we have received your file concerning Non deployment of the airbags in a collision, we do require some further information regarding your vehicle and the incident. You can contact me at 1-866-790-5700 x41345 and you can reference SR# 71-756557677

TeresaMlcak/ATX/PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:16:43 AM	KINZERTH	MLCAKTE	Notify CRM		Done	9/18/2009 05:31:14 PM	File Assigned
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:16:36 AM	KINZERTH	MLCAKTE	Research		Done	9/22/2009 04:55:20 PM	Research VIN
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS Performed VIN Scan:

GMVIS:Found no open recalls

VIN: Found no duplicate file

SVC History: No service history related to allegation

TeresaMlcak.ATX.PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:16:20 AM	KINZERTH	MLCAKTE	BRC PAR	Case Assigned	Done	9/18/2009 05:31:11 PM	Assigned to Teresa Mlcak x41345
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:16:01 AM	KINZERTH	BOADOJE	SR Opened		Done	9/18/2009 10:16:01 AM	SR in Status of Closed has been Re-Opened by KINZERTH
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 10:15:59 AM	KINZERTH	BOADOJE	SR Closed - Satisfied		Done	9/18/2009 10:16:00 AM	Service Request has been Closed Satisfied.
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/18/2009 07:21:32 AM	BOADOJE	KINZERTH	Escalation	Initiate PAR	Done	9/18/2009 10:15:55 AM	Assigning activity to PAR QUEUE
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days

Received and assigned in PAR

Thaddeus Kinzer/PAR Workflow/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/16/2009 12:33:47 PM	BOADOJE	BOADOJE	Inbound Call Customer	Complex Request	Done	9/18/2009 08:30:53 AM	cust returning call
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

- cust called in to return ocrs' previous msg
- discussed pre-par case at length and provided necessary details
- informed cust that a PAR representative will contact her in 24-48 business hrs
- no other contact #, can call her anytime at primary number

Jenny Boado/MLA/CACT1/Whitemail/L1

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/15/2009 11:13:04 AM	BOADOJE	BOADOJE	Scheduled Outbound Call Cust	Cancelled - Cust Called Prior	Done	9/16/2009 12:33:29 PM	3rd consecutive attempt to contact cust
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

initiate PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/15/2009 11:04:25 AM	BOADOJE	BOADOJE	Outbound Call Customer	Left Message	Done	9/15/2009 11:13:50 AM	prepar
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

- left brief msg indicating reason for call, ocrs' direct line and work hrs, sr#
- requested callback at cust's earliest convenience

Jenny Boado/MLA/CACT1/Whitemail/L1

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/14/2009 03:45:48 PM	BOADOJE	BOADOJE	Scheduled Outbound Call		Done	9/15/2009 11:04:23 AM	initiate PAR
			Cust				
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/11/2009 03:15:32 PM	BOADOJE	BOADOJE	Scheduled Outbound Call Cust	Rescheduled - Rep	Done	9/14/2009 03:45:48 PM	2nd consecutive attempt to contact cust
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/11/2009 03:14:32 PM	BOADOJE	BOADOJE	Outbound Call Customer	Received No Answer	Done	9/11/2009 03:15:29 PM	cust call
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
- phone just keeps on ringing							
- no option to leave VM							

Jenny Boado/MLA/CACT1/Whitemail/L1

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/10/2009 02:59:45 PM	BOADOJE	BOADOJE	Scheduled Outbound Call Cust	Initial Attempt	Done	9/11/2009 03:14:31 PM	initial contact
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
follow pre-par procedures							

Jenny Boado/MLA/CACT1/Whitemail/L1

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/9/2009 09:19:17 AM	VALEZAJ0	BOADOJE	Notify CRM		Done	9/10/2009 02:59:21 PM	document attached, if you cant view the document, please notify me
Contact Last Name	Contact First Name	Account	EAC Code				
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/9/2009 09:17:09 AM	SADMIN	BOADOJE	Inbound White Mail	Customer	Done	9/10/2009 02:59:18 PM	BRC PAR Scanned: 2009-09-08-08.20.00.000000, MSXDocNum: 00018AA8
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

DOCUMENTS RECEIVED:

- letter from cust

"I am writing this letter in regard to my daughter's 2006 Chevrolet Cobalt. On 9/24/2009 she was involved in a collision of which her air bags DID NOT deploy!!! I would think that this is an issue you need to investigate. The was driving at least 50mph on Rt. 40 in the fast lane (2 lane highway), a vehicle (#1) pulled out of a business without looking which prompted the vehicle (#2) in front of my daughter to hit him, followed by my daughter (#3) hitting her. The airbags in the other vehicles deployed, however, hers did not. Needless to say she suffered greatly from the neck down, but did not go to the hospital due to the fact that she is a work-a-holic and did not want to miss any time. Unfortunately the vehicle is totaled, but I feel that GM needs to check other Cobalts and resolve this issue, and I sincerely hope she does not develop problems later in life with her back or neck."

CUST SKS:

- to inform us of non-deployment of airbags during a vehicle accident

ACTION PLAN:

- create new SR and attach docs
- establish phone contact to address concerns

Jenny Boado/MLA/CACT1/Whitemail/L1

UCC Codes

UCC Code	UCC Symptom	UCC Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front