


EWR D&I ANNOTATION



FAN-000001L101001DP151-8997

Artemis # : 000001L101001DP151**Record Created Date :** 01/05/2011**Printed Date :** 01/05/2011**Description :**

DI10-062 SEQUENCE 151 GENERAL MOTORS 1 INJURY 2007 CHEVROLET COBALT A SINGLE VEHICLE CRASH OCCURRED ON A RESIDENTIAL STREET IN THE DISTRICT OF COLUMBIA. THE DRIVER HAD PULLED OUT OF HER DRIVEWAY IN REVERSE AND THEN PLACED THE GEAR IN PARK. THE CAR SUDDENLY ACCELERATED AND RAN INTO A TRASH CAN THAT WAS PUSHED INTO THE WALL OF HER HOUSE. THE VEHICLE HAD DAMAGES TO THE FRONT AND THE DOORS WERE JAMMED. THE DRIVER WAS BELTED SHE SUSTAINED INJURIES CONSISTING OF A SEVERED TONGUE, 2 BROKEN FINGERS, AND A BRUISE UNDER HER LEFT BREAST. THE INSURANCE COMPANY TOTALED THE CAR. NO SIMILAR FIELD REPORTS, VOQS, OR TSBS. *AA

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

September 16, 2010

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-062

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 16, 34, 38, 53, 67, 77, 91, 94, 113, 114, 125, 151, 167, 172, 173, 183, 195, 196, 208, 217, 225, 231, 253, 261, 267, 268, 285, 286, 293, 320, 323, 357, 365, 409, 410, 451, 506, 516, 539, 540, 585	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the

information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **October 15, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

October 13, 2010

OCT 15 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-062

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated September 16, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2010.

GM's response is comprised of 41 disks for the incidents that are the subject of DI10-062.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 16 298093428-690125 and 2005 BUICK RAINIER. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 16 298093428-690125_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-062
16 298093428-690125
2005 BUICK RAINIER

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

16 298093428-690125_01_001- is the first document responsive to Inquiry no.1.

16 298093428-690125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI10-062, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(41 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
16	5GADT13S552 [REDACTED]	NISM
34	1G6DP577760 [REDACTED]	NISM
38	1G6DP57V680 [REDACTED]	NISM
53	1GYFK43569R [REDACTED]	NISM
67	1G6DK67V490 [REDACTED]	NISM
77	KL1TD52695B [REDACTED]	LIT
91	2G1FK1EJ3A9 [REDACTED]	NISM
94	2G1FB1EV4A9 [REDACTED]	NISM
113	1G1AM58B367 [REDACTED]	NISM
114	1G1AK55F667 [REDACTED]	NISM
125	1G1AK55F767 [REDACTED]	PAR
151	1G1AL55FX77 [REDACTED]	NISM
167	1G1AL58F787 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
172	1G1AT58H497 [REDACTED]	NISM
173	1G1AT58H797 [REDACTED]	NISM
183	1G1AG1FX3A7 [REDACTED]	NISM
195	1GCDT19E898 [REDACTED]	NISM
196	1G1YY32G935 [REDACTED]	NISM
208	2CNDL13F576 [REDACTED]	PAR
217	1GCFG15X481 [REDACTED]	NISM
225	3GNCA33D28S [REDACTED]	NISM
231	3GNBABDB4AS [REDACTED]	NISM
253	2G1WB55K379 [REDACTED]	NISM
261	2G1WB58K789 [REDACTED]	NISM
267	2G1WT57K491 [REDACTED]	NISM
268	2G1WC57M091 [REDACTED]	NISM
285	1G1ZH57B384 [REDACTED]	NISM
286	1G1ZJ57B28F [REDACTED]	LIT
293	1G1ZH57B39F [REDACTED]	NISM
320	1GCEC19X17Z [REDACTED]	NISM
323	3GCEC13J48G [REDACTED]	NISM
357	1GNFK13J57J [REDACTED]	NISM
365	1GNFK13559R [REDACTED]	NISM
409	1GNEV23D19S [REDACTED]	NISM
410	1GNLRHED5AS [REDACTED]	NISM
451	1GTEK19047Z [REDACTED]	NISM
506	1G2ZG57B994 [REDACTED]	NISM
516	1G2NW52EX2M [REDACTED]	NISM
539	5Y2SP67019Z [REDACTED]	NISM
540	5Y2SM67079Z [REDACTED]	PAR
585	5GZCZ53477S [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.


GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing

responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read "M. Carmen Benavides". The signature is fluid and cursive, with a large initial "M" and a stylized "B" at the end.

M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 41 Disks
Attachment A

Attachment A


Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.




Selected Death Incidents from the
 3rd Quarter 2004
 For Reporting Category: Light Vehicles

(c) Vallen-Systeme GmbH, www.vallen.de/freeware



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a 'CIVIL CASE COVER SHEET' form for the case 'CARDONA V. CHEVROLET'. The form includes sections for case information, case type, and a list of case categories. Annotations on the right side of the form indicate the following steps:

- Step 7: Next File (Image)**: Points to the 'Next Image' button.
- Step 7: Next Page**: Points to the 'Next page' button.
- Step 8: Scale Image**: Points to the 'Scale' section, which includes options for 'Fit Scale to fit', 'Scale 50%', 'Scale 100%', and 'Scale 200%'.
- Step 7: Image Properties**: Points to the 'Image Properties' button.

The form itself contains the following information:

ATTORNEY OR PARTY WITHOUT ATTORNEY (Name, title, address, and e-mail)
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 BUSINESS NO: 909-469-5127 FAX NO: 909-469-5126
 ATTORNEY FOR: PLAINTIFF'S
 REPORT MADE BY COURT, JUDICIAL OFFICE, AND JUDICIAL OFFICE, AND
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIC COURT
 CASE NAME: CARDONA V. CHEVROLET
 CIVIL CASE COVER SHEET
 Complex Case Designation
☐ Counter ☐ Joinder
☒ Limited ☒ Unlimited
 Filed with first appearance by defendant
 (Cal. Rules of Court, rule 1811)
 Please complete all five (5) items below:
 1. Check one box below for the case type that best describes this case:
 Auto Tort
☒ Auto (22)
 Other PIP/NOV (Personal Injury/Property Damage/Verbal/Debt) Tort
☐ Assault (24)
☐ Medical malpractice (40)
☐ Other PIP/NOV (23)
 Non-PIP/NOV (Other) Tort
☐ Business tort/unfair business practice (27)
☐ Child abuse (e.g., discrimination, false arrest) (30)
☐ Defamation (e.g., slander, libel) (13)
☐ Fraud (16)
☐ Intellectual property (15)
☐ Professional negligence (e.g., legal malpractice) (20)
☐ Other non-PIP/NOV tort (38)
☐ Employment
☐ Wrongful termination (36)
 Contract
☐ Breach of contract/warranty (24)
☐ Collection (e.g., money owed, open book accounts) (22)
☐ Insurance coverage (18)
☐ Other contract (37)
 Real Property
☐ Eminent domain/condemnation (14)
☐ Wrongful eviction (23)
☐ Other real property (e.g., quiet title) (26)
 Unlawful Detainer
☐ Commercial (31)
☐ Residential (32)
☐ Drugs (34)
☐ Judicial Review
☐ Asset forfeiture (35)
☐ Petition for attachment award (11)
 2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring exceptional judicial management:
 a. ☒ Large number of separately represented parties d. ☒ Large number of
 b. ☒ Extensive motion practice raising difficult or novel issues that will be time-consuming to resolve e. ☐ Coordination and
 c. ☒ Substantial amount of documentary evidence f. ☐ Substantial post
 3. Type of remedies sought (check all that apply):
 a. ☒ monetary ☐ nonmonetary, declaratory or injunctive relief c. ☐
 4. Number of causes of action (specify): FIVE
 5. This case ☒ is ☐ is not a class action suit
 Date: JULY 3, 2003
 ERIC D. PARIS, ESQ., S/B# 147836
 (TYPE OR PRINT NAME)
 NOTICE
 • Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (except under the Probate, Family, or Welfare and Institutions Code) (Cal. Rules of Court, rule 1811)
 • File this cover sheet in addition to any cover sheet required by local court rules.
 • If this case is complex under rule 1800 of the California Rules of Court, you must
 • other parties to the action or proceeding.
 • Unless this is a complex case, this cover sheet shall be used for statistical purposes only.
 Form Approved for Mandatory Use
 Superior Courts of California
 982.2(b)(1) Rev. January 1, 2008
 CIVIL CASE COVER SHEET
 EXIF Image Information...
 Preferences... Ctrl+R
 Copy file to... Ctrl+C
 Move file to... Ctrl+X
 Rename file... F2
 Delete file... Del
 Rotate left Ctrl+Alt+L
 Rotate right Ctrl+Alt+R
 Rotate by 180°
 Copy to clipboard
 Full screen image Ctrl+F11
 Slide show F10
 Next page Ctrl+PgDn
 Previous page Ctrl+PgUp
 Next Image
 Previous Image
 Fit Scale to fit F5
 Scale 50% F6
 Scale 100% F7
 Scale 200% F8

DI10-062
151 298093287 – 689835
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No.	71-807867814	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Transmission - Automatic	Sub-Area	Initial PAR- Injury
Address		City	Washington	Involved Dir	Ourisman Chevrolet CO., Inc.	Safety	Yes
State	DC	Con Acct		Source	Phone	Updated	3/2/2010 11:35:10 AM
Serial #/VIN	1G1AL55FX77	Model Year	2007	Priority	Medium	License #	CHEVROL
Make	Chevrolet	Warr. Start	10/30/2010	Status	Open	Owner	MERCADTO
Model	Cobalt	Mileage	7200	Sub-Status	Dissatisfied	Opened	3/1/2010 03:35:42 PM
Abstract	Transmission - Automatic (Collision/Injury)						
Customer Description	This is a BRC PAR File. Please do not Assume. DO NOT ADVISE. Forward all Inquiries to Tonle @ ext 41183						

Pre-PAR

PAR Notifier	2/17/2010 09:45:00 AM	Injuries	Y	Other Veh	0	People in Veh	1	Road Surface	Concrete	Road Cond	Dry	Fire Report	n/a	Police Report	n/a
Driver Last Name		Driver First Name		DOB	58	Disabilities	None								
Insurance Agent Last Name		Insurance Agent First Name		Phone #		Insurance Agency									
Unk		Unk				Geico									
Incident Loc	Cust's Driveway: Washington DC					Incident Desc	I was on my way to the beauty parlor. I reversed out in my driveway and then put it in park so that I can drive away and the vehicle just accelerated on its own uncontrollably and I ran into the trashcan and pushed it all the way into the wall. No damage to the wall of my home. The front								
Component	Throttle - Unwanted acceleration					Damage Desc	Front end of the vehicle pushed back								
Vehicle Loc	Ourisman Chevrolet CO., Inc. 4400 BRANCH AVE Phone: (301) 423-4000					Add'l Info	Ins Info unavail.								
Emgcy Svc Names	n/a					Maint Loc	Ourisman Chevrolet CO., Inc.								

PAR Detail

Collision	Y	Non Collision		Property Damage	N	Thermal Evt	N	Spec Equip	None		
Vehicle Speed	5	Weather Condition	Dry	Prop Owner	n/a	Property Type	n/a	Prop Est Repair Cost	\$0.00		
Last Service Date		Loc Last Service		Property Location	n/a	Prop Damage Description	n/a	Inspection Date/Time			
Veh Est Repair Cost	\$10,000.00	Spec Equip Installer	n/a	Inspected By	Inspection Not Performed						
Primary Veh Use	Personal	Inspection Type	Accelerator/Throttle Systems	Explain Other	File going to ESIS						
Veh Damage Description	Front end of the vehicle pushed back, front doors was jammed										

Service Request Detail

PAR Injuries

DOB	Location	Phone #	Seating Pos	Restraint type
	Occupant of Owner's Vehicle		Driver	Seat Belt
Injury Description	Medical Rpt#	Treatment Location	Treated By	
Mouth: severed tongue, will be having surgery, 2 broken fingers on left hand, bruised on my side under my left breast	Unk	United Medical Center	Unk	
City	State	Zip Code		
Washington	DC			

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 11:38:40 AM	MERCADTO	MERCADTO	Scheduled Follow-up		Scheduled Alarm		Hood - ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CHECK CASE STATUS FOR ESIS PAJ

NOTE TO ASSISTING CRS'S. THIS IS NOT A SCHEDULED CALL TO THE CUSTOMER. PLEASE DO NOT ADVISE CUSTOMER OF THIS SCHEDULED ACTIVITY. ALL INQUIRIES NEED TO BE FORWARDED TO OGRS @ EXT 41183

TONIE MERCADO/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 11:35:31 AM	MERCADTO	ESISBIQU	Escalation	ESIS - Injuries	In Progress		ESIS - Injuries - Insurance Involvement
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Customer alleging vehicle experienced unwanted acceleration causing her to collide w/a wall. Driver sustained injury that required medical attention.

Insurance Claim Filed, insurance totalled vehicle.

Tonie Mercado/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 11:11:49 AM	MERCADTO	MERCADTO	Outbound Call Customer	Made Contact	Done	3/2/2010 11:23:02 AM	

Contact Last Name	Contact First Name	Account	BAC Code

Comments

See Inl and ack

Tonia Mercado/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 10:48:50 AM	MERCADTO	MERCADTO	Outbound Call Dealer	Left Message	Done	3/2/2010 10:52:56 AM	Ourisman Chevrolet @ (301) 423-4000

Contact Last Name	Contact First Name	Account	BAC Code
McCormick	Pat	Ourisman Chevrolet CO., Inc.	113708

Comments

Crs Spoke w/ Pat McCormick Svc Mgr

Crs Adv: Was calling regarding vehicle and incident. There is documentation in the file indicating that the vehicle as at your dealer. Just wanted to see what info you had on the vehicle and incident and would like to know if the vehicle has yet been diag. Ultimately the file will be forwarded to our central claims ESIS office for further handling. Please call when you get a chance. Provided contact info and SR

Tonia Mercado/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 10:03:37 AM	MERCADTO	MERCADTO	Ownership Changed	Ownership Escalated to BRC	Done	3/2/2010 10:03:38 AM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:21:40 AM	MARTIRAM	MERCADTO	Ownership Changed		Done	3/2/2010 09:21:40 AM	Service Request Ownership has changed FROM: SERVANTO TO: MERCADTO

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:21:29 AM	MARTIRAM	MERCADTO	BRC PAR	Initial Contact- Phone	Done	3/2/2010 11:35:17 AM	called

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Crs verified pre par and par detail information

Cust sts: I was on my way to the beauty parlor. I reversed out in my driveway and then put it in park so that I can drive away and the vehicle just accelerated on its own uncontrollably and I ran into the trashcan and pushed it all the way into the wall. No damage to the wall of my home. The front end of the vehicle was pushed back and the doors were jammed. I couldn't get out of the vehicle on my own. There has been an insurance claim filed and they said that it's a total loss. Injuries: Mouth: severed tongue, will be having surgery, 2 broken fingers on left hand, bruised on my side under my left breast Treated at United Medical Center.

Crs Adv: Due to the nature of the concern we will be forwarding the file to our central claims office for further handling. They will be in contact w/ you w/ 7-10 business days. If no contact by the end of that time frame please call back and we will assist you in getting in contact w/ them.

Tonia Mercado/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:21:26 AM	MARTIRAM	MERCADTO	BRC PAR	Initial Contact- Dealer	Done	3/2/2010 10:04:25 AM	Not required

Contact Last Name	Contact First Name	Account	BAC Code

Comments

No dlr visit in the last 2 yrs.

Tonia Mercado/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:21:20 AM	MARTIRAM	MERCADTO	BRC PAR	Initial Contact- AVM	Done	3/2/2010 11:09:11 AM	called FFOm Winters Zachary Zach 914055 8065

Contact Last Name	Contact First Name	Account	BAC Code
Hood	Elizabeth		

Comments

FFOM Name: Zachary Winters
Node/Mailbox: 914055-8065
This is Tonie Mercado
calling from the GM Product Allegation Dept to make you aware of a file that was received in your area.
The request number is: 71-807867814
The Customer's name is: [REDACTED]
The dealer involved is: Ourlman Chevrolet
Located in: Marlow Heights MD
The vehicle is a: 2007 Chevrolet Cobalt
With current mileage: 7K
The last 8 digits of the VIN# are: 77 [REDACTED]
This involves: Customer is alleging that when she placed the vehicle in reverse and went to reverse the vehicle it went forward rather than backward. Because driver sustained injuries and sought medical attention we will be forwarding the file to our central claims ESIS office for further handling
This message is for informational purposes only. However if you do have any questions please feel free to give me a call. Provided contact info.

Tonie Mercado/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:21:16 AM	MARTIRAM	MERCADTO	BRC PAR	Acknowledgement	Done	3/2/2010 11:23:39 AM	called [REDACTED]

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments

Crs Adv: This is Tonie Mercado calling from the GM Product Allegation Dept. I have received your file and do require further information. Do you have a moment to speak to me?

Cust sts: Yes

Continued In Initial

Tonie Mercado/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:21:10 AM	MARTIRAM	MERCADTO	Notify CRM		Done	3/2/2010 11:38:58 AM	file assigned

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:20:58 AM	MARTIRAM	MERCADTO	Research		Done	3/2/2010 10:04:10 AM	Research VIN

Contact Last Name	Contact First Name	Account	BAC Code

Comments

No open recalls

No prev related claim history

No other files

Tonle Mercado/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:20:30 AM	MARTIRAM	MERCADTO	BRC PAR	Case Assigned	Done	3/2/2010 10:01:49 AM	file assigned to Tonle Mercado ext 41183

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Received

Tonle Mercado/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:20:25 AM	MARTIRAM	SERVANTO	SR Opened		Done	3/2/2010 09:20:25 AM	SR In Status of Closed has been Re-Opened by MARTIRAM

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2010 09:20:23 AM	MARTIRAM	SERVANTO	SR Closed - Dissatisfied		Done	3/2/2010 09:20:24 AM	Service Request has been Closed Dissatisfied.
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/1/2010 04:35:14 PM	SERVANTO	MARTIRAM	Escalation	Initiate PAR	Done	3/2/2010 09:20:18 AM	Assigning activity to PAR QUEUE
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
CRS advised that a person from the PAR Department will contact the customer within 2 business days							
Tomas Servant/CAC Lvl 0/BA							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/1/2010 03:39:45 PM	SERVANTO	SERVANTO	Inbound Call Dealer	Complex Request	Done	3/1/2010 04:40:47 PM	Alleged product allegation PAR Injury
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
cust sis cust was starting the car put seatbelt on and warmed the veh put in reverse and the in stead of going going reverse aparently she felt a jump on the transmission and the went forward crashing the wall that was between 1 to 2 feet away causing injuris in her severed toungue broken lips and and broke two fingers left hand ring and midle fingers.							
Mr. had to have surferly to repair toungue and lips.							
Confidential Comments							

UCC Information

UCC Code	Symptom	Description
K30	Shift - Abnormal (Hard/Late)	Transmission - Automatic

GM Vehicle Inquiry System Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AL55FX77
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AL69 -2007 COBALT 4-DOOR LT SEDAN		Warranty Start Date :		10/30/2007		
BARS Order Type :	70 - RETAIL - STOCK						
Delivering Dealer :	OURISMAN CHEVROLET CO., INC. 4400 BRANCH AVE MARLOW HEIGHTS , MD 20748-1899 (301) 423-4000			Selling Source :		13 - CHEVROLET	
				Site Code :		14443	
				Business Associate Code :		113708	
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns
--

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information
--

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	10/30/2007	76 miles	10/30/2010	36076 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	10/30/2007	76 miles	10/30/2013	100076 miles
60/100000 POWERTRAIN COVERAGE LIMITED WARRANTY	10/30/2007	76 miles	10/30/2012	100076 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	10/30/2007	76 miles	10/30/2015	80076 miles
36/36000 FEDERAL EMISSION	10/30/2007	76 miles	10/30/2010	36076 miles

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading

08/01/2007	242605	I	Z6999 - PDI RELATED FLUID ADDS	2 miles
07/27/2007	A10109	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.
--

© 2009 General Motors. All Rights Reserved.



Mr. GMVIS 2

March 2, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

**INTERFACE WITH
CUSTOMER****View Vehicle Summary**

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

For this:

View V

Vehicle Information

VIN: 1G1AL55FX77

Model: 1AL69-2007 COBALT LT SEDAN

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: [0_Open](#)[VIEW VEHICLE AND OWNER VIN](#)

View V

View V

Comp

View V

Transa

Detail

View V

Inform

Required Field Actions

Open field actions are highlighted

Vehicle has no current record of required field actions.

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio Information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Emission Select Component Ltd Wty	02/21/2010	10/30/2007	75 MI	10/30/2015	80,076 MI

Powertrain Limited Warranty	02/21/2010	10/30/2007	76 MI	10/30/2012	100,076 MI
Corrosion Limited Warranty	02/21/2010	10/30/2007	76 MI	10/30/2013	100,076 MI
Bumper to Bumper Limited Warranty	02/21/2010	10/30/2007	76 MI	10/30/2010	36,076 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History

[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
08/01/2007	242605	ZPDI—Pre-Delivery Inspection		Z6999 - PDI Related Fluid Adds	2 MI
07/27/2007	A10109	ZPDI—Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.



Warranty

Mr. GMVIS 2

March 2, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH CUSTOMER

View Vehicle Build



This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available)

For this

View V

Vehicle Information

VIN: 1G1AL55FX77

Model: 1AL69-2007 COBALT LT SEDAN

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: 0_Open

REQUEST ANOTHER VIN

View V

View V

Comp

View V

Transa

Detail

View V

Inform

Vehicle Build

Model: 1AL69-2007 COBALT LT SEDAN

Order Number: MCNZCN

Gross Vehicle Weight: 1,712

Build Date: 07/27/2007

Build Plant: 7-

Option Codes

*GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

14C - GRAY

14J - GRAY

1LT - 1LT BASE PACKAGE

1SZ - OPTION PACKAGE DISCOUNT

29U - SPORT RED TINT COAT

6AR - FRONT SPRING

7AR - FRONT SPRING

8AA - REAR SPRING

9AA - REAR SPRING

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS

AL0 - SENSOR INDICATOR INFLATABLE RESTRAINT, FRT PASS/CHILD PRESENCE DETECTOR

AR9 - DELUXE FRONT BUCKET SEAT

AT8 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING

AU0 - REMOTE KEYLESS ENTRY

AU3 - POWER DOOR LOCKS W/REMOTE KEYLESS ENTRY

B34 - FLOOR MATS, FRONT/REAR

B35 - REAR FLOOR MATS

C67 - ELECT. FRONT AIR CONDITIONER

D36 - MIRROR VS RV TILT

DG7 - BODY COLOR POWER MIRRORS

FE1 - SUSPENSION SYSTEM-SOFT RIDE

FE9 - FEDERAL EMISSIONS

FY1 - TRANS/AXLE 3.63 RATIO

IPC - INTERIOR TRIM DESIGN

J41 - BRAKE, FRONT DISC/REAR DRUM

K64 - 115 AMP GENERATOR

L61 - ENGINE, 2.2L DOHC 4V ECOTEC

LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO

MN5 - 4 SPEED AUTO TRANSMISSION

MX0 - TRANSMISSION, 4 SPD AUTOMATIC

N45 - 3 SPOKE STEERING WHEEL

NT7 - FEDERAL EMISSION TIER 2

NW7 - TRACTION CONTROL

PG1 - 15" STEEL WHEEL

OTU - P195/60R15 TOURING BW TIRES

R6K - ONSTAR

R6P - PREMIUM PAINT

R9N - HEATED LEATHER APPOINTED FRONT BUCKET SEATS

R9X - XM TRACKING CODE

SLM - STOCK ORDERS

T43 - REAR SPOILER

UQ4 - BASE SPEAKER SYSTEM

US8 - AM/FM STEREO, CD PLAYER & MP3 PLAYER

V73 - STATEMENT OF VEHICLE CERT.-
U.S. /CANADA

VK3 - FRONT LICENSE PLATE BRACKET

VT7 - OWNERS MANUAL ENGLISH

Added Option Codes

Vehicle has no current record of SAIO codes.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.

**Warranty**

Mr. GMVIS 2

March 2, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

**INTERFACE WITH
CUSTOMER****View Vehicle Component Summary**

This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build

For this

- View V

Vehicle Information

VIN: 1G1AL55FX77

Model: 1AL69-2007 COBALT LT SEDAN

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: 0 Open

REQUEST ANOTHER VIN

- View V

View V

Comp

View V

Transa

Detail

View V

Inform

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY

Traceability: 707242100

Source Plant: T-CPC TONAWANDA, NEW YORK

Part / Number Broadcast: AWD

Date Scanned: 07/27/2007

Time Scanned: 15:27:00 Scan Station: 04

Component Code: 61-TRANSMISSION

Traceability: CN4A

Source Plant: J-HYDRAMATIC WINDSOR, ONTARIO

Part / Number Broadcast: 7EHJ

Date Scanned: 07/27/2007

Time Scanned: 15:27:00 Scan Station: 04

Component Code: 86-ELECTRONIC CONTROL MODULE (ECM)

Traceability: 2715701HW

Source Plant: 2-

Part / Number Broadcast:
YPCX

Date Scanned: 07/27/2007

Time Scanned: 20:55:00 Scan Station: 05

Component Code: 87-BODY CONTROL MODULE

Traceability: A71700012

Source Plant: R-

Part / Number Broadcast: 8392

Date Scanned: 07/27/2007

Time Scanned: 20:55:00 Scan Station: 04

Component Code: AB-IR-MODULE ASM-INFLATOR

Traceability: 2B1580120

Source Plant: M-MORTON-THIOKOL

Part / Number Broadcast: 6195

Date Scanned: 07/27/2007

Time Scanned: 16:55:00 Scan Station: 04

Component Code: AL-IR-MODULE ASM-UP

Traceability: 8190E1205

Source Plant: 9-

Part / Number Broadcast: 5893

Date Scanned: 07/27/2007

Time Scanned: 12:55:00 Scan Station: 04

Component Code: BK-INTERNATIONAL TRANS. CONTROL MODULE

Traceability: 072050572

Source Plant: K-

Part / Number Broadcast:
YHRL

Date Scanned: 07/27/2007

Time Scanned: 20:55:00 Scan Station: 04

Component Code: CB-SEQ NUM (FLEX) BODY ASM

Traceability: 3000483

Source Plant: -

Part / Number Broadcast: 1ZZ

Date Scanned: 07/25/2007

Time Scanned: 05:55:00 Scan Station:

Component Code: CP-SEQ NUM (FLEX) GEN ASM

Source Plant: -

Date Scanned: 07/26/2007

Traceability: 7310557

Part / Number Broadcast: 1XX

Time Scanned: 16:39:00 Scan Station:

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.



Warranty

Mr. GMVIS 2

March 2, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail



This screen allows GMVIS users to view the available information on individual transaction for the VIN selected

For this

View V

Vehicle Information

VIN 1G1AL55FX77

Model: 1AL69-2007 COBALT LT SEDAN

Service Contract No

Branded Title No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions 0 Open

SELECT ANOTHER VIN

View V

View V

Compt

View V

Transa

Detail

View V

Inform

Job Card Date: 08/01/2007

Job Card Number: 242605

Repair Service Agent: 113679

Odometer Reading: 2 MI

JIM MCKAY CHEVROLET, INC.

Authorization Code:

3509 UNIVERSITY DR

FAIRFAX VA 22030-2313

7035914800

Process Date

08/10/2007

Transaction Type:

ZPDI—Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z6999-PDI Related Fluid Adds

Causal Part Number

See other Parts and/or Net Items

Line Total: USD 2.27

Job Card Date: 07/27/2007

Job Card Number: A10109

Repair Service Agent: 113679

Odometer Reading: 0 MI

JIM MCKAY CHEVROLET, INC.

Authorization Code:

3509 UNIVERSITY DR

FAIRFAX VA 22030-2313

7035914800

Process Date

07/31/2007

Transaction Type:

ZPDI—Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time
Causal Part Number

Line Total: USD 115.26

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.

**Warranty**

Mr. GMVIS 2

March 2, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

**INTERFACE WITH
CUSTOMER****View Vehicle Delivery Information**

②

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

For this

View V

Vehicle Information

VIN: 1G1AL55FX77

Model: 1AL69-2007 COBALT LT SEDAN

Service Contract No Branded Title No

Warranty Block: No

PDI Status No

Order Type: 70 - RETAIL - STOCK

Field Actions: [0_Open](#)[VIEW MORE INFORMATION](#)

View V

View V

Comp

View V

Transa
DetailView V
Inform**Invoice Information**

Invoicing Service Agent: 113679

JIM MCKAY CHEVROLET, INC.

3509 UNIVERSITY DR

FAIRFAX VA 22030-2313 7035914800

Invoice Date: 07/27/2007

Ship to Information

Invoicing Service Agent: 113679

JIM MCKAY CHEVROLET, INC.

3509 UNIVERSITY DR

FAIRFAX VA 22030-2313 7035914800

Ship to Date: N/A

Delivery Information

Delivery Service Agent: 113708

OURISMAN CHEVROLET CO., INC.

4400 BRANCH AVE

MARLOW HEIGHTS MD 20748-1899 3014234000

Delivery Date: 10/30/2007

Delivery Type: 010--INDIVIDUAL

Delivery Odometer: 76

In Service Information

Invoicing Service Agent:

In Service Date: N/A

In Service Type: 0000

In Service Odometer: 0

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors