


EWR D&I ANNOTATION



FAN-000001L103001DP113-6439

Artemis # : 000001L103001DP113**Record Created Date :****Printed Date :** 03/25/2011

Description : DI11-005. SEQ ID 113. 2010 Q3. WE RECEIVED A POLICE REPORT AND VEHICLE WARRANTY SUMMARY FOR A 2006 CHEVY COBALT. THE DRIVER WAS TRAVELING ON A HWY WITH A POSTED SPEED LIMIT OF 55MPH WHEN A COLLISION HAPPENED. THE DRIVER STATES HE DID NOT SEE THE VEHICLE IN FRONT SLOWING FOR TRAFFIC WHICH CAUSED HIM TO COLLIDE WITH THE REAR END OF THAT VEHICLE. THE DRIVER ALLEGES THAT HE RECEIVED SERIOUS INJURIES AS A RESULT OF THE AIR BAG FAILURE. THE SPEED OF THE COLLISION IS NOT NOTED. SIMILAR RELATED AIR BAG COMPLAINTS FOR THE 2006 COBALT: VOQ-18. FR-100 (TOTAL AIRBAGS). PURSUIT-1 (FRONTAL AIRBAGS) RECALL-0. TSB-0. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

February 15, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-005

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 7, 8, 19, 20, 21, 23, 24, 50, 51, 68, 73, 83, 94, 113, 124, 136, 138, 147, 170, 172, 175, 177, 181, 183, 187, 191, 195, 197, 205, 225, 227, 274, 321, 323, 324, 327, 329, 369, 374, 375, 376, 377, 378, 379, 401, 418, 419, 437, 454, 455, 461, 468, 473, 474, 481, 483, 484, 487, 504, 511, 541, 560, 565, 570, 618, 619, 633	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly

identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CRF 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **March 18, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name and last name clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

March 17, 2011

MAR 18 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-005

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated February 15, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2010.

GM's response is comprised of 68 disks for the incidents that are the subject of DI11-005.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 7 316869715-696125 and 2010 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 7 316869715-696125_00_**Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-005
7 316869715-696125
2010 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

7 316869715-696125_01_001- is the first document responsive to Inquiry no.1.

7 316869715-696125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-107, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(67 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
7	5GALRBED2AJ [REDACTED]	NISM
8	5GALRAEDXAJ [REDACTED]	NISM
19	1G4HD572X7U [REDACTED]	NISM
20	1G4HD57257U [REDACTED]	NISM
21	1G4HR57Y77U [REDACTED]	NISM
23	1G4HA5EM8AU [REDACTED]	NISM
24	1G4HC5EM3AU [REDACTED]	NISM
50	1G6DE5EG6A0 [REDACTED]	NISM
51	1G6DE5EY7B0 [REDACTED]	NISM
68	3GYFNFY9AS [REDACTED]	NISM
73	3GNEC12097G [REDACTED]	LIT
83	KL1TD66638B [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
94	2G1FB1EV5A9	NISM
113	1G1AK15F567	NISM
124	1G1AK55F267	NISM
136	1G1AK15F967	NISM
138	1G1AL55F767	NISM
147	1G1AL15F277	PAR
170	1G1AL18F087	NISM
172	1G1AL58F887	NISM
175	1G1AK18F087	NISM
177	1G1AK18F987	NISM
181	1G1AK18H197	PAR
183	1G1AS18H397	NISM
187	1G1AT58H697	NISM
191	1G1AS58H297	NISM
195	1G1AB5F59A7	NISM
197	1G1AB5F57A7	NISM
205	1GTJTCDE1A8	NISM
225	2CNALDEW3A6	PAR
227	2CNALBEC0B6	NISM
274	2G1WA5EN4A1	NISM
321	1G1ZC5E05AF	NISM
323	1G1ZD5E7XAF	NISM
324	1G1ZA5E08AF	NISM
327	1G1ZE5EB4AF	NISM
329	1G1ZC5EU2BF	NISM
369	1GCEC290X9Z	RMR
374	1GCEK290X9Z	NISM
375	3GCRKSE31AG	NISM
376	3GCRKSE39AG	NISM
377	3GCXKTE29AG	NISM
378	1GCSKREA0AZ	NISM
379	1GCSKSEA2AZ	NISM
401	1GNUKKE32AR	NISM
418	1GNFK13017R	NISM
419	1GNFC13J97R	NISM
437	1GNDS13S052	LIT
454	1GNLRFEDXAS	PAR
455	1GNLVGED3AS	NISM
461	1GNDV33178D	LIT
468	1GNDV23E45D	NISM
473	1GKEV23738J	NISM
474	1GKEV23798J	NISM
481	1GKDS13SX52	NISM
483	1GKDT13S652	NISM
484	1GKDS13S652	NISM
487	1GKET63M672	NISM
504	1GTPKVE02AZ	PAR
511	1GKEC13T75R	LIT
541	1G2AL15F677	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
560	1G2ZH36N874 [REDACTED]	NISM
565	1G2ZM177984 [REDACTED]	NISM
570	1G2ZG57N494 [REDACTED]	NISM
618	1G8AJ55F47Z [REDACTED]	NISM
619	1G8AN15F17Z [REDACTED]	NISM
633	3GSCL33P58S [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 68 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The image shows a legal case cover sheet for 'CARDONA V. CHEVROLET' and a right-click context menu. Annotations point to specific menu items:

- Step 7: Next File (Image)** points to the 'Next Image' menu item.
- Step 7: Next Page** points to the 'Next page' menu item.
- Step 8: Scale Image** points to the '1:1 Scale 100%' menu item.
- Step 7: Image Properties** points to the 'Image Properties' menu item.

The cover sheet includes the following information:

- ATTOYNEY OR PARTY WITHOUT ATTORNEY:** ERIC D. PARIS, ESQ., S/B# 147836
- LAW OFFICES OF ERIC D. PARIS & ASSOCIATES:** 281 S. THOMAS STREET, SUITE 403, PUNAH, CALIFORNIA 91766
- TELEPHONE NO.:** 909-469-5127 **FAX NO.:** 909-469-5126
- ATTORNEY FOR:** PLAINTIFF'S
- CASE NAME:** CARDONA V. CHEVROLET
- CIVIL CASE COVER SHEET:** Limited ☐ Unlimited ☒
- Complex Case Designation:** Counter ☐ Joinder ☐
- FILED WITH FIRST APPEARANCE BY DEFENDANT:** (Cal. Rules of Court, rule 1811)
- PLEASE COMPLETE ALL FIVE (5) SECTIONS BELOW:**
- 1. Check one box below for the case type that best describes this case:**
 - ☒ Auto Tort (22)
 - ☐ Other PIP/DWD (Personal Injury/Property Damage/Wrongful Death) Tort
 - ☐ Asbestos (24)
 - ☐ Product Liability (24)
 - ☐ Medical malpractice (40)
 - ☐ Other PIP/DWD (23)
 - ☐ Non-PIP/DWD (Other) Tort
 - ☐ Business tortious business practice (27)
 - ☐ Civil rights (e.g., discrimination, false arrest) (30)
 - ☐ Defamation (e.g., slander, libel) (13)
 - ☐ Fraud (16)
 - ☐ Intellectual property (12)
 - ☐ Professional negligence (e.g., legal malpractice) (25)
 - ☐ Other non-PIP/DWD tort (38)
 - ☐ Employment
 - ☐ Wrongful termination (36)
 - ☐ Other employment (15)
 - ☐ Contract
 - ☐ Breach of contract/warranty (26)
 - ☐ Collection (e.g., money owed, open bank account) (28)
 - ☐ Insurance coverage (18)
 - ☐ Other contract (37)
 - ☐ Real Property
 - ☐ Eminent domain/inverse condemnation (14)
 - ☐ Wrongful eviction (23)
 - ☐ Other real property (e.g., quiet title) (26)
 - ☐ Unlawful Detainer
 - ☐ Commercial (31)
 - ☐ Residential (32)
 - ☐ Drugs (34)
 - ☐ Judicial Review
 - ☐ Asset forfeiture (29)
 - ☐ Petition re: arbitration award (11)
 - ☐ Writ of mandate (23)
 - ☐ Cover judicial review (28)
 - ☐ Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 1800-1812)
 - ☐ Arbitration/Trials regulation (23)
 - ☐ Construction defect (16)
 - ☐ Claims involving minors (24)
- 2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring exceptional judicial management.**
 - a. ☒ Large number of separately represented parties
 - b. ☒ Extensive motion practice raising difficult or novel issues that will be time consuming to resolve
 - c. ☒ Substantial amount of documentary evidence
 - d. ☒ Large number of dispositive motions
 - e. ☐ Substantial post-trial issues
- 3. Type of remedies sought (check all that apply):**
 - a. ☒ monetary b. ☐ nonmonetary, declaratory or injunctive relief
- 4. Number of causes of action (specify):** FIVE
- 5. This case ☐ is ☒ is not a class action suit.**
- Date:** JULY 3, 2003
- ERIC D. PARIS, ESQ., S/B# 147836**
- NOTICE:** Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (ex. under the Probate, Family, or Welfare and Institutions Code). (Cal. Rules of Court, rule 1800.)
- FILE THIS COVER SHEET IN ADDITION TO ANY COVER SHEET REQUIRED BY LOCAL COURT RULE.**
- IF THIS CASE IS COMPLEX UNDER RULE 1800 AT SEQ. OF THE CALIFORNIA RULES OF COURT, YOU MUST FILE THIS COVER SHEET WITH THE ACTION OR PROCEEDING.**
- UNLESS THIS IS A COMPLEX CASE, THIS COVER SHEET SHALL BE USED FOR STATISTICAL PURPOSES ONLY.**
- Form Adopted by Mandatory Local Judicial Councils in California: 902/231 (Rev. January 1, 2004)**
- CIVIL CASE COVER SHEET**

DI11-005
113 316870609 – 698035
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Received from BRC

**MINORA, MINORA, COLBASSANI,
KROWIAK & MATTIOLI**

Amil M. Minora
John J. Minora
Joseph S. Colbassani
Edward G. Krowiak
Jason J. Mattioli

ATTORNEYS AND COUNSELORS AT LAW
700 VINE STREET AT JEFFERSON AVENUE
SCRANTON, PA 18510-2441
PHONE (570) 961-1616
FAX (570) 961-1691 OR (570) 558-1110

Paul J. Ware
John R. Williams, Jr.
Patrick M. Scanlon
Thomas W. Munley

August 31, 2010

Chevrolet Corporation
P.O. Box 33170
Detroit, MI 48232-5170

Re: Our Client: [REDACTED]
D/A: 07/23/2010

RECEIVED

SEP 09 2010

ESIS-GM CLAIMS UNIT

To Whom It May Concern:


Please be advised that this office represents the interests of [REDACTED] who sustained severe injuries and damages in an accident involving the failure of the air bag to deploy while operating his 2006 Chevrolet Cobalt on or about the above date.

Upon receipt of this letter of representation, kindly turn this matter over to your insurance carrier or attorney for further handling and representation, with the request that they contact me at once.

Thank you.

Very truly yours,

MINORA, MINORA, COLBASSANI,
KROWIAK AND MATTIOLI


Jason J. Mattioli, Esquire

JJM:nmh

TA000110151

[Logout](#)

February 22, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER

View Vehicle Summary

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

Vehicle Information

VIN: 1G1AK15F567 [REDACTED] Model: 1AK37-2006 COBALT 2-DOOR LS COUPE
Service Contract: Yes Branded Title: No Warranty Block: No PDI Status: No
Order Type: 70 - RETAIL - STOCK
Field Actions: [1 Open](#)

[REDACTED]

For this vehicle:

[View Vehicle Summary](#)[Service Contract](#)[Branded Title](#)[Warranty Block](#)[View Vehicle Build](#)[View Vehicle](#)[Component Summary](#)[View Vehicle](#)[Transaction History Detail](#)[View Vehicle Delivery Information](#)

Required Field Actions

Open field actions are
highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Emission Recall	N060090	06090	ENGINE FUEL INJECTORS - REPLACE	01/22/2007	Closed
Product Safety Recall	N100023	10023	LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR	03/18/2010	Open
Noncompliance Recall	N060217	06217	HEAD IMPACT PROTECTION	03/13/2007	Closed

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Emission Select Component Ltd Wty	03/12/2010	12/19/2005	9 MI	12/19/2013	80,009 MI
	Bumper to Bumper Limited Warranty	03/12/2010	12/19/2005	9 MI	12/19/2008	36,009 MI

Certified Used Powertrain Limited Wty	03/12/2010	12/19/2005	9 MI	12/19/2010	100,009 MI
Corrosion Limited Warranty	03/12/2010	12/19/2005	9 MI	12/19/2011	100,009 MI
Special Coverage 09014	03/12/2010	12/19/2005	9 MI	12/19/2020	150,009 MI
Certified Used Limited Warranty	03/12/2010	12/19/2005	9 MI	12/19/2009	48,009 MI
Powertrain Limited Warranty	03/12/2010	12/19/2005	9 MI	12/19/2010	60,009 MI

Service Contract

Policy Number: [REDACTED]

Owner: [REDACTED]

Description: GM CERT 48/48 USED MG

Deductible Amount: 100.00

Effective Date: 01/20/2009

Expiration Date: 01/20/2013

Effective Odometer: 35683 MI

Expiration Odometer: 83683 MI

Daily Rental Limit: 35.00

Transaction History[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
06/03/2009	113446	ZREG----Regular Vehicle Transaction		E2141 - Link or Bushings, Front Stabilizer Shaft At Control Arm - Left - R&R Or Replace	47,827 MI
12/03/2008	081613	ZREG----Regular Vehicle Transaction		N0657 - Rear License Plate Lamp Bulb Replacement	35,556 MI
12/03/2008	081613	ZREG----Regular Vehicle Transaction		N0441 - Bulb, Composite Headlamp (Left) - Replace	35,556 MI
04/24/2007	220034	ZFAT----Field Action Recall		V1553 - 06090 - Injector, Fuel - Replace All	16,927 MI
04/24/2007	220034	ZFAT----Field Action Recall		V1556 - 06217 - Install Energy Absorbing Device	16,927 MI
01/01/2006	A14286	ZREG----Regular Vehicle Transaction		Z2084 - ROADSIDE SERVICE (FLAT TIRE)	500 MI
12/01/2005	186681	ZPDI----Pre-Delivery Inspection		Z6999 - PDI Related Fluid Adds	5 MI
11/30/2005	A37379	ZPDI----Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

February 22, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

**INTERFACE WITH
CUSTOMER****View Vehicle Build**

This screen allows GMV/S users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN: 1G1AK15F567 Model: 1AK37-2006 COBALT 2-DOOR LS COUPE
Service Contract: Yes Branded Title: No Warranty Block: No PDI Status: No
Order Type: 70 - RETAIL - STOCK
Field Actions: [1 - Open](#)

For this vehicle:[View Vehicle Summary](#)[Service
Contract](#)[Branded Title](#)[Warranty Block](#)[View Vehicle Build](#)[View Vehicle](#)[Component Summary](#)[View Vehicle](#)[Transaction History
Detail](#)[View Vehicle Delivery
Information](#)**Vehicle Build**

Model: 1AK37-2006 COBALT 2-DOOR LS COUPE
Gross Vehicle Weight: 1,677

Order Number: JPJQ18
Build Date: 11/30/2005
Build Plant: 7-

Option Codes

*IVH is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

14B - GRAY	14I - GRAY
1LS - 1LS BASE PACKAGE	1SZ - OPTION PACKAGE DISCOUNT
6AR - FRONT SPRING	7AR - FRONT SPRING
8AA - REAR SPRING	95U - ULTRA SILVER METALLIC
9AA - REAR SPRING	AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS
AR9 - DELUXE FRONT BUCKET SEAT	B34 - FLOOR MATS
B35 - REAR FLOOR MATS	C67 - ELECT. FRONT AIR CONDITIONER
DC8 - MIRROR, O/S MANUAL FLDG, BLK	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FE9 - FEDERAL EMISSIONS	FY1 - TRANS/AXLE 3.63 RATIO
IPB - INTERIOR TRIM DESIGN	J41 - POWER DISC FRONT BRAKES
K64 - 115 AMP GENERATOR	L61 - 2.2L DOHC 4 CYL ENGINE
LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO	MN5 - 4 SPEED AUTO TRANSMISSION
MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE	N46 - 4 SPOKE STEERING WHEEL
NT7 - FEDERAL EMISSION TIER 2	PG1 - 15" STEEL WHEEL
QTU - P195/60R15 TOURING BW TIRES	R6P - PREMIUM PAINT
SLM - STOCK ORDERS	T43 - REAR DECK-LID SPOILER
UN0 - AM/FM STEREO W/CD & RDS	UQ4 - BASE SPEAKER SYSTEM
V73 - STATEMENT OF VEHICLE CERT.-U.S. /CANADA	

Added Option Codes

-AN - SPECIAL COVERAGE APPLIED

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.


[Logout](#)

February 22, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary

This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build.

Vehicle Information

VIN: 1G1AK15F567 Model: 1AK37-2008 COBALT 2-DOOR LS COUPE
 Service Contract: Yes Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [1 Open](#) [REQUEST ANOTHER VIN](#)

For this vehicle:

→ [View Vehicle Summary](#)→ [Service Contract](#)→ [Branded Title](#)→ [Warranty Block](#)→ [View Vehicle Build](#)→ [View Vehicle Component Summary](#)→ [View Vehicle Transaction History Detail](#)→ [View Vehicle Delivery Information](#)

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY	Traceability: 511211793
Source Plant: T-CPC TONAWANDA, NEW YORK	Part / Number Broadcast: TZJ
Date Scanned: 11/30/2005	Time Scanned: 00:44:00 Scan Station: 04
Component Code: 61-TRANSMISSION	Traceability: 1Z5Z
Source Plant: J-HYDRAMATIC WINDSOR, ONTARIO	Part / Number Broadcast: 6EHJ
Date Scanned: 11/30/2005	Time Scanned: 00:44:00 Scan Station: 04
Component Code: 86-ELECTRONIC CONTROL MODULE (ECM)	Traceability: 00000ULQC
Source Plant: T-	Part / Number Broadcast: YMYZ
Date Scanned: N/A	Time Scanned: N/A Scan Station: 06
Component Code: 87-BODY CONTROL MODULE	Traceability: A53140177
Source Plant: R-	Part / Number Broadcast: 0944
Date Scanned: 11/29/2005	Time Scanned: 21:22:00 Scan Station: 04
Component Code: AB-IR-MODULE ASM-INFLATOR	Traceability: H325C2339
Source Plant: I-INLAND	Part / Number Broadcast: 1649
Date Scanned: 11/30/2005	Time Scanned: 02:03:00 Scan Station: 04
Component Code: AL-IR-MODULE ASM-I/P	Traceability: G325C1650
Source Plant: I-INLAND	Part / Number Broadcast: 4446
Date Scanned: 11/29/2005	Time Scanned: 22:04:00 Scan Station: 04
Component Code: BK-INTERNATIONAL TRANS. CONTROL MODULE	Traceability: 053240370
Source Plant: K-	Part / Number Broadcast: YLXH
Date Scanned: 11/30/2005	Time Scanned: 04:05:00 Scan Station: 04
Component Code: CB-SEQ NUM (FLEX) BODY ASM	Traceability: 1130202
Source Plant: -	Part / Number Broadcast: 1ZZ
Date Scanned: 11/23/2005	Time Scanned: 05:18:00 Scan Station:

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors All rights reserved.


[Logout](#)

February 22, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail

This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN: 1G1AK15F56 [REDACTED] Model: 1AK37-2006 COBALT 2-DOOR LS COUPE
 Service Contract: Yes Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [1. Open](#)

For this vehicle:

→ [View Vehicle Summary](#)→ [Service Contract](#)→ [Branded Title](#)→ [Warranty Block](#)→ [View Vehicle Build](#)→ [View Vehicle](#)→ [Component Summary](#)→ [View Vehicle](#)→ [Transaction History Detail](#)→ [View Vehicle Delivery Information](#)

Job Card Date: 06/03/2009

Job Card Number: 113446

Repair Service Agent: 216853
 KEN POLLOCK CHEVROLET CADILLAC
 2 MEREDITH ST EXCHANGE
 CARBONDALE PA 18407-2959
 5702821000

Odometer Reading: 47,827 MI

Authorization Code:

Process Date:
07/03/2009Transaction Type:
ZREG---Regular Vehicle TransactionTransaction Expense Category:
Customer EnthusiasmCustomer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op E2141-Link or Bushings, Front Stabilizer Shaft At Control Arm - Left - R&R Or Replace

Causal Part Number

→ [See other Parts and/or Net Items](#)

Line Total: USD 52.64

Job Card Date: 12/03/2008

Job Card Number: 081613

Repair Service Agent: 188062
 KEN POLLOCK CHEVROLET, INC.
 339 HWY 315
 PITTSBURGH PA 15201-3907
 5706554575

Odometer Reading: 35,556 MI

Authorization Code:

Process Date:
12/12/2008Transaction Type:
ZREG---Regular Vehicle TransactionTransaction Expense Category:
WarrantyCustomer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op N0657-Rear License Plate Lamp Bulb Replacement

Causal Part Number

→ [See other Parts and/or Net Items](#)

Line Total: USD 13.14

Job Card Date: 12/03/2008

Job Card Number: 081613

Repair Service Agent: 188062
KEN POLLOCK CHEVROLET, INC.
339 HWY 315
PITTSBURGH PA 15201-3907
5706554575

Odometer Reading: 35,556 MI
Authorization Code:

Process Date:
12/12/2008

Transaction Type:
ZREG---Regular Vehicle Transaction

Transaction Expense Category:
Warranty

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 2 Transaction Adjustment:
Labour Op N0441-Bulb, Composite Headlamp (Left) - Replace

Cause Code: 0000-Converted Claims

Causal Part Number

--See other Parts and/or Net Items

Line Total: USD 40.08

Job Card Date: 04/24/2007

Job Card Number: 220034

Repair Service Agent: 115096
LES STANFORD CHEVROLET CADILLAC INC
21730 MICHIGAN AVE
DEARBORN MI 48124-2350
3135656000

Odometer Reading: 16,927 MI
Authorization Code:

Process Date:
04/27/2007

Transaction Type:
ZFAT---Field Action Recall

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1 Transaction Adjustment:
Labour Op V1553-06090 - Injector, Fuel - Replace All

Cause Code: 0000-Converted Claims

Causal Part Number

--See other Parts and/or Net Items

Line Total: USD 145.98

Job Card Date: 04/24/2007

Job Card Number: 220034

Repair Service Agent: 115096
LES STANFORD CHEVROLET CADILLAC INC
21730 MICHIGAN AVE
DEARBORN MI 48124-2350
3135656000

Odometer Reading: 16,927 MI
Authorization Code:

Process Date:
04/27/2007

Transaction Type:
ZFAT---Field Action Recall

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 2 Transaction Adjustment:
Labour Op V1556-06217 - Install Energy Absorbing Device

Cause Code: 0000-Converted Claims

Causal Part Number

--See other Parts and/or Net Items

Line Total: USD 64.52

Job Card Date: 01/01/2006

Job Card Number: A14286

Repair Service Agent: 207453
GM ROADSIDE ASSISTANCE/CCAS
ONE CABOT RD
MEDFORD MA 02155-5117

Odometer Reading: 500 MI
Authorization Code: C

Process Date:
01/06/2006

Transaction Type:
ZREG---Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z2084-ROADSIDE SERVICE (FLAT TIRE)

Causal Part Number

---See other Parts and/or Net Items

Line Total: USD 44.07

Job Card Date: 12/01/2005

Job Card Number: 186681

Repair Service Agent: 115096
LES STANFORD CHEVROLET CADILLAC INC
21730 MICHIGAN AVE
DEARBORN MI 48124-2350
3135656000

Odometer Reading: 5 MI
Authorization Code:

Process Date:
12/06/2005

Transaction Type:
ZPDI---Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z6999-PDI Related Fluid Adds

Causal Part Number

---See other Parts and/or Net Items

Line Total: USD 1.25

Job Card Date: 11/30/2005

Job Card Number: A37379

Repair Service Agent: 115096
LES STANFORD CHEVROLET CADILLAC INC
21730 MICHIGAN AVE
DEARBORN MI 48124-2350
3135656000

Odometer Reading: 0 MI
Authorization Code:

Process Date:
12/06/2005

Transaction Type:
ZPDI---Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time

Causal Part Number

Line Total: USD 98.93

Global Warranty Management: Site Map

Privacy Policy | Terms of Use

© 2005 General Motors. All rights reserved.

[Logout](#)

February 22, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMER

View Vehicle Delivery Information

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN: 1G1AK15F56
Service Contract: **Yes** Branded Title: No Warranty Block: No PDI Status: No
Order Type: 70 - RETAIL - STOCK
Field Actions: [1 - Open](#)

[REQUEST ANOTHER VIN](#)

Invoice Information

Invoicing Service Agent: 115096
LES STANFORD CHEVROLET CADILLAC INC
21730 MICHIGAN AVE
DEARBORN MI 48124-2350 3135656000

Invoice Date: 11/30/2005

Ship to Information

Invoicing Service Agent: 115096
LES STANFORD CHEVROLET CADILLAC INC
21730 MICHIGAN AVE
DEARBORN MI 48124-2350 3135656000

Ship to Date: N/A

Delivery Information

Delivery Service Agent: 115096
LES STANFORD CHEVROLET CADILLAC
INC
21730 MICHIGAN AVE
DEARBORN MI 48124-2350 3135656000

Delivery Date: 12/19/2005
Delivery Type: 032--RETAILLEASE-EMPLOYEEESTOCK
(GMS)
Delivery Odometer: 9

In Service Information

Invoicing Service Agent:

In Service Date: N/A
In Service Type: 0000
In Service Odometer: 0

For this vehicle:

[→ View Vehicle Summary](#)[→ Service
Contract](#)[→ Branded Title](#)[→ Warranty Block](#)[→ View Vehicle Build](#)[→ View Vehicle
Component Summary](#)[→ View Vehicle
Transaction History
Detail](#)[→ View Vehicle Delivery
Information](#)

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

Police Crash Report

REPORTABLE CRASH

Crash Involves:

- ☐ DUI ☐ Fatality ☐ Hit and Run ☐ Commercial Vehicle ☐ State Police Vehicle ☐ Local Police Vehicle
☒ N/A ☐ Work Zone ☐ ATV ☐ Snowmobile ☐ Commonwealth Vehicle ☐ Local Gov Vehicle

Police Agency Data	Agency Name PA STATE POLICE - DUNMORE				Case Closed YES		Patrol Zone 72		Investigation Date 07/23/2010				
	Dispatch Time 16:37 hrs.		Arrival Time 16:51 hrs.		Investigator KREMPASKY, THOMAS J				Badge Number 08303				
Crash Data	Approval Date 07/26/2010				Reviewer GUTOWSKI, PETER P				Reviewer Badge Number 08004				
	Date of Crash 07/23/2010		Time of Crash 16:35 hrs.		Day of the Week FRIDAY		Crash Description REAR END						
Crash Data	County LACKAWANNA				Municipality MOOSIC BORO								
	Weather Conditions NO ADVERSE CONDITIONS				Relation to Roadway ON TRAVEL LANES								
Crash Data	Elimination DAYLIGHT				Road Surface Conditions DRY								
	# of Units 002	# of People 003	# of Injured 000	# Killed 000	EMS Agency NONE			Medical Facility NONE					
Crash Data	School Bus Related NO		School Zone Related NO		PennDOT Notified NO		Type of Intersection MIDBLOCK		Special Location NOT APPLICABLE				
	Work Zone NO		Work Zone Type		Where in Work Zone								
Work Zone	Speed Limit	Workers Present	Officer Present	Work Zone Characteristics									
				☐ Lane Closure ☐ Road Closed with Detour ☐ Work on Shoulder or Median ☐ Intermittent or Moving Work ☐ Flagger Control ☐ Other									
Principal Road	Route Signing INTERSTATE(NOT TURNPIKE)				Route Number 0081		Segment Number		Travel Lanes 02		Speed Limit 55 MPH	Orientation NORTH	
	House Number				Street Name 181				St. Ending HIGHWAY				
Intersecting Rd.	Used in Intersection Crashes				Route Signing		Route Number		Segment Number		Travel Lanes	Speed Limit	Orientation
					Street Name				St. Ending				
Distance From Landmark	Used for Mid-Block Crashes	Landmark 1	Route Number		Or Mile Post	Tenths	Or Segment Marker		Ramp Use Only		Feet		
			Street Name EXIT 182		Street Ending HIGHWAY		Or Miles 00		Tenths 2				
Distance From Landmark	Used for Mid-Block Crashes	Landmark 2	Route Number		Or Mile Post	Tenths	Or Segment Marker		Ramp Use Only		The above entry is the distance from the Crash Scene to Landmark 1		
			Street Name DAVIS		Street Ending STREET								
GPS	Latitude:		Degrees 41	Minutes 22	Seconds 04	Decimal 656	Longitude:		Degrees 75	Minutes 41	Seconds 27	Decimal 042	
	Traffic Control Device NOT APPLICABLE		Traffic Control Functioning NO CONTROLS										
Lane	Lane Closed FULLY		Lane Closure Direction NORTH		Traffic Detoured NO		Estimated Time Closed < 30 MIN.						
Event Information	Environmental / Roadway Potential Factors (E/R)												
	Factor 1 NONE				Factor 2				Factor 3				
Event Information	First Harmful Event in the Crash						Most Harmful Event in the Crash						
	Unit Number 001	Harmful Event HIT UNIT 2					Unit Number 001	Harmful Event HIT UNIT 2					
Event Information	Indicated Prime Factor DRIVER ACTION		Unit Number 001	Prime Factor Driver Action DRIVING TOO FAST FOR CONDITIONS									
	Prime Factor Environmental/Roadway				Prime Factor Vehicle Failure				Prime Factor Pedestrian Action				
Event Information	Road Surface Type						Special Jurisdiction						

Police Crash Report

REPORTABLE CRASH

Crash Involves:

- ☐ DUI ☐ Fatality ☐ Hit and Run ☐ Commercial Vehicle ☐ State Police Vehicle ☐ Local Police Vehicle
☒ N/A ☐ Work Zone ☐ ATV ☐ Snowmobile ☐ Commonwealth Vehicle ☐ Local Gov Vehicle

Driver/Pedestrian Information	Unit Number	Type Unit		Commercial Vehicle			
	001	Motor Vehicle In Transport		No			
	First Name	MI	Last Name	Suffix	DOB	Telephone Number	
	Street Address		City		State	Zip Code	
			THORNHURST		PA		
	Gender	License Number	License State	Class	Expiration Date	Owner/Driver	
	MALE		PA	C		PRIVATE VEHICLE OWNED/LEASED BY DRIVER	
	Driver Presence	Physical Condition		Primary Vehicle Code Violation		Person Charged	
	DRIVER OPERATED VEHICLE	APPARENTLY NORMAL		75 PA. C.S. 3361		YES	
	Alcohol/Drugs Suspected		Alcohol Test Type		Alcohol Test Results		
NO		TEST NOT GIVEN					
Driver Action DRIVING TOO FAST FOR CONDITIONS							
Pedestrian Action		Pedestrian Signals		Pedestrian Clothing	Pedestrian Location		
1st Harmful Event		Left or Right Side	Most Harmful	Utility Pole Number			
HIT UNIT 2			YES				
2nd Harmful Event		Left or Right Side	Most Harmful	Utility Pole Number			
3rd Harmful Event		Left or Right Side	Most Harmful	Utility Pole Number			
4th Harmful Event		Left or Right Side	Most Harmful	Utility Pole Number			
Vehicle Information	Owner First Name	Owner MI	Owner Last Name or Business Name		Suffix		
	Street Address		City		State	Zip Code	
			THORNHURST		PA		
	Vehicle Type		Special Usage		Government Equipment Number		
	AUTOMOBILE		NOT APPLICABLE				
	Model Year	Vehicle Make	Vehicle Model	Vehicle Color	VIN		
	2006	CHEVROLET	COBALT	SILVER	1G1AK15F567		
	License Plate	Reg. State	Est. Speed	Vehicle Towed	Towed By		
		PA	999	YES	ANDY'S TOWING		
	Insurance	Insurance Company	Policy Number		Expiration Date		
	YES	UNKNOWN	UNKNOWN				
	Direction of Travel	Vehicle Position	Vehicle Movement		Initial Impact Point		
	NORTH	LEFT LANE	GOING STRAIGHT		12 O'CLOCK		
	Damage Indicator	Gradient	Road Alignment	Possible Vehicle Failures			
	DISABLING	LEVEL	STRAIGHT	NONE			
# of Units	Type Unit 1	Tag Number	Tag Year	Tag State			
0							
Trailing Units	Unit Make		Unit Owner				
	Type Unit 2	Tag Number	Tag Year	Tag State			
	Unit Make	Unit Owner					
Motorcycle	Engine Size	Passenger?	Saddle Bag/Trunk?	Trailer?	Driver Education?		
	cc						
	Driver Helmet Type	Helmet Stayed On?	DOT/Snell Designation?	Eye Protection?	Long Sleeves?	Long Pants?	Over Ankle Boots?
	Passenger Helmet Type	Helmet Stayed On?	DOT/Snell Designation?	Eye Protection?	Long Sleeves?	Long Pants?	Over Ankle Boots?
Pedalcycle	Passenger?		Helmet?				
	Head Lights?		Rear Reflectors?				

Police Crash Report

REPORTABLE CRASH

Crash Involves:

- ☐ DUI ☐ Fatality ☐ Hit and Run ☐ Commercial Vehicle ☐ State Police Vehicle ☐ Local Police Vehicle
☒ N/A ☐ Work Zone ☐ ATV ☐ Snowmobile ☐ Commonwealth Vehicle ☐ Local Gov Vehicle

Driver/Pedestrian Information	Unit Number	002		Type Unit	Motor Vehicle In Transport		Commercial Vehicle	No	
	First Name			M	M	Last Name			Telephone Number
	Street Address			City	MILLVILLE		State	PA	Zip Code
	Gender	MALE		License Number			License State	PA	Class
	Expiration Date			Owner/Driver	PRIVATE VEHICLE OWNED/LEASED BY DRIVER				
	Driver Presence	DRIVER OPERATED VEHICLE		Physical Condition	APPARENTLY NORMAL		Primary Vehicle Code Violation		
	Alcohol/Drugs Suspected	NO		Alcohol Test Type	TEST NOT GIVEN		Alcohol Test Results		
	Driver Action	NO CONTRIBUTING ACTION							
	Pedestrian Action			Pedestrian Signals			Pedestrian Clothing	Pedestrian Location	
	1st Harmful Event	STRUCK BY UNIT 1		Left or Right Side			Most Harmful	YES	
2nd Harmful Event			Left or Right Side			Most Harmful			
3rd Harmful Event			Left or Right Side			Most Harmful			
4th Harmful Event			Left or Right Side			Most Harmful			
Vehicle Information	Owner First Name			Owner M	M	Owner Last Name or Business Name			Suffix
	Street Address			City	MILLVILLE		State	PA	Zip Code
	Vehicle Type	AUTOMOBILE		Special Usage	NOT APPLICABLE		Government Equipment Number		
	Model Year	2008		Vehicle Make	SUBARU		Vehicle Model	IMPREZA	
	Vehicle Color	BLUE		VIN	JF1GE61698H				
	License Plate			Reg. State	PA		Est. Speed	999	
	Vehicle Towed	YES		Towed By	ANDY'S TOWING				
	Insurance	YES		Insurance Company	ALLSTATE		Policy Number		
	Expiration Date								
	Direction of Travel	NORTH		Vehicle Position	LEFT LANE		Vehicle Movement	SLOWING/STOPPING IN LANE	
	Initial Impact Point	6 O'CLOCK							
	Damage Indicator	DISABLING		Gradient	LEVEL		Road Alignment	STRAIGHT	
	Possible Vehicle Failures	NONE							
	# of Units	0		Type Unit 1			Tag Number		
	Tag Year			Tag State					
Unit Make			Unit Owner						
Type Unit 2			Tag Number			Tag Year			
Tag State									
Unit Make			Unit Owner						
Engine Size	cc		Passenger?			Saddle Bag/Trunk?			
Trailer?			Driver Education?						
Driver Helmet Type			Helmet Stayed On?			DOT/Shell Designation?			
Eye Protection?			Long Sleeves?			Long Pants?			
Over Ankle Boots?									
Passenger Helmet Type			Helmet Stayed On?			DOT/Shell Designation?			
Eye Protection?			Long Sleeves?			Long Pants?			
Over Ankle Boots?									
Passenger?			Helmet?						
Head Lights?			Rear Reflectors?						

Police Crash Report

REPORTABLE CRASH

Crash Involves:

☐ DUI☐ Fatality☐ Hit and Run☐ Commercial Vehicle☐ State Police Vehicle☐ Local Police Vehicle☒ N/A☐ Work Zone☐ ATV☐ Snowmobile☐ Commonwealth Vehicle☐ Local Gov Vehicle

People Information	Unit #	Person No.	First Name	MI	Last Name	Suffix	DOB
	001	001		M			
	Street Address			City		State	Zip Code
				THORNHURST		PA	
	Phone Number	EMS Transport	Person Type	Gender	Injury Severity		
		NO	DRIVER	MALE	NOT INJURED		
People Information	Seat Position			Safety Equipment 1			
	DRIVER - ALL VEHICLES			LAP AND SHOULDER BELT USED			
	Safety Equipment 2			Extrication			
	AIR BAG NOT DEPLOYED - UNK SWITCH SETTING			NOT EXTRICATED			
	Ejection			Ejection Path			
	NOT EJECTED			NOT EJECTED/NOT APPLICABLE			
People Information	Unit #	Person No.	First Name	MI	Last Name	Suffix	DOB
	002	002		M			
	Street Address			City		State	Zip Code
				MILLVILLE		PA	
	Phone Number	EMS Transport	Person Type	Gender	Injury Severity		
		NO	DRIVER	MALE	NOT INJURED		
People Information	Seat Position			Safety Equipment 1			
	DRIVER - ALL VEHICLES			LAP AND SHOULDER BELT USED			
	Safety Equipment 2			Extrication			
	AIR BAG NOT DEPLOYED - UNK SWITCH SETTING			NOT EXTRICATED			
	Ejection			Ejection Path			
	NOT EJECTED			NOT EJECTED/NOT APPLICABLE			
People Information	Unit #	Person No.	First Name	MI	Last Name	Suffix	DOB
	002	003		A			
	Street Address			City		State	Zip Code
				BLOOMSBURG		PA	
	Phone Number	EMS Transport	Person Type	Gender	Injury Severity		
		NO	PASSENGER	FEMALE	NOT INJURED		
People Information	Seat Position			Safety Equipment 1			
	FRONT SEAT RIGHT SIDE			LAP AND SHOULDER BELT USED			
	Safety Equipment 2			Extrication			
	AIR BAG NOT DEPLOYED - UNK SWITCH SETTING			NOT EXTRICATED			
	Ejection			Ejection Path			
	NOT EJECTED			NOT EJECTED/NOT APPLICABLE			

Crash Involves:


☐ DUI☐ Fatality☐ Hit and Run☐ Commercial Vehicle

REPORTABLE CRASH

☐ State Police Vehicle☐ Local Police Vehicle☒ N/A☐ Work Zone☐ ATV☐ Snowmobile☐ Commonwealth Vehicle☐ Local Gov Vehicle

Police Crash Report

Diagram



Crash Synopsis

This crash occurred as both Unit #1 and Unit #1 were travelling North in the left N.B. lane of I-81 N.B. In doing so Unit #1, being operated behind Unit #2, struck Unit #2 in it's rear end with it's front end as Unit #2 was slowing in congested traffic. This was initial impact/final rest for both Units.

Narrative

This crash occurred as both Unit #1 and Unit #1 were travelling North in the left N.B. lane of I-81 N.B. In doing so Unit #1, being operated behind Unit #2, struck Unit #2 in it's rear end with it's front end as Unit #2 was slowing in congested traffic. This was initial impact/final rest for both Units.

Physical evidence at the scene consisted of both Units in the position of final rest (both Units facing North in the left N.B. lane of I-81 N.B.) with disabling damage to the rear end of Unit #2 and disabling damage to the front end of Unit #1.

Operator #1 was interviewed on scene on 07/23/10 at approximately 1651 hours. He related that he did not notice Unit #1 slowing down and collided with the rear end of that vehicle.

Operator #2 was interviewed on scene on 07/23/10 at approximately 1656 hours. He related that as he was slowing down in congested traffic, he felt his vehicle being

Police Crash Report

REPORTABLE CRASH

Crash Involves:

- | | | | | | |
|--------------------------------------|---------------------------------|-----------------------------------|--|--|--|
| ☐ DUI | ☐ Fatality | ☐ Hit and Run | ☐ Commercial Vehicle | ☐ State Police Vehicle | ☐ Local Police Vehicle |
| ☒ N/A | ☐ Work Zone | ☐ ATV | ☐ Snowmobile | ☐ Commonwealth Vehicle | ☐ Local Gov Vehicle |

Impacted from behind.
