


EWR D&I ANNOTATION



FAN-000001L103001DP124-8600

Artemis # : 000001L103001DP124**Record Created Date :** 03/25/2011**Printed Date :** 03/28/2011**Description :**

DI11-005. SEQ ID 124. 2010 Q3. WE RECEIVED A CALL LOG AND A POLICE REPORT FOR A 2006 CHEVY COBALT. THE DRIVER WAS BEHIND A SEMI TRUCK ON HWY RAMP WHEN SHE LOOKED DOWN FOR HER PHONE. THE VEHICLE DRIFTED ONTO THE SHOULDER AND WENT ALONG THE SIDE OF TRUCK. THE SEMI WAS THEN TRYING TO MERGE ONTO THE SHOULDER TO PARK AND PUSHED THE COBALT OFF THE ROAD. THE CAR WENT THROUGH A FENCE AND HIT A DITCH. THERE WAS RIGHT FRONT DAMAGE TO THE VEHICLE, BUT THE EXTENT IS UNKOWN. THE VEHICLE SPEED WAS AROUND 60MPH BEFORE THE ACCIDENT. THE SPEED AT IMPACT IS UNKOWN. THE DRIVER'S HEAD HIT THE STEERING WHEEL AND IS WONDERING WHY THE AIR BAGS DID NOT DEPLOY. FRONTAL COLLISIONS WITH THE 2006 COBALT: VOQ-18. FR-100 (TOTAL AIRBAGS). PURSUIT-1 (FRONTAL AIRBAGS). RECALL-0. TSB-0. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

February 15, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-005

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 7, 8, 19, 20, 21, 23, 24, 50, 51, 68, 73, 83, 94, 113, 124, 136, 138, 147, 170, 172, 175, 177, 181, 183, 187, 191, 195, 197, 205, 225, 227, 274, 321, 323, 324, 327, 329, 369, 374, 375, 376, 377, 378, 379, 401, 418, 419, 437, 454, 455, 461, 468, 473, 474, 481, 483, 484, 487, 504, 511, 541, 560, 565, 570, 618, 619, 633	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly

identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CRF 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **March 18, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in cursive script that reads "Christina Morgan".

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

March 17, 2011

MAR 18 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-005

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated February 15, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2010.

GM's response is comprised of 68 disks for the incidents that are the subject of DI11-005.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 7 316869715-696125 and 2010 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 7 316869715-696125_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-005
7 316869715-696125
2010 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

7 316869715-696125_01_001- is the first document responsive to Inquiry no.1.

7 316869715-696125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-107, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(67 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
7	5GALRBED2AJ [REDACTED]	NISM
8	5GALRAEDXAJ [REDACTED]	NISM
19	1G4HD572X7U [REDACTED]	NISM
20	1G4HD57257U [REDACTED]	NISM
21	1G4HR57Y77U [REDACTED]	NISM
23	1G4HA5EM8AU [REDACTED]	NISM
24	1G4HC5EM3AU [REDACTED]	NISM
50	1G6DE5EG6A0 [REDACTED]	NISM
51	1G6DE5EY7B0 [REDACTED]	NISM
68	3GYFNFY9AS [REDACTED]	NISM
73	3GNEC12097G [REDACTED]	LIT
83	KL1TD66638B [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
94	2G1FB1EV5A9	NISM
113	1G1AK15F567	NISM
124	1G1AK55F267	NISM
136	1G1AK15F967	NISM
138	1G1AL55F767	NISM
147	1G1AL15F277	PAR
170	1G1AL18F087	NISM
172	1G1AL58F887	NISM
175	1G1AK18F087	NISM
177	1G1AK18F987	NISM
181	1G1AK18H197	PAR
183	1G1AS18H397	NISM
187	1G1AT58H697	NISM
191	1G1AS58H297	NISM
195	1G1AB5F59A7	NISM
197	1G1AB5F57A7	NISM
205	1GTJTCDE1A8	NISM
225	2CNALDEW3A6	PAR
227	2CNALBEC0B6	NISM
274	2G1WA5EN4A1	NISM
321	1G1ZC5E05AF	NISM
323	1G1ZD5E7XAF	NISM
324	1G1ZA5E08AF	NISM
327	1G1ZE5EB4AF	NISM
329	1G1ZC5EU2BF	NISM
369	1GCEC290X9Z	RMR
374	1GCEK290X9Z	NISM
375	3GCRKSE31AG	NISM
376	3GCRKSE39AG	NISM
377	3GCXKTE29AG	NISM
378	1GCSKREA0AZ	NISM
379	1GCSKSEA2AZ	NISM
401	1GNUKKE32AR	NISM
418	1GNFK13017R	NISM
419	1GNFC13J97R	NISM
437	1GNDS13S052	LIT
454	1GNLRFEDXAS	PAR
455	1GNLVGED3AS	NISM
461	1GNDV33178D	LIT
468	1GNDV23E45D	NISM
473	1GKEV23738J	NISM
474	1GKEV23798J	NISM
481	1GKDS13SX52	NISM
483	1GKDT13S652	NISM
484	1GKDS13S652	NISM
487	1GKET63M672	NISM
504	1GTPKVE02AZ	PAR
511	1GKEC13T75R	LIT
541	1G2AL15F677	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
560	1G2ZH36N874 [REDACTED]	NISM
565	1G2ZM177984 [REDACTED]	NISM
570	1G2ZG57N494 [REDACTED]	NISM
618	1G8AJ55F47Z [REDACTED]	NISM
619	1G8AN15F17Z [REDACTED]	NISM
633	3GSCL33P58S [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 68 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot displays a legal case cover sheet for 'CARDONA V. CHEVROLET' and a context menu overlaid on the right side. Annotations with arrows point to specific menu items:

- Step 7: Next File (Image)** points to the 'Next Image' menu item.
- Step 7: Next Page** points to the 'Next page' menu item.
- Step 8: Scale Image** points to the '1:1 Scale 100%' menu item.
- Step 7: Image Properties** points to the 'EXIF Image Information...' menu item.

The cover sheet includes the following information:

- ATTORNEY OR PARTY WITHOUT ATTORNEY:** ERIC D. PARIS, ESQ., S/B# 147836, LAW OFFICES OF ERIC D. PARIS & ASSOCIATES, 281 S. THOMAS STREET, SUITE 403, PUNAHUA, CALIFORNIA 91766. TELEPHONE NO. 909-469-5127, FAX NO. 909-469-5126.
- ATTORNEY FOR:** PLAINTIFF'S
- CASE NAME:** CARDONA V. CHEVROLET
- CIVIL CASE COVER SHEET:** Complex Case Designation (Limited ☐, Unlimited ☒), Counter ☐, Joinder ☐.
- Check one box below for the case type that best describes this case:**
 - ☒ Auto Tort (22)
 - ☐ Other PIP/DIVD (Personal Injury/Property Damage/Wrongful Death) Tort
 - ☐ Asbestos (04)
 - ☐ Product Liability (24)
 - ☐ Medical malpractice (40)
 - ☐ Other PIP/DIVD (23)
 - ☐ Non-PIP/DIVD (Other) Tort
 - ☐ Business tortious business practice (07)
 - ☐ Civil rights (e.g., discrimination, labor union) (05)
 - ☐ Defamation (e.g., slander, libel) (13)
 - ☐ Fraud (16)
 - ☐ Intellectual property (15)
 - ☐ Professional negligence (e.g., legal malpractice) (25)
 - ☐ Other non-PIP/DIVD tort (20)
 - ☐ Employment
 - ☐ Wrongful termination (30)
 - ☐ Other employment (15)
 - ☐ Contract
 - ☐ Breach of contract/warranty (06)
 - ☐ Collections (e.g., money owed, open hotel accounts) (08)
 - ☐ Insurance coverage (18)
 - ☐ Other contract (37)
 - ☐ Real Property
 - ☐ Eminent domain/inverse condemnation (14)
 - ☐ Wrongful eviction (33)
 - ☐ Other real property (e.g., quiet title) (20)
 - ☐ Unlawful Detainer
 - ☐ Commercial (21)
 - ☐ Residential (32)
 - ☐ Drugs (38)
 - ☐ Judicial Review
 - ☐ Adult (offense) (05)
 - ☐ Petition for writ of habeas corpus (11)
 - ☐ Writ of mandate (02)
 - ☐ Other judicial review (28)
 - ☐ Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 1800-1812)
 - ☐ Antitrust/Trade regulation (03)
 - ☐ Construction defect (10)
 - ☐ Claims involving more than 10 parties
- 2. The case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring exceptional judicial management.**
 - a. ☒ Large number of separately represented parties
 - b. ☒ Extensive motion practice raising difficult or novel issues that will be time-consuming to resolve
 - c. ☒ Substantial amount of documentary evidence
 - d. ☒ Large number of parties
 - e. ☐ Coordination in other courts
 - f. ☐ Substantial post-trial issues
- 3. Type of remedies sought (check all that apply):**
 - ☒ monetary
 - ☐ nonmonetary, declaratory or injunctive relief
- 4. Number of causes of action (specify):** FIVE
- 5. This case ☒ is ☐ is not a class action suit.**
- Date:** JULY 3, 2003
- ERIC D. PARIS, ESQ., S/B# 147836**

NOTICE: Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (except under the Probate, Family, or Welfare and Institutions Code). (Cal. Rules of Court, rule 1800.)

CIVIL CASE COVER SHEET

DI11-005
124 316869375 – 695498
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Slt	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Collision
Address	City	Involved Dir		Safety	Yes
State IL ZipCd	Con Acct	Source	Phone	Updated	7/6/2010 09:20:43 AM
Serial #/VIN 1G1AK55P267	Model Year 2006	Priority	Medium License #	Owner	CUNNING1
Make Chevrolet	Warr. Start 08/05/2005	Status	Open	Opened	6/16/2010 08:24:55 AM
Model Cobalt	Mileage 80000	Sub-Status	Dissatisfied	Closed	
Abstract	Restraints - (SIR) - Driver Front - Non Deployment				
Customer Description	Please Do Not Assume. This is a PAR File. Forward all Inquiries to Patrick at xt 31395				

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	Other Veh	# People in Veh	Road Surface	Road Cond	Fire Report	Police Report
Owner	6/14/2010 08:45:00 AM	Y	1	1	Concrete	Dry	none	ISP-5710-20100614-190308
Driver Last Name	Driver First Name	DOB	Height	Weight	DOB	DOB	DOB	DOB
		53"						Deaf
St Name	Phone #	Insurance Agency	Progressive Insurance					
Unknown	Unknown							
Incident Loc	Ramp of I272 going on to I255, Madison County, IL		Incident Desc	I had passed a semi, and was going along. The semi truck was in front of me and the semi truck came up beside me and pushed my vehicle off the road and into the gravel and was sliding around and the front of my car struck the front of the semi. The vehicle then went into a ditch. No				
Component	Airbags		Damage Desc	Front Right; Back Right of vehicle and frame of vehicle is bent				
Vehicle Loc	R&R Towing Company, 6208 Illinois Rt 111, Granite City, IL 62040		Add'l Info	Insurance Contact Information: Unknown				
Emergency Svc Names	Illinois State Police Incident Report 11-10-01679		Maint Loc	Unknown				

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	None
Vehicle Speed	60	Weather Condition	Clear	Prop Owner	N/A	Property Type	N/A	
Last Service Date		Loc Last Service		Property Location	N/A	Prop Est Repair Cost	\$0.00	
Veh Est Repair Cost	\$0.00	Spec Equip Installer	N/A	Prop Damage Description	N/A	Inspected By	Inspection Not Performed	Inspection Date/Time
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt	Explains Other	Srv Date and Location: Unknown			
Veh Damage Description	Front Right; Back Right of vehicle and frame of vehicle is bent							

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
		10/03/75	Occupant of Owner's Vehicle		Driver	Seat Belts
Injury Description		Medical Rpt#		Treatment Location		Treated By
Headaches; neckaches; and continuing back pain		Unknown		Gateway Hospital in Granite, IL		Dr. Dedadrata
Street Address		City	State	Zip Code		
		Godfrey	IL			

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/6/2010 10:20:52 AM	KINZERTH	ESISBIQU	Escalation	ESIS - Injuries	In Progress		ESIS - Injuries
Contact Last Name		Contact First Name	Account		BAC Code		
Comments							
Customer claims frontal airbag did not deploy during collision - customer received medical treatment for injuries							
Thaddeus Kinzer/PA/ATX							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description					
7/6/2010 09:24:33 AM	CUNNINC1	CUNNINC1	Scheduled Follow-up		Scheduled Alarm		ESIS pickup					
Contact Last Name		Contact First Name	Account		BAC Code							
Comments												
Confidential Comments												

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/6/2010 09:23:35 AM	CUNNINC1	KINZERTH	Notify CRM		Done	7/6/2010 10:20:51 AM	ESIS - Injuries with Medical Treatment
Contact Last Name		Contact First Name	Account		BAC Code		
Comments							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/6/2010 09:08:34 AM	CUNNING1	CUNNING1	Inbound Call Customer	Complex Request	Done	7/6/2010 09:23:34 AM	Cust called in on the case
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS Adv: Need to get some additional information in regards to your case.

Cust sts: Pre-PAR and PAR Detail Information, I had passed a semi, and was going along. The semi truck was in front of me and the semi truck came up beside me and pushed my vehicle off the road and into the gravel and was sliding around and the front of my car struck the front of the semi. The vehicle then went into a ditch. No airbags deployed. My head hit the steering wheel very hard. I had some spinal injuries and went to the hospital, the insurance company is totaling the vehicle.

CRS Adv: Case will need to be escalated to ESIS, will contact you within 10 business days.

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/6/2010 09:08:18 AM	CUNNING1	CUNNING1	SR Opened		Done	7/6/2010 09:08:18 AM	SR in Status of Closed has been Re-Opened by CUNNING1
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 05:24:32 PM	CUNNING1	CUNNING1	SR Closed - Dissatisfied		Done	6/18/2010 05:24:32 PM	Service Request has been Closed Dissatisfied.
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 02:52:47 PM	BURCHAM	CUNNING1	Notify CRM		Done	6/18/2010 05:24:28 PM	letter approved

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 02:43:16 PM	CUNNING1	CUNNING1	Ownership Changed	Ownership Escalated to BRC	Done	6/18/2010 02:43:16 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 02:24:14 PM	CUNNING1	CUNNING1	Scheduled Follow-up		Done	6/18/2010 05:24:30 PM	Close File

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 02:23:53 PM	CUNNING1	GARCIAJR	Submit for Approval	Letter (Non Goodwill)	Done	6/18/2010 02:52:24 PM	sending UTC Letter

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 02:23:09 PM	CUNNINC1	CUNNINC1	Correspondence		Done	6/18/2010 02:23:09 PM	Created:BRCPAR_PA0011. SR#71-839756514

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 02:18:49 PM	CUNNINC1	CUNNINC1	Outbound Call Customer	Left Message	Done	6/18/2010 02:19:41 PM	CRS Left Message

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

CRS left Message: SR# and Phone#, Need to speak with you to gather some additional information, please call back.

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 10:09:08 AM	CUNNINC1	CUNNINC1	Scheduled Outbound Call Cust	Follow-up Attempt	Done	6/18/2010 02:17:13 PM	3rd Contact Attempt

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Action Plan: 3rd Contact Attempt

Friday 6/18

2-4 PM EST

Patrick Cunningham/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2010 10:08:59 AM	CUNNING1	CUNNING1	Outbound Call Customer	Left Message	Done	6/18/2010 10:09:03 AM	CRS Left Message
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

CRS left Message: SR# and Phone#, Need to speak with you to gather some additional information, please call back.

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 03:49:33 PM	CUNNING1	CUNNING1	Scheduled Outbound Call	Follow-up Attempt	Done	6/18/2010 10:07:19 AM	2nd Contact Attempt
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Action Plan: 2nd Contact Attempt

Friday 6/18
10-12 PM EST

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 03:47:56 PM	CUNNING1	CUNNING1	Outbound Call Customer	Left Message	Done	6/17/2010 03:49:22 PM	CRS Left Message
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

CRS left Message: SR# and Phone#, Need to speak with you to gather some additional information, please call back.

Patrick Cunningham/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 02:14:49 PM	CUNNING1	CUNNING1	Inbound Call Customer	Voice Mail Received	Done	6/17/2010 02:15:18 PM	Cust left voice mail
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Cust sts: calling about my case, we were in an accident and the airbag did not deploy, will be available to answer till 5 pm.

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 11:50:24 AM	CUNNING1	CUNNING1	Scheduled Outbound Call	Follow-up Attempt	Done	6/17/2010 03:46:09 PM	2nd Contact Attempt
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Action Plan: 2nd Contact Attempt

Thursday 6/17
3:45-5:45 PM EST

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:47:18 AM	BURCHAM	CUNNING1	Ownership Changed		Done	6/17/2010 09:47:18 AM	Service Request Ownership has changed FROM: BEUTHIDE TO: CUNNING1
Contact Last Name		Contact First Name		Account		BAC Code	

CONFIDENTIAL

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:52 AM	BURCHAM	CUNNING1	BRC PAR	Initial Contact- AVM	Done	6/18/2010 02:21:14 PM	called RCCDVM Smith DaKendrick 469417 7325
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

called RCCDVM Smith DaKendrick 469417 7325

CRS Left Message: SR#, Cust Name and VIN, no involved dir, cust alleges vehicle was involved in a collision in which the airbags did not deploy, sending case to esls for processing due to medical treatment, message is for information only, no need to reply, please call if you have any questions.

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:49 AM	BURCHAM	CUNNING1	BRC PAR	Initial Contact- Dealer	Done	6/17/2010 10:58:52 AM	Vehicle has not been to dir in over two years
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Vehicle has not been to dir in over two years

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:36 AM	BURCHAM	CUNNING1	BRC PAR	Initial Contact- 10 Day Letter	Done	6/18/2010 02:20:14 PM	Initial Contact- UTC Letter
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Initial Contact- UTC Letter

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:31 AM	BURCHAM	CUNNING1	BRC PAR	Acknowledgement	Done	6/17/2010 11:50:19 AM	CRS called Cust to Initiate Case
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS left Message: SR# and Phone#, Need to speak with you to gather some additional information, please call back, Will FU 6/17 3:45-5:45 PM EST.

Patrick Cunningham/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:26 AM	BURCHAM	CUNNING1	Notify CRM		Done	6/17/2010 10:56:44 AM	File assigned
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:21 AM	BURCHAM	CUNNING1	Research		Done	6/17/2010 10:57:16 AM	Research VIN
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							

Research Completed:
No Previous Related Repairs
No Related Recalls
No Other SR's

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:07 AM	BURCHAM	CUNNING1	BRC PAR	Case Assigned	Done	6/17/2010 10:56:41 AM	File assigned to Patrick Cunningham @ ext 31395
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:02 AM	BURCHAM	BEUTHIDE	SR Opened		Done	6/17/2010 09:44:02 AM	SR in Status of Closed has been Re-Opened by BURCHAM
Contact Last Name	Contact First Name	Account			BAC Code		
Comments							

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/17/2010 09:44:01 AM	BURCHAM	BEUTHIDE	SR Closed - Dissatisfied		Done	6/17/2010 09:44:01 AM	Service Request has been Closed Dissatisfied.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/16/2010 09:38:31 AM	BEUTHIDE	MERCADTO	Escalation	Initiate PAR	Done	6/17/2010 09:43:47 AM	Assigning activity to PAR QUEUE Received and assigned in PAR Torte Mercado/PAR Workflow/ATX

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days.

Debbie Beuthin/Saginaw/Tier 1/GWE0

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/16/2010 08:38:30 AM	BEUTHIDE	BEUTHIDE	Inbound Call Customer	Complex Request	Done	6/16/2010 09:38:47 AM	Hit head on steering wheel

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Customer States: Was in accident; airbag did not deploy; injured head and back; has neck and backaches; Accident was June 14 2010. Customer was involved with an 18-wheeler on an entrance ramp of a highway. Customer has been deaf since birth.

Debbie Beuthin/Saginaw/Tier 1/GWE0

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C48	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front

[Logout](#)

February 23, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER

View Vehicle Summary

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

Vehicle Information

VIN: 1G1AK55F267 [REDACTED] Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN
Service Contract: No Branded Title: Yes Warranty Block: Yes PDI Status: No
Order Type 50 - FLEET
Field Actions: 1 Open

[REQUEST ANOTHER VIN](#)

For this vehicle:

- [View Vehicle Summary](#)
 - [Service Contract](#)
 - [Branded Title](#)
 - [Warranty Block](#)
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Required Field Actions

Open field actions are
highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N100023	10023	LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR	03/18/2010	Open

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Brand Description: JUNK

Date Branded: 08/01/2010

Title Number: [REDACTED]

Reporting Source Code:

Reported By: IL

Effective Date: 01/14/2011

Warranty Block

Code	Description	Effective Date
BT	BRANDED TITLE	01/14/2011
Block Transaction Types:		Blocked Labour Ops:
ZPDI		
ZPTI		
ZREG		
ZSCT		

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
-------	-------------	-------------------	------------	--------------------	----------	--------------

Corrosion Limited Warranty	01/14/2011	08/05/2005	10 MI	08/05/2011	100,010 MI
Powertrain Limited Warranty	01/14/2011	08/05/2005	10 MI	08/05/2010	60,010 MI
Emission Select Component Ltd Wty	01/14/2011	08/05/2005	10 MI	08/05/2013	80,010 MI
Bumper to Bumper Limited Warranty	01/14/2011	08/05/2005	10 MI	08/05/2008	36,010 MI
Special Coverage 09014	01/14/2011	08/05/2005	10 MI	08/05/2020	150,010 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
08/04/2005	A29177	ZPDI - Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

February 23, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN: 1G1AK55F267
 Service Contract: No Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type: 50 - FLEET
 Field Actions: [1 Open](#)

[REQUEST ANOTHER VIN](#)

Vehicle Build

Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN
 Gross Vehicle Weight: 1,705

Order Number: JDMR7Q
 Build Date: 08/04/2005
 Build Plant: 7-

For this vehicle:

- [View Vehicle Summary](#)
 - [Service Contract](#)
 - [Branded Title](#)
 - [Warranty Block](#)
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Option Codes

*IVH is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

14B - GRAY	14I - GRAY
1LS - 1LS BASE PACKAGE	1SZ - OPTION PACKAGE DISCOUNT
6AR - FRONT SPRING	7AR - FRONT SPRING
8AA - REAR SPRING	95U - ULTRA SILVER METALLIC
9AA - REAR SPRING	AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS
AR9 - DELUXE FRONT BUCKET SEAT	B0L - GM PRODUCTION WEEK #29
C1U - FLT-ENTERPRISE RENT A CAR	C67 - ELECT. FRONT AIR CONDITIONER
DC8 - MIRROR, O/S MANUAL FLDG, BLK	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FE9 - FEDERAL EMISSIONS	FLT - FLEET PROCESSING OPTION
FY1 - TRANS/AXLE 3.63 RATIO	IPB - INTERIOR TRIM DESIGN
J41 - POWER DISC FRONT BRAKES	K64 - 115 AMP GENERATOR
L61 - 2.2L DOHC 4 CYL ENGINE	LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO
MN5 - 4 SPEED AUTO TRANSMISSION	MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE
N46 - 4 SPOKE STEERING WHEEL	NT7 - FEDERAL EMISSION TIER 2
PG1 - 15" STEEL WHEEL	QTU - P195/60R15 TOURING BW TIRES
R6F - IDENTIFY B-CODE USERS	R6P - PREMIUM PAINT
UN0 - AM/FM STEREO W/CD & RDS	UQ4 - BASE SPEAKER SYSTEM
V2G - FULL FUEL FILL CREDIT	V73 - STATEMENT OF VEHICLE CERT.-U.S. /CANADA
VQ2 - FLEET ORDERING AND ASSISTANCE	VX7 - LONG TERM DAILY RENTAL PROGRAM


Added Option Codes

~AN - SPECIAL COVERAGE APPLIED

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

February 23, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

**INTERFACE WITH
CUSTOMER****View Vehicle Component Summary**

This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build.

Vehicle Information

VIN: 1G1AK55F267 [REDACTED] Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN
Service Contract: No Branded Title: Yes Warranty Block: Yes PDI Status: No
Order Type: 50 - FLEET
Field Actions: [1 Open](#)

For this vehicle:

→ [View Vehicle Summary](#)
→ Service
→ Contract
→ [Branded Title](#)
→ [Warranty Block](#)

→ [View Vehicle Build](#)
→ [View Vehicle Component Summary](#)
→ [View Vehicle Transaction History Detail](#)
→ [View Vehicle Delivery Information](#)

Vehicle Component

Component Code: CB-SEQ NUM (FLEX) BODY ASM Traceability: 0250771
Source Plant: - Part / Number Broadcast: 1ZZ
Date Scanned: 08/01/2005 Time Scanned: 05:07:00 Scan Station:


Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

February 23, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail



This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN: 1G1AK55F267

Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN

Service Contract: No

Branded Title: YesWarranty Block: Yes

PDI Status: No

Order Type: 50 - FLEET

Field Actions: [Open](#)[REQUEST ANOTHER VIN](#)

For this vehicle:

[View Vehicle Summary](#)[Service
Contract](#)[Branded Title](#)[Warranty Block](#)[View Vehicle Build](#)[View Vehicle](#)[Component Summary](#)[View Vehicle](#)[Transaction History
Detail](#)[View Vehicle Delivery
Information](#)

Job Card Date: 08/04/2005

Job Card Number: A29177

Repair Service Agent: 114708

Odometer Reading: 0 MI

COX CHEVROLET, INCORPORATED
2900 CORTEZ RD W
BRADENTON FL 34207-1136
9417560621

Authorization Code:

Process Date:
08/09/2005Transaction Type:
ZPDI---Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time

Causal Part Number

Line Total: USD 93.91

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

February 23, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMER

View Vehicle Delivery Information

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN: 1G1AK55F267
Service Contract: No Branded Title: Yes Warranty Block: Yes PDI Status: No
Order Type: 50 - FLEET
Field Actions: [1 Open](#)

Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN

REQUEST MORE INFO

Invoice Information

Invoicing Service Agent: 114708
COX CHEVROLET, INCORPORATED
2900 CORTEZ RD W
BRADENTON FL 34207-1136 9417560621

Invoice Date: 08/04/2005

Ship to Information

Invoicing Service Agent: 114708
COX CHEVROLET, INCORPORATED
2900 CORTEZ RD W
BRADENTON FL 34207-1136 9417560621

Ship to Date: N/A

Delivery Information

Delivery Service Agent: 114708
COX CHEVROLET, INCORPORATED
2900 CORTEZ RD W
BRADENTON FL 34207-1136 9417560621

Delivery Date: 08/05/2005
Delivery Type: 020---DAILYRENTAL
Delivery Odometer: 10

In Service Information

Invoicing Service Agent:

In Service Date: N/A
In Service Type: 0000
In Service Odometer: 0

For this vehicle:

[→ View Vehicle Summary](#)[→ Service
Contract](#)[→ Branded Title](#)[→ Warranty Block](#)[→ View Vehicle Build](#)[→ View Vehicle](#)[→ Component Summary](#)[→ View Vehicle](#)[→ Transaction History
Detail](#)[→ View Vehicle Delivery
Information](#)

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

ILLINOIS TRAFFIC CRASH REPORT

Sheet 1 of 1 Sheets

(b) (6)



2003047

DRAC	DRAC	PEDV	PEDV	TRFD	TRFC	WEAT	DRVA	DRVA	VIS	VIS	VEHD	VEHD	LGHT	COLL	MANV	MANV	PPA	PPA	PPL	PPL
1	1			12	4	1	99	1	1	1	1	1	1	12	99	1	99	99	9	9
U1	U2	U1	U2				U1	U2	U1	U2	U1	U2			U1	U2	U1	U2	U1	U2

INVESTIGATING AGENCY ILLINOIS STATE POLICE	DAMAGE TO ANY ONE PERSON'S VEHICLE / PROPERTY ☐ \$500 OR LESS ☐ \$501 - \$1,500 ☒ OVER \$1,500	TYPE OF REPORT 1 On-scene	TYPE OF CRASH B Injury	AGENCY CRASH REPORT NO. (b) (6)	TRFW 5
--	---	-------------------------------------	----------------------------------	---	------------------

ADDRESS NO.	HIGHWAY or STREET NAME RAMP TO I-255 S/B	CITY CHOUTEAU TWP	INTERSECTION RELATED ☐ Yes ☒ No	DATE OF CRASH 06/14/2010	TIME OF CRASH 06:34	LARS CODE	VEHT 1
(CIRCLE) ☐ 0.23 FT / MI	(CIRCLE) N E S W	COUNTY MADISON	PRIVATE PROPERTY ☐ Yes ☒ No	CIRCLE DAY OF WEEK SU MO TU WE TH FR SA	NUMBER MOTOR VEHICLES INVLD 2	LARS CODE	VEHT 7
AT INTERSECTION WITH (NAME OF INTERSECTION OR ROAD FEATURE)		HIT & RUN ☐ Yes ☒ No					U1 7

NAME ☒ DRIVER ☐ PARKED-NO DRIVER ☐ PED ☐ PEDAL ☐ EQUUS ☐ NMV ☐ NCV	DATE OF BIRTH mo day yr 2 4 2010	MAKE Chevrolet	MODEL Cobalt	YEAR 2006	DAMAGED AREA(S) 00 - NONE 10 - UNDER CARRIAGE 11 - TOTAL (ALL AREAS) 12 - OTHER 99 - UNKNOWN		TOWED DUE TO CRASH ☒ Y ☐ N	FIRE ☐ ☒	HAZMAT SPILL ☐ ☒	COMVEH *IF YES SEE SIDEBAR ☐ ☒	# LANES 1
STREET ADDRESS	SEX F	SAFT 2	AIR 4	PLATE NO. 1G1AK55F267	STATE IL		YEAR 2010	POINT OF FIRST CONTACT 6	INSURANCE CO. No INSURANCE	TELEPHONE	POLICY NO. 00000000
CITY BRIGHTON	STATE IL	ZIP	INJURY B	EJECT 1	VIN 1G1AK55F267						RSUR 1
TELEPHONE	DRIVER LICENSE NO.	STATE IL	CLASS D*	VEHICLE OWNER (LAST, FIRST, MI)							VEHU 2
TAKEN TO	EMS AGENCY Abbott Ambulance	OWNER ADDRESS (STREET, CITY, STATE, ZIP)									U1 9
Gateway Reg-Granite City		GODFREY, IL,									U2 9

NAME ☒ DRIVER ☐ PARKED-NO DRIVER ☐ PED ☐ PEDAL ☐ EQUUS ☐ NMV ☐ NCV	DATE OF BIRTH mo day yr 2 4 2010	MAKE International	MODEL Cot Truck Tractor	YEAR 2009	DAMAGED AREA(S) 00 - NONE 10 - UNDER CARRIAGE 11 - TOTAL (ALL AREAS) 12 - OTHER 99 - UNKNOWN		TOWED DUE TO CRASH ☐ Y ☒ N	FIRE ☐ ☒	HAZMAT SPILL ☐ ☒	COMVEH *IF YES SEE SIDEBAR ☒ ☐	BAC 96
STREET ADDRESS	SEX M	SAFT 2	AIR 4	PLATE NO.	STATE IN		YEAR 2010	POINT OF FIRST CONTACT 2	INSURANCE CO. As QUALIFIED SELF-INSURED	TELEPHONE	POLICY NO.
CITY EWING	STATE MO	ZIP	INJURY O	EJECT 1	VIN 2HSCTAPR79C						U2 96
TELEPHONE	DRIVER LICENSE NO.	STATE MO	CLASS A	VEHICLE OWNER (LAST, FIRST, MI)							# OCCS 1
TAKEN TO	EMS AGENCY	OWNER ADDRESS (STREET, CITY, STATE, ZIP)									U1 96
		321 TECH DRIVE, CHESTERTON, IN, 46304									U2 96


UNIT	SEAT	DOB	SEX	SAFT	AIR	INJ	EJCT	PASSENGERS & WITNESSES ONLY (NAME, ADDR, TEL)	HOSP	EMS

EVNO	MOST	EVNT	LOC	DAMAGE PROPERTY OWNER NAME IDOT - IL Dept of Transportation	DAMAGED PROPERTY 50 ft of Fence	CONTRIBUTORY CAUSE(S) PRIMARY 20 Improper lane usage	POSTED SPEED LIMIT
1	☐	11	1	PROPERTY OWNER ADDRESS (STREET, CITY, STATE, ZIP) 2300 S. DIRKSEN PARKWAY, SPRINGFIELD, IL 62764		SECONDARY 41 Distraction - from inside vehicle	
2	☐	1	3	ARREST NAME	SECTION Oper of uninsured mtr veh	DATE NOTIFIED 06/14/2010	TIME NOTIFIED 06:34
3	☒	39	3		SECTION Imp lane usage/laned roadway	COURT DATE 06/04/2010	COURT TIME 01:00
1	☒	11	1	OFFICER ID 5710	SIGNATURE	BEAT / DIST 11	SUPERVISOR ID
2	☐						
3	☐						

SR 1050 JANUARY 2009 (MCR)

TA000110183

DIAGRAM



NARRATIVE (Refer to vehicle by Unit No.)

UNIT 1 AND UNIT 2 WERE TRAVELING ON THE RAMP FROM I-270 EAST BOUND TO I-255 SOUTH BOUND. UNIT 1 WAS TRAVELING DIRECTLY BEHIND UNIT 2.

DRIVER OF UNIT 1 STATED SHE DROPPED HER CELL PHONE. DRIVER OF UNIT 1 STATED SHE LOOKED AWAY FROM THE ROADWAY TO RETRIEVE HER CELL PHONE. SUBSEQUENTLY CAUSING UNIT 1 TO TRAVEL ONTO THE SHOULDER LOCATED ON THE RIGHT (WEST) SIDE OF THE ROADWAY.

UNIT 2 WAS ATTEMPTING TO MERGE ONTO THE SHOULDER TO PARK. WHILE UNIT 2 WAS ATTEMPTING TO MERGE, UNIT 1 TRAVELED PAST UNIT 2 ON THE SHOULDER CAUSING THE RIGHT FRONT SIDE OF UNIT 2 TO STRIKE LEFT SIDE OF UNIT 1.

UPON BEING STRUCK, UNIT 1 TRAVELED OFF THE SHOULDER AND CONTINUED TO TRAVEL THROUGH A FENCE. UNIT 1 CAME TO A REST IN THE DITCH/EMBANKMENT AREA LOCATED ON THE RIGHT (WEST) SIDE OF THE ROADWAY. THE FRONT END OF UNIT 1 WAS FACING WEST.

LOCAL USE ONLY Nothing

U1 Color: Silver	U1 Towed By / To: R & R Towing / R & R Towing
U2 Color: White	U2 Towed By / To: /

COMMERCIAL VEHICLE

Unit 1

CARRIER NAME	SOURCE	
ADDRESS	SIDE OF TRUCK	
CITY	STATE	ZIP
ID Number:	GVWR	
USDOT	ICCMC	
OR State No.	State Name	None
HAZARDOUS MATERIALS PLACARDED ?		
IF YES: 4 DIGITS 1 DIGIT Name		
HAZARDOUS CARGO RELEASED FROM TRUCK? N		
VIOLATION OF HAZMAT REGS. CONTRIBUTE TO CRASH?		
VIOLATION OF MCS REGS CONTRIBUTE TO CRASH?		
INSPECTION FROM COMPLETED?		
HAZMAT	OUT OF SERVICE?	FORM NO.
MCS	OUT OF SERVICE?	
IDOT PERMIT#	WideLoad	
TRAILER WIDTH(S)	TRAILER LENGTH(S)	Vehicle Length
TRAILER 1	TRAILER 1	Total - Ft
TRAILER 2	TRAILER 2	No Of Axles
Vehicle Configuration	Cargo Body Type	LoadType

COMMERCIAL VEHICLE

Unit 2

CARRIER NAME	SOURCE	
USA TRUCK INC.	X SIDE OF TRUCK	
ADDRESS	PAPERS	
321 TECH DRIVE	DRIVER	
CITY	STATE	ZIP
CHESTERTON, IN	46304	LOG BOOK
ID Number:	GVWR 80000	
USDOT	ICCMC	
213754		
OR State No.	State Name	IN None
HAZARDOUS MATERIALS PLACARDED ? No		
IF YES: 4 DIGITS 1 DIGIT Name		
HAZARDOUS CARGO RELEASED FROM TRUCK? N		
VIOLATION OF HAZMAT REGS. CONTRIBUTE TO CRASH? N		
VIOLATION OF MCS REGS CONTRIBUTE TO CRASH? N		
INSPECTION FROM COMPLETED?		
HAZMAT	N	OUT OF SERVICE? N
MCS	N	OUT OF SERVICE? N
IDOT PERMIT#	WideLoad	
TRAILER WIDTH(S)	TRAILER LENGTH(S)	Vehicle Length
TRAILER 1	0-96"	TRAILER 1 53
TRAILER 2		TRAILER 2
Vehicle Configuration	6	Cargo Body Type 2
		LoadType 9