


EWR D&I ANNOTATION



FAN-000001L084001DP92-3505

Artemis # : 000001L084001DP92**Record Created Date :** 01/25/2010**Printed Date :** 01/25/2010

Description : DI09-033 SEQUENCE 92 CHEVROLET 1 INJURY 2007 CHEVROLET COBALT VEHICLE. ACCORDING TO A SERVICE REQUEST ACTIVITY REPORT, A CUSTOMER CALLED TO REPORT A SINGLE VEHICLE CRASH. WHILE DRIVING ON A SNOWY DAY, THE VEHICLE LOST CONTROL AND HIT A POLE HEAD-ON, WITH THE FRONT, CENTER OF THE VEHICLE. THE SEAT BELTS AND AIR BAGS DID NOT WORK. THE DRIVER SUFFERED MINOR INJURIES BECAUSE THE SEAT BELT DID NOT LOCK-UP. THE CRASH DID NOT REQUIRE MEDICAL ATTENTION. THE DEALER INSPECTED THE VEHICLE AND STATED THE VEHICLE DID NOT HAVE THE CORRECT AMOUNT OF DECELERATION TO LOCK UP AND THAT THE SEAT BELTS WORKED ACCORDING TO DESIGN. WHEN TESTED, THEY DID LOCK. GM LISTS THE REPORT AS CLOSED WITH THE CUSTOMER SATISFIED. GM DID NOT OFFER ANY ASSISTANCE IN THE REPAIRS. A SEARCH OF OUR DATABASE INDICATED 6 VOQS RELATED TO FRONTAL CRASHES THAT EXPERIENCED NON AIR BAG DEPLOYMENT. NHTSA HAS NO OPEN OR CLOSED INVESTIGATIONS RELATED TO THAT PROBLEM. THERE ARE NO RECALLS, TSBS, OF FIELD REPORTS. AA

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

May 8, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-033

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 4th quarter of 2008. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 2, 6, 8, 29, 34, 51, 58, 74, 88, 91, 92, 99, 105, 115, 116, 122, 135, 148, 186, 192, 197, 198, 292, 299, 308, 316, 324, 333, 334, 350, 352, 353, 372	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality

for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **June 12, 2009**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS CORPORATION

Vehicle Structure & Safety Integration

RECEIVED
NVS-217

12 June 2009

2009 JUN 15 P 2:45

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-033

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated May 8, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from 4th quarter of 2008.

GM's response is comprised of 40 disks for the incidents that are the subject of DI09-033.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 2 265593560 - 665008 and 2007 BUICK LACROSSE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 2 265593560 - 665008_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index for the disk are as follows:

DI09-033
2 265593560-665008
2007 BUICK LACROSSE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

2 265593560 - 665008_01_001 - is the first document responsive to Inquiry no. 1.
2 265593560 - 665008_02_001 - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

Product Investigations

Mail Code: 480-210-G11 • 30001 Van Dyke • Warren, MI 48090
DI09-033 Response.doc

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incidents that are the subject of DI09-033, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR), or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further. As such, the document included in response to Inquiry 1 that can be found on the enclosed disk for the PAR and Rumor case listed in the table, may not be a claim or notice of the type generally defined as such by §579.4(c).

(33 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
2	265593560-665008	NISM
6	265592847-663246	LITIGATION
8	265592902-663377	NISM
29	267080984-71-677299995	PAR
34	265592908-663389	NISM
51	265592277-661710	NISM
58	265593426-664559	NISM
74	265592522-662362	NISM
88	265592632-662631	NISM
91	265592409-662024	NISM
92	267081033-71-688868663	PAR
99	265593131-663854	NISM
105	265592075-662565	NISM
115	265593052-663718	NISM
116	265592720-662926	NISM
122	265593511-664690	NISM
135	265592841-663237	NISM
148	265592763-662993	NISM
186	265592855-663266	NISM
192	265592955-663487	NISM
197	265592786-663108	NISM
198	265593031-663629	NISM
292	265592180-661489	NISM
299	265593275-664252	NISM
308	265592964-663492	See note *
316	265592641-662660	NISM
324	265592728-662943	NISM
333	265592239-661625	NISM
334	265593086-663788	NISM
350	265592968-663513	NISM
352	265592252-661641	NISM
353	265593242-664141	NISM
372	265593510-664688	NISM

* Sequence ID 308 was reported in error. There is no Product liability claim on this vehicle.

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**


Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators, and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,



Gay P. Kent
Director


Product Investigations

Enclosures: 40 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl +PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl +PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl +PgDn** or **Ctrl +PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a legal document cover sheet titled "CIVIL CASE COVER SHEET" for the case "CARDONA V. CHEVROLET". The document is filed in the Superior Court for the State of California, Indio County. The cover sheet includes various checkboxes for case type, complexity, and other legal details. Annotations with arrows point to specific features:

- Step 7 Next File (Image)**: Points to the "Next Image" button in the right-hand menu.
- Step 7 Next page**: Points to the "Next page" button in the right-hand menu.
- Step 8 Scale Image**: Points to the "Scale 100%" option in the right-hand menu.
- Step 7 Image Properties**: Points to the "Image Properties" button at the bottom of the right-hand menu.

The cover sheet itself contains the following information:

ATTORNEY OR PARTY WITHOUT ATTORNEY (Print name and address, not e-mail)
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 Telephone no.: 909-469-5127 FAX NO: 909-469-5126
 ADDRESS FOR SERVICE: PLAINTIFF'S
 COURT NAME OF COURT, JUDGE, JURY, AND TRIAL COURT, IF ANY
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COUNTY
 CASE NAME: CARDONA V. CHEVROLET
 CIVIL CASE COVER SHEET
☐ Limited ☒ Unlimited
 Complex Case Designation
☐ Counter ☐ Joinder
 Filed with first appearance by defendant
 (Cal. Rules of Court, rule 1811)
 Please complete all five (5) items below
 1. Check one box below for the case type that best describes this case:
☒ Auto Tort (22)
☐ Other PIP/DWD (Personal Injury/Property Damage/Wrongful Death) Tort
☐ Asbestos (24)
☐ Product liability (24)
☐ Medical malpractice (40)
☐ Other PIP/DWD (23)
☐ Non-PIP/DWD (Other) Tort
☐ Business tort/real business practice (27)
☐ Civil rights (e.g., discrimination, false arrest) (30)
☐ Defamation (e.g., slander, libel) (13)
☐ Fraud (16)
☐ Intellectual property (19)
☐ Professional negligence (e.g., legal malpractice) (25)
☐ Other non-PIP/DWD tort (35)
☐ Employment
☐ Wrongful termination (36)
☐ Other employment (15)
☐ Breach of contract/warranty (25)
☐ Collections (e.g., money owed, open book accounts) (39)
☐ Insurance coverage (18)
☐ Other contract (37)
☐ Real Property
☐ Eminent domain/inverse condemnation (14)
☐ Wrongful eviction (38)
☐ Other real property (e.g., quiet title) (34)
☐ Unintentional Defendant
☐ Commercial (31)
☐ Residential (32)
☐ Drugs (34)
☐ Judicial Review
☐ Asset forfeiture (30)
☐ Public re: arbitration award (11)
☐ Will of marauder (22)
☐ Other judicial review (38)
☐ Previously Complex Civil Litigation (Cal. Rules of Court, rules 1800 - 1813)
☐ Arbitration/Trade regulation (33)
☐ Construction defect (10)
☐ Claims resolution means not legal
 2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring exceptional judicial management.
 a. ☒ Large number of separately represented parties d. ☒ Large number of
 b. ☒ Extensive motion practice making difficult or novel e. ☐ Coordination and
 issues that will be time-consuming to resolve in other counties
 c. ☒ Substantial amount of documentary evidence f. ☐ Substantial point
 Type of remedies sought (check all that apply)
 a. ☒ Monetary b. ☐ Nonmonetary, declaratory or injunctive relief c. ☐
 4. Number of causes of action (specify): FIVE
 5. This case ☐ is ☒ is not a class action suit.
 Date: JULY 3, 2003
 ERIC D. PARIS, ESQ., S/B# 147836
 (Type or print name)
 NOTICE
 Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (or under the Probate, Family, or Welfare and Institutions Code) (Cal. Rules of Court, rule 1800).
 - File this cover sheet in addition to any cover sheet required by local court rule.
 - If this case is complex under rule 1800 of the California Rules of Court, you must file this cover sheet with the action or proceeding.
 - Unless this is a complex case, this cover sheet shall be used for statistical purposes only.
 Form Required by Rule 1800 of the California Rules of Court
 Adopted December 2002
 1800-CVS (Rev. January 1, 2003)
 CIVIL CASE COVER SHEET

DI09-003
92 267081033 - 71 - 688868663
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Activity

SR No.	(b) (6)	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Restraints - Seat Belt System /	Sub-Area	Initiate PAR- Collision
Address		City	Poham	Involved Dlr	Banks Chevrolet-Cadillac, Inc.	Safety	Yes
State	NH	Con. Acct.		Source	Phone	Updated	1/5/2009 12:29:22 PM
Serial #/VIN	1G1AL15F477	Model Year	2007	Priority	Medium	License #	
Make	Chevrolet	Warr. Start	04/03/2007	Status	Closed	Owner	SANCHERI
Model	Cobalt	Mileage	36,744	Sub-Status	Satisfied	Opened	12/19/2008 12:44:45 PM
Abstract	seatbelt and airbags not operating /07 Chevy Cobalt						
Customer Description	***This is a BRC PAR Case. Please do not assume. Forward any inquiries to Rita Sanchez at ext.31227 ***						

GMPP Details

GMPP Term	GMPP Mileage	GMPP Retail Cost
-----------	--------------	------------------

Component Coverage

Component Coverage	Expiration Mileage	Expiration Date
--------------------	--------------------	-----------------

Certificate Details

Certificate Number	Amount	Expiration Date
--------------------	--------	-----------------

Pre-Authorization Basics

Service Dealer	BAC Code	Div. Dealer Code	Repair Order #
----------------	----------	------------------	----------------

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
1/5/2009 12:29:18 PM	SANCHERI	SANCHERI	SR Closed - Satisfied		Done	1/5/2009 12:29:18 PM	Service Request has been Closed
Contact Last Name	Contact First Name	Account	BAC Code	Satisfied.			
Comments							

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
1/5/2009 12:27:17 PM	SANCHERI	SANCHERI	BRC PAR	Close-No Offer to Repair/Rep	Done	1/5/2009 12:28:05 PM	Close-No Offer to Repair/Rep

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Close-No Offer to Repair/Rep

Eaa inspection done , air bags and seat belts were working as designed

Rita Sanchez/ATX/ PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
1/5/2009 12:22:21 PM	SANCHERI	SANCHERI	Outbound Call Customer	Made Contact	Done	1/5/2009 12:27:16 PM	called cust

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

* vehicle was hit right of the center line of the vehicle, the vehicle didnt have the correct amount of deceleration, seatbelts were working according to design, tested and locked -

cust sts the seatbelts were not working i know they werent

crs sts: I had the vehicle inspected an from the information, they appeared to be operating as designed

cust sts: i guess this will go to the next level

crs sts: have a great day sir

Rita Sanchez/ATX/ PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
1/2/2009 11:58:12 AM	SANCHERI	SANCHERI	Scheduled Follow-up		Done	1/5/2009 12:22:18 PM	f/u with resolution

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

1/5

11-1

* vehicle was hit right of the center line of the vehicle, the vehicle didnt have the correct amount of deceleration, seatbelts were working according to design, tested and locked -

Rita Sanchez/ATX/ PAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
1/2/2009 11:57:27 AM	SANCHER	SANCHER	Outbound Call Customer	Left Message	Done	1/2/2009 11:58:07 AM	called cust
Contact Last Name	Contact First Name		Account		BAC Code		

Comments
left msg

Rita Sanchez/ATX/PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/30/2008 11:07:40 AM	SANCHER	SANCHER	Scheduled Follow-up		Done	1/2/2009 11:57:04 AM	called cust
Contact Last Name	Contact First Name		Account		BAC Code		

Comments
1/2

11-1

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/30/2008 11:00:54 AM	SANCHER	SANCHER	Outbound Call Customer	Made Contact	Done	12/30/2008 11:07:32 AM	called cust
Contact Last Name	Contact First Name		Account		BAC Code		

Comments
advised cust that i was still waiting for inspection information

cust sts: ok

Rita Sanchez/ATX/PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/23/2008 09:13:28 AM	SANCHER	SANCHER	Scheduled Follow-up		Done	12/30/2008 11:00:53 AM	7 day f/u eaa inspection
Contact Last Name	Contact First Name		Account		BAC Code		

Comments
12/30

9-11

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/23/2008 08:53:16 AM	SANCHER	SANCHER	BRC PAR	Inspection- EAA- Airbag	Done	12/23/2008 08:58:45 AM	sent EAA inspection
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 04:39:55 PM	SANCHERI	SANCHERI	Scheduled Outbound Call	Cust	Done	12/23/2008 08:53:14 AM	f/u
Contact Last Name		Contact First Name		Account		BAC Code	

Comments
do the initials

Rita Sanchez/

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 04:14:15 PM	SANCHERI	SANCHERI	Ownership Changed	Ownership Escalated to BRC	Done	12/22/2008 04:14:15 PM	Ownership Escalated to BRC
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 10:24:38 AM	KINZERTH	SANCHERI	Ownership Changed		Done	12/22/2008 10:24:39 AM	Service Request Ownership has changed FROM: GONZALE5 TO: SANCHERI
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 10:24:18 AM	KINZERTH	SANCHERI	8RC PAR	Initial Contact-AVM	Done	12/23/2008 08:22:37 AM	Called Lampman Thomas 914055 8440
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

This is Rita Sanchez calling from gm par dept.

Customer

Service Request: 771-66866663

Vehicle Information: 07 Chevy cobalt

Last 8 of the VIN: 77

Involved Dealership:

Nature of allegation: airbags non deployment /seatbelt concern

CRS adv if you have any additional information pertaining to customer or vehicle please contact me at 1-866-790-5600 ext 31227. If not then this is an FYI to let you know what is going on in your district.

Rita Sanchez/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 10:24:05 AM	KINZERTH	SANCHERI	BRC PAR	Initial Contact- Dealer	Done	12/23/2008 08:38:23 AM	Called Banks Chevrolet-Cadillac, Inc. (603) 224-4055
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

left a msg: Service Manager - Mike Mercer
CRS adv: Calling on regards to an claim that was called in by an cust by the names of [REDACTED] they have an 2007 Chevrolet Cobalt
-. Calling to make dlr aware of allegation and checking to see what dlr knows of allegation seat belt failure and airbag non deployment
if you could pls call me with any information pertaining to this cust or vehicle at 866-790-5600 x 31227

Rita Sanchez/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 10:23:53 AM	KINZERTH	SANCHERI	BRC PAR	Initial Contact- Phone	Done	12/22/2008 04:39:43 PM	called [REDACTED]
Contact Last Name		Contact First Name		Account		BAC Code	

cust sts that his son was driving the vehicle and it had just snowed and he was making the corner and lost control of the vehicle, and the vehicle went head on into a pole. the vehicle seatbelts didnt work causeing his son to hit his head on the dash board and the airbags didnt not deploy

crs sts did your son recieve any stitches to his head

cust sts: no

crs sts: what we can do is get this vehicle inspected where is the vehicle located

cust sts: its at the body shop on
you would have to speak with Tommy and i have authorized Charles Auto Body
611 Main St Willinton MA 01887- Phone # 978-685-5360

crs sts ok i will get that inspector out to take a look at the vehicle

cust sts: ok

Rita Sanchez/ATX/PAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 10:23:43 AM	KINZERTH	SANCHERI	BRC PAR	Acknowledgement	Done	12/22/2008 04:22:06 PM	Called cust

Contact Last Name Contact First Name Account BAC Code

Comments

See Initial Contact

Rita Sanchez/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 10:23:29 AM	KINZERTH	SANCHERI	Notify CRM		Done	12/22/2008 03:54:02 PM	File Assigned

Contact Last Name Contact First Name Account BAC Code

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 10:22:47 AM	KINZERTH	SANCHERI	Research		Done	12/22/2008 03:52:49 PM	Research VIN 1G1AL15F477

Contact Last Name Contact First Name Account BAC Code

Comments

CRS Performed VIN Scan
GMVIS:- Found No Open Recalls

VIN: - Found No Duplicate File

SVC History: No Service History Related to Allegation

Rita Sanchez/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 10:22:26 AM	KINZERTH	SANCHERI	BRC PAR	Case Assigned	Done	12/22/2008 03:51:18 PM	Assigned to Rita Sanchez x31227

Contact Last Name Contact First Name Account BAC Code

Comments

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 08:13:15 AM	KINZERTH	GONZALE5	SR Opened		Done	12/22/2008 08:13:15 AM	SR In Status of Closed has been Re-
Contact Last Name	Contact First Name		Account		BAC Code		Opened by KINZERTH
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/22/2008 08:13:13 AM	KINZERTH	GONZALE5	SR Closed - Satisfied		Done	12/22/2008 08:13:14 AM	Service Request has been Closed
Contact Last Name	Contact First Name		Account		BAC Code		Satisfied.
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/19/2008 01:15:28 PM	GONZALE5	KINZERTH	Escalation	Initiate PAR	Done	12/22/2008 08:12:36 AM	Assigning activity to PAR QUEUE
Contact Last Name		Contact First Name		Account		BAC Code	

Cust's collision occurred out of state, will find out info on exact hospital and injuries.

CRS advised that a person from the PAR Department will contact the customer within 2 business days

Elizabeth Gonzalez/cac/atb/t1

Received and assigned in PAR
Thaddeus Kinzer/PAR Workflow/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
12/19/2008 12:48:03 PM	GONZALE5	GONZALE5	Inbound Call Customer	Complex Request	Done	12/19/2008 01:15:25 PM	Complaint Vehicle
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust's collision occurred out of state, will find out info on exact hospital and injuries.

Cust sts: Two days ago 2007 Chevy Cobalt and my son and his friend was calling got into an accident and neither the airbags deployed. Both sustained injuries. The safety belts didn't restrain either individual in veh.

Owner Specific:

Orig owner? no

Primary driver? yes

Personal or business use? personal

Veh Specific:

Where purchased? Merchants Auto Sale

If 2nd Owner of Veh, when/what mlg? 33000

Current approx mlg? 36000

Ext Svc Plan? yes but not through GM

Cust Sks: To voice concern about collision that occurred.

CRS adv: CRS advised that a person from the PAR Department will contact the customer within 2 business days.

Elizabeth Gonzalez/cac/abc/t1

UCC Codes

UCC Code	UCC Symptom	UCC Description
C28	Inoperative	Restraints - Seat Belt System / Buckles / Tether Anchor
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C48	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Front