


EWR D&I ANNOTATION



FAN-000001L084001DP88-6531

Artemis # : 000001L084001DP88**Record Created Date :** 01/15/2010**Printed Date :** 01/20/2010

Description : DI09-033 SEQUENCE 88 CHEVROLET 1 INJURY 2006 CHEVROLET COBALT VEHICLE. ACCORDING TO A POLICE REPORT, TRAVELING ON A RAINY DAY, SOUTHBOUND ON A TWO-WAY ROAD IN TENNESSEE, A SINGLE-VEHICLE CRASH OCCURRED. THE POLICE REPORT INDICATED THE DRIVER FAILED TO NEGOTIATE A CURVE AND TRAVELED OFF THE RIGHT SIDE OF THE ROADWAY STRIKING A DITCH. THE VEHICLE THEN CROSSED A DRIVEWAY AND OVERTURNED. THE AIR BAGS DID NOT DEPLOY. THE DRIVER WAS ABLE TO ESCAPE THROUGH A BROKEN WINDOW. THERE ARE NO ALLEGATIONS TO A SAFETY DEFECT. AA

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

May 8, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-033

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 4th quarter of 2008. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 2, 6, 8, 29, 34, 51, 58, 74, 88, 91, 92, 99, 105, 115, 116, 122, 135, 148, 186, 192, 197, 198, 292, 299, 308, 316, 324, 333, 334, 350, 352, 353, 372	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality

for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **June 12, 2009**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name and last name clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS CORPORATION
Vehicle Structure & Safety Integration

RECEIVED
NVS-210

2009 JUN 15 P 2:45

12 June 2009

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-033

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated May 8, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from 4th quarter of 2008.

GM's response is comprised of 40 disks for the incidents that are the subject of DI09-033.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 2 265593560 - 665008 and 2007 BUICK LACROSSE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 2 265593560 - 665008_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index for the disk are as follows:

DI09-033
2 265593560-665008
2007 BUICK LACROSSE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

2 265593560 - 665008_01_001 - is the first document responsive to Inquiry no. 1.
2 265593560 - 665008_02_001 - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

Product Investigations

Mail Code: 480-210-G11 • 30001 Van Dyke • Warren, MI 48090
DI09-033 Response.doc

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incidents that are the subject of DI09-033, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR), or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further. As such, the document included in response to Inquiry 1 that can be found on the enclosed disk for the PAR and Rumor case listed in the table, may not be a claim or notice of the type generally defined as such by §579.4(c).

(33 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
2	265593560	NISM
6	265592847	LITIGATION
8	265592902	NISM
29	267080984-71-	PAR
34	265592908	NISM
51	265592277	NISM
58	265593426	NISM
74	265592522	NISM
88	265592632	NISM
91	265592409	NISM
92	267081033-71-	PAR
99	265593131	NISM
105	265592075	NISM
115	265593052	NISM
116	265592720	NISM
122	265593511	NISM
135	265592841	NISM
148	265592763	NISM
186	265592855	NISM
192	265592955	NISM
197	265592786	NISM
198	265593031	NISM
292	265592180	NISM
299	265593275	NISM
308	265592964	See note *
316	265592641	NISM
324	265592728	NISM
333	265592239	NISM
334	265593086	NISM
350	265592968	NISM
352	265592252	NISM
353	265593242	NISM
372	265593510	NISM

* Sequence ID 308 was reported in error. There is no Product liability claim on this vehicle.

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**


Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators, and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,



Gay P. Kent

Director


Product Investigations

Enclosures: 40 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl +PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl +PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl +PgDn** or **Ctrl +PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The image shows a 'CIVIL CASE COVER SHEET' form for the case 'CARDONA V. CHEVROLET'. The form includes sections for case information, case type, and case management. Annotations point to specific features:

- Step 7 Next File (Image)**: Points to the 'Next Image' button in the right-hand menu.
- Step 7 Next page**: Points to the 'Next page' button in the right-hand menu.
- Step 8 Scale Image**: Points to the 'Scale to fit', 'Scale 50%', 'Scale 100%', and 'Scale 200%' options in the right-hand menu.
- Step 7 Image Properties**: Points to the 'Image Properties' button at the bottom of the right-hand menu.

The form itself contains the following information:

ATTOYNEY OF COUNCIL WITHOUT ATTORNEY FEE: ERIC D. PARIS, ESQ., 5/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 TELEPHONE NO.: 909-469-5127 FAX NO.: 909-469-5126

PLAINTIFF'S
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COURT

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET
☐ Limited ☒ Unlimited

Complex Case Designation
☐ Complex ☐ Joinder
 Filed with first appearance by defendant
 (Cal. Rules of Court, rule 1811)

Plaintiff's Case Description (Check one box below for the case type that best describes the case):

- ☒ Auto (22)
- ☐ Other PIP/DWD (Personal Injury/Property Damage/Wrongful Death) Tort
- ☐ Adversity (24)
- ☐ Medical malpractice (45)
- ☐ Other PIP/DWD (25)
- ☐ Non-PIP/DWD (Other) Tort
- ☐ Business tort/unfair business practice (27)
- ☐ Civil rights (e.g., discrimination, false arrest) (28)
- ☐ Defamation (e.g., slander, libel) (13)
- ☐ Fraud (18)
- ☐ Intellectual property (19)
- ☐ Professional negligence (e.g., injury malpractice) (25)
- ☐ Other non-PIP/DWD tort (35)
- ☐ Employment
- ☐ Wrongful termination (36)
- ☐ Contract
- ☐ Search of contract/merchandise (26)
- ☐ Collections (e.g., money owed, open book accounts) (29)
- ☐ Insurance coverage (14)
- ☐ Other contract (37)
- ☐ Real Property
- ☐ Eminent domain/diverse condemnation (14)
- ☐ Wrongful eviction (38)
- ☐ Other real property (e.g., quiet title) (19)
- ☐ Unlawful Detainer
- ☐ Commercial (31)
- ☐ Residential (32)
- ☐ Drugs (34)
- ☐ Judicial Review
- ☐ Asset forfeiture (35)
- ☐ Probation re: probation award (11)
- ☐ Viol of mandate (22)
- ☐ Other judicial review (39)
- ☐ Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 1206 - 1812)
- ☐ Arbitration/Trade regulation (33)
- ☐ Construction defect (10)
- ☐ Claims resolution re: a fire (34)

2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring on-official judicial management.

a. ☒ Large number of separately represented parties d. ☒ Large number of issues that will be time-consuming to resolve in other courts

c. ☒ Substantial amount of documentary evidence e. ☐ Substantial proof

3. Type of remedies sought (check all that apply):

a. ☒ Monetary b. ☐ Nonmonetary, declaratory or injunctive relief c. ☐ Other

4. Number of causes of action (specify): FIVE

5. This case ☐ is ☒ is not a class action suit.

Date: JULY 3, 2003

ERIC D. PARIS, ESQ., 5/B# 147836

(Type or print name)

NOTICE

Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (or under the Probate, Family, or Welfare and Institutions Code), (Cal. Rules of Court, rule 1800). This cover sheet is in addition to any cover sheet required by local court rule.

If this case is complex under rule 1800 of the California Rules of Court, you must file this cover sheet with the first paper filed in the action or proceeding.

Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

Form Approved by Managing Law
 Judicial Council of California
 1993 (JCS) (Rev. January 1, 2002)

CIVIL CASE COVER SHEET

Right-hand menu:

- Next Image
- Previous Image
- Next page Ctrl+PgDn
- Previous page Ctrl+PgUp
- Full screen image Ctrl+F11
- Slide show F10
- Fit Scale to fit F5
- Scale 50% F6
- Scale 100% F7
- Scale 200% F8
- Rotate left Ctrl+Alt+L
- Rotate right Ctrl+Alt+R
- Rotate by 180°
- Copy to clipboard
- Copy file to... Ctrl+C
- Move file to... Ctrl+X
- Rename file... F2
- Delete file... Del
- Exit Image Information... Ctrl+I
- Preferences... Ctrl+P

DI09-033
88 265592632 – 662631
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR - Collision
Address	City	Involved Dir	Montstown Chevrolet-Buick, Inc.	Safety	No
State TN ZipCd	Con Acct	Source	Phone	Updated	11/4/2008 04:35:03 PM
Serial #/VIN 1G1AL58F56	Model Year 2008	Priority	Medium License # CHEVROL	Owner	MERCADTO
Make Chevrolet	Warr. Start 08/09/2008	Status	Open	Opened	11/1/2008 09:20:38 AM
Model Cobalt	Mileage 48000	Sub-Status	Satisfied	Closed	
Abstract	Restraints - (SIR) - Driver Front (Non Deployment)				
Customer Description	This is a PAR File. Please Do Not Assume. Forward all inquiries to Tonie Mercado @ ext 41183				

Pre-PAR

PAR Notification	Incident Date/Time	Injuries	Other Veh	# People in Veh	Road Surface	Road Cond	Fire Report	Police Report
Owner	10/24/2008 11:00:00 AM	Y	0	1	Asphalt	Wet	NA	Unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5'6"		None				
Insurance Agency Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
unknown	unknown	(931) 388-7872	Farm Bureau					
Incident Loc	State Hill Road In Montstown TN.		Incident Desc	she was on her way home. rainy day. on a curved road. hit a dip in the road. car spun sideways. hit covert head on. veh rolled over around 4 times and she ended upside down in a ditch. The passenger side window was broken out and this is how she got out				
Component	Airbags		Damage Desc	Damage All Over bumpers hood doors windows. top of car is crushed in				
Vehicle Loc	Lumpkins Towing-4239230153/4232726226/4232726814		Add'l Info	Customer cannot remember how fast she was going.				
Emgcy Svc Names	Unknown		Maint Loc	Montstown Chevrolet-Buick, Inc.				

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	None
Vehicle Speed		Weather Condition	Wet/rainy		Prop Owner	n/a	Property Type	n/a
Last Service Date	10/11/2008	Loc Last Service			Property Location	n/a	Prop Est Repair Cost	
Veh Est Repair Cost		Spec Equip Installer			Prop Damage Description	n/a		
Primary Veh Use	Personal	Inspection Type			Inspected By	Inspection Not Performed	Inspection Date/Time	
Veh Damage Description	front damage hood damage top of veh crushed in. Cust not sure of how fast vehicle was traveling.				Explain Other	File going to ESIS		

Service Request Detail

PAR Injuries

Last Name:	First Name:	DOB:	Location:	Phone #:	Seating Pos:	Restraint Type:
			Occupant of Owner's Vehicle		Driver	Seat Belt
Injury Description:			Medical Rpt#:		Treatment Location:	Treated By:
6 inch cut on left of her forehead above eyebrow, front tooth broken, neck and shoulder pain and she has a concussion.			unknown		Morrisstown Hospital-4235864231	Dr. Yu James
Street Address:			City:	State:	Zip Code:	
			Moorestburg	TN		

Activities

Created:	Created By:	Assigned To:	Activity Type:	Activity Sub-Type:	Status:	Completed:	Description:
11/5/2008 01:15:19 PM	MARQUEM	MARQUEMO	BRC PAR	ESIS - Injuries	Done	11/5/2008 01:22:20 PM	ESIS - Injuries

Contact Last Name:	Contact First Name:	Account:	BAC Code:

Comments:

File being forwarded to ESIS due to major injuries involved in collision.

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments:

Created:	Created By:	Assigned To:	Activity Type:	Activity Sub-Type:	Status:	Completed:	Description:
11/5/2008 01:14:50 PM	MARQUEM	ESSISQU	Escalation	ESIS - Injuries	In Progress		Assign to ESIS

Contact Last Name:	Contact First Name:	Account:	BAC Code:

Comments:

Injuries

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments:

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/4/2008 05:53:14 PM	GARCIAJR	MARQUEMO	Notify CRM		Done	11/5/2008 01:14:48 PM	Injuries

Contact Last Name: [REDACTED] Contact First Name: [REDACTED] Account: [REDACTED] BAC Code: [REDACTED]

Comments: [REDACTED]

Confidential Comments: [REDACTED]

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/4/2008 04:35:13 PM	MERCADTO	GARCIAJR	BRC PAR	ESIS- Injuries	Done	11/4/2008 05:53:13 PM	ESIS

Contact Last Name: [REDACTED] Contact First Name: [REDACTED] Account: [REDACTED] BAC Code: [REDACTED]

Comments: [REDACTED]

Customer Sustained concussion and broken tooth due to rollover collision and alleged non deployment of airbags

Tonia Mercado/PAR/ATX

Received and assigned for ESIS escalation.
Joe G/ATX/Workflow Par

Confidential Comments: [REDACTED]

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/4/2008 03:24:37 PM	MARQUEMO	MERCADTO	Notify CRM		Done	11/4/2008 04:35:11 PM	ESIS Rejection

Contact Last Name: [REDACTED] Contact First Name: [REDACTED] Account: [REDACTED] BAC Code: [REDACTED]

Comments: [REDACTED]

Please the following and resubmit:

- Incident location needs to include city and state if available – if not then document unknown of city and state
- Please update injuries desc with all the injuries that's included in documentation

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments: [REDACTED]

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/4/2008 09:37:38 AM	MERCADTO	MERCADTO	Outbound Call Customer	Made Contact	Done	11/4/2008 09:49:18 AM	

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Crs Adv: Was returning your call

Cust sts: Spoke to wife last night and telling about the situation. And she was telling me that she locked her keys in the car in Ohio and someone came out to unlock the car and they messed up the lock on the drivers side and couldn't get it open, but they had to get in thru the passenger side. And after that we recalled that everytime getting out the car the driver door would shock you. And we took to Morislow and they said there was nothing wrong w/ it. But I just wanted to have this documented. She called Chevy roadside assistance when this happened

Crs Adv: will doc that in the file and I have already sent it to central calms and you should hear from someone wll 7-10 days.

Cust sts: Ok thanks

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/4/2008 09:34:35 AM	MERCADTO	MERCADTO	Inbound Call Customer	Voice Mail Received	Done	11/4/2008 09:35:00 AM	

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Cust sts: Please return call
sent 11/4 917am est

Tonle Mercada/PA/ATX

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 05:58:05 PM	GARCIAJR	MARQUEMO	Notify CRM		Done	11/4/2008 03:24:34 PM	Injuries

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Confidential Comments:

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 02:50:49 PM	MERCADTO	MERCADTO	Inbound Call Dealer	Voice Mail Received	Done	11/3/2008 02:51:15 PM	Bobby at Morristown

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Cust sts: Bobby at Morristown Chevy
423-586-6021 ref# 71-676269427
sent 11/3 234am est

Tonia Mercado/PA/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 02:43:30 PM	MERCADTO	MERCADTO	Scheduled Follow-up	Scheduled Alarm			ESIS

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Check Case status.

11/10,
5-7pm est

Tonia Mercado/PA/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 02:42:50 PM	MERCADTO	GARCIAJR	BRC PAR	ESIS- Injuries	Done	11/3/2008 05:56:00 PM	ESIS

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Customer was in rollover collision and sustained concussion, broken front tooth and neck and back pain.

Tonia Mercado/PA/ATX

Received and assigned for ESIS escalation.
Joe GIATX/Workflow Par

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 02:07:10 PM	MERCADTO	MERCADTO	Ownership Changed	Ownership Escalated to BRC	Done	11/3/2008 02:07:11 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 12:38:47 PM	GARCIAJR	MERCADTO	Ownership Changed		Done	11/3/2008 12:38:47 PM	Service Request Ownership has changed FROM: CAGUIAJI TO: MERCADTO

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 12:38:23 PM	GARCIAJR	MERCADTO	BRC PAR	Initial Contact- Phone	Done	11/3/2008 02:39:06 PM	called

Contact Last Name	Contact First Name	Account	BAG Code

Comments

Crs Adv: This is Tonie Mercado calling from

the GM Product Allegation Dept. I have

received your file and do require further

information. Do you have a moment to speak to

me?

Cust sts: Yes

Crs verified pre par info and filled out par detail.

Cust sts: She went into a ditch and hit covert head on which put her in a roll and she ended upside down in a ditch. The passenger side window was broken out and this is how she got out

Doesn't know how fast she was going. She can't remember anything. She doesn't remember how she got out of the vehicle or how she was transported. Doesn't remember the ambulance ride.

She has a 6 inch cut on left of her forehead above eyebrow, front tooth broken, neck and shoulder pain and she has a concussion.

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 12:37:52 PM	GARCIAJR	MERCADTO	BRC PAR	Initial Contact- Dealer	Done	11/3/2008 02:25:54 PM	called Morristown Chevrolet-Buick @

Contact Last Name	Contact First Name	Account	BAG Code

Comments

Crs Spoke w/ David

Crs Adv: was calling because I received a file in your area and wanted to make you aware of the situation. Would like to speak to service manager

Dir sts: he's on the other line

Crs Adv: provided contact info and SR and requested call back

Tonie Mercado/Par/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 12:37:45 PM	GARCIAJR	MERCADTO	BRC PAR	Initial Contact-AVM	Done	11/3/2008 02:14:46 PM	called Cbolns Michael Mike 404082 8158

Contact Last Name	Contact First Name	Account	BAG Code

Comments

DVM Name: Mike Cbolns
Node/Mailbox: 404082-8158
This is Tonia Mercado
calling from the GM Product Allegation Dept:

The request number is: 71-876269427
The Customer's name is (spell):
The dealer involved is: Morristown Chevrolet-Buick
Located in (be specific): Morristown TN
The vehicle is a (year/make/model): 2006 Chevy Cobalt
With current mileage: 48k
The last 8 digits of the VIN# are: 67
This involves: Customer was in a rollover collision in which the airbags didn't deploy. The customer is seeking GM to investigate the concern.
This message is for informational purposes

only. However if you do have any questions

please feel free to give me a call.

Confidential Comments:

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 12:37:33 PM	GARCIAJR	MERCADTO	ERC PAR	Acknowledgement	Done	11/3/2008 02:14:02 PM	called Cboins Michael Mike 404082 8158

Contact Last Name	Contact First Name	Account	BAC Code

Comments

DVM Name: Mike Cboins

Node/Mailbox: 404082-8158

This is Torle Mercado

calling from the GM Product Allegation Dept:

The request number is: 71-676269427

The Customer's name is (spell) [REDACTED]

The dealer involved is: Morristown Chevrolet-Buick

Located in (be specific): Morristown TN

The vehicle is a (year/make/model): 2006 Chevy Cobalt

With current mileage: 48k

The last 8 digits of the VIN# are: 67 [REDACTED]

This involves: Customer was in a rollover collision in which the airbags didn't deploy. The customer is seeking GM to investigate the concern.

This message is for informational purposes

only. However if you do have any questions

please feel free to give me a call.

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 12:37:17 PM	GARCIAJR	MERCADTO	Notify CRM		Done	11/3/2008 02:44:03 PM	File Assigned

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 12:38:45 PM	GARCIAJR	MERCADTO	Research		Done	11/3/2008 02:08:06 PM	Research vln

Contact Last Name	Contact First Name	Account	BAC Code

Comments

No open recalls
No prev Related claim history
No other files

Tonie Mercado/PA/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/3/2008 12:35:26 PM	GARCIAJR	MERCADTO	BRC PAR	Case Assigned	Done	11/3/2008 02:44:06 PM	file assigned to Tonie Mercado ext 41183

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/1/2008 09:35:09 AM	CAGUIAJI	GARCIAJR	Escalation	Initiate PAR	Done	11/3/2008 11:12:18 AM	assigning activity to par queue

Contact Last Name	Contact First Name	Account	BAC Code

Comments

we filled out a Pre Par Form. i will forward this to par, they will call you within 2 business days

JoeyAnderson/MAN/Tier 1/PB/L1

Received and assigned in PAR.

Joe G/ATX/Workflow Par

Confidential Comments

Service Request Detail

Activities

Created By	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
11/1/2008 09:31:31 AM	CAGUIAJI	CAGUIAJI	Inbound Call Customer	Complex Request	Done	11/1/2008 09:35:08 AM	Pre Par-Airbags did not deploy-Injury

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Customer states:

my wife had an accident, veh rolled over 4 times, none of the airbags deployed

Customer seeks:

file a report

CRS Advised:

we filled out a Pre Par Form. I will forward this to par. they will call you within 2 business days

JoeyAnderson/MAN/Tier1/PBL1

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C47	SIR - Did Not Deploy	Restraints - (SIR) - Driver Side - Side Impact

GM Vehicle Inquiry System Summary

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) -
[Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AL58F567
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AL69 -2006 COBALT 4-DOOR LT SEDAN				Warranty Start Date :		09/09/2006		
BARS Order Type :	70 - RETAIL - STOCK								
Delivering Dealer :	MORRISTOWN CHEVROLET-BUICK, INC. PO BOX 1753 MORRISTOWN , TN 37816-1753 (423) 586-6021				Selling Source :		13 - CHEVROLET		
					Site Code :		09441		
					Business Associate Code :		112462		
Service Contract :	No	Branded Title :		No	Warranty Block :		No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information

ON STAR AND XM SATELLITE RADIO INFORMATION

OnStar Equipped	No	OnStar Status	N/A	Refer to Help page for details or go to OnStar Online Enrollment (located on the "OnStar" tab in GM InfoNET) or (888)ONSTAR1 (888) 667-8271.			
XM Equipped	Yes	XM Radio ID	2QNRC08G	XM Status	Inactive	Refer to Help page for details or: www.xmradio.gm.ca or Dealer Hotline 1.877.GET.XMST (1-877-438-9677).	

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	09/09/2006	16 miles	09/09/2009	36016 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	09/09/2006	16 miles	09/09/2012	100016 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	09/09/2006	16 miles	09/09/2014	80016 miles
36/36000 FEDERAL EMISSION	09/09/2006	16 miles	09/09/2009	36016 miles

<http://198.208.187.167/gmvis/main/Summary?languageSelected=EN&VIN=1G1AL58F56...> 11/5/2008

60/60000 POWERTRAIN - U.S. LIMITED WARRANTY	09/09/2006	16 miles	09/09/2011	60016 miles
---	------------	----------	------------	-------------

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
08/08/2008	156414	#	B4261 - FRONT SIDE DOOR LOCK REPLACEMENT - LEFT SIDE	51788 miles
06/28/2008	W09950	#	Z2081 - ROADSIDE SERVICE (LOCKOUT)	48 miles
02/28/2008	020712	#	J6441 - EVAPORATIVE EMISSION CANISTER VENT SOLENOID VALVE REPLACEM	38883 miles
12/17/2007	149027	#	J6354 - POWERTRAIN CONTROL MODULE ENGINE REPROGRAMMING WITH SPS	35041 miles
10/19/2007	147092	#	H0122 - FRONT BRAKE ROTOR REFINISHING	32029 miles
10/19/2007	147092	#	K5225 - CONTROL ASSEMBLY, FLOOR SHIFT - REPLACE	32029 miles
09/11/2006	133379	#	N6632 - WIRING AND/OR CONNECTOR - VEHICLE ENTERTAINMENT - REPAIR O	164 miles
08/16/2006	132468	#	J6980 - VACUUM HOSE - REPAIR OR REPLACE	86 miles
09/12/2005	A65325	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AL58F567
-------	-------------

CLAIM HISTORY

Repair Order Date :		08/08/2008		Repair Order Number :		156414		Odometer Reading :		51788 miles	
Serviced By :		MORRISTOWN CHEVROLET-BUICK, INC. PO BOX 1753 MORRISTOWN, TN 37816-1753 (423) 586-6021				Selling Source :			13 - CHEVROLET		
						Site Code :			09441		
						Business Associate Code :			112462		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
08/15/2008	926	01	#	B4261 - FRONT SIDE DOOR LOCK REPLACEMENT - LEFT SIDE		25938089 - LOCK		A	N/A	\$ 119.99	N

Repair Order Date :		06/28/2008		Repair Order Number :		W09950		Odometer Reading :		48 miles	
Serviced By :		GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117				Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
07/04/2008	914	01	#	Z2081 - ROADSIDE SERVICE (LOCKOUT)		N/A		C	N/A	\$ 43.89	N

Repair Order Date :		02/28/2008		Repair Order Number :		020712		Odometer Reading :		38883 miles	
Serviced By :		BOOSE CHEVROLET COMPANY PO BOX 39 BROOKVILLE, OH 45309-0039 (937) 833-4011				Selling Source :		13 - CHEVROLET			
						Site Code :		09073			
						Business Associate Code :		112756			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
				J6441 - EVAPORATIVE							

<http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=1G1AL58...> 11/5/2008

03/04/2008	879	01	#	EMISSION CANISTER VENT SOLENOID VALVE REPLACEM	15788844 - VALVE	A	N/A	\$ 69.81	N
------------	-----	----	---	--	---------------------	---	-----	----------	---

Repair Order Date :		12/17/2007		Repair Order Number :		149027		Odometer Reading :		35041 miles	
Serviced By :		MORRISTOWN CHEVROLET-BUICK, INC. PO BOX 1753 MORRISTOWN, TN 37816-1753 (423) 586-6021				Selling Source :		13 - CHEVROLET			
						Site Code :		09441			
						Business Associate Code :		112462			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
12/21/2007	858	01	#	J6354 - POWERTRAIN CONTROL MODULE ENGINE REPROGRAMMING WITH SPS		N/A	N/A	N/A	\$ 25.04	N	

Repair Order Date :		10/19/2007		Repair Order Number :		147092		Odometer Reading :		32029 miles	
Serviced By :		MORRISTOWN CHEVROLET-BUICK, INC. PO BOX 1753 MORRISTOWN, TN 37816-1753 (423) 586-6021				Selling Source :		13 - CHEVROLET			
						Site Code :		09441			
						Business Associate Code :		112462			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
10/26/2007	842	01	#	H0122 - FRONT BRAKE ROTOR REFINISHING		N/A		N/A	N/A	\$ 125.22	N
10/26/2007	842	02	#	K5225 - CONTROL ASSEMBLY, FLOOR SHIFT - REPLACE		15926820 - CONTROL		N/A	N/A	\$ 130.32	N

Repair Order Date :		09/11/2006		Repair Order Number :		133379		Odometer Reading :		164 miles	
Serviced By :		MORRISTOWN CHEVROLET-BUICK, INC. PO BOX 1753 MORRISTOWN, TN 37816-1753 (423) 586-6021				Selling Source :		13 - CHEVROLET			
						Site Code :		09441			
						Business Associate Code :		112462			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
09/19/2006	727	01	#	N6632 - WIRING AND/OR CONNECTOR - VEHICLE ENTERTAINMENT - REPAIR O		N/A	N/A	N/A	\$30.18	N	

Repair Order Date :		08/16/2006		Repair Order Number :		132468		Odometer Reading :		86 miles	
Serviced By :	MORRISTOWN CHEVROLET-BUICK, INC. PO BOX 1753 MORRISTOWN, TN 37816-1753 (423) 586-6021					Selling Source :		13 - CHEVROLET			
						Site Code :		09441			
						Business Associate Code :		112462			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
08/25/2006	720	01	#	J6980 - VACUUM HOSE - REPAIR OR REPLACE		N/A		N/A	N/A	\$ 12.07	N

Repair Order Date :		09/12/2005		Repair Order Number :		A65325		Odometer Reading :		0 miles	
Serviced By :	MIKE GRUBBS CHEVROLET CADILLAC PO BOX 2737 MOULTRIE, GA 31776-2737 (229) 985-2400					Selling Source :			13 - CHEVROLET		
						Site Code :			08275		
						Business Associate Code :			206954		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
09/16/2005	622	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A		N/A	N/A	\$ 76.73	N

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Vehicle Build

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN	1G1AL58F567
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AL69 -2006 COBALT 4-DOOR LT SEDAN		
Gross Vehicle Weight Rating :	1727 kg (3808 lb)	Order Number :	JKX14J
Build Date :	09/12/2005	Build Plant :	167A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AR9 - DELUXE FRONT BUCKET SEAT
ASF - AIRBAGS, SIDE HEAD-CURTAIN	B34 - FLOOR MATS
B35 - REAR FLOOR MATS	C67 - ELECT. FRONT AIR CONDITIONER
DG7 - BODY COLOR POWER MIRRORS	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FE9 - FEDERAL EMISSIONS	FY1 - TRANS/AXLE 3.63 RATIO
IPC - INTERIOR TRIM DESIGN	JJK - SUSPENSION, REAR INSTALLED
JM4 - 4-WHEEL ANTI-LOCK BRAKE SYSTEM	K64 - 115 AMP GENERATOR
LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO	L61 - 2.2L DOHC 4 CYL ENGINE
MN5 - 4 SPEED AUTO TRANSMISSION	MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE
NT7 - FEDERAL EMISSION TIER 2	NW7 - TRACTION CONTROL
N46 - 4 SPOKE STEERING WHEEL	PF7 - 15" ALUMINUM WHEELS
QTU - P195/60R15 TOURING BW TIRES	R6P - PREMIUM PAINT
SLM - STOCK ORDERS	T43 - REAR DECK-LID SPOILER
UQ3 - PIONEER 7 SPKR AMPLIFIED SYSTEM	US8 - AM/FM STEREO W/CD & MP3 (REPLACES STD/OPT RADIO)
U2K - XM SATELLITE RADIO-SERVICE FEE EXTRA. 1ST 3 MONTHS INCL.	V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA
1LT - 1LT BASE PACKAGE	1SZ - OPTION PACKAGE DISCOUNT
14C - GRAY	14I - GRAY
6AR - FRONT SPRING	7AR - FRONT SPRING

<http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=1G1AL58...> 11/5/2008

8AA - REAR SPRING	9AA - REAR SPRING
95U - ULTRA SILVER METALLIC	.

© 1998-2005 General Motors Corporation. All Rights Reserved.

11/02/2008



Master Record Number	(b) (6)
Type of Crash: Injury-Possible	
Approved By	80CR

Tennessee Electronic Traffic Crash Report

Incident Information

Date Of Crash 10/24/2008	Day of Crash Friday	Local Agency Number THP/CRAC	Reporting Agency Name Tennessee Highway Patrol	Agency Tracking Number (b) (6)
Time of Crash 11:30	Time Notified 11:37	Time Arrived 11:51	County Hawkins	City
Total 1	Total 1	Total 0	Total 0	Total 1
Vehicles	Occupants	Non-Occupants	Killed	Injured
Hit and Run N	Solved? N	Police Pursuit N	School Bus Involved? No	Photos Taken? N
Area Residential	Interchange Related? N	Intersect Type Not at Intersection	Photographer Name	
Block Number				
Roadway Number		Roadway Name SLATE HILL		Suffix RD
Est Distance 200.00	Distance Type Feet	Direction South	From Highway Number/Intersection LAKE ACCESS	Suffix RD
Roadway Local ID		Intersect Local ID		
Relation to Junction Non-Junction		Relation to Roadway Roadside-Right		Route Signing County Route
Work Zone None		Construction Zone		
Construction Location		Workers Present		
First Harmful Event Ditch		Trafficway Type Trafficway-OPEN		
Weather Conditions Rain		Light Conditions Daylight	Latitude	Longitude
Rail Crossing ID				
Manner of Collision Not Collision with Motor Vehicle in Transport				
1st Collision Factor		2nd Collision Factor		3rd Collision Factor

Investigating Officer Details

Investigation Complete Y	Rank SERGEANT	First Name CHRISTY	Middle Initial	Last Name OSBORNE	Suffix
Badge Number 83CO	District/Zone 5	Car Number 5515	Report Date 10/24/2008		

Vehicle Number	No. of Occupants	Driver Presence
	1	Driver Operated

Driver Information

First Name	Initial	Last Name	Suffix	Date of Birth	Age
Address Line 1	Address Line 2	City	State	Zip	
		MOORESBURG	TN		
Phone 1	Phone 2	Phone 3	Race	Ethnicity	Gender
			Caucasian	White	F
Air Bag Available-No Deployment					
Safety Equipment Shoulder And Lap Belt Used					
Driver's License Number	License State	Expiration Date	License Class	License Status	Seat Position
	TN	2009	D	Valid	Front Seat-Left Side
Endorsements 1	Complied With?	Endorsements 2	Complied With?	Endorsements 3	Complied With?
Restrictions 1	Complied With?	Restrictions 2	Complied With?	Restrictions 3	Complied With?
Ejected	Ejection Path	Trapped/Extricated			
Not Ejected	Not Ejected	Not Trapped			
Injury Code	Medical Transport	Ambulance/Hospital			
Non-Incapacitating Evident	EMS-Ground	MORRISTOWN/HAMBLE HOSPITAL			

Driver Conditions and Actions

Hit and Run?	Driver/Vehicle Maneuver	Distraction
No Hit And Run	Negotiating A Curve	None
Driver's 1st Condition	Driver's 2nd Condition	Driver's 3rd Condition
Appeared Normal		
Driver's 1st Action	Driver's 2nd Action	
Unknown		
Driver's 3rd Action	Driver's 4th Action	

Alcohol and Drugs

Presence of Alcohol	Determination Method	Alcohol Test Status
No	Observed	Test Not Given
1st Alcohol Test Type	1st Alcohol Test Result	2nd Alcohol Test Type
Not Tested	None Given	
2nd Alcohol Test Result		
Presence of Drugs	Determination Method	Drug Test Status
No	Observed	Test Not Given
1st Drug Test Type	1st Drug Test Result	2nd Drug Test Type
Not Tested For Drugs	No Drug Reported	
2nd Drug Test Result	3rd Drug Test Type	3rd Drug Test Result

Driver Violations

1st Violation	1st Violation Category	1st Violation Description	1st Violation Statute
2nd Violation	2nd Violation Category	2nd Violation Description	2nd Violation Statute
3rd Violation	3rd Violation Category	3rd Violation Description	3rd Violation Statute
4th Violation	4th Violation Category	4th Violation Description	4th Violation Statute
5th Violation	5th Violation Category	5th Violation Description	5th Violation Statute

Vehicle Information

Owner Same as Driver?	Owner First Name	Middle Name	Owner Last Name	Owner Suffix
Y				
Street 1	Street 2	City	State	Zip
		MOORESBURG	TN	
Phone Number 2	Phone Number 3	Vehicle Year	Vehicle Make	Vehicle Model
		2006	CHEV	COLB
VIN	License Plate Number	State	Exp Year	Body Code
YG1ALS8F567		Tennessee	042009	Four-Door Sedan Hardtop
HAZMAT?	FMCSA	Bus Use	Unit Type	
N	Renovable? N	Not Used As School Bus	Motor Vehicle In-Transport	
Gross Weight			Vehicle Configuration	
10000 or Less-No Haz-8 Or Less				
Vehicle Operation Type			Cargo Body Type	
Personally Owned/Used				
1st Factor	2nd Factor	3rd Factor		
Tires				
Insurance 1	Insurance 1 Type	Insurance 1 Carrier	Insurance 1 Start Date	Insurance 1 End Date
	Owner	TN FARMERS MUTAL		
Insurance 2	Insurance 2 Type	Insurance 2 Carrier	Insurance 2 Start Date	Insurance 2 End Date
Insurance 3	Insurance 3 Type	Insurance 3 Carrier	Insurance 3 Start Date	Insurance 3 End Date

Vehicle Damage and Roadway Characteristics

Most Harmful Event Over Turn, Roll Over		Emergency Use? N	Over Underride No Underride-Override		Fire in Vehicle? N
Events 1 Ditch		Events 2 Over Turn, Roll Over		Events 3	
Events 4		Events 5		Events 6	
Point of First Impact Front End		Extent of Damage Disabling Damage		Officer Damage Estimate Greater Than 400 Dollars	
Areas of Vehicle Damage All Areas					
Vehicle Special Use No Special Use	Towed? Towed Due To Vehicle Damage	Towed Where? CARL LUMPKINS WRECKE	1st Trailer No Trailer	1st Trailer Licence Plate Information	
2nd Trailer	2nd Trailer Licence Plate Information		3rd Trailer	3rd Trailer Licence Plate Information	
Travel Direction South		Traveling On SLATE HILL ROAD			
Trafficway Flow Two-Way Not Divided		Roadway Surface Type Asphalt	Number of Travel Lanes Two Lanes		
Trafficway Hazards None					
Traffic Control Devices No Control		Traffic Control Device Functioning No Controls		Roadway Route Signing County Route	
Roadway Surface Conditions Wet		Roadway Character Alignment Curve Right		Roadway Character Profile Level	
Speed Limit 30	Access Control No Control				

Commercial Carrier Information

US DOT	Carrier Name		Carrier Type		ICC MC	TN DOS
Address Line 1		Address Line 2		City	State	Zip Code
1st Hazardous Materials		HAZMAT Class	Placard?	Placard #	Released?	Hazardous Materials Released
2nd Hazardous Materials		HAZMAT Class	Placard?	Placard #	Released?	Hazardous Materials Released
3rd Hazardous Materials		HAZMAT Class	Placard?	Placard #	Released?	Hazardous Materials Released

Narrative

VEHICLE 1 WAS TRAVELING SOUTH ON SLATE HILL ROAD AND DRIVER FAILED TO NEGOTIATE A CURVE. THE VEHICLE TRAVELED OFF THE RIGHT SIDE OF THE ROADWAY STRIKING A DITCH. THIS CAUSED THE VEHICLE TO TRAVELING ACROSS A DRIVEWAY AND OVERTURN.

NOT TO SCALE

