


EWR D&I ANNOTATION



FAN-000001L091001DP98-6621

Artemis # : 000001L091001DP98**Record Created Date :****Printed Date :** 12/23/2009

Description : DI09-066, Seq ID# 98, response consists of PAR. Consumer alleges that rear control arm broke into 2 pieces while driving causing a loss of control, ending up in wooded area. Consumer asked for third party inspector. No mention of injury is found in PAR. Third party inspector concluded control arm broke due to impact damage. *BH



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

September 4, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-066

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 2, 17, 20, 75, 76, 79, 87, 98, 103, 122, 124, 126, 133, 139, 147, 150, 157, 159, 160, 164, 179, 186, 196, 203, 204, 205, 209, 216, 254, 257, 266, 268, 282, 283, 296, 325, 331, 339, 354, 355, 357, 358, 374, 380, 396, 407, 432, 435, 436, 439, 440, 456, 457, 462, 469, 471, 504, 507, 511	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new

requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **October 2, 2009**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Josh Neff at (202) 366-0698 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS COMPANY
Global Interior and Safety Center

14 October 2009

OCT 15 2009

OCT 15 2009

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-066

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated September 4th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2009.

GM's response is comprised of 65 disks for the incidents that are the subject of DI09-066. Sequence ID number 457, is a NISM (Not In Suit Matters) that originated in China and will be submitted as soon as the documents are located.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 2 274020230 - 671278 and 2008 BUICK LACROSSE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 2 274020230 - 671278_00_**Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index for the disk are as follows:

DI09-066
2 274020230-671278
2008 BUICK LACROSSE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 2 274020230 - 671278_01_001 - is the first document responsive to Inquiry no. 1.
- 2 274020230 - 671278_02_001 - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(1 Vehicle from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
2	UNKNOWN	NISM
17	3G5DA03E25S [REDACTED]	NISM
20	3G5DA03L97S [REDACTED]	NISM
75	KL1TG52655B [REDACTED]	NISM
76	KL1TD52685B [REDACTED]	NISM
79	KL1TD56677B [REDACTED]	NISM
87	KL1TD56EX9B [REDACTED]	NISM
98	1G1AZ55F267 [REDACTED]	PAR
103	1G1AK55F067 [REDACTED]	NISM
122	1G1AL58F887 [REDACTED]	NISM
124	1G1AL58F887 [REDACTED]	NISM
126	1G1AM18BX87 [REDACTED]	NISM
133	1G1AT58H497 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
139	1GCDS49E288	NISM
147	2CNDL73F866	NISM
150	2CNDL63F166	PAR
157	1GBJG316481	RUMOR
159	3GNDA23D96S	NISM
160	3GNDA23DX7S	NISM
164	3GNDA13D18S	NISM
179	2G1WF52E359	NISM
186	2G1WT58K879	NISM
196	2G1WB57K291	NISM
203	1G1ZU57NX7F	NISM
204	1G1ZU57N77F	NISM
205	1G1ZT58F57F	NISM
209	1G1ZG57BX8F	NISM
216	2G1WM15K069	NISM
254	2GCEK133971	NISM
257	2GCEK19J071	PAR
266	2GCEK19JX81	NISM
268	2GCEK13C181	NISM
282	1GCHK29D87E	NISM
283	1GCHK53679F	LIT
296	1GNFK16358R	NISM
325	1GNDT13S552	NISM
331	1GNDT13S772	NISM
339	1GNDT13S882	PAR
354	1GKEV33798J	NISM
355	1GKER23738J	NISM
357	1GKEV33748J	NISM
358	1GKEV33748J	NISM
374	1GKDT13S862	NISM
380	1GKDT13S772	NISM
396	3GTEC13047G	NISM
407	1GTHK23668F	NISM
432	1G2ZH57N284	NISM
435	1G2ZF57B084	NISM
436	1G2ZH57NX84	NISM
439	1G2ZH57N394	NISM
440	1G2ZH57N094	NISM
456	2G2WP552281	NISM
457	UNKNOWN	NISM
462	1G2MB33B76Y	NISM
469	YS3FD79Y856	NISM
471	YS3FD79Y376	NISM
504	5GZCZ53466S	NISM
507	5GZCZ33D36S	PAR
511	3GSDL73768S	NISM

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in dark ink, appearing to read 'G. Kent', with a long, sweeping horizontal line extending to the right.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 65 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl +PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl +PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl +PgDn** or **Ctrl +PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The image shows a legal case cover sheet for 'CARDONA V. CHEVROLET' and an 'Image Properties' dialog box. The cover sheet includes sections for case information, case type, and a notice. The image properties dialog box has tabs for 'Image' and 'Image Properties', with the 'Image' tab currently selected. It contains options for 'Next Image', 'Previous Image', 'Next page', 'Previous page', 'Full screen image', 'Slide show', 'Fit', 'Scale to fit', 'Scale 50%', 'Scale 100%', 'Scale 200%', 'Rotate left', 'Rotate right', 'Rotate by 180°', 'Copy to clipboard', 'Copy file to...', 'Move file to...', 'Rename file...', 'Delete file...', 'EXIF Image Information...', and 'Preferences...'. Arrows point from the dialog box to the steps described in the text.

ATTESTATION OF PARTY HIRING AN ATTORNEY (Please print name and address)
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 TELEPHONE NO: 909-469-5127 FAX NO: 909-469-5126
 ATTORNEY FOR: PLAINTIFF'S

NOTICE TO DEFENDANT, COUNTERCLAIM, AND WAIVER OF COURT APPEARANCE
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COURT

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET

Complex Case Designation
☐ Limited ☒ Unlimited ☐ Counter ☐ Joinder
 Filed with first appearance by defendant
 (Cal. Rules of Court, rule 1811)

CASE NUMBER: 9822(b)(1)
 ASSIGNED JUDGE:

1. Check one box below for the case type that best describes this case:
☒ Auto Tort (22)
☐ Auto (22)
☐ Other PIP/DWD (Personal Injury/Property Damage)/Wrongful Death Tort
☐ Asbestos (24)
☐ Product Liability (24)
☐ Medical malpractice (45)
☐ Other PIP/DWD (22)
☐ Non-PIP/DWD (Other) Tort
☐ Receiver/beneficiary business practice (20)
☐ Civil rights (e.g., discrimination, false arrest) (20)
☐ Defamation (e.g., slander, libel) (12)
☐ Fraud (16)
☐ Intellectual property (19)
☐ Professional negligence (e.g., legal malpractice) (20)
☐ Other non-PIP/DWD tort (20)
☐ Employment
☐ Wrongful termination (26)
☐ Other employee (15)
☐ Contract
☐ Breach of contract/warranty (20)
☐ Collection (e.g., money owed, note paid, promissory) (20)
☐ Insurance coverage (18)
☐ Other contract (37)
☐ Real Property
☐ Eminent domain/Inverse condemnation (14)
☐ Wrongful eviction (22)
☐ Other real property (e.g., quiet title) (26)
☐ Unlawful Detainer
☐ Commercial (21)
☐ Residential (22)
☐ Drugs (39)
☐ Judicial Review
☐ Asset forfeiture (55)
☐ Prisoner re: substitution award (11)
☐ Will of decedent (22)
☐ Other judicial review (29)
☐ Previously Complex Civil Litigation (Cal. Rules of Court, rules 1899-1912)
☐ Antitrust/Trade regulation (23)
☐ Construction defect (10)
☐ Claims involving mass tort (20)

2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring exceptional judicial management.
 a. ☒ Large number of separately represented parties d. ☒ Large number of coordination or in other counties
 b. ☒ Extensive motion practice raising difficult or novel issues that will be time-consuming to resolve e. ☐ Substantial cross
 c. ☒ Substantial amount of documentary evidence f. ☐ Substantial cross

3. Type of remedies sought (check all that apply):
 a. ☒ necessary ☐ nonmonetary, declaratory or injunctive relief e. ☐

4. Number of causes of action (specify): FIVE

5. This case ☐ is ☒ is not a class action suit.

Date: JULY 3, 2003

ERIC D. PARIS, ESQ., S/B# 147836
 (Print, do not write)

NOTICE
 • Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (ex. under the Probate, Family, or Welfare and Institutions Codes) (Cal. Rules of Court, rule 1800).
 • File this cover sheet in addition to any cover sheet required by local court rule.
 • If this case is complex under rule 1800 of the California Rules of Court, you must also submit to the local court rule.
 • Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

From: Integrated to e-File
 9/2/2007 (Rev. January 1, 2003)

CIVIL CASE COVER SHEET

Step 7: Next File (Image)

Step 7: Next page

Step 8: Scale Image

Step 7: Image Properties

DI09-066
98 273621278 - 71 - 699151195
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Activity

SR No.	71-699151195	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Suspension - Rear Control Arms /	Sub-Area	Initiate PAR- Collision
Address		City	Houston	Involved Dir	Chuck Davis Chevrolet, Inc	Safety	Yes
State	TX	Postal Cd		Source	Phone	Updated	3/10/2009 03:08:05 PM
Serial #/VIN	1G1AZ55F267	Model Year	2006	Priority	Medium	License #	CHEVROL
Make	Chevrolet	Warr. Start	01/13/2006	Status	Closed	Opened	2/2/2009 12:13:38 PM
Model	Cobalt	Mileage	51,400	Sub-Status	Dissatisfied	Closed	3/10/2009 03:07:41 PM
Abstract	Suspension - Failed (Causing Collision)						
Customer Description	This is a PAR File. Please do not Assume. Forward all inquiries to Tonie Mercado @ ext 41183						

GMPP Details

GMPP Term	GMPP Mileage	GMPP Retail Cost
-----------	--------------	------------------

Component Coverage

Component Coverage	Expiration Mileage	Expiration Date
--------------------	--------------------	-----------------

Certificate Details

Certificate Number	Amount	Expiration Date
--------------------	--------	-----------------

Pre-Authorization Basics

Service Dealer	BAC Code	Div. Dealer Code	Repair Order #
----------------	----------	------------------	----------------

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/10/2009 03:07:39 PM	MERCADTO	MERCADTO	SR Closed - Dissatisfied		Done	3/10/2009 03:07:39 PM	Service Request has been Closed
Contact Last Name	Contact First Name	Account	BAC Code				Dissatisfied.
Comments							

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/10/2009 03:03:48 PM	MERCADTO	MERCADTO	Outbound Call Third Party	Made Contact	Done	3/10/2009 03:07:29 PM	Rosie Lopez @ Frederick Law Firm @ 713-645-2539
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs Adv: Was returning your phone call. I received the message. The file was sent to contral claims office. You will need to contact them for any updates.

667122 Lisa Cudworth
800-888-0164

TP sts: Just wanted to know what was going on w/ the case.

Crs provided ESIS info and advised will need to contact them for any updates.

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/10/2009 03:03:10 PM	MERCADTO	MERCADTO	Inbound Call Customer	Voice Mail Received	Done	3/10/2009 03:03:33 PM	Rosie w/ Frederick Law Firm
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts: Rosie w/ Frederick Law Firm 71-599151195. We represent [REDACTED] we have sent over letter of representation and we have received confirmation that the fax has gone through and we need a letter of confirmation from GM.

sent 3/10 219pm est

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/10/2009 03:03:08 PM	MERCADTO	MERCADTO	SR Opened		Done	3/10/2009 03:03:09 PM	SR in Status of Closed has been Re-Opened by MERCADTO
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/5/2009 09:40:54 AM	MERCADTO	MERCADTO	SR Closed - Satisfied		Done	3/5/2009 09:40:54 AM	Service Request has been Closed Satisfied.
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/5/2009 09:38:08 AM	MERCADTO	MERCADTO	Outbound Call Customer	Left Message	Done	3/5/2009 09:40:40 AM	
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

667122 Lisa Cudworth
800-888-0164

Crs Adv: Was f/u with you. I received your message and I understand you want an update on your case. Your file was sent to the central claims office. They have already p/u the file. Provided ESIS info and contact name.

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/5/2009 09:28:47 AM	MERCADTO	MERCADTO	Outbound Call Customer	Received No Answer	Done	3/5/2009 09:38:06 AM	
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Received No answer

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/5/2009 09:27:41 AM	MERCADTO	MERCADTO	Outbound Call Customer	Received No Answer	Done	3/5/2009 09:28:41 AM	
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

call was answered then disconnected.

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/5/2009 09:25:06 AM	MERCADTO	MERCADTO	Inbound Call Customer	Voice Mail Received	Done	3/5/2009 09:26:04 AM	
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Cust sts: 71-699151195. Was calling about the

status on my case. home cell work

sent 3/4 550pm est

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
3/5/2009 09:25:05 AM	MERCADTO	MERCADTO	SR Opened		Done	3/5/2009 09:25:05 AM	SR in Status of Closed has been Re-
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/16/2009 05:45:21 PM	MERCADTO	MERCADTO	SR Closed - Satisfied		Done	2/16/2009 05:45:21 PM	Service Request has been Closed
Contact Last Name	Contact First Name		Account		BAC Code		
Satisfied.							
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/16/2009 05:42:33 PM	MERCADTO	MERCADTO	BRC PAR	Close	Done	2/16/2009 05:42:53 PM	Closing file
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							
ESIS p/u file							

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/12/2009 05:36:20 PM	RODRIGOS	RODRIGOS	BRC PAR	ESIS- Thermal Event	Done	2/12/2009 05:37:09 PM	Esis case
Contact Last Name		Contact First Name		Account		BAC Code	
[REDACTED]		[REDACTED]		[REDACTED]		[REDACTED]	
Comments							

Case was sent to ESIS, due to a Thermal Event.

Jose Rodriguez ATX PAR

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/12/2009 05:35:23 PM	RODRJOS	TOPOROW M	Escalation	ESIS - Atty Involvement	Done	2/16/2009 01:44:20 PM	Assigned to ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Attorney Rosie Lopez
713-520-1064
Frederick Law Firm.

667122 Lisa Cudworth

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/11/2009 12:57:36 PM	KINZERTH	RODRJOS	Notify CRM		Done	2/12/2009 05:35:22 PM	ESIS - Attorney Involvement

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Received And Assigned to ESIS

Jose Rodriguez ATX PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/11/2009 11:45:18 AM	OGLESBBI	MERCADTO	Scheduled Follow-up		Done	2/16/2009 05:42:31 PM	-Check for ESIS pickup

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/11/2009 11:43:49 AM	OGLESBBI	KINZERTH	BRC PAR	ESIS- Atty Involvement	Done	2/11/2009 12:57:35 PM	Escalating to ESIS, cust has retained an attorney

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Escalating case to ESIS because cust has retained an attorney. Attorney Rosie Lopez from Frederick Law Firm.

Michelle Oglesby/ATX/PAR

Received and assigned for ESIS escalation
Thaddeus Kinzer/PAR Workflow/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/11/2009 11:40:49 AM	OGLESBBI	OGLESBBI	Outbound Call Third Party	Left Message	Done	2/11/2009 11:43:16 AM	Called Attorney Rosie Lopez @ 713-520-1064
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS left message for attorney

CRS sts: Calling to let you know that I'm handling the case right now since the OCRS is out of the office. I will be forwarding this case to Central Claims for further handling. They will be in touch with you within 10 business days. If they are not, call back the OCRS and she will get you their info. If you have any questions before Monday, call me and I'll help as best I can. Provided phone # and OCRS phone #.

Michelle Oglesby/ATX/PAR

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/11/2009 10:21:00 AM	MENESECA	MERCADTO	Notify CRM		Done	2/11/2009 11:38:03 AM	pls see attached docs
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/11/2009 10:20:30 AM	SADMIN	MERCADTO	Inbound White Mail	Customer	Done	2/11/2009 10:21:20 AM	Scanned: 2009-02-11-09.00.47.000000, MSXDocNum: 00007867
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

customer name:

SR#71-699151195

deleaship:

Cust States:

-cust sent in documents

Cust Seeks:

-cust asking for assistance

CRS Advice/Plan of action:

-attach to SR#71-699151195

-notify OCRS

JASON BIGGS/TIER1/WHITEMAILMANILA/Lv1Emp

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/11/2009 08:48:17 AM	CRUZAL	CRUZAL	Inbound Call Third Party		Done	2/11/2009 08:49:58 AM	Ms.Rosie Lpoez called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Ms.Rosie Lopez from Frederick Law Firm called

wish to get the Divisional address and the fax number

crs gave information

crs connected Ms.Lopez to OCRS's VM

Alex Scofield CAC Tier 1 MLA LVL 1

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/9/2009 05:21:46 PM	CUNNING1	CUNNING1	Inbound Call Third Party	Complex Request	Done	2/9/2009 05:23:40 PM	CRS Called Inspector
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

TP Inspector Called In

TP Sts: Calling you back.

CRS Adv: what I can tell is that this looks more like it was caused by impact over some kind of defect.

TP Sts: Yes I would say that is correct. The broken component shows no signs of the normal damage of a defect.

Patrick Cunningham/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/9/2009 05:08:25 PM	CUNNING1	CUNNING1	Outbound Call Third Party	Left Message	Done	2/9/2009 05:09:52 PM	CRS Called Inspector
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

ACRS Left Message: SR# and phone#, Wanted to get some additional information on the

Patrick Cunningham/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/5/2009 01:34:27 PM	MERCADTO	MERCADTO	Inbound Call Third Party	Voice Mail Received	Done	2/5/2009 01:34:39 PM	Eddie w/ EAA
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts: Eddie Jenkins w/ EAA. I talked to the customer [REDACTED] and she gave me the correct VIN which is the one on the vehicle itself, so the info on the file is incorrect. So everything is straight and I have already looked at the vehicle and will now be getting the report ready, if you need to call me my # 512-970-8779 sent 2/5 1245pm est

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/5/2009 12:36:23 PM	MERCADTO	MERCADTO	Inbound Call Third Party	Complex Request	Done	2/5/2009 12:36:46 PM	Eddie Jenkins w/ EAA
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

TP sts: I'm at the dealer and the VIN #'s are different on what you have and what's on the car. And I was trying to figure out how this might've happened. The Vin on vehicle is 1g1aZf26677 [REDACTED] and what you have is diffent than that. So I dont know if I should look at the vehicle.

Crs Adv: I will attempt to reach the customer to see if she has anything on hand that she can veirify the VIN w/.

TP sts: Will you give me a call if you talk to her and I will call you if I talk to her. But I am going to go ahead and look at it. There's more damage that what she indicated and that's why I was wondering about looking at it. But I'll go ahead and take a look.

My # is 512-970-8779

Crs Adv: Ok I will see what I can find.

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/4/2009 04:13:09 PM	MERCADTO	MERCADTO	Email - Inbound		Done	2/4/2009 04:13:35 PM	EAA
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

I will inspect this vehicle on Thursday 2/5/09.
Eddie

Tonie Mercado/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/4/2009 10:06:51 AM	MERCADTO	MERCADTO	Scheduled Follow-up		Done	2/11/2009 11:43:38 AM	
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Action Plan: Inspection request was sent one week ago. Just f/u w/ customer to advise we are still awaiting results and I will f/u when I receive them.

No committed time was made

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/4/2009 10:06:24 AM	MERCADTO	MERCADTO	Email - Outbound		Done	2/4/2009 10:06:37 AM	EAA Inspection request has been sent
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/4/2009 10:04:03 AM	MERCADTO	MERCADTO	Outbound Call Customer	Made Contact	Done	2/4/2009 10:05:13 AM	
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Crs Adv: Was just calling you back, I did get your message so I went ahead and sent out the inspection request. I will just f/u with you in about a week from today.

Cust sts: Ok thanks

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/4/2009 09:55:20 AM	MERCADTO	MERCADTO	Inbound Call Customer	Voice Mail Received	Done	2/4/2009 09:55:41 AM	
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Cust sts: 71-699151195. I just wanted you to know that the vehicle is already at the dealer I towed it there yesterday. Thanks sent 2/4 904am est

Tonie Mercado/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 12:39:08 PM	MERCADTO	MERCADTO	Scheduled Outbound Call Cust	Cancelled - Completed Early	Done	2/4/2009 10:05:29 AM	

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Action Plan: if no customer contact yet call her to see if she has been able to get vehicle towed in to the dlr

2/4

11-1pm est

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 12:36:45 PM	MERCADTO	MERCADTO	Outbound Call Customer	Made Contact	Done	2/3/2009 12:39:00 PM	

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Crs Adv: I was just calling to touch base w/ you. I have called the dlr and they are ok w/ the vehicle being there for the inspection. When can you have it there

Cust sts: I will try to get it there today.

Crs Adv: ok well just give me a call once it's there at the dlr so that I can get the inspection request sent out.

Cust sts: will do

Crs Adv: if I don't hear from you by EOB today I will call you tomorrow and we'll see where we are at that time

Cust sts: ok thanks

Tonie Mercado/PAR/aTX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 12:34:22 PM	MERCADTO	MERCADTO	Outbound Call Dealer	Made Contact	Done	2/3/2009 12:36:40 PM	Tom Pierson Svc Mgr @ Chuck Davis - 832-204-7332

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Crs Adv: Was calling to see if you would be ok w/ hosting an inspection. we need facility. Customer has allegation that the rear control arms broke while driving causing a collision and we want to have 3rd party come out and take a look at the vehicle

Dlr sts: Sure we can help you out with that

Tonie mercado/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 12:28:52 PM	MERCADTO	MERCADTO	Outbound Call Dealer	Made Contact	Done	2/3/2009 12:34:10 PM	Chuck Davis Chevrolet @ 713-794-2500
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs Spoke w/: Service Tech

Crs Adv: I was calling to see if you would mind having this vehicle inspected at your facility. You won't have to touch the vehicle we will send out a third party.

Dlr sts: I will give you direct # because this is something that you would need to run by him

Crs Adv: ok will do

dlr sts: 832-204-7332 is his direct dial.

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 10:32:48 AM	MERCADTO	MERCADTO	Inbound Call Customer	Service Request Update	Done	2/3/2009 10:38:18 AM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts: I have claim # for insurance
Claim #

Crs Adv: Ok I will update your file w/ that informaton. I have contacted Chuck Davis Chevrolet and I am currently awaiting a phone call back from the svc mgr and once I hear from them I will be sure to get the inspection request sent out and I will notify you when I do that. And it does take between 7-14 days before the inspection is fully completed and the report is sent over to me. So I will just wait to hear from the svc mgr and we'll take it from there

Cust sts: ok thanks you

Crs adv: do you have any questions?

Cust sts: No not at this time

Tonie Mercado/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 10:00:05 AM	MERCADTO	MERCADTO	Scheduled Outbound Call	Cust	Done	2/3/2009 12:39:03 PM	

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Action Plan: contact customer after dlr contact to advise if vehicle can be taken there for the inspection.

2/3
1230-230pm est

Tonie Mercado/PAr/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 09:56:15 AM	MERCADTO	MERCADTO	Outbound Call Dealer	Left Message	Done	2/3/2009 09:59:17 AM	Chuck Davis Chevrolet @ 713-794-2500

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Crs Spoke w/ Tom Pierson Svc Mgr Voice Mail

Crs Adv: I was calling because I received a file concerning customer and I was wondering if you would mind if customer brought the vehicle to your dealer for an inspection. Please give me a call when you get a chance. Provided contact info and SR

Tonie Mercado/PAr/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 09:41:56 AM	MERCADTO	MERCADTO	Outbound Call Customer	Made Contact	Done	2/3/2009 09:52:39 AM	

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Crs Adv: Was calling to go over case information w/ you. Do you have moment to speak?

Cust sts: yes

Continued in initial contact

Tonie Mercado/PAr/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/3/2009 09:39:59 AM	MERCADTO	MERCADTO	Outbound Call Customer	Made Contact	Done	2/3/2009 09:41:51 AM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs Adv: Was calling because I received your file concernig your vehicle and I wanted to go over case information w/ you.

Cust sts: Call me on another # because I am in elevator and you may get cut off

Crs Adv: Ok thanks

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 01:54:55 PM	MERCADTO	MERCADTO	Scheduled Outbound Call	Cust	Done	2/3/2009 09:59:24 AM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Action Plan: 2nd attempt to do initial if no answer try as alt # and get address

2/3

10-12pm est

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 01:52:57 PM	MERCADTO	MERCADTO	Outbound Call Customer	Received No Answer	Done	2/2/2009 01:54:46 PM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Phone continued to ring w/ no answer and wasn't able to leave message.

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 01:51:11 PM	MERCADTO	MERCADTO	Outbound Call Customer	Left Message	Done	2/2/2009 01:52:38 PM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

See acknowledgment

Tonie Mercado/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 01:43:56 PM	MERCADTO	MERCADTO	Ownership Changed	Ownership Escalated to BRC	Done	2/2/2009 01:43:56 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:36:00 PM	KINZERTH	MERCADTO	Ownership Changed		Done	2/2/2009 12:36:00 PM	Service Request Ownership has changed FROM: ROMEROS1 TO: MERCADTO

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:35:47 PM	KINZERTH	MERCADTO	BRC PAR	Initial Contact- AVM	Done	2/2/2009 01:50:22 PM	Called Campbell Joshua 972075 8000

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

DVM Name: Joshua Campbell

Node/Mailbox: 972075-8000

This is Tonie Mercado

calling from the GM Product Allegation Dept to make you aware of a file that was received in your area.

The request number is: 71-699151195

The Customer's name is (spell):

The dealer involved is: Munday Chevrolet

Located In (be specific): Houston TX

The vehicle is a (year/make/model): 2006 Chevrolet Cobalt

With current mileage: 51k

The last 8 digits of the VIN# are: 67

This involves: customer is alleging that the suspension failed on the vehicle causing a collision. We will be investigating this case.

This message is for informational purposes only. However if you do have any questions please feel free to give me a call.

Provided contact info.

Tonie Mercado/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:35:38 PM	KINZERTH	MERCADTO	BRC PAR	Initial Contact- Dealer	Done	2/2/2009 01:50:53 PM	Not required
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

No dlr visit in the last 2 years

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:35:29 PM	KINZERTH	MERCADTO	BRC PAR	Initial Contact- Phone	Done	2/3/2009 09:56:10 AM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

crs verified pre par and par detail info

Cust sts: I was heading home and I heard an noise from under the car and then I heard loud popping noise and the car spun out of control and I ended up in wooded area. The muffler came out from under the vehicle. The control Arm split in 2.

Crs Adv: What component do you believe caused this collision

Cust sts: the control arm is what split in 2.

Crs adv: Ok, well what we can do is have vehicle inspected, however, due to the nature of the collision it has to be inspected at a Chevrolet Dlr, We are unable to do the inspection there where the vehicle is currently

Cust sts: ok

Crs Adv: and are you able to get it to the dlr for the inspection

Cust sts: Would like to get it to Davis Chevrolet

Crs Adv: will call them and find out if it is ok for us to have vehicle taken there for the inspection. I can call them while you hold or I can call you back

Cust sts: Please call me back and give me about 20-30 minutes

Crs Adv: ok will do

Tonie Mercado/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:35:21 PM	KINZERTH	MERCADTO	BRC PAR	Acknowledgement	Done	2/2/2009 01:52:26 PM	Called
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Crs Adv: This is Tonie Mercado calling from the GM Product Allegation Dept. I have received your file and do require further information. Please give me a call when you get a chance. Provided contact info and SR

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:35:12 PM	KINZERTH	MERCADTO	Notify CRM		Done	2/2/2009 01:55:53 PM	File Assigned
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:35:03 PM	KINZERTH	MERCADTO	Research		Done	2/2/2009 01:44:40 PM	Research VIN
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

No open recalls
No prev related claim history
No other files

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:34:42 PM	KINZERTH	MERCADTO	BRC PAR	Case Assigned	Done	2/2/2009 01:41:25 PM	Assigned to Tonie Mercado x41183
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Received

Tonie Mercado/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:34:36 PM	KINZERTH	ROMEROS1	SR Opened		Done	2/2/2009 12:34:36 PM	SR in Status of Closed has been Re-Opened by KINZERTH
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:34:34 PM	KINZERTH	ROMEROS1	SR Closed - Satisfied		Done	2/2/2009 12:34:35 PM	Service Request has been Closed Satisfied.
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:28:46 PM	ROMEROS1	KINZERTH	Escalation	Initiate PAR	Done	2/2/2009 12:34:30 PM	Assigning activity to PAR QUEUE
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

CRS advised that a person from the PAR Department will contact the customer within 2 business days.

Barbara Robinson (Soledad Romero) CAC T1 / L1 / BA

Received and assigned in PAR
Thaddeus Kinzer/PAR Workflow/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
2/2/2009 12:16:04 PM	ROMEROS1	ROMEROS1	Inbound Call Customer	Complex Request	Done	2/2/2009 12:18:09 PM	Alleged product allegation-Collision
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Customer states she was driving down the hwy when she started to hear a noise coming from underneath the veh and then the veh lost control.

Customer seeks to notify GM about this and have the case review.

CRS advised customer that their information will be forwarded to the Product Allegation Department within the BRC

Barbara Robinson (Soledad Romero) CAC T1 / L1 / BA

UCC Codes

UCC Code	UCC Symptom	UCC Description
F34	Broken	Suspension - Rear Control Arms / Bushings / Ball Joints