


EWR D&I ANNOTATION



FAN-000001L091001DP104-6722

Artemis # : 000001L091001DP104**Record Created Date :** 01/12/2010**Printed Date :** 01/13/2010

Description : DI09-066, SEQ ID# 104, (RESPONSE CD INCORRECTLY LABELED '103') RESPONSE INCLUDED PRE-PAR DOCUMENT, AND POLICE REPORT. IN PRE-PAR, CONSUMER ALLEGES THAT THE STEERING WHEEL LOCKED UP WHILE TRYING TO NEGOTIATE A SHARP TURN IN THE ROADWAY, CAUSING HER TO LOSE CONTROL, DRIVING OFF ROAD AND ROLLING VEHICLE. CONSUMER REPORTS INJURIES AS BRUISING ALL OVER AND PAIN IN ELBOW PREVENTING USE OF IT. ACCORDING TO THE OFFICER'S DIAGRAM IN THE POLICE REPORT, WHILE ENTERING A LEFT-HAND CURVE ON A TWO-LANE HIGHWAY THE CAR SWERVED SLIGHTLY RIGHT THEN LEFT ACROSS ONCOMING LANE AND ONTO AN EMBANKMENT. OFFICER NOTES, ROADWAY WAS DRY AND 'OPERATOR STATES SHE HAS AN UNKNOWN MECHANICAL PROBLEM AND IS UNABLE TO CONTROL VEHICLE. 'OFFICER DOES NOT MAKE ANY FURTHER RELEVANT NOTES IN POLICE REPORT.*BH

Print

Close



GENERAL MOTORS COMPANY
Global Interior and Safety Center

14 October 2009

OCT 15 2009

OCT 15 2009

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-066

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated September 4th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2009.

GM's response is comprised of 65 disks for the incidents that are the subject of DI09-066. Sequence ID number 457, is a NISM (Not In Suit Matters) that originated in China and will be submitted as soon as the documents are located.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 2 274020230 - 671278 and 2008 BUICK LACROSSE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 2 274020230 - 671278_00_**Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index for the disk are as follows:

DI09-066
2 274020230-671278
2008 BUICK LACROSSE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 2 274020230 - 671278_01_001 - is the first document responsive to Inquiry no. 1.
- 2 274020230 - 671278_02_001 - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(1 Vehicle from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
2	UNKNOWN	NISM
17	3G5DA03E25S [REDACTED]	NISM
20	3G5DA03L97S [REDACTED]	NISM
75	KL1TG52655B [REDACTED]	NISM
76	KL1TD52685B [REDACTED]	NISM
79	KL1TD56677B [REDACTED]	NISM
87	KL1TD56EX9B [REDACTED]	NISM
98	1G1AZ55F267 [REDACTED]	PAR
103	1G1AK55F067 [REDACTED]	NISM
122	1G1AL58F887 [REDACTED]	NISM
124	1G1AL58F887 [REDACTED]	NISM
126	1G1AM18BX87 [REDACTED]	NISM
133	1G1AT58H497 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
139	1GCDS49E288	NISM
147	2CNDL73F866	NISM
150	2CNDL63F166	PAR
157	1GBJG316481	RUMOR
159	3GNDA23D96S	NISM
160	3GNDA23DX7S	NISM
164	3GNDA13D18S	NISM
179	2G1WF52E359	NISM
186	2G1WT58K879	NISM
196	2G1WB57K291	NISM
203	1G1ZU57NX7F	NISM
204	1G1ZU57N77F	NISM
205	1G1ZT58F57F	NISM
209	1G1ZG57BX8F	NISM
216	2G1WM15K069	NISM
254	2GCEK133971	NISM
257	2GCEK19J071	PAR
266	2GCEK19JX81	NISM
268	2GCEK13C181	NISM
282	1GCHK29D87E	NISM
283	1GCHK53679F	LIT
296	1GNFK16358R	NISM
325	1GNDT13S552	NISM
331	1GNDT13S772	NISM
339	1GNDT13S882	PAR
354	1GKEV33798J	NISM
355	1GKER23738J	NISM
357	1GKEV33748J	NISM
358	1GKEV33748J	NISM
374	1GKDT13S862	NISM
380	1GKDT13S772	NISM
396	3GTEC13047G	NISM
407	1GTHK23668F	NISM
432	1G2ZH57N284	NISM
435	1G2ZF57B084	NISM
436	1G2ZH57NX84	NISM
439	1G2ZH57N394	NISM
440	1G2ZH57N094	NISM
456	2G2WP552281	NISM
457	UNKNOWN	NISM
462	1G2MB33B76Y	NISM
469	YS3FD79Y856	NISM
471	YS3FD79Y376	NISM
504	5GZCZ53466S	NISM
507	5GZCZ33D36S	PAR
511	3GSDL73768S	NISM

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in dark ink, appearing to read "G. Kent", with a long, sweeping horizontal line extending to the right.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 65 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer


1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl +PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl +PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl +PgDn** or **Ctrl +PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



DI09-066
103 272742381 – 668168
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Documents.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No.	71-706534701	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Steering - General	Sub-Area	Initiate PAR- Collision
Address		City	Farmington	Involved Dir	Farnsworth Chevrolet, Inc.	Safety	Yes
State	NY ZipCd	Con Acct		Source	Phone	Updated	3/6/2009 09:29:24 AM
Serfal #/VIN	1G1AK55F067	Model Year	2006	Priority	Medium License #	Owner	OGLESBIM
Make	Chevrolet	Warr. Start	05/09/2006	Status	Open	Opened	3/3/2009 10:42:18 AM
Model	Cobalt	Mileage	35000	Sub-Status		Closed	
Abstract	06 Cobalt-Steering failure						
Customer Description	This is a BRC PAR Case. Do not assume. Forward any inquiries to Michelle Oglesby at ex. 31394.						

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Relative	2/28/2009 10:40:14 PM	Y	0	1	Asphalt	Dry	n/a	sp1e40000346
Driver Last Name	Driver First Name	DOB	Height	Disabilities				
			5'11	None				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Nash	Sam	(585) 425-8830	Allstate Insurance Company					
Incident Loc	State Route 96, Farmington, NY	Incident Desc	My daughter was driving down the road and came upon a sharp turn. She slowed down to make the turn when all of a sudden the steering wheel locked up and she lost control of the vehicle. She went head on into a dirt embankment, spun sideways, rolled up onto it's right side, and rolled					
Component	Steering	Damage Desc	Front and side of the vehicle all smashed up. Possibly totaled.					
Vehicle Loc	Farnsworth Chevrolet/5853943260	Add'l Info						
Emgcy Svc Names	NY State Police/Michael Dundon	Maint Loc	Farnsworth Chevrolet/5853943260					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	None
Vehicle Speed	50	Weather Condition	dry	Prop Owner	n/a	Property Type	n/a	
Last Service Date		Loc Last Service		Property Location	n/a	Prop Est Repair Cost		
Veh Est Repair Cost	\$0.00	Spec Equip Installer	n/a	Prop Damage Description	n/a			
Primary Veh Use	Personal	Inspection Type		Inspected By		Inspection Date/Time		
Veh Damage Description	Front and side of the vehicle all smashed up. Possibly totaled. No estimate on the damage yet.			Explain Other	n/a			

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	seatbelt
Injury Description		Medical Rpt#		Treatment Location		Treated By
Bruising all over, pain in her elbow preventing her from using it		unk		F. F. Thompson Hospital		Dr. Tamara Prull
Street Address			City	State	Zip Code	
			Farmington	NY		

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/6/2009 09:31:07 AM	MARQUEM O	MARQUEMO	BRC PAR	ESIS- Insurance Involvement	Done	3/6/2009 09:31:45 AM	ESIS- Insurance Involvement

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

File being forwarded to ESIS due to insurance comp is involved.

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/6/2009 09:29:55 AM	MARQUEM O	ESISBIQU	Escalation	ESIS - Insurance Involvement	In Progress		Assign to ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Insurance Involvement

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/6/2009 09:07:29 AM	KINZERTH	MARQUEMO	Notify CRM		Done	3/6/2009 09:29:53 AM	ESIS - Insurance Involvement
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/5/2009 11:33:06 AM	MERCADTO	MERCADTO	Outbound Call Dealer	Made Contact	Done	3/5/2009 11:42:18 AM	Farnsworth Chevy @ 585-394-2360
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Crs Spoke w/ Body Shop Manager Charles Hall

Crs Adv: Was calling to inform you that the case is going to central claims office for further handling because of the insurance involvement.

Dir sts: I'm the body shop manager and I can pass this message on to Keith. What should we do w/ the vehicle.

Crs Adv: At this point, it's pretty much up to the customer. We recommend that nothing is done to the vehicle so that we can investigate, however, it's up to the customer.

Dir sts: ok thanks

Tonle Mercado/PA/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 06:42:17 PM	OGLESBMI	OGLESBMI	Scheduled Follow-up		Scheduled Alarm		Check for ESIS pickup
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 08:41:16 PM	OGLESBBI	KINZERTH	BRC PAR	ESIS- Insurance Involvement	Done	3/6/2009 09:07:28 AM	Escalating to ESIS, Insurance Involvement

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Vehicle involved in a collision due to alleged steering failure, insurance company Allstate is involved. Escalating to ESIS.

Michelle Oglesby/ATX/PAR

Received and assigned for ESIS escalation

Thaddeus Kinzel/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 06:40:16 PM	OGLESBBI	OGLESBBI	Ownership Changed	Ownership Escalated to BRC	Done	3/4/2009 06:40:17 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 05:59:08 PM	OGLESBBI	OGLESBBI	Scheduled Outbound Call	Cust	Done	3/5/2009 11:36:34 AM	-Call dir to let them know case went to central claims

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 05:58:40 PM	OGLESBBI	OGLESBBI	Outbound Call Customer	Left Message	Done	3/4/2009 05:58:54 PM	Called
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

CRS left message for cust with SR and phone #. Requesting more info/contact for case.

Michelle Oglesby/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 11:30:09 AM	OGLESBBI	OGLESBBI	Scheduled Outbound Call	Cust	Done	3/4/2009 05:51:50 PM	Call for Initial
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 10:30:20 AM	ALARINAL	OGLESBBI	Notify CRM	Other	Done	3/4/2009 11:08:26 AM	dealer called in seeking for info
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

-assisting only-

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 10:24:51 AM	ALARINAL	ALARINAL	Inbound Call Dealer	Complex Request	Done	3/4/2009 10:30:18 AM	Mr Keith Young calling (asst mgr for Body shop)
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

DLR STS:

-this is keith young asst mgr for the body shop

-case number 71-706534701

-Cust had an accident, it was towed into our dr, made us aware that this has something to do w/ the insurance, we just wanna know how to proceed from here

DLR SKS:

-assistance

CRS STS:

-tried calling ext of rep but only got VM

-will be sending notification to the rep who handles file

Btlr Johnson/Mk/CAC T1/LMD emp

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:33:24 PM	KINZERTH	OGLESBIM	Ownership Changed		Done	3/3/2009 01:33:24 PM	Service Request Ownership has changed FROM: ARRIBAAI TO: OGLESBIM
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:33:05 PM	KINZERTH	OGLESBIM	BRC PAR	Initial Contact- AVM	Done	3/4/2009 11:27:50 AM	Called DVM Patrick Dubay
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

DVM Name: Patrick Dubay
Node/Mailbox: 814055 8134
This is Michelle Oglesby
calling from the GM Product Allegation Dept.
The request number is: 71-706534701
The Customer's name is: [REDACTED]
The dealer involved is: Farnsworth Chevrolet
The vehicle is: 2006 Chevrolet Cobalt
The last 8 digits of the VIN# are: 67[REDACTED]
This involves: Cust alleges a steering failure caused a collision

Michelle Oglesby/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:32:57 PM	KINZERTH	OGLESBIM	BRC PAR	Initial Contact- Dealer	Done	3/4/2009 11:25:57 AM	Called Farnsworth Chevrolet @ 585-394-2350
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Spoke with Body Shop Personell Keith Young

CRS sts: Calling for info on the case.

Dir sts: This vehicle was towed in from an accident. Initially they had said they had Allstate Insurance, so we were preparing an estimate. Then she said she felt that there may have been a defect that caused the collision. At that point, we didn't want to do any further work on the car. We didn't want to take it apart and possibly risk interfering with any investigation. Just by looking at it, though, it looks like this vehicle is going to be totaled.

Michelle Oglesby/ATX/PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:32:49 PM	KINZERTH	OGLESBBI	BRC PAR	Initial Contact- Phone	Done	3/4/2009 08:39:40 PM	Called

Contact Last Name: Contact First Name: Account: BAC Code:

Comments

Cust sts: My daughter was driving down the road and came upon a sharp turn. She slowed down to make the turn when all of a sudden the steering wheel locked up and she lost control of the vehicle. She went head on into a dirt embankment, spun sideways, rolled up onto it's right side, and rolled back onto all four wheels. Something similar to this happened about a month ago. I have a claim going with my insurance company and I'm not sure if they're going to total it or not.

CRS sts: Because of the insurance involvement in this case, I will need to escalate your case to Central Claims for further handling. It will take them about 10 business days for them to get in touch with you. If you don't hear from Central claims by that time, call me and I can get you your new agent and file info.

Michelle Oglesby/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:32:42 PM	KINZERTH	OGLESBBI	BRC PAR	Acknowledgement	Done	3/4/2009 11:30:08 AM	Called

Contact Last Name: Contact First Name: Account: BAC Code:

Comments

CRS left message for cust with SR and phone #. Requesting more info/contact for case.

Michelle Oglesby/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:32:35 PM	KINZERTH	OGLESBBI	Notify CRM		Done	3/3/2009 03:16:44 PM	File Assigned

Contact Last Name: Contact First Name: Account: BAC Code:

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:32:28 PM	KINZERTH	OGLESBMI	Research		Done	3/3/2009 03:15:52 PM	Research VIN
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Research

Recalls: No open recalls

Related repairs: No related repairs

Previous SRs: No previous SRs

Michelle Oglesby/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:32:08 PM	KINZERTH	OGLESBMI	BRC PAR	Case Assigned	Done	3/3/2009 03:14:41 PM	Assigned to Michelle Oglesby x31394
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:17:12 PM	KINZERTH	ARRIBAAI	SR Opened		Done	3/3/2009 01:17:12 PM	SR In Status of Closed has been Re-Opened by KINZERTH
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 01:17:11 PM	KINZERTH	ARRIBAAI	SR Closed - Satisfied		Done	3/3/2009 01:17:11 PM	Service Request has been Closed Satisfied.
Contact Last Name		Contact First Name		Account		BAC Code	

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 12:12:41 PM	KINZERTH	KINZERTH	Escalation	Initiate PAR	Done	3/3/2009 01:17:08 PM	Assigning activity to PAR QUEUE
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days

Received and assigned in PAR
Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 11:55:08 AM	ARRIBAAI	ARRIBAAI	Escalation	Initiate PAR	Done	3/3/2009 11:56:22 AM	Assigning activity to PAR QUEUE
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days."

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 11:38:26 AM	ARRIBAAI	ARRIBAAI	Inbound Call Customer	Complex Request	Done	3/3/2009 12:12:40 PM	Pre Par
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust Stc:

- 2006 Cobalt
- my daughter was driving the other night and the tire
- the car is possibly totalled
- she went into a curve and couldn't straight it back

Cust Skc:

- assistance

CRS Advsd:

- advsd cust that will gather add info to better assist her
- gave SR#
- advsd cust that Par dept will contact her after two business days once case will be forwarded to them

Allen Speed/CAC/Tier1/Mn/Lvl0

Confidential Comments

UCC Information

UCC Code	Symptom	Description
M01	Misaligned	Steering - General

GM Vehicle Inquiry System Summary

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AK55F067
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AK69 -2006 COBALT 4-DOOR LS SEDAN			Warranty Start Date :		05/09/2006	
BARS Order Type :	50 - FLEET						
Delivering Dealer :	DAVID PENSKE CHEVROLET, INC. 100 S MUSEUM ROAD SHILLINGTON , PA 19607 (610) 337-3100			Selling Source :		13 - CHEVROLET	
				Site Code :		15147	
				Business Associate Code :		113831	
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	05/09/2006	10 miles	05/09/2009	36010 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	05/09/2006	10 miles	05/09/2012	100010 miles
48/48000 GM CERTIFIED USED LIMITED WARRANTY	05/09/2006	10 miles	05/09/2010	48010 miles
60/100000 GM CERTIFIED USED POWERTRAIN LIMITED WARRANTY	05/09/2006	10 miles	05/09/2011	100010 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	05/09/2006	10 miles	05/09/2014	80010 miles
36/36000 FEDERAL EMISSION	05/09/2006	10 miles	05/09/2009	36010 miles

http://198.208.187.167/gmvis/main/Summary?languageSelected=EN&VIN=1G1AK55F067... 3/6/2009

60/60000 POWERTRAIN - U.S. LIMITED WARRANTY	05/09/2006	10 miles	05/09/2011	60010 miles
---	------------	----------	------------	-------------

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
11/25/2008	251500	#	E7059 - TURN SIGNAL MULTIFUNCTION SWITCH REPLACEMENT	34791 miles
06/20/2008	245336	#	H0122 - FRONT BRAKE ROTOR REFINISHING	34390 miles
05/08/2008	V19957	#	Z2080 - ROADSIDE SERVICE (TOWING)	32421 miles
03/10/2008	144556	#	J5650 - FUEL INJECTOR REPLACEMENT	30897 miles
02/20/2008	182749	#	K5225 - CONTROL ASSEMBLY, FLOOR SHIFT - REPLACE	29993 miles
02/20/2008	182749	#	N0110 - BATTERY REPLACEMENT	29993 miles
02/19/2008	T52105	#	Z2080 - ROADSIDE SERVICE (TOWING)	23426 miles
02/19/2008	T52106	#	Z2080 - ROADSIDE SERVICE (TOWING)	23426 miles
05/08/2006	A57887	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AK55F067
-------	-------------

CLAIM HISTORY

Repair Order Date :		11/25/2008		Repair Order Number :		251500		Odometer Reading :		34791 miles	
Serviced By :		FARNSWORTH CHEVROLET CADILLAC PO BOX 25009 CANANDAIGUA, NY 14425-0009 (585) 394-2360				Selling Source :		13 - CHEVROLET			
						Site Code :		13056			
						Business Associate Code :		115350			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
12/02/2008	957	01	#	E7059 - TURN SIGNAL MULTIFUNCTION SWITCH REPLACEMENT		15915857 - SWITCH	N/A	N/A	\$ 110.53	N	

Repair Order Date :		06/20/2008		Repair Order Number :		245336		Odometer Reading :		34390 miles	
Serviced By :	FARNSWORTH CHEVROLET CADILLAC PO BOX 25009 CANANDAIGUA, NY 14425-0009 (585) 394-2360					Selling Source :		13 - CHEVROLET			
						Site Code :		13056			
						Business Associate Code :		115350			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
07/01/2008	913	01	#	H0122 - FRONT BRAKE ROTOR REFINISHING		N/A		N/A	N/A	\$ 144.63	N

Repair Order Date :		05/08/2008		Repair Order Number :		V19957		Odometer Reading :		32421 miles	
Serviced By :	GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117					Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments

<http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=1G1AK55F...> 3/6/2009

05/20/2008	901	01	#	Z2080 - ROADSIDE SERVICE (TOWING)	N/A	C	N/A	\$ 69.00	N
------------	-----	----	---	-----------------------------------	-----	---	-----	----------	---

Repair Order Date :		03/10/2008		Repair Order Number :		144556		Odometer Reading :		30897 miles	
Served By :	CARFAGNO CHEVROLET PO BOX 530 PLYMOUTH MEETING, PA 19462-0530 (610) 275-0507					Selling Source :		13 - CHEVROLET			
						Site Code :		15087			
						Business Associate Code :		113793			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
03/25/2008	885	01	#	J5650 - FUEL INJECTOR REPLACEMENT		12582219 - INJECTOR		N/A	N/A	\$ 122.13	Y

Repair Order Date :		02/20/2008		Repair Order Number :		182749		Odometer Reading :		29993 miles	
Serviced By :	MOORE CHEVROLET-OLDSMOBILE PO BOX 192 CONSHOHOCKEN, PA 19428-0192 (610) 825-5600					Selling Source :		13 - CHEVROLET			
						Site Code :		15426			
						Business Associate Code :		113824			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
02/29/2008	878	01	#	K5225 - CONTROL ASSEMBLY, FLOOR SHIFT - REPLACE		15926820 - CONTROL	N/A	N/A	\$ 166.06	N	
02/29/2008	878	02	#	N0110 - BATTERY REPLACEMENT		89022163 - BATTERY	N/A	N/A	\$ 175.27	N	

Repair Order Date :		02/19/2008		Repair Order Number :		T52105		Odometer Reading :		23426 miles	
Served By :	GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117					Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
02/29/2008	878	01	#	Z2080 - ROADSIDE SERVICE (TOWING)		N/A		C	N/A	\$ 58.94	N

Repair Order Date :		02/19/2008	Repair Order Number :		T52106	Odometer Reading :		23426 miles	
Served By :	GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD				Selling Source :		13 - CHEVROLET		

MEDFORD, MA 02155-5117				Site Code :		34415			
				Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments
02/29/2008	878	01	#	Z2080 - ROADSIDE SERVICE (TOWING)	N/A	C	N/A	\$ 58.94	N

Repair Order Date :		05/08/2006		Repair Order Number :		A57887		Odometer Reading :		0 miles	
Serviced By :		DAVID PENSKE CHEVROLET, INC. 100 S MUSEUM ROAD SHILLINGTON, PA 19607 (610) 337-3100				Selling Source :		13 - CHEVROLET			
						Site Code :		15147			
						Business Associate Code :		113831			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
05/12/2006	690	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A	N/A	N/A	\$ 98.72	N	

CHECK HISTORY

Vehicle Has No Associated Check History.										
--	--	--	--	--	--	--	--	--	--	--

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System Vehicle Build

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN	1G1AK55F067
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AK69 -2006 COBALT 4-DOOR LS SEDAN		
Gross Vehicle Weight Rating :	1701 kg (3751 lb)	Order Number :	KBPV5S
Build Date :	05/08/2006	Build Plant :	167A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AR9 - DELUXE FRONT BUCKET SEAT
BZ9 - GM PRODUCTION WEEK #18	CIU - FLT-ENTERPRISE RENT A CAR
C67 - ELECT. FRONT AIR CONDITIONER	DC8 - MIRROR, O/S MANUAL FLDG, BLK
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FE9 - FEDERAL EMISSIONS
FLT - FLEET PROCESSING OPTION	FY1 - TRANS/AXLE 3.63 RATIO
IPB - INTERIOR TRIM DESIGN	J41 - POWER DISC FRONT BRAKES
K64 - 115 AMP GENERATOR	LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO
L61 - 2.2L DOHC 4 CYL ENGINE	MN5 - 4 SPEED AUTO TRANSMISSION
MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE	NT7 - FEDERAL EMISSION TIER 2
N46 - 4 SPOKE STEERING WHEEL	PG1 - 15" STEEL WHEEL
QTU - P195/60R15 TOURING BW TIRES	R6F - IDENTIFY B-CODE USERS
R6P - PREMIUM PAINT	R8K - *****
UN0 - AM/FM STEREO W/CD & RDS	UQ4 - BASE SPEAKER SYSTEM
VQ2 - FLEET ORDERING AND ASSISTANCE	VX7 - LONG TERM DAILY RENTAL PROGRAM
V2G - FULL FUEL FILL CREDIT	V73 - STATEMENT OF VEHICLE CERT.- U.S./CANADA
1LS - 1LS BASE PACKAGE	1SZ - OPTION PACKAGE DISCOUNT
14B - GRAY	14I - GRAY
46U - BLUE GRANITE METALLIC	6AR - FRONT SPRING

<http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=1G1AK55F...> 3/6/2009

7AR - FRONT SPRING	8AA - REAR SPRING
9AA - REAR SPRING	

© 1998-2005 General Motors Corporation. All Rights Reserved.

Local Codes

SP1E40000346

New York State Department of Motor Vehicles

POLICE ACCIDENT REPORT

MV-104A (6/04)

DMV COPY

Download Page 1 of 2

32 934 303-375 163

☐ AMENDED REPORT

1		Accident Date Month 02 Day 28 Year 2009		Day of Week Sat		Military Time 22:15		No. of Vehicles 1		No. Injured 1		No. Killed 0		Not Investigated at Scene ☐		Left Scene ☐		Police Photos ☐ Yes ☒ No			
2		VEHICLE 1 License ID Number [REDACTED] Driver Name - exactly as printed on license [REDACTED] Address (Include Number & Street) [REDACTED] City or Town FARMINGTON State NY Zip Code [REDACTED] Date of Birth [REDACTED] Sex F Unlicensed ☐ No. of Occupants 1 Public Property Damaged ☐ Name - exactly as printed on registration [REDACTED] Address (Include Number & Street) [REDACTED] City or Town FARMINGTON State NY Zip Code [REDACTED] Plate Number [REDACTED] State of Reg. NY Vehicle Year & Make 2006 CHEV Vehicle Type 4DSD Ins. Code 011 Ticket/Arrest Number(s) [REDACTED] Violation Section(s) [REDACTED]										VEHICLE 2 License ID Number [REDACTED] Driver Name - exactly as printed on license [REDACTED] Address (Include Number & Street) [REDACTED] City or Town [REDACTED] State [REDACTED] Zip Code [REDACTED] Date of Birth [REDACTED] Sex [REDACTED] Unlicensed ☐ No. of Occupants [REDACTED] Public Property Damaged ☐ Name - exactly as printed on registration [REDACTED] Address (Include Number & Street) [REDACTED] City or Town [REDACTED] State [REDACTED] Zip Code [REDACTED] Plate Number [REDACTED] State of Reg. [REDACTED] Vehicle Year & Make [REDACTED] Vehicle Type [REDACTED] Ins. Code [REDACTED] Ticket/Arrest Number(s) [REDACTED] Violation Section(s) [REDACTED]									
3		VEHICLE 1 DAMAGE CODES Box 1 - Point of Impact 1 2 Box 2 - Most Damage 3 4 5 Enter up to three more Damage Codes 3 1 5 Vehicle By FARMINGTON SVC Towed To FARMINGTON SVC VEHICLE DAMAGE CODING: 1-13. SEE DIAGRAM ON RIGHT. 14. UNDERCARRIAGE 17. DEMOLISHED 15. TRAILER 18. NO DAMAGE 16. OVERTURNED 19. OTHER										VEHICLE 2 DAMAGE CODES Box 1 - Point of Impact 1 2 Box 2 - Most Damage 3 4 5 Enter up to three more Damage Codes 3 4 5 Vehicle By [REDACTED] Towed To [REDACTED] VEHICLE DAMAGE CODING: 1-13. SEE DIAGRAM ON RIGHT. 14. UNDERCARRIAGE 17. DEMOLISHED 15. TRAILER 18. NO DAMAGE 16. OVERTURNED 19. OTHER									
4		Check if involved vehicle is: ☐ more than 95 inches wide; ☐ more than 34 feet long; ☐ operated with an overweight permit; ☐ operated with an overdimension permit.										Check if involved vehicle is: ☐ more than 95 inches wide; ☐ more than 34 feet long; ☐ operated with an overweight permit; ☐ operated with an overdimension permit.									
5		Circle the diagram below that describes the accident, or draw your own diagram in space #9. Number the vehicles.										Circle the diagram below that describes the accident, or draw your own diagram in space #9. Number the vehicles.									
6		VEHICLE 1 DAMAGE CODES Box 1 - Point of Impact 1 2 Box 2 - Most Damage 3 4 5 Enter up to three more Damage Codes 3 1 5 Vehicle By FARMINGTON SVC Towed To FARMINGTON SVC VEHICLE DAMAGE CODING: 1-13. SEE DIAGRAM ON RIGHT. 14. UNDERCARRIAGE 17. DEMOLISHED 15. TRAILER 18. NO DAMAGE 16. OVERTURNED 19. OTHER										VEHICLE 2 DAMAGE CODES Box 1 - Point of Impact 1 2 Box 2 - Most Damage 3 4 5 Enter up to three more Damage Codes 3 4 5 Vehicle By [REDACTED] Towed To [REDACTED] VEHICLE DAMAGE CODING: 1-13. SEE DIAGRAM ON RIGHT. 14. UNDERCARRIAGE 17. DEMOLISHED 15. TRAILER 18. NO DAMAGE 16. OVERTURNED 19. OTHER									
7		Reference Marker										Coordinates (if available)									
8		9 6										Latitude/Northing: 313061									
9		4 4 0 4										Longitude/Easting: 4759717									
10		1 1 7 6										4759717									
11		Accident Description/Officer's Notes										Place Where Accident Occurred:									
12		V-1 TRAVELING EAST SR-96. V-1 OPERATOR STATES SHE HAS AN UNKNOWN MECHANICAL PROBLEM AND IS UNABLE TO CONTROL VEHICLE. V-1 OPERATOR LOSES CONTROL AND V-1 TRAVELS ACROSS WESTBOUND LANE STRIKING THE EARTH ENBANKMENT/DITCH ON NORTH SHOULDER OF ROADWAY.										County ONTARIO ☐ City ☐ Village ☒ Town of FARMINGTON, TOWN OF									
13												Road on which accident occurred STATE ROUTE 96									
14												at 1) intersecting street (Route Number or Street Name)									
15												or 2) .2 ☐ N ☐ S ☐ E ☐ W of PAYNE RD (Route Number or Street Name)									
16												Feet Miles (Milepost, Nearest intersecting Route Number or Street Name)									
17												Cost of repairs to any one vehicle will be more than \$1000. ☐ Unknown/Unable to Determine ☒ Yes ☐ No									
18												See the second page for the accident diagram									
19												Cost of repairs to any one vehicle will be more than \$1000. ☐ Unknown/Unable to Determine ☒ Yes ☐ No									
20												See the second page for the accident diagram									
21												Cost of repairs to any one vehicle will be more than \$1000. ☐ Unknown/Unable to Determine ☒ Yes ☐ No									
22												See the second page for the accident diagram									
23												Cost of repairs to any one vehicle will be more than \$1000. ☐ Unknown/Unable to Determine ☒ Yes ☐ No									
24												See the second page for the accident diagram									
25												Cost of repairs to any one vehicle will be more than \$1000. ☐ Unknown/Unable to Determine ☒ Yes ☐ No									
26												See the second page for the accident diagram									
27												Cost of repairs to any one vehicle will be more than \$1000. ☐ Unknown/Unable to Determine ☒ Yes ☐ No									
28												See the second page for the accident diagram									
29												Cost of repairs to any one vehicle will be more than \$1000. ☐ Unknown/Unable to Determine ☒ Yes ☐ No									
30												See the second page for the accident diagram									


ALL INVOLVED		8		9		10		11		12		13		14		15		16		17		18		BY		TO		Names of all involved		Date of Death Only	
A		01		1		4		1		F		8		12		6		9995													
B																															
C																															
D																															
E																															
F																															
Officer's Rank and Signature		TROO		Michael P Dundon		Badge/ID No.		4618		NCIC No.		13401		Precinct/Post		E1		Station/Beat/Sector		41		Reviewing Officer		Bonanni, W J		Date/Time Reviewed		03/03/200 12:15			

This is to certify that this document is a true and complete copy of a record on file in the New York State Department of Motor Vehicles, Albany, New York.

COMMISSIONER OF MOTOR VEHICLES

TA000100532

NOT TO SCALE



This is to certify that this document is a true and complete copy of a record on file in the New York State Department of Motor Vehicles Albany, New York.

David J. Hunt
COMMISSIONER OF MOTOR VEHICLES

PEDESTRIAN/BICYCLIST/OTHER PEDESTRIAN LOCATION
1. Pedestrian/Bicyclist/Other Pedestrian at Intersection
2. Pedestrian/Bicyclist/Other Pedestrian Not at Intersection
PEDESTRIAN/BICYCLIST/OTHER PEDESTRIAN ACTION
1. Crossing, With Signal
2. Crossing, Against Signal
3. Crossing, No Signal, Marked Crosswalk
4. Crossing, No Signal or Crosswalk
5. Riding/Walking/Skating Along Highway With Traffic
6. Riding/Walking/Skating Along Highway Against Traffic
7. Emerging from in Front of/Behind Parked Vehicle
8. Going to/From Stopped School Bus
9. Getting On/Off Vehicle Other Than School Bus
10. Working in Roadway
11. Playing in Roadway
12. Other Actions in Roadway*
13. Not in Roadway (Indicate)*
TRAFFIC CONTROL
1. None
2. Traffic Signal
3. Stop Sign
4. Flashing Light
5. Yield Sign
6. Officer/Guard
7. No Passing Zone
8. RR Crossing Sign
9. RR Crossing Flashing Light
10. RR Crossing Gates
11. Stopped School Bus-Red Lights Flashing
12. Construction Work Area
13. Maintenance Work Area
14. Utility Work Area
15. Police/Fire Emergency
16. School Zone
20. Other*
LIGHT CONDITIONS
1. Daylight
2. Dawn
3. Dusk
4. Dark-Road Lighted
5. Dark-Road Unlighted
ROADWAY CHARACTER
1. Straight and Level
2. Straight and Grade
3. Straight at Hillcrest
4. Curve and Level
5. Curve and Grade
6. Curve at Hillcrest
ROADWAY SURFACE CONDITION
1. Dry
2. Wet
3. Muddy
4. Snow/Ice
5. Slush
6. Flooded
0. Other*
WEATHER
1. Clear
2. Cloudy
3. Rain
4. Snow
5. Sleet/Hail/Freezing Rain
6. Fog/Smog/Smoke
0. Other*
WHICH VEHICLE OCCUPIED
1. Vehicle No. 1 A. All-Terrain Vehicle (ATV) O. Other*
2. Vehicle No. 2 B. Bicyclist P. Pedestrian
I. In-Line Skater S. Snowmobiler
POSITION IN/ON VEHICLE
1. Driver 2-7. Passengers
8. Riding/Hanging on Outside
SAFETY EQUIPMENT USED
1. None
2. Lap Belt
3. Harness
4. Lap Belt/Harness
5. Child Restraint Only
6. Helmet (Motorcycle Only)
7. Air Bag Deployed
8. Air Bag Deployed/Lap Belt
9. Air Bag Deployed/Harness
A. Air Bag Deployed/Lap Belt/Harness
B. Air Bag Deployed/Child Restraint
In-Line Skater/Bicyclist
C. Helmet Only
D. Helmet/Other
E. Pads Only
F. Stoppers Only
0. Other*
EJECTION FROM VEHICLE
1. Not Ejected
2. Partially Ejected
3. Ejected
AGE SEX M/F
INJURED TAKEN
17 BY TO 18
APPARENT CONTRIBUTING FACTORS
Human
1. Alcohol Involvement
2. Backing Unsafely
3. Driver Inattention/Distracted*
4. Driver Inexperience*
5. Drugs (Illegal)
6. Failure to Yield Right-of-Way
7. Failure to Keep Right
8. Fatigued/Drowsy
9. Fell Asleep
10. Following Too Closely
11. Illness
12. Lost Consciousness
13. Passenger Distraction
14. Passing or Lane Usage Improper
15. Pedestrian/Bicyclist/Other Pedestrian Error/Confusion
16. Physical Disability
17. Prescription Medication
18. Traffic Control Disregarded
19. Turning Improperly
20. Unsafe Speed
21. Unsafe Lane Changing
22. Cell Phone (hand-held)
23. Cell Phone (hands-free)
24. Other Electronic Device*
25. Outside Car Distraction*
26. Reaction to Other Uninvolved Vehicle
27. Aggressive Driving/Road Rage
Vehicular
41. Accelerator Defective
42. Brakes Defective
43. Headlights Defective
44. Other Lighting Defects
45. Oversized Vehicle
46. Steering Failure
47. Tire Failure/Inadequate
48. Tow Hitch Defective
49. Windshield Inadequate
50. Driverless/Runaway Vehicle
60. Other Vehicular*
Environmental
61. Animal's Action
62. Glare
63. Lane Marking Improper/Inadequate
64. Obstruction/Debris
65. Pavement Defective
66. Pavement Slippery
67. Shoulders Defective/Improper
68. Traffic Control Device Improper/Non-Working
69. View Obstructed/Limited
DIRECTION OF VEHICLE:
PRE-ACCIDENT VEHICLE ACTION
1. Going Straight Ahead
2. Making Right Turn
16. Making Right Turn on Red
3. Making Left Turn
17. Making Left Turn on Red
4. Making U Turn
5. Starting from Parking
6. Starting in Traffic
7. Slowing or Stopping
8. Stopped in Traffic
9. Entering Parked Position
10. Parked
11. Avoiding Object in Roadway
12. Changing Lanes
13. Passing
14. Merging
15. Backing
18. Police Pursuit
20. Other*
LOCATION OF FIRST EVENT
1. On Roadway 2. Off Roadway
TYPE OF ACCIDENT - COLLISION WITH
1. Other Motor Vehicle 6. In-Line Skater
2. Pedestrian 7. Deer
3. Bicyclist 8. Other Pedestrian
4. Animal 10. Other Object (Not Fixed)*
5. Railroad Train
COLLISION WITH FIXED OBJECT
11. Light Support/Utility Pole
12. Guide Rail-Not At End
25. Guide Rail-End
13. Crash Cushion
14. Sign Post
15. Tree
16. Building/Wall
17. Curbing
18. Fence
19. Bridge Structure
20. Culvert/Head Wall
21. Median-Not At End
26. Median-End
27. Barrier
22. Snow Embankment
23. Earth Embankment/Rock Cut/Ditch
24. Fire Hydrant
30. Other Fixed Object*
NO COLLISION
31. Overturned
32. Fire/Explosion
33. Submersion
34. Ran Off Roadway Only
40. Other*
COVER SHEET N