


EWR D&I ANNOTATION



FAN-000001L092001DP87

Artemis # : 000001L092001DP87

Record Created Date :

Printed Date : 06/14/2010

Description :

DI09-096. SEQ ID 87. 2009 Q2. DRIVER OF A 2006 CHEVY COBALT REAR ENDED ANOTHER VEHICLE THAT WAS STOPPED. FRONT END DAMAGED. DRIVER ALLEGES AIR BAGS SHOULD HAVE DEPLOYED. DRIVING SPEED NOT GIVEN. NO POLICE REPORT FILED. SEARCHED 2005-2006. VOQ-27. PURSUIT-1. TSB-0. RECALLS-0. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

December 16, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-096

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 2nd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 3, 7, 15, 39, 63, 78, 81, 82, 85, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 98, 100, 101, 103, 105, 106, 107, 108, 109, 110, 131, 137, 145, 146, 148, 149, 158, 167, 168, 178, 209, 216, 219, 231, 243, 253, 254, 255, 256, 257, 258, 259, 261, 263, 264, 266, 270, 271, 276, 281, 282, 288, 289, 290, 291, 292, 293, 297, 299, 300, 311, 312, 327, 338, 339, 341, 343, 344, 345, 346, 348, 349, 351, 352, 354, 370, 382, 390, 391	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new

requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

12660

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **January 22, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,



Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement

11 February 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-096

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated December 16th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 2nd quarter of 2009.

GM's response is comprised of 88 disks for the incidents that are the subject of DI09-096.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 3 18605620-675350 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 3 18605620-675350_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI09-096
3 18605620-675350
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 3 18605620-675350 **_01_001** - is the first document responsive to Inquiry no. 1.
- 3 18605620-675350 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

<i>(88 Vehicles from the Light Vehicle Template)</i>		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
3	5GAER23D69J [REDACTED]	NISM
7	UNKNOWN	NISM
15	5GADS13S142 [REDACTED]	NISM
39	1G6DU57V090 [REDACTED]	LIT
63	UNKNOWN	NISM
78	1G1AL52F957 [REDACTED]	NISM
81	1G1AK52F257 [REDACTED]	NISM
82	1G1AK55F167 [REDACTED]	NISM
85	1G1AK15F467 [REDACTED]	NISM
87	1G1AK55F267 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
88	1G1AM15B367	NISM
89	1G1AL15FX67	NISM
90	1G1AK15F367	NISM
91	1G1AL58F977	NISM
92	1G1AK15F077	NISM
93	1G1AK55F577	NISM
94	1G1AK15F477	NISM
95	1G1AK55F577	LIT
96	1G1AK15F077	NISM
98	1G1AK58FX77	NISM
100	1G1AK55FX77	NISM
101	1G1AK15F477	NISM
103	1G1AK18F887	NISM
105	1G1AL58F287	NISM
106	1G1AK18F187	NISM
107	1G1AL58F987	NISM
108	1G1AK58F987	NISM
109	1G1AL58F987	NISM
110	1G1AT58H097	NISM
131	3GNDA23P76S	NISM
137	3GNDA13D48S	NISM
145	2G1WF52E049	NISM
146	2G1WF52E249	NISM
148	2G1WH52K049	NISM
149	2G1WH52K049	NISM
158	2G1WT58N279	NISM
167	2G1WT57K791	NISM
168	2G1WC57M591	NISM
178	1G1ZG57B39F	NISM
209	1GCEK24009Z	NISM
216	1GCHK29K57E	NISM
219	1GBJC34K78E	NISM
231	1GNFC16047J	NISM
243	1GNFK33059R	NISM
253	1GNDS13S642	NISM
254	1GNDT13S052	NISM
255	1GNDT13S052	NISM
256	1GNDS13SX52	NISM
257	1GNDT13S852	NISM
258	1GNDT13S052	NISM
259	1GNDT13S352	NISM
251	1GNDT13S662	NISM
263	1GNDT13S682	NISM
264	1GNDT13S882	NISM
266	1GNDS33S892	NISM
270	1GNES16S866	NISM
271	1GNEV23D29S	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
276	1GNDU03E64D [REDACTED]	NISM
281	1GKEV23D59J [REDACTED]	NISM
282	1GKEV23D99J [REDACTED]	NISM
288	UNKNOWN	NISM
289	1GKDS13S442 [REDACTED]	NISM
290	1GKDT13S442 [REDACTED]	NISM
291	1GKDT13S552 [REDACTED]	NISM
292	1GKDS13S962 [REDACTED]	NISM
293	1GKDS13S462 [REDACTED]	NISM
297	1GKET16S956 [REDACTED]	NISM
299	1GKES12S046 [REDACTED]	NISM
300	1GKES12S956 [REDACTED]	NISM
311	3GTEC13C48G [REDACTED]	NISM
312	3GTEK13378G [REDACTED]	NISM
327	5GTDN136568 [REDACTED]	NISM
338	1G2ZF55B264 [REDACTED]	NISM
339	1G2ZF55B064 [REDACTED]	NISM
341	1G2ZG558364 [REDACTED]	NISM
343	1G2ZH18N374 [REDACTED]	NISM
344	1G2ZG58B574 [REDACTED]	NISM
345	1G2ZH57N584 [REDACTED]	NISM
346	1G2ZG57B384 [REDACTED]	NISM
348	1G2ZH57N684 [REDACTED]	NISM
349	1G2ZF57B584 [REDACTED]	NISM
351	1G2ZJ57B494 [REDACTED]	NISM
352	1G2ZH36N994 [REDACTED]	NISM
354	6G2EC57Y19L [REDACTED]	NISM
370	2G2WP552881 [REDACTED]	NISM
382	5S3ET13S662 [REDACTED]	NISM
390	5GZER13737J [REDACTED]	NISM
391	5GZEV23748J [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing

responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read 'Gay P. Kent', with a stylized flourish at the end.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 88 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a 'CIVIL CASE COVER SHEET' form for the case 'CARDONA V. CHEVROLET'. The form includes sections for case information, case type, and case details. Annotations on the right side of the form indicate the following steps:

- Step 7: Next File (Image)**: Points to the 'Next Image' button in the 'Next Page' section.
- Step 7: Next page**: Points to the 'Next page' button in the 'Next Page' section.
- Step 8: Scale Image**: Points to the 'Scale' section, which includes buttons for 'Fit Scale to fit', '1:2 Scale 50%', '1:1 Scale 100%', and '2:1 Scale 200%'.
- Step 7: Image Properties**: Points to the 'Image Properties' button in the 'Image Properties' section.

The form also includes a 'NOTICE' section at the bottom, which states that the cover sheet must be filed with the first paper filed in the action or proceeding, and that it must be filed in addition to any cover sheet required by local court rules.

DI09-096
87 5428726 – 675067
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Injury
Address	City Canterbury	Involved Dir	Banks Chevrolet-Cadillac, Inc.	Safety	Yes
State NH ZipCd	Con Acct	Source	Phone	Updated	7/6/2009 02:35:17 PM
Serial #/VIN 1G1AK55F267	Model Year 2006	Priority	Medium License # CHEVROL	Owner	MARQUEMO
Make Chevrolet	Warr. Start 05/17/2006	Status	Closed	Opened	6/15/2009 12:30:48 PM
Model Cobalt	Mileage 52820	Sub-Status	Dissatisfied	Closed	7/5/2009 02:35:16 PM
Abstract Collision - Injuries - Restraints - (SIR) - Driver Front					
Customer Description	***This is a BRC PAR Case. Please do not assume. Forward any inquiries to Monica Marquez at ext121072 ***				

Pre-PAR

PAR Number	Incident Date/Time	Injuries	# Other Veh	# People In Veh	Road Surface	Road Cond	Fire Report	Police Report
Relative	6/11/2009 03:00:00 PM	Y	1	5	Asphalt	Dry	N/A	Unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5'5"		No				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
N/A	N/A		No Insurance Involved					
Incident Loc	Route 3 Boscawin, NH	Incident Desc	Cust sts: She was driving when a vehicle in front of her had No brake lights was working and when cust noticed that the vehicle wasn't moving she ended up hitting the vehicle in front of her. Cust sts no airbags deployed causing injuries.					
Component	Restraints - (SIR) - Driver Front	Damage Desc	Whole front end is damaged					
Vehicle Loc	Canterbury, NH	Add'l Info	Customer states: Not the first time air bags does not deploy. Customer did not have with him the police and medical reports to provide their numbers.					
Emgcy Svc Names	Boscawin Police department	Main Loc	N/A					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	none	Property Type	Silver Vehicle
Vehicle Speed	45		Weather Condition	Dry			Prop Owner	Unknown	Prop Est Repair Cost	
Last Service Date			Loc Last Service				Property Location	Unknown		
Veh Est Repair Cost			Spec Equip Installer	none			Prop Damage Description	Back end damages		
Primary Veh Use	Personal		Inspection Type				Inspected By	Inspection Not Performed	Inspection Date/Time	
Veh Damage Description	Whole front end is damaged						Explain Other	Inspection Not Performed		

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Front Passenger	Seat Belt
Injury Description			Medical Rpt#	Treatment Location	Treated By	
Knees and both arms bruised pretty bad, no lacerations - trouble walking				Concord Hospital in Concord NH	ER	
Street Address			City	State	Zip Code	
			Canterbury	NH		
Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	Seat Belt
Injury Description			Medical Rpt#	Treatment Location	Treated By	
Belly hit by the steering wheel. She is pregnant. Muscles are sore - baby is okay				Concord Hospital in Concord NH	ER	
Street Address			City	State	Zip Code	
			Canterbury	NH		
Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Middle Rear Passenger	unknown
Injury Description			Medical Rpt#	Treatment Location	Treated By	
Abrasion in head				Concord Hospital in Concord NH	ER	
Street Address			City	State	Zip Code	

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/6/2009 02:35:16 PM	MARQUEM	MARQUEMO	SR Closed - Dissatisfied		Done	7/6/2009 02:35:16 PM	Service Request has been Closed Dissatisfied.
Contact Last Name	Contact First Name	Account	RAC Code				
Comments							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/6/2009 02:32:10 PM	MARQUEM	MARQUEMO	Inbound Call Customer	Complex Request	Done	7/6/2009 02:35:09 PM	cust called in

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Cust called in asking why no one has contacted customer back.

CRS adv. Provided ESIS info claim - Rep 500 number - 1-800-888-0164 advised to give ESIS info to operator and they will transfer cust to agent that is working the file. Transferred call.

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/6/2009 02:30:37 PM	TOLENTEL	MARQUEMO	SR Opened		Done	7/6/2009 02:30:37 PM	SR in Status of Closed has been Re-Opened by TOLENTEL

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/29/2009 02:21:30 PM	MARQUEM	MARQUEMO	SR Closed - Dissatisfied		Done	6/29/2009 02:21:31 PM	Service Request has been Closed Dissatisfied.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/29/2009 02:14:32 PM	MARQUEM	MARQUEMO	Inbound Call Third Party	Complex Request	Done	6/29/2009 02:21:27 PM	aunt called

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Tip sts: wanting to know when someone will contact customer - has concerns on airbags - tp sts her and her kid was injuries and doesn't have medical coverage

CRS adv: file was sent to ESIS on the 16th and they should be incontact with customer in 7-10 business days. advised customer would get a call by the 2nd

Tip sts: doesn't understand why its taking that long - sts the airbags should have deployed - sts will get an lawyer and disconnected the call.

Monica Marquez/BRCPAR/ATX

x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/29/2009 02:14:17 PM	MARQUEM	MARQUEMO	SR Opened		Done	6/29/2009 02:14:17 PM	SR in Status of Closed has been Re-Opened by MARQUEMO

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2009 06:46:57 PM	MARQUEM	MARQUEMO	SR Closed - Dissatisfied		Done	6/23/2009 06:46:57 PM	Service Request has been Closed Dissatisfied.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2009 06:46:34 PM	MARQUEM	MARQUEMO	BRC PAR	Close-No Offer to Repair/Rep	Done	6/23/2009 06:46:54 PM	Closing PAR File

Contact Last Name	Contact First Name	Account	BAC Code

Comments
File being forwarded to ESIS due to injuries and there was medical attention sought. CRS advised that file will be forwarded to ESIS and will be in contact within 7-10 business days by mail or phone. Closing PAR file since ESIS has picked up file.

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/22/2009 12:43:41 PM	MARQUEM	MARQUEMO	Outbound Call Third Party	Left Message	Done	6/22/2009 12:47:07 PM	Called: [REDACTED]

Contact Last Name	Contact First Name	Account	BAC Code

Comments
Spoke with - Taylor Dish - Banks Collision Center

CRS adv: Returning the call back on claim for [REDACTED] advised unknown what tp is seeking - advised to call CRS back - provided number and extension.

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/22/2009 12:42:38 PM	MARQUEM	MARQUEMO	Inbound Call Third Party	Voice Mail Received	Done	6/22/2009 12:43:40 PM	Unknown party - Taylor called in

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Tip sts: tp asked to be called back at [redacted] on claim for [redacted]

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 03:17:48 PM	MARQUEM	MARQUEMO	Scheduled Follow-up		Done	6/23/2009 06:46:32 PM	ESIS

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 03:16:43 PM	MARQUEM	MARQUEMO	BRC PAR	ESIS- Injuries	Done	6/18/2009 03:17:42 PM	ESIS - Injuries

Contact Last Name	Contact First Name	Account	BAC Code

Comments

File being forwarded to ESIS due to injuries and there was medical attention sought.

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 03:15:48 PM	MARQUEM	TOPOROW	Escalation	ESIS - Injuries	Done	6/19/2009 11:02:08 AM	Assign to ESIS

Contact Last Name	Contact First Name	Account	BAC Code

Comments
Injuries

Monica Marquez/BRCPAR/ATX
x21072

674790 - Rep 500

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 02:37:23 PM	MARQUEM	MARQUEMO	Outbound Call Customer		Done	6/18/2009 02:38:25 PM	Called

Contact Last Name	Contact First Name	Account	BAC Code

Comments
CRS adv: asked for [REDACTED] and was advised he is not home
asked who owns vehicle and was advised [REDACTED] and to contact her on Cell phone [REDACTED]

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 11:59:11 AM	MARQUEM	MARQUEMO	Ownership Changed	Ownership Escalated to BRC	Done	6/18/2009 11:59:11 AM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:49:04 AM	KINZERTH	MARQUEMO	Ownership Changed		Done	6/18/2009 08:49:04 AM	Service Request Ownership has changed FROM: GARCIAFE TO: MARQUEMO
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:48:45 AM	KINZERTH	MARQUEMO	BRC PAR	Initial Contact- AVM	Done	6/18/2009 03:15:18 PM	Called FDVM Lampman Thomas 814055 8440 BANKS CHEVROLET-CADILLAC, INC. CONCORD NH
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
This is Monica Marquez calling from gm par dept. Customer: [REDACTED] Service Request: 71-733311242 Vehicle Information: 08 Chevrolet Cobalt Last 8 of the VIN: 67 [REDACTED] Involved Dealership: BANKS CHEVROLET-CADILLAC Nature of allegation: cust sts they were involved in a collision where airbags didn't deploy - since there was medical attention sought and driver is pregnant - file will be forwarded to ESIS. CRS adv if you have any additional information pertaining to customer or vehicle please contact me at 1-866-790-5700 ext 21072. If not then this is an FYI to let you know what is going on in your district. Monica Marquez/BRC PAR/ATX X21072							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:48:36 AM	KINZERTH	MARQUEMO	BRC PAR	Initial Contact- Dealer	Done	6/18/2009 03:13:39 PM	Called

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Left message with Service Manager -

CRS adv: Calling on regards to an claim that was called in by an cust by the names of [REDACTED] They have an 06 Chevrolet Cobalt. Calling to make dir aware of allegation and checking to see what dir knows of allegation -they were involved in a collision where they state no airbags deployed - last 8 of VIN - 07 [REDACTED] provided number and extension to call CRS back.

Monica Marquez/BRCPAR/ATX
X21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:48:26 AM	KINZERTH	MARQUEMO	BRC PAR	Initial Contact- Phone	Done	6/18/2009 03:10:12 PM	Called

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Cust sts: She was driving when a vehicle in front of her had No brake lights was working and when cust noticed that the vehicle wasn't moving she ended up hitting the vehicle in front of her. Cust sts no airbags deployed causing injuries. Driver is pregnant and went to the hospital and so did the passenger and customer's nephew. Cust sts she is okay and baby is okay. Cust sts she doesn't know if she is being held responsible for the damages yet - cust sts the police dept did arrive and cust doesn't have a report yet. There was no insurance involved and vehicle is located at [REDACTED] Canterbury, NH [REDACTED] Cust sts the whole front end is damaged. Cust sts she has the medical reports from the hospital.

Cust sts: Investigation on airbags

CRS adv: File will be forwarded to ESIS due to injuries and there was medical attention seeked, and that dept will be incontact with cust in 7-10 business days.

Monica Marquez/BRCPAR/ATX
X21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:48:18 AM	KINZERTH	MARQUEMO	BRC PAR	Acknowledgement	Done	6/18/2009 03:09:32 PM	Called owner

Contact Last Name	Contact First Name	Account	BAC Code

Comments

See Initial Contact

Monica Marquez/BRC PAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:48:08 AM	KINZERTH	MARQUEMO	Nolity CRM		Done	6/18/2009 02:39:25 PM	File Assigned

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:48:00 AM	KINZERTH	MARQUEMO	Research		Done	6/18/2009 02:39:22 PM	Research VIN

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS Performed VIN Scan:

GMVIS: Found No Open Recalls

VIN: Found No Duplicate File

SVC History: No Service History Related to Allegation

Monica Marquez/BRC PAR/ATX
X21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:47:41 AM	KINZERTH	MARQUEMO	BRC PAR	Case Assigned	Done	6/18/2009 12:01:52 PM	Assigned to Monica Marquez x21072

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:47:34 AM	KINZERTH	GARCIAFE	SR Opened		Done	6/18/2009 08:47:34 AM	SR in Status of Closed has been Re-Opened by KINZERTH

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/18/2009 08:47:32 AM	KINZERTH	GARCIAFE	SR Closed - Satisfied		Done	6/18/2009 08:47:32 AM	Service Request has been Closed Satisfied.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/15/2009 12:58:21 PM	GARCIAFE	KINZERTH	Escalation	Initiate PAR	Done	6/18/2009 08:47:28 AM	Assigning activity to PAR QUEUE

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS advised that a person from the PAR Department will contact the customer within 5* business days.

Bruce Johnson / CAC / BA T1 Lvo

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/15/2009 12:33:17 PM	GARCIAFE	GARCIAFE	Inbound Call Customer	Complex Request	Done	6/15/2009 12:57:50 PM	Alleged product allegation - Air Bags did not deploy.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Cust states: Her girlfriend was driving the vehicle. She looked away from the road to get her cell phone. The vehicle in front of them stop abruptly and she could not brake in time. There were 5 people in the vehicle.

Cust seeks: Some sort of assistance.

CRS advised customer his information will be forward to the Product allegation Department.

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C47	SIR - Did Not Deploy	Restraints - (SIR) - Driver Side - Side Impact
C48	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Front
C49	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Side -Side Impact

Service Request Detail

SR No. SP-10459802
 Account Banks Chevrolet-Cadillac, Inc.
 Last Name [REDACTED]
 Daytime # [REDACTED]
 Address [REDACTED]
 State ZipCd
 Serial #VIN 1G1AK55F267
 Make Chevrolet
 Model Cobalt
 Abstract DD-1,TH-1,F7D-1,FCD-1,FCTR-
 Customer when using the turn signal
 Description

Ref No.
 Site 114996
 First Name [REDACTED]
 Evening # [REDACTED]
 City
 Con Acct
 Model Year 2006
 Warr. Start 05/17/2006
 Mileage 38167

Goodwill
 GW SubType
 Approval
 UCC
 Involved Dir
 Source Phone
 Priority 1 - SELF
 Status Closed
 Sub-Status Inactive
 License # CHEVROL

BRC Type N/A
 Bus. Unit TAC US
 Area Body and Accessories
 Sub-Area Lighting Systems
 Safety N
 Updated 1/28/2010 11:37:08 AM
 Owner LESZCZLE
 Opened 8/26/2008 04:12:22 PM
 Closed 8/26/2008 04:23:08 PM

Pre-PAR

PAR Notifier: [REDACTED] Incident Date/Time: [REDACTED] Injuries: [REDACTED] Other Vehicle # [REDACTED] People in Vehicle [REDACTED] Road Surface [REDACTED] Road Condition [REDACTED] Fire Report [REDACTED] Police Report [REDACTED]

Driver Last Name [REDACTED] Driver First Name [REDACTED] Height [REDACTED] DOB [REDACTED] Disabilities [REDACTED]

Insurance Agent Last Name [REDACTED] Insurance Agent First Name [REDACTED] Phone # [REDACTED] Insurance Agency [REDACTED]

Incident Loc
 Component
 Vehicle Loc
 Emgcy Svc Names
 Incident Desc
 Damage Desc
 Add'l Info
 Maint Loc

PAR Detail

Collision	Non Collision	Property Damage	Thermal Evt	Spec Equip	Property Type
Vehicle Speed	Weather Condition	Prop Owner		Property Location	Prop Est Repair Cost
Last Service Date	Loc Last Service	Spec Equip Installer		Prop Damage Description	
Veh Est Repair Cost	Inspection Type	Inspected By		Inspection Date/Time	
Primary Veh Use		Explain Other			
Veh Damage Description					

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/26/2008 04:22:19 PM	TZJMV2		Vehicle Data Conversion		Done	8/26/2008 04:22:19 PM	08/26/2008 16:22:19 SBD Template - LESZCYNski
Contact Last Name	Contact First Name	Account		BAC Code			Strategy based diagnostics (Vers

Comments

08/26/2008 16:22:19 SBD Template - LESZCYNski
Strategy based diagnostics (Version 8a)
1 Number of times in for the same condition
1 Number of days vehicle in dealership for same condition
n Y/N Is the vehicle modified/non-production accessories?
n Y/N Has the concern been duplicated?
y Y/N Relevant Diagnostics have been performed?
SI DOC used? 1583540
n Any TCC Keywords?

Callers name - S/M

Customer concern - headlamps go off when using the left turn signal

Dealer comments/diagnosis - (DTC'S, what's been done?)
Dealer cannot duplicate the concern Dealer is asking for previous case information

TAG Recommendations -
Advised dealer of previous case information on multifunction switch failures Advised dealer on bulletin 01-00-89-010 cannot duplicate form and have the service advisor along with the owner fill out the sections only that pertain to the concern

Confidential Comments

08/26/2008 16:22:19 History - LESZCYNski