


EWR D&I ANNOTATION



FAN-000001L102001DP119-9136

Artemis # : 000001L102001DP119**Record Created Date :****Printed Date :** 02/03/2011**Description :**

DI10-107. SEQ ID 119. 2010 Q2. THIS REPORT INCLUDES A LEGAL LETTER ABOUT A 2005 CHEVY COBALT. THE LEGAL LETTER IS A REQUEST FOR EVIDENCE FROM THE ACCIDENT AND INCLUDES THE VEHICLE'S MAINTENANCE HISTORY. THERE IS NO INFORMATION ABOUT THE INCIDENT OTHER THAN THE DRIVER WAS INJURED. *RM



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

December 16, 2010

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-107

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 2nd quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 20, 52, 53, 54, 73, 81, 107, 108, 119, 150, 231, 263, 283, 298, 299, 317, 318, 324, 331, 349, 350, 351, 355, 440, 474, 486, 508, 546, 550	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the

information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **January 14, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly legible.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

JAN 21 2011

January 20, 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-107

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated December 16, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 2nd quarter of 2010.

GM's response is comprised of 29 disks for the incidents that are the subject of DI10-107.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 20 307364907-693048 and 2007 BUICK LUCERNE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 20 307364907-693048_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-107
20 307364907-693048
2007 BUICK LUCERNE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those



showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

20 307364907-693048_01_001- is the first document responsive to Inquiry no.1.

20 307364907-693048_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-107, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(29 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
**20	1G4HP57297U [REDACTED]	NISM
52	1G6DM57T870 [REDACTED]	NISM
53	1G6DP577070 [REDACTED]	NISM
54	1G6DP577670 [REDACTED]	NISM
73	1GYUKBEF4AR [REDACTED]	NISM
81	3GYFNAEY5AS [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
107	2G1FJ1EJ0A9 [REDACTED]	NISM
108	2G1FT1EWXA9 [REDACTED]	NISM
119	1G1AK52F357 [REDACTED]	NISM
150	1G1AK55F667 [REDACTED]	NISM
231	1G1AK18F787 [REDACTED]	NISM
263	1G1AD5F54A7 [REDACTED]	NISM
283	2CNALPEW6A6 [REDACTED]	NISM
298	3GNBAADB5AS [REDACTED]	NISM
299	3GNBAADB5AS [REDACTED]	NISM
317	2G1WB58K089 [REDACTED]	NISM
318	2G1WT58N889 [REDACTED]	NISM
324	2G1WB5EK2A1 [REDACTED]	NISM
331	1G1ZT54835F [REDACTED]	NISM
349	1G1ZB5EB9AF2 [REDACTED]	NISM
350	1G1ZC5EB7AF [REDACTED]	NISM
351	1G1ZB5EB0A4 [REDACTED]	NISM
355	1G1ZE5E7XAF [REDACTED]	NISM
440	1GNDT13S962 [REDACTED]	NISM
474	1GKLVLED1AJ [REDACTED]	NISM
486	1GKDT13S352 [REDACTED]	NISM
508	2CTFLHEY1A6 [REDACTED]	NISM
546	1G2ZG57N084 [REDACTED]	NISM
550	1G2ZG57B394 [REDACTED]	NISM

** Sequence 20, is being submitted with missing police report photographs and a incorrect Crash Data Retrieval (CDR) file. Once the missing photographs and correct CDR file are recovered, they will be submitted with a new, updated file.

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney

work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,



FOR
M. CARMEN
BENAVIDES


M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 29 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run Jpegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an Image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

AT FURNISH ON PLAIN WHITE COPY-READY PAPER, with the caption and address: ERIC D. PARIS, Esq., 8/88 147836 LAW OFFICE OF ERIC D. PARIS & ASSOCIATES 281 S. THOMAS STREET SUITE 103 PORONA, CALIFORNIA 93766 Telephone (916) 908-689-5127 Fax (916) 908-689-5126		FILED ONLY (SEE 802.5)(U)	
ATTORNEY FOR PLAINTIFF SUPERIOR COURT FOR THE STATE OF CALIFORNIA INDIO COUNTY		CASE NAME: CARDONA V. CHRYSLER	
CIVIL CASE COVER SHEET ☐ Limited ☒ Unlimited		Complete Case Description ☐ Complete ☒ Partial Filed with first appearance by defendant (Cal. Prob. of Court, rule 1811)	
PREPARE DOCUMENTS BY DATE 1800 OF THE CALIFORNIA RULES REQUIRING DISCOVERY PROCEEDINGS			
1. Check one box below for the case type that best describes this case:			
☒ Auto (22) Other PERSONAL INJURY/PROPERTY DAMAGE/OTHER DAMAGE/Death (41) ☐ Automobile (84) ☐ Personal Injury (24) ☐ Medical Malpractice (40) ☐ Other PERSONAL INJURY (24) ☐ Non-PERSONAL INJURY (24) ☐ Business/Commercial/Real Estate (22) ☐ Contracts (e.g., distribution, lease and sale) (24) ☐ Defamation (e.g., libel, slander) (24) ☐ Fraud (14) ☐ Intellectual Property (14) ☐ Professional negligence (e.g., legal malpractice) (24) ☐ Other non-PERSONAL INJURY (24) ☐ Employment ☐ No explicit limitation (22)		☐ Other employment (14) ☐ Contract ☐ Breach of contract/negligence (24) ☐ Contract (e.g., money owed) (24) ☐ Other contract (24) ☐ Insurance coverage (14) ☐ Other tort (24) ☐ Real Property ☐ Eminent domain/condemnation (14) ☐ Wrongful death (24) ☐ Other real property (e.g., land) (24) ☐ Unrelated Defendant ☐ Contractual (24) ☐ Real Property (24) ☐ Drugs (24) ☐ Juvenile/Minor ☐ Public Interest (24) ☐ Plaintiff on withdrawal award (11)	
2. This case is ☒ is not ☐ sample under rule 1800 of the California Rules requiring discovery proceedings.			
a. ☒ Large number of potentially interested parties ☐ Large number of potentially interested parties b. ☒ Extensive issues involve raising difficult or novel legal issues that will be time consuming to resolve ☐ Substantial amount of documentary evidence c. ☒ Substantial amount of documentary evidence ☐ Substantial amount of documentary evidence			
3. Type of remedies sought (check all that apply): ☒ Damages ☐ Injunctive ☐ Declaratory ☐ Other			
4. Number of cases at this location: CIVIC			
5. This case is ☐ is not ☒ a case action suit.			
Date: JULY 3, 2003 ERIC D. PARIS, Esq., 8/88 147836 (PRINTED NAME AND ADDRESS)			
NOTICE			
* Plaintiff must file this cover sheet with the first paper filed in the matter or proceeding (as under the Probate, if any), or Welfare and Institutions Code (Cal. Prob. of Court, rule 1811) or this case shall be subject to any other Court rule required by local court rule. * If this case is exempt under rule 1800 or any of the California Rules of Court, you may file other papers to the extent of proceeding. * Unless this is a complete case, this cover sheet must be used for subsequent papers and			
CIVIL CASE COVER SHEET			

**Step 7: Next File
(Image)**

Step 7: Next Page

Step 8: Scale Image

Step 7: Image Properties

DI10-107
119 307364470 – 692124
2005 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

W. Randall Mainor
(1941-2007)



MAINOR EGLET COTTLE
TRIAL LAWYERS

Robert T. Eglet
Robert W. Cottle*
Tracy A. Eglet †
Robert M. Adams
Bradley S. Mainor
David A. Tanner ▲
Jonathan T. Remmel*
Lesley B. Miller
Bradley J. Myers †
Marni K. Rubin
Joseph J. Wirth
Brice J. Crafton

REC'D MAR 19 2010

February 22, 2010

General Motors Corporation
Attn: Risk Management
100 Renaissance Center
Detroit, MI 48243

*Also admitted in Utah
† Also admitted in Ohio
▲ Also admitted in Texas
● Also admitted in Arizona

RE: Claimant : [REDACTED]
Our Case No. : 232142
Date of Loss : September 24, 2009

To Whom It May Concern:

This office represents [REDACTED] in connection with injuries sustained as the result of an incident on September 24, 2009.

Please forward a copy of the security incident report, any photos or videotapes, witness statements, written statements, engineering or internal maintenance report and any other evidence in your possession regarding the above referenced incident. Destruction or disposal of these or any other items relating to this incident will be viewed as spoliation of evidence.

Please refer this letter to your liability insurance carrier with instructions to contact this office.

Sincerely,

Robert W. Cottle, Esq.
MAINOR EGLET COTTLE, LLP

RWC

RECEIVED

MAR 13 2010

ESII-GM CLAIMS UNIT

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMER

View Vehicle Delivery Information

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN: 1G1AK52F357
Service Contract: Yes Branded Title: Yes Model: 1AK69-2005 COBALT 4-DOOR LS SEDAN
Order Type: 70 - RETAIL - STOCK Warranty Block: Yes PDI Status: No
Field Actions: 1 Open

Invoice Information

Invoicing Service Agent: 132366
HENDERSON CHEVROLET CO.
240 N GIBSON RD
HENDERSON NV 89014-6700 7025582438

Invoice Date: 01/17/2005

Ship to Information

Invoicing Service Agent: 132366
HENDERSON CHEVROLET CO.
240 N GIBSON RD
HENDERSON NV 89014-6700 7025582438

Ship to Date: N/A

Delivery Information

Delivery Service Agent: 132366
HENDERSON CHEVROLET CO.
240 N GIBSON RD
HENDERSON NV 89014-6700 7025582438

Delivery Date: 03/09/2005
Delivery Type: 010—INDIVIDUAL
Delivery Odometer: 17

In Service Information

Invoicing Service Agent

In Service Date: N/A
In Service Type: 0000
In Service Odometer: 0


For this vehicle:

- View Vehicle Summary
 - Service Contract
 - Branded Title
 - Warranty Block
- View Vehicle Build
- View Vehicle Component Summary
- View Vehicle Transaction History Detail
- View Vehicle Delivery Information

Global Warranty Management: Site Map

Privacy Policy | Terms of Use

© 2005 General Motors. All rights reserved.



Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail



This screen allows GMVIS users to view the available information on individual transaction for the VIN selected

Vehicle Information

VIN: 1G1AK52F357 [REDACTED] Model: 1AK09-2005 COBALT 4-DOOR LS SEDAN
 Service Contract: Yes Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: 1 Open

For this vehicle:

- View Vehicle Summary
 - Service Contract
 - Branded Title
 - Warranty Block
- View Vehicle Build
- View Vehicle Component Summary
- View Vehicle
- Transaction History Detail
- View Vehicle Delivery Information

Job Card Date: 06/09/2005

Job Card Number: 074794

Repair Service Agent: 132366
 HENDERSON CHEVROLET CO.
 240 N GIBSON RD
 HENDERSON NV 89014-6700
 7025582438

Odometer Reading: 6,370 MI
 Authorization Code:

Process Date:
 06/17/2005

Transaction Type:
 ZFAT---Field Action Recall
 Transaction Expense Category:
 Customer Complaint Code:
 0000-Converted Claim

Job Card Line #: 1 Transaction Adjustment: Cause Code: 0000-Converted Claims
 Labour Op V1359-05046 - Rewire Airbag and Install Jumper Harness
 Causal Part Number
 -See other Parts and/or Not Items

Line Total: USD 37.75

Job Card Date: 01/17/2005

Job Card Number: A28717

Repair Service Agent: 132366
 HENDERSON CHEVROLET CO.
 240 N GIBSON RD
 HENDERSON NV 89014-6700
 7025582438

Odometer Reading: 0 MI
 Authorization Code:

Process Date:
 01/21/2005

Transaction Type:
 ZPDI---Pre-Delivery Inspection
 Transaction Expense Category:
 Customer Complaint Code:
 0000-Converted Claim

Job Card Line #: 1 Transaction Adjustment: Cause Code: 0000-Converted Claims
 Labour Op Z7000-Pre-Delivery Inspection - Base Time
 Causal Part Number

Line Total: USD 87.11

Global Warranty Management: Site Map

Privacy Policy | Terms of Use

© 2005 General Motors. All rights reserved.

Global Warranty Management: [Main](#) - [Interface Web Customer](#) - [View Vehicle Component Summary](#)

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary ⑦

This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build.

Vehicle Information

VIN: 1G1AK52F357 XXXXXXXXXX Model: 1AK69-2005 COBALT 4-DOOR LS SEDAN
 Service Contract: Yes Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: 1 Open XXXXXXXXXX

For this vehicle:

- [View Vehicle Summary](#)
 - [Service Contract](#)
 - [Branded Title](#)
 - [Warranty Block](#)
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY	Traceability: 412080892
Source Plant: T-CPC TONAWANDA, NEW YORK	Part / Number Broadcast: TMS
Date Scanned: 12/23/2004	Time Scanned: 20:00:00 Scan Station: 04
Component Code: 61-TRANSMISSION	Traceability: 2211
Source Plant: J-HYDRAMATIC WINDSOR, ONTARIO	Part / Number Broadcast: 5EHJ
Date Scanned: 12/23/2004	Time Scanned: 20:00:00 Scan Station: 04
Component Code: 66-ELECTRONIC CONTROL MODULE (ECM)	Traceability: 00000MFLD
Source Plant: T-	Part / Number Broadcast: YLAA
Date Scanned: 01/30/2005	Time Scanned: 02:33:00 Scan Station: 06
Component Code: 87-BODY CONTROL MODULE	Traceability: A43480212
Source Plant: R-	Part / Number Broadcast: 7064
Date Scanned: 12/23/2004	Time Scanned: 16:07:00 Scan Station: 04
Component Code: AB-IR-MODULE ASM-INFLATOR	Traceability: H353B1421
Source Plant: I-INLAND	Part / Number Broadcast: 1650
Date Scanned: 01/29/2005	Time Scanned: 22:27:00 Scan Station: 04
Component Code: AL-IR-MODULE ASM-IP	Traceability: G35082122
Source Plant: I-INLAND	Part / Number Broadcast: 4985
Date Scanned: 12/23/2004	Time Scanned: 16:21:00 Scan Station: 04
Component Code: BK-INTERNATIONAL TRANS. CONTROL MODULE	Traceability: 043510015
Source Plant: K-	Part / Number Broadcast: YLBT
Date Scanned: 01/30/2005	Time Scanned: 02:33:00 Scan Station: 04
Component Code: CB-SEQ NUM (FLEX) BODY ASM	Traceability: 1330394
Source Plant: -	Part / Number Broadcast: 1ZZ
Date Scanned: 12/21/2004	Time Scanned: 06:52:00 Scan Station:
Component Code: CP-SEQ NUM (FLEX) GEN ASM	Traceability: 5140677
Source Plant: -	Part / Number Broadcast: 1XX
Date Scanned: 12/21/2004	Time Scanned: 09:47:00 Scan Station:


Service Agent Installed Component

Vehicle has no current record of vehicle component.

[Global Warranty Management: Site Map](#)

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.



Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN: 1G1AK52F357 [REDACTED] Model: 1AK69-2005 COBALT 4-DOOR LS SEDAN
 Service Contract: Yes Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: 1 Open

REQUIRED ACTION: [REDACTED]

For this vehicle:

- View Vehicle Summary
 - Service Contract
 - Branded Title
 - Warranty Block
- View Vehicle Build
 - View Vehicle Component Summary
 - View Vehicle Transaction History Detail
 - View Vehicle Delivery Information

Vehicle Build

Model: 1AK69-2005 COBALT 4-DOOR LS SEDAN Order Number: HTZG6J
 Gross Vehicle Weight: 1,721 Build Date: 01/17/2005
 Build Plant: 7-

Option Codes

*GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

14B - GRAY	14I - GRAY
15A - BASE PACKAGE	15Z - OPTION PACKAGE DISCOUNT
50U - SUMMIT WHITE	6AR - FRONT SPRING
7AR - FRONT SPRING	8AA - REAR SPRING
9AA - REAR SPRING	AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS
AP9 - TRUNK CARGO NET	AR9 - DELUXE FRONT BUCKET SEAT
B34 - FLOOR MATS	B35 - REAR FLOOR MATS
C67 - ELECT. FRONT AIR CONDITIONER	DC8 -
DT4 - ASHTRAY AND LIGHTER	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FY1 - TRANS/AXLE 3.63 RATIO	IPB - INTERIOR TRIM DESIGN
J41 -	K34 - CRUISE CONTROL
K64 - 115 AMP GENERATOR	L61 - 2.2L DOHC 4 CYL ENGINE
LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO	MN5 - 4 SPEED AUTO TRANSMISSION
MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE	N46 - 4 SPOKE STEERING WHEEL
NC7 - FEDERAL EMISSIONS OVERRIDE	NU1 - CALIF EMISSIONS LEV 2
PG1 - 15" STEEL WHEEL	QTU - P195/60R15 TOURING BW TIRES
SLM - STOCK ORDERS	UN0 - AM/FM STEREO W/CD PLAYER
UQ4 - BASE SPEAKER SYSTEM	V73 - STATEMENT OF VEHICLE CERT.-U.S./CANADA
VK3 - FRONT LICENSE PLATE MOUNT	VM3 - CONSUMER INFORMATION LABEL
VF5 - 50-STATE EMISSIONS	

Added Option Codes

Vehicle has no current record of SAIO codes.

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

<http://gmvis2.gotd.gm.com/gmvis2/showVehicleBuild.do?VIN=1G1AK52F357> [REDACTED] o... 4/26/2010

TA000108745


Warranty

Mr. GMVIS 2
 April 26, 2010

[Logout](#)

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH CUSTOMER

View Vehicle Summary

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

Vehicle Information

VIN: 1G1AK52F357 Model: 1AK69-2005 COBALT 4-DOOR LS SEDAN
 Service Contract: Yes Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: 1 Open

For this vehicle:

- View Vehicle Summary
 - Service Contract
 - Branded Title
 - Warranty Block
- View Vehicle Build
 - View Vehicle
 - Component Summary
 - View Vehicle
 - Transaction History Detail
 - View Vehicle Delivery Information

Required Field Actions

Open field actions are highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Customer Satisfaction Program	N050046	05046	A/C SYSTEM WIRING AND DUAL STAGE AIRBAG MODULE WIRING	05/11/2005	Closed
Product Safety Recall	N100023	10023	LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR	03/18/2010	Open

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Brand Description: JUNK

Date Branded: 11/01/2009

Title Number:

Reporting Source Code:

Reported By: NY

Effective Date: 12/11/2009

Warranty Block

Code	Description	Effective Date
BT	BRANDED TITLE	12/11/2009
Block Transaction Types:		Blocked Labour Ops.
ZPDI		
ZPTI		
ZREG		
ZSCT		

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Certified Used Powertrain Limited Wty	02/21/2010	03/09/2005	17 MI	03/09/2010	100,017 MI
	Powertrain Limited Warranty	02/21/2010	03/09/2005	17 MI	03/09/2010	60,017 MI
	Certified Used Limited Warranty	02/21/2010	10/12/2007	42,196 MI	01/12/2008	45,196 MI
	Emission Select Component Ltd Wty	02/21/2010	03/09/2005	17 MI	03/09/2013	80,017 MI
	Corrosion Limited Warranty	02/21/2010	03/09/2005	17 MI	03/09/2011	100,017 MI
	Emission Select State Component Ltd Wty	02/21/2010	03/09/2005	17 MI	03/09/2012	70,017 MI
	Emission Limited Warranty	02/21/2010	03/09/2005	17 MI	03/09/2008	50,017 MI
	Bumper to Bumper Limited Warranty	02/21/2010	03/09/2005	17 MI	03/09/2008	36,017 MI

Service Contract

Policy Number: [REDACTED]

Owner: URENO

Description: GMPP 60/60 MAJOR GUARD

Deductible Amount: 100.00

Effective Date: 03/09/2005

Expiration Date: 03/09/2010

Effective Odometer: 17 MI

Expiration Odometer: 60017 MI

Daily Rental Limit: 35.00

Transaction History

View Details

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
06/09/2005	074794	ZFAT—Field Action Recall		V1359 - 05046 - Rewire Airbag and Install Jumper Harness	6,370 MI
01/17/2005	A28717	ZPDI—Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management: Site Map

Privacy Policy | Terms of Use

© 2005 General Motors. All rights reserved.