


EWR D&I ANNOTATION

FAN-000001L104001DP543-7927

Artemis # : 000001L104001DP543**Record Created Date :** 07/07/2011**Printed Date :** 07/07/2011**Description :**

DI11-045 SEQ#543: 1 INJURY. 2007 SATURN ION. WHILE DRIVING ABOUT 85 OR 90 (UNITS WERE NOT SPECIFIED), THE SUBJECT VEHICLES BRAKES WENT OUT AND THE VEHICLE SWERVED. SUBJECT VEHICLE WENT ONTO THE SIDE OF THE ROAD AND HIT A WALL. THE VEHICLE THEN SPUN AND ROLLED OVER. THE DRIVER CLAIMS THAT THE AIRBAGS DID NOT DEPLOY AND THE BRAKES DID NOT OPERATE. THE DRIVER SUFFERED A BROKEN SHOULDER AND COLLAR BONE AND A NECK SPRAIN. THE WEATHER WAS LISTED AS CLEAR IT IS UNKNOWN IF THE DRIVER WAS WEARING A SEATBELT. A SEARCH IN ARTEMIS YIELDED NO RECALLS, PURSUITS, OR TSB'S RELATED TO AIRBAG NON-DEPLOYMENT AND BRAKE FAILURE. FIVE COMPLAINTS AND ONE FIELD REPORT WERE FOUND ON THE SUBJECT OF AIRBAG NON-DEPLOYMENT. NO COMPLAINTS WERE FOUND FOR BRAKE FAILURE AND ONLY BRAKE VIBRATION ISSUES WERE FOUND IN FIELD REPORTS. GM HAS OPTED NOT TO RESPOND. GM'S ASSESSMENT AND THE SERVICE REQUEST DETAIL WERE PROVIDED. *LA

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

April 14, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-045

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 4th quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 9, 12, 35, 41, 50, 51, 61, 62, 64, 74, 75, 102, 104, 105, 106, 132, 138, 142, 155, 158, 163, 167, 168, 177, 187, 198, 199, 231, 235, 236, 238, 260, 265, 268, 292, 294, 306, 315, 324, 325, 339, 341, 343, 358, 359, 380, 383, 401, 402, 403, 418, 454, 504, 517, 523, 525, 531, 543, 556	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **May 13, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is fluid and cursive, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

May 12, 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

MAY 13 2011

NVS-217kb
DI11-045

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated April 14, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 4th quarter of 2010.

GM's response is comprised of 59 disks for the incidents that are the subject of DI11-045.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 9 327100506-71-877948747 and 2011 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 9 327100506-71-877948747_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-045
9 327100506-71-877948747
2011 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

9 327100506-71-877948747_01_001- is the first document responsive to Inquiry no.1.
 9 327100506-71-877948747_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI11-045, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(59 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
9	5GAKRBED9BJ [REDACTED]	PAR
12	1G4GE5GDxBF [REDACTED]	PAR
35	1G6DP567150 [REDACTED]	NISM
41	1G6DM57T170 [REDACTED]	NISM
50	1G6DA5EY4B0 [REDACTED]	NISM
51	1G6DG8EG2A0 [REDACTED]	NISM
61	1G6KA5EY8AU [REDACTED]	NISM
62	1G6KD5EY2AU [REDACTED]	NISM
64	1GYUKBEF6AR [REDACTED]	NISM
74	3GYFNAEYXAS [REDACTED]	NISM
75	3GYFNDEY9BS [REDACTED]	NISM
102	KL1TD5DE4AB [REDACTED]	NISM
104	KL1TD5DE1AB [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
105	UNKNOWN	NISM
106	2G1FB1EV2A9[REDACTED]	NISM
132	1G1AP18P577[REDACTED]	NISM
138	1G1AL58F487[REDACTED]	NISM
142	1G1AL58F987[REDACTED]	NISM
155	1G1AS58H897[REDACTED]	NISM
158	1G1AK18H197[REDACTED]	NISM
163	1G1AB1F59A7[REDACTED]	NISM
167	1G1AB5F5XA7[REDACTED]	NISM
168	1G1AB5F53A7[REDACTED]	NISM
177	1G1PG5S97B7[REDACTED]	NISM
187	2CNALDECXB6[REDACTED]	NISM
198	3GNBABDB8AS[REDACTED]	NISM
199	3GNBABDV7AS[REDACTED]	PAR
231	2G1WT57N191[REDACTED]	NISM
235	2G1WC5EM4A1[REDACTED]	NISM
236	2G1WB5EK2A1[REDACTED]	NISM
238	2G1WB5EK6A1[REDACTED]	NISM
260	1G1ZK57758F[REDACTED]	NISM
265	1G1ZE5EB8AF[REDACTED]	NISM
268	1G1ZD5EU9BF[REDACTED]	RUMOR
292	1GCEC19Z87Z[REDACTED]	RUMOR
294	2GCEK13M771[REDACTED]	NISM
306	1GCEC19CX9Z[REDACTED]	PAR
315	1GCNCPEX1BZ[REDACTED]	NISM
324	1GBHK29K87E[REDACTED]	NISM
325	1GCHK24K97E[REDACTED]	NISM
339	1GNFC16037J[REDACTED]	PAR
341	1GNFK36349R[REDACTED]	NISM
343	1GNSCJE07BR[REDACTED]	NISM
358	1GNFC13088R[REDACTED]	NISM
359	1GNUKCE08AR[REDACTED]	NISM
380	1GNDT13S652[REDACTED]	NISM
383	1GNDS13SX52[REDACTED]	PAR
401	UNKNOWN	NISM
402	1GNKRLED3BJ[REDACTED]	NISM
403	UNKNOWN	NISM
418	1GKLRLED0AJ[REDACTED]	PAR
454	1GT120EG1BF[REDACTED]	PAR
504	1G2ZG57B594[REDACTED]	NISM
517	1G2MB35B68Y[REDACTED]	PAR
523	5Y2SL63885Z[REDACTED]	PAR
525	5Y2SL65888Z[REDACTED]	PAR
531	1G8ZX57789F[REDACTED]	NISM
543	UNKNOWN	NISM
556	3GSDL537X9S[REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 59 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a legal document cover sheet for the case **CARDONA V. CHEVROLET** filed in the Superior Court for the State of California, Indio County. The document is a **CIVIL CASE COVER SHEET** with various checkboxes for case type, complexity, and other details. A context menu is overlaid on the right side of the document, showing options for navigating between images and pages, as well as scaling and rotating the image.

Step 7: Next File (Image)

Step 7: Next Page

Step 8: Scale Image

Step 7: Image Properties

DI11-045
543 325750901 – 701589
2007 SATURN ION

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Side - Side	Sub-Area	Initiate PAR- Injury
Address	City Orange	Involved Dir		Safety	Yes
State CA ZipCd	Con Acct	Source	Phone	Updated	12/13/2010 05:33:49 PM
Serial #VIN	Model Year 2007	Priority	Medium License #	Owner	SANCHER
Make Saturn - GM	Warr. Start	Status	Open	Opened	12/10/2010 02:32:19 PM
Model ION 2	Mileage 66500	Sub-Status	Dissatisfied	Closed	
Abstract	PAR-Airbag did not deploy and brakes didnt operate				
Customer Description	***This is a BRC PAR Case. Please do not assume. Forward any inquiries to Rita Sanchez at ext.31227 ***				

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	12/8/2010 10:00:00 AM	Y	0	1	Asphalt	Dry	na	unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
				na				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
unknown	unknown		Unknown					
Incident Loc	22 freeway orange Ca	Incident Desc	I was driving about 85 or 90 and the brakes went out my vehicle swirled and my vehicle went into the side of the road and hit a wall and the vehicle spinned and then rolled over and the airbags didnt deploy					
Component	brakes and airbags	Damage Desc	front end and all around damage					
Vehicle Loc	american ellstate tow	Add'l Info	I dont know what my insurance is and i didnt contact them					
Emgcy Svc Names	california highway patrol	Maint Loc	na					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	na
Vehicle Speed	85	Weather Condition	clear	Prop Owner	na	Property Type	na	
Last Service Date		Loc Last Service		Property Location	na	Prop Est Repair Cost	\$0.00	
Veh Est Repair Cost	\$0.00	Spec Equip Installer	na	Prop Damage Description	na	Inspection Date/Time		
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt	Inspected By	Inspection Not Performed			
Veh Damage Description	all around damage			Explain Other	brakes			

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
		02/28/92	Occupant of Owner's Vehicle		Driver	seatbelt
Injury Description	Medical Rpt#	Treatment Location	Treated By			
back and neck	na	Western medical center	cr doctor			
Street Address	City	State	Zip Code			
	Orange	CA				

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/13/2010 05:34:09 PM	GARCIAJR	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Injuries - ESIS
Contact Last Name	Contact First Name	Account			BAC Code		
Comments							
- neck and back injuries - went to Western medical center							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 03:13:45 PM	SANCHER	SANCHER	Scheduled Follow-up		Scheduled Alarm		thru esls pick up
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 03:13:29 PM	SANCHERI	GARCIAJR	Notify CRM		Done	12/13/2010 05:35:00 PM	esls - Injurs
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 03:10:33 PM	SANCHERI	SANCHERI	Ownership Changed	Ownership Escalated to BRC	Done	12/10/2010 03:10:33 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 03:10:33 PM	SANCHERI	SANCHERI	Ownership Changed		Done	12/10/2010 03:10:33 PM	Service Request Ownership has changed FROM: CROCKEJO TO: SANCHERI

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 02:42:09 PM	SANCHERI	SANCHERI	BRC PAR	Initial Contact- AVM	Done	12/10/2010 03:13:28 PM	call

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Due to the brand an initial contact to the FOM is not required.

Rita Sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 02:41:27 PM	SANCHERI	SANCHERI	BRC PAR	Initial Contact- Dealer	Done	12/10/2010 03:13:11 PM	call

Contact Last Name	Contact First Name	Account	BAC Code

Comments

No need to call Dir. Vehicle beyond warranty and has not been to dealer in two years.

Rita Sanchez/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 02:41:03 PM	SANCHERJ	SANCHERJ	BRC PAR	Initial Contact- Phone	Done	12/10/2010 03:12:54 PM	call

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

verified information and allegation

provided required statements

cust sts i want to proceed

ors sts what happen

cust sts i was driving about 85 or 90 and the brakes went out my vehicle swirved and my vehide went into the side of the road and hit a wall and the vehicle spinned and then rolled over and the airbags didnt deploy the police had the vehicle towed and i dont know my insurance information i have been in the hospital

ors sts ok well i will get this over to our central claims office and they will be in contact with you within 7-10 business days

cust sts ok thanks

rita sanchez/ATx/PAr

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 02:39:14 PM	SANCHERJ	SANCHERJ	Research		Done	12/10/2010 02:43:41 PM	vin

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

customer does not have number to do further research

rita sanchez/ATx/PAr

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 02:38:14 PM	SANCHER	SANCHER	BRC PAR	Acknowledgement	Done	12/10/2010 02:43:21 PM	call

Contact Last Name	Contact First Name	Account	BAC Code

Comments

See Initial Contact

Rita Sanchez/PA/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 02:38:04 PM	SANCHER	SANCHER	BRC PAR	Case Assigned	Done	12/10/2010 02:43:03 PM	File assigned to Rita Sanchez @ ext 31227

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
12/10/2010 02:33:54 PM	CROCKEJO	CROCKEJO	Inbound Call Customer	Complex Request	Done	12/10/2010 02:35:41 PM	PAR-Airbag Deployment

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Cust Sta: Wed I flipped over my car, my air bags did not deploy. I was getting on the freeway, I was spinning and the car flipped over. And I broke my shoulder and collar bone, Been in the hospital 2 days. My neck is sprained as well.

VIN: NOT AVAILABLE

Mileage:

CRS Adv: Let em get you to our PAR department.

Josh Crocker/ATX T1/L1

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C47	SIR - Did Not Deploy	Restraints - (SIR) - Driver Side - Side Impact
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
H01	Inoperative	Brakes - General