


EWR D&I ANNOTATION

FAN-000001L111001DP115-1105

Artemis # : 000001L111001DP115**Record Created Date :****Printed Date :** 08/11/2011**Description :**

DI11-072 SEQUENCE ID 115: SERVICE REQUEST DETAIL LOG FOR GENERAL MOTORS CORPORATION MAKES THE ALLEGATION THAT A 2007 CHEVROLET COBALT IS POTENTIALLY DANGEROUS AND UNSAFE. THE LOG STATES THAT THE VEHICLE IN QUESTION HAD A 'STEERING COLUMN FAILURE' WHICH LED TO A FATAL ACCIDENT. THE D&I ANNOTIONS LISTS 'ROLLOVER-24' AS A DEFECTIVE COMPONENT AS WELL. NO MENTION OF ROLLOVER IN THE SEQUENCE DOCUMENTATION. ALSO, NO ESTIMATED SPEED WAS MENTIONED. LITTLE INFORMATION WAS PROVIDED WITH THE SEQUENCE DOCUMENTATION. FROM A SEARCH OF STEERING COMPONENT CODES RECALL #10V073000 WAS FOUND FOR THE ELECTRIC POWER STEERING WHEREBY THE PROBLEM DESCRIPTION MENTIONS THAT IF 'POWER STEERING ASSIST' IS LOST THAT MORE EFFORT WOULD BE NEEDED TO STEER THE VEHICLE AT LOW SPEEDS. NO PURSUITS WERE FOUND RELATING THIS VEHICLE TO THE ALLEGED SAFETY DEFECT. 3 TSBS WERE FOUND FOR THE STEERING COMPONENT CODE WHEREBY ALL 3 MENTIONED A RATTLE NOISE AT THE STEERING COLUMN AT SLOW SPEEDS. FROM A VOQ SEARCH, OVER 400 REPORTS WERE FOUND FOR THE STEERING COMPONENT CODE FOR THE VEHICLE. FROM A FIELD REPORT SEARCH, REPORTS MENTION A LOSS OF POWER STEERING ASSIST. *NO



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

June 22, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-072

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2011. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 6, 12, 23, 40, 42, 44, 46, 47, 60, 61, 64, 73, 81, 82, 87, 89, 91, 115, 121, 125, 129, 131, 139, 143, 144, 145, 154, 157, 167, 170, 171, 172, 188, 189, 214, 217, 218, 221, 231, 236, 240, 243, 244, 245, 246, 270, 276, 277, 279, 280, 281, 292, 302, 304, 312, 314, 322, 323, 324, 336, 409, 410, 412, 434, 465, 473	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **July 22, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is fluid and cursive, with the first name "Christina" and last name "Morgan" clearly legible.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

July 22, 2011

JUL 22 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-072

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated June 22, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2011.

GM's response is comprised of 66 disks for the incidents that are the subject of DI11-072.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 6 333829231-724510 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 6 333829231-724510_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-072
6 333829231-724510
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

6 333829231-724510_01_001- is the first document responsive to Inquiry no.1.

6 333829231-724510_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI11-072, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(66 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
6	5GAEV23D59J	NISM
12	1G4GE5ED8BF	NISM
23	1G4HJ5EM0BU	NISM
40	1G6DS57V290	NISM
42	1G6DU57V090	NISM
44	1G6DE5EG3A0	NISM
46	1G6DP1ED3B0	PAR
47	1G6DS1ED5B0	NISM
60	1GYEE437390	PAR
61	3GYFNCEY2AS	NISM
64	3GYFNBEYXBS	NISM
73	3GNFK12357G	NISM
81	KL1TD66698B	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
82	KL1TD66628E	NISM
87	KL1TG5DEXAB	NISM
89	2G1FJ1EJ0A9	NISM
91	2G1FA1ED6B9	NISM
115	1G1AL55F077	NISM
121	1G1AL15F977	NISM
125	1G1AM15B477	NISM
129	1G1AK18F587	NISM
131	1G1AK18F087	NISM
139	1G1AS18H297	NISM
143	1G1AT58H397	NISM
144	1G1AD1F57A7	NISM
145	1G1AF5F59A7	NISM
154	1G1YY24U555	NISM
157	1G1YY26E185	NISM
167	2CNALBEW2A6	NISM
170	2CNALBEC2B6	NISM
171	2CNFLNEC9B6	NISM
172	2CNALDEC2B6	NISM
188	3GNBABDV7AS	NISM
189	3GNBAADB0AS	NISM
214	2G1WT57N291	NISM
217	2G1WB5EK8A1	NISM
218	2G1WB5EK2A1	NISM
221	2G1WA5EK7A1	NISM
231	1G1ZS58N97F	NISM
236	1G1ZF57588F	NISM
240	1G1ZB5EB5A4	LIT
243	1G1ZD5EB6AF	NISM
244	1G1ZB5E17BF	NISM
245	1G1ZA5E1XBF	NISM
246	1G1ZB5E11BF	NISM
270	3GCEC13C28G	LIT
276	3GCEC23089G	NISM
277	1GCSCSE08AZ	NISM
279	1GCRKSE37BZ	NISM
280	1GCRCSE00BZ	NISM
281	UNKNOWN	NISM
292	1GC1KXC89BF	NISM
302	1GNFC16J47J	Rumor
304	3GNFC16087G	PAR
312	1GNFC13047R	PAR
314	1GNFC13J78R	NISM
322	1GNSCAE06BR	NISM
323	1GNSKDFJ9BR	Rumor
324	1GNSKCE0XBR	NISM
336	1GNDT13S052	NISM
409	2CTFLEEW0A6	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
410	2CTALSEC6B6[REDACTED]	NISM
412	2CTALSEC2B6[REDACTED]	NISM
434	KL2TD66E39B[REDACTED]	NISM
465	1G2ZG57B694[REDACTED]	NISM
473	2G2WP552781[REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.


Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 66 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

CIVIL CASE COVER SHEET

Case Information:
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91764
 Telephone: 909-469-5127 Fax: 909-469-5126
 ATTORNEY FOR PLAINTIFF
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COURT

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET
☐ Limited ☒ Unlimited

Case Type:
☐ Contract ☐ Tort ☐ Other (Specify: _____)
☐ Real Property ☐ Other (Specify: _____)

Check one box below for the case type that best describes this case:

1. Check one box below for the case type that best describes this case:

2. This case is:
 a. ☒ Large number of separately represented parties
 b. ☒ Extensive motion practice raising difficult or novel issues that will be time-consuming to resolve
 c. ☒ Substantial amount of documentary evidence
 d. ☒ Other (Specify: _____)

3. Type of monetary relief sought (check all that apply):
 a. ☒ monetary b. ☐ non-monetary, declaratory or injunctive relief

4. Number of causes of action (Specify): FIVE

5. This case is: ☒ in ☐ is not a class action suit.

Date: JUL 3, 2005

ERIC D. PARIS, ESQ., S/B# 147836
 (Print on front sheet)

NOTICE
 Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (as under the Probate, Family, or Welfare and Institutions Codes, Cal. Rules of Court, rule 100.1).
 Plaintiff must file this cover sheet in addition to any cover sheet required by local court rules.
 If this case is brought under rule 100.1 of the California Rules of Court, you must file this cover sheet with the action or proceeding.
 Unless this is a complex case, this cover sheet shall be used for individual proposed and

CIVIL CASE COVER SHEET

Step 7: Next File
(Image)

Step 7: Next Page

Step 8: Scale
Image

Step 7: Image Properties

DI11-072
115 333829466-725155
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No.	71-919897244	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Steering - Power Steering Pump /	Sub-Area	Initiate PAR- Collision
Address		City	Davenport	Involved Dir		Safety	Yes
State	IA	ZipCd		Source	Phone	Updated	2/22/2011 06:24:17 PM
Serial #/VIN	1G1AL55F077	Model Year	2007	Priority	Medium	License #	
Make	Chevrolet	Warr. Start	04/12/2007	Status	Open	Owner	MERCADTO
Model	Cobalt	Mileage	40000	Sub-Status	Dissatisfied	Opened	2/19/2011 05:16:32 PM
Abstract	Steering - Power Steering Pump / Brackets (Fatal Collision)						
Customer Description	This is a BRC PAR File. Please do not assume or advise. Forward any inquiries to Tonle @ ext 41183						
Closed							

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People In Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Incident Loc	Incident Desc							
Component	Damage Desc							
Vehicle Loc	Add'l Info				n/a			
Emgcy Svc Names	Maint Loc							

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	
Vehicle Speed		Weather Condition	Prop Owner		Property Location		Property Type	
Last Service Date		Spec Equip Installer	Prop Damage Description		Inspected By		Prop Est Repair Cost	
Veh Est Repair Cost		Inspection Type	Inspection Date/Time		Explain Other			
Primary Veh Use								
Veh Damage Description								

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/22/2011 06:24:54 PM	GARCIAJR	ESISBIQU	Escalation	ESIS - Fatalities	In Progress		Fatality - ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Fatality

Joe G/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 05:28:58 PM	MERCADTO	MERCADTO	Scheduled Follow-up		Scheduled Alarm		Gray - ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Check case status for ESIS plu

Tonia/BRC PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 05:27:47 PM	MERCADTO	GARCIAJR	Notify CRM		Done	2/22/2011 05:25:38 PM	ESIS - Fatality

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Cust's spouse was driving the vehicle and was allegedly involved in fatal collision due to the power steering recall

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 05:27:48 PM	MERCADTO	MERCADTO	Ownership Changed	Ownership Escalated to BRC	Done	2/21/2011 05:27:46 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 05:15:31 PM	MERCADTO	MERCADTO	Inbound Call Third Party	Voice Mail Received	Done	2/21/2011 05:15:45 PM	PAR Voice Mail
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Sls: Terry from the CAC dept. 71-619897244 -
Sent 2/19/11 536pm

Tonle/BRC PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:19:33 AM	MERCADTO	MERCADTO	Ownership Changed		Done	2/21/2011 11:19:33 AM	Service Request Ownership has changed FROM: KHANTH TO: MERCADTO
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:19:24 AM	MERCADTO	MERCADTO	BRC PAR	Initial Contact- AVM	Done	2/21/2011 05:28:16 PM	called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs Adv: calling to make you aware of a file in which customer is alleging that his spouse was driving the vehicle and the power steering went out causing her to be in a collision which turned fatal. There is no action required on your part. This is just to make you aware of what is going on in your area. If you have any questions please don't hesitate to contact me. Provided contact info and SR

Tonle/BRC PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:19:22 AM	MERCADTO	MERCADTO	BRC PAR	Initial Contact- Dealer	Done	2/21/2011 02:20:05 PM	call not required
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Dealer hasn't been to the dealer w/in the last 2 yrs.

Tonle/BRC PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:19:16 AM	MERCADTO	MERCADTO	BRC PAR	Initial Contact- Phone	Done	2/21/2011 02:14:13 PM	call not required
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Fatality Case - No call required

Tonle/BRC PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:19:10 AM	MERCADTO	MERCADTO	BRC PAR	Acknowledgement	Done	2/21/2011 02:16:33 PM	call not required
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Fatality Case - No call required

Tonle/BRC PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:19:05 AM	MERCADTO	MERCADTO	Notify CRM		Done	2/21/2011 05:26:22 PM	File assigned
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:18:54 AM	MERCADTO	MERCADTO	Research		Done	2/21/2011 02:12:22 PM	Research
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

1 open recall:

10023 LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR

No prev related repairs

1 related closed file:

71-886452750

State agency - Wisconsin

State Trooper Investigation

Tonle/BRC PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:18:39 AM	MERCADTO	MERCADTO	BRC PAR	Case Assigned	Done	2/21/2011 02:09:25 PM	File assigned to Tonle Mercado @ ext 41183
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Received

Tonle/BRC PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:18:31 AM	MERCADTO	KHANTH	SR Opened		Done	2/21/2011 11:18:31 AM	SR in Status of Closed has been Re-Opened by MERCADTO
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/21/2011 11:18:30 AM	MERCADTO	KHANTH	SR Closed - Dissatisfied		Done	2/21/2011 11:18:30 AM	Service Request has been Closed Dissatisfied.

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/18/2011 05:30:42 PM	KHANTH	MERCADTO	Notify CRM		Done	2/21/2011 11:18:18 AM	PAR

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Terry Khan/CAC T1/ATX/L0

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/19/2011 05:16:57 PM	KHANTH	KHANTH	Inbound Call Customer	Complex Request	Done	2/19/2011 05:30:40 PM	PAR

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

* Date of Incident: 10-22-10 -

* Performed vin scan ; no PAR case was found

* Customer claims vehicle was involved in a collision due to product failure.

* Customer claims product failure caused bodily injury or death

Terry Khan/CAC T1/ATX/L0

Confidential Comments

UCC Information

UCC Code	Symptom	Description
M30	Inoperative	Steering - Power Steering Pump / Brackets


[Logout](#)

February 23, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMERView Vehicle Summary ?

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable)

Vehicle Information

VIN 1G1AL55F077 XXXXXXXXXX Model 1AL69-2007 COBALT LT SEDAN
 Service Contract No Branded Title Yes Warranty Block Yes PDI Status No
 Order Type 50 - FLEET
 Field Actions 1 Open XXXXXXXXXX

For this vehicle:

- [View Vehicle Summary](#)
 - [Service Contract](#)
 - [Branded Title](#)
 - [Warranty Block](#)
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Required Field Actions

Open field actions are
highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N100023	10023	LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR	03/18/2010	Open

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever

Brand Description SALVAGED

Date Branded 08/01/2009

Title Number 09237C5160016

Reporting Source Code

Reported By WI

Effective Date 09/12/2009

Warranty Block

Code	Description	Effective Date
BT	BRANDED TITLE	09/11/2009
Block Transaction Types		Blocked Labour Ops
ZPDI		
ZPTI		
ZREG		
ZSCT		

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Refer to Help page for details. For OnStar contact 888.ON.STAR1 (888.667.8271) and for XM Radio contact 877.GET.XMST (877.438.9677).

OnStar Equipped: N

OnStar Status: NA

XM Equipped Y

XM Radio ID: X71YT04B

XM Status: Inactive

OnStar Vehicle Diagnostics N

DMN Enabled: N

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Bumper to Bumper Limited Warranty	02/21/2010	04/12/2007	10 MI	04/12/2010	38,010 MI
	Corrosion Limited Warranty	02/21/2010	04/12/2007	10 MI	04/12/2013	100,010 MI
	Emission Select Component Ltd Wty	02/21/2010	04/12/2007	10 MI	04/12/2015	80,010 MI
	Powertrain Limited Warranty	02/21/2010	04/12/2007	10 MI	04/12/2012	100,010 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
04/11/2007	A23285	ZPD1—Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved



Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN 1G1AL55F077 [REDACTED] Model 1AL69-2007 COBALT LT SEDAN
 Service Contract: No Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type: SO - FLEET
 Field Actions: [1. Open](#) [REDACTED]

Vehicle Build

Model 1AL69-2007 COBALT LT SEDAN Order Number KVGW3Z
 Gross Vehicle Weight 1,737 Build Date 04/11/2007
 Build Plant 7-

Option Codes

*IVH is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

14C - GRAY	14J - GRAY
1S2 - OPTION PACKAGE DISCOUNT	21U - LASER BLUE METALLIC
3LT - 3LT-SPORT PACKAGE *WHEELS, 16" ALUMINUM, MACHINE FACED (REPLACES STD/OPT WHEELS) *XM SATELLITE RADIO - SERVICE FEE EXTRA 1ST 3 MONTHS INCL. *16" TOURING TIRES *ANTILOCK BRAKE SYSTEM *CONVENIENCE NET, CARGO *CRUISE CONTROL *BODY COLOR, BODYSIDE MOLDINGS *CHROME EXHAUST TIP *REAR SPOILER *WHITE FACED GAUGES *LEATHER WRAP STEERING WHEEL, STEERING WHEEL AUDIO CONTROLS *LEATHER WRAPPED SHIFT KNOB	6AP - FRONT SPRING
7AP - FRONT SPRING	8AB - REAR SPRING
9AB - REAR SPRING	AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS
AL0 - SENSOR INDICATOR INFLATABLE RESTRAINT, FRT PASS/CHILD PRESENCE DETECTOR	AP9 - CONVENIENCE NET, CARGO
AR9 - DELUXE FRONT BUCKET SEAT	AT8 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING
AU0 - REMOTE KEYLESS ENTRY	AU3 - POWER DOOR LOCKS W/REMOTE KEYLESS ENTRY
B34 - FLOOR MATS, FRONT/REAR	B35 - REAR FLOOR MATS
B84 - BODY COLOR, BODYSIDE MOLDINGS	BZ7 - GM PRODUCTION WEEK #16
C67 - ELECT. FRONT AIR CONDITIONER	D36 - MIRROR I/S R/V TILT
DG7 - BODY COLOR POWER MIRRORS	FCH - HERTZ RENT A CAR
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FE9 - FEDERAL EMISSIONS
FLT - FLEET PROCESSING OPTION	FY1 - TRANS/AXLE 3.63 RATIO
IPC - INTERIOR TRIM DESIGN	JM4 - ANTILOCK BRAKE SYSTEM
K34 - CRUISE CONTROL	K64 - 115 AMP GENERATOR
L81 - ENGINE, 2.2L DOHC 4V ECOTEC	LOD - ASSEMBLY PLANT -

For this vehicle:

[-- View Vehicle Summary](#)

[Service Contract](#)
[Branded Title](#)
[Warranty Block](#)

[-- View Vehicle Build](#)

[View Vehicle Component Summary](#)
[View Vehicle Transaction History Detail](#)
[View Vehicle Delivery Information](#)

MNS - 4 SPEED AUTO TRANSMISSION

N34 - 3 SPOKE LEATHER STEERING WHEEL

NW7 - TRACTION CONTROL

QLG - TIRE ALL P205/55R16-89H BW

R6K - ONSTAR

R9N - HEATED LEATHER APPOINTED FRONT BUCKET SEATS

RE8 - UPGRADE ORNAMENTATION

TV5 - SPORT PACKAGE

UK3 - LEATHER WRAP STEERING WHEEL, STEERING WHEEL AUDIO CONTROLS

US8 - AM/FM STEREO, CD PLAYER & MP3 PLAYER

V73 - STATEMENT OF VEHICLE CERT.-U.S. /CANADA

VQ2 - FLEET ORDERING AND ASSISTANCE

VX7 - LONG TERM DAILY RENTAL PROGRAM

LORDSTOWN, OHIO

MX0 - TRANSMISSION, 4 SPD AUTOMATIC

NT7 - FEDERAL EMISSION TIER 2

N20 - 16" MACHINED-FACE ALUMINUM WHEELS

R8F - IDENTIFY B-CODE USERS

R6P - PREMIUM PAINT

R9X - XM TRACKING CODE

T43 - REAR SPOILER

U2K - XM SATELLITE RADIO-SERVICE FEE EXTRA 1ST 3 MONTHS INCL

UQ4 - BASE SPEAKER SYSTEM

V2G - FULL FUEL FILL CREDIT

VK3 - FRONT LICENSE PLATE BRACKET

VT7 - OWNERS MANUAL ENGLISH

VY7 - LEATHER SHIFT KNOB

Added Option Codes

Vehicle has no current record of SAIO codes.

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved


[Logout](#)

February 23 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary



This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build

Vehicle Information

VIN 1G1AL55F077 [REDACTED] Model 1AL69-2007 COBALT LT SEDAN
 Service Contract No Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type 50 - FLEET
 Field Actions 1 Open [REDACTED]

For this vehicle:

[View Vehicle Summary](#)
[Service Contract](#)
[Branded Title](#)
[Warranty Block](#)
[View Vehicle Build](#)
[View Vehicle Component Summary](#)
[View Vehicle Transaction History Detail](#)
[View Vehicle Delivery Information](#)

Vehicle Component

Component Code 10-ENGINE ASSEMBLY Traceability 704040208
 Source Plant T-CPC TONAWANDA, NEW YORK Part / Number Broadcast AWD
 Date Scanned 04/11/2007 Time Scanned 09:41:00 Scan Station 04

Component Code 81-TRANSMISSION Traceability AM18
 Source Plant J-HYDRAMATIC WINDSOR, ONTARIO Part / Number Broadcast 7EHJ
 Date Scanned 04/11/2007 Time Scanned 09:41:00 Scan Station 04

Component Code 74-ELECTRON BRAKE & TRACTION CTRL Traceability 0927G0687
 MOD ASM
 Source Plant P- Part / Number Broadcast 6488
 Date Scanned 04/11/2007 Time Scanned 07:15:00 Scan Station 04

Component Code 86-ELECTRONIC CONTROL MODULE Traceability 2707300S9
 (ECM)
 Source Plant 2- Part / Number Broadcast YPCX
 Date Scanned 04/11/2007 Time Scanned 10:56:00 Scan Station 06

Component Code 87-BODY CONTROL MODULE Traceability A70800221
 Source Plant R- Part / Number Broadcast 8392
 Date Scanned 04/11/2007 Time Scanned 10:56:00 Scan Station 04

Component Code AB-IR-MODULE ASM-INFLATOR Traceability 2B0780191
 Source Plant M-MORTON-THIOKOL Part / Number Broadcast 8196
 Date Scanned 04/11/2007 Time Scanned 08:58:00 Scan Station 04

Component Code AL-IR-MODULE ASM-I/P Traceability G093E1285
 Source Plant I-INLAND Part / Number Broadcast 5892
 Date Scanned 04/10/2007 Time Scanned 21:58:00 Scan Station 04

Component Code BK-INTERNATIONAL TRANS. CONTROL Traceability 070645778
 MODULE
 Source Plant K- Part / Number Broadcast YHRL
 Date Scanned 04/11/2007 Time Scanned 10:56:00 Scan Station 04

Component Code CB-SEQ NUM (FLEX) BODY ASM Traceability 2180047
 Source Plant - Part / Number Broadcast 1ZZ
 Date Scanned 04/05/2007 Time Scanned 06:02:00 Scan Station

Service Agent Installed Component

Vehicle has no current record of vehicle component.

[Global Warranty Management](#) [Site Map](#)

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved

[Logout](#)

February 23, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMERView Vehicle Transaction History Detail ?

This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN 1G1AL55F077

Model: 1AL69-2007 COBALT LT SEDAN

Service Contract: No

Branded Title: Yes

Warranty Block: Yes

PDI Status: No

Order Type: 50 - FLEET

Field Actions: [1 Open](#)

For this vehicle:

[-- View Vehicle Summary](#)[-- Service
Contract](#)[-- Branded Title
Warranty Block](#)[-- View Vehicle Build](#)[-- View Vehicle](#)[-- Component Summary](#)[-- View Vehicle](#)[-- Transaction History
Detail](#)[-- View Vehicle Delivery
Information](#)

Job Card Date: 04/11/2007

Job Card Number: A23285

Repair Service Agent: 128639

Odometer Reading: 0 MI

HERTZ CORPORATION-CLEVELAND

Authorization Code

19025 MAPLEDALE AVENUE

CLEVELAND OH 44135-0000

33026789000000

Process Date

04/17/2007

Transaction Type:

ZPDI--Pre-Delivery Inspection

Transaction Expense Category

Customer Complaint Code:

0000-Converted Claim

Job Card Line # 1

Transaction Adjustment

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time

Causal Part Number

Line Total: USD 59.07

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

February 23, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMERView Vehicle Delivery Information

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN 1G1AL55F077  Model 1A169-2007 COBALT LT SEDAN
Service Contract No Branded Title Yes Warranty Block Yes PDI Status No
Order Type 50 - FLEET
Field Actions: 1 Open 

Invoice Information

Invoicing Service Agent 112243
JAMES WOOD CHEVROLET-OLDSMOBILE
2111 S HWY 287
DECATUR TX 76234-2722 8406272177

Invoice Date 04/11/2007

Ship to Information

Invoicing Service Agent 145005
HERTZ RENT A CAR
18026 MAPLEDALE AVE
CLEVELAND OH 44135-0000

Ship to Date N/A

Delivery Information

Delivery Service Agent 112243
JAMES WOOD CHEVROLET-OLDSMOBILE
2111 S HWY 287
DECATUR TX 76234-2722 8406272177

Delivery Date 04/12/2007
Delivery Type: 020---DAILYRENTAL
Delivery Odometer 10

In Service Information

Invoicing Service Agent

In Service Date N/A
In Service Type 0000
In Service Odometer 0

For this vehicle:

[View Vehicle Summary](#)

- [Service Contract](#)

- [Branded Title](#)

- [Warranty Block](#)

[View Vehicle Build](#)[View Vehicle](#)[Component Summary](#)[View Vehicle](#)[Transaction History Detail](#)[View Vehicle Delivery Information](#)

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.