



Roof Replacement Estimate

Prepared for Property Owner · Three options for your home

CUSTOMER

Name **Property Owner**

Email **—**

Phone **—**

Prepared by **Apex Estimator**

PROPERTY

21106 Kenswick Meadows Ct, Humble, TX 77338, USA

Roof area **2,490 sqft**

Pitch **7:12**

Squares **24.90**



FOOTPRINT 2,150	RIDGE 33 lf	HIP 102 lf	VALLEY 19 lf	RAKE 5 lf	EAVE 165 lf
---------------------------	-----------------------	----------------------	------------------------	---------------------	-----------------------

RECOMMENDED		TOTAL
Architectural Laminate		\$17,741
ITEM	AMOUNT	
Architectural Laminate (27.89 sq, includes 12% waste)	\$4,044	
Tear-off (24.9 sq, 1 layer)	\$872	
Underlayment (26.15 sq)	\$654	
Trim & flashing (drip edge 165 lf, ridge 33 lf, valley 19 lf)	\$1,233	
Penetrations & vents (boots, chimney, ridge vents)	\$670	
Decking allowance (5.45 sheets, contingency)	\$300	
Labor (24.9 sq @ 2.84 h/sq)	\$6,002	
Overhead (12%)	\$1,653	
Profit (15%)	\$2,314	
Total	\$17,741	

COMPARE OPTIONS

3-Tab Asphalt Shingle

\$14,834

25-yr · 3-tab asphalt

Architectural Laminate

\$17,741

30-yr · architectural laminate

Designer / Impact-Resistant

\$22,084

Lifetime · designer / impact-resistant

PRE-INSPECTION OBSERVATIONS		Concerning	3 OBSERVATIONS
	Other	MEDIUM · 90%	
	The entire roof surface within the bounding box is a bright white/light gray color — starkly different from every surrounding home's dark gray asphalt shingle roofs. This is consistent with a flat or very low-slope membrane roofing system (e.g., TPO or modified bitumen) rather than traditional pitched shingles.		
	ENTIRE SUBJECT ROOF SURFACE		
	Debris	LOW · 75%	
	Multiple small dark circular/dot-shaped objects are scattered across the light roof surface at irregular intervals — at least 6–8 visible items distributed across the field of the roof.		
	SCATTERED ACROSS THE CENTRAL AND SOUTH PORTIONS OF THE FLAT ROOF		
	Debris	MEDIUM · 95%	
	Large quantities of stacked lumber and construction materials are visibly piled along the east and south perimeter of the subject property, directly adjacent to the structure.		
	EAST AND SOUTH PERIMETER OF SUBJECT PROPERTY, AT ROOF/GROUND LEVEL		
AI VISION CONDITION ASSESSMENT · PRE-INSPECTION ONLY · NOT A DIAGNOSIS			

Estimate notes. Pricing reflects 2,490 sqft of roof area at 7:12 pitch (24.90 squares). Estimate valid for 30 days from the date issued. Final pricing subject to inspection at framing if any unforeseen conditions are discovered. Permits, dumpster, and disposal included where required by local code.

Warranty: tier-dependent (see manufacturer documentation). **Payment:** 30% on contract signing, 60% at material delivery, 10% at completion.

CUSTOMER SIGNATURE · DATE	APEX AUTHORIZED · DATE
---------------------------	------------------------