

Flight Authorization Form

Task		
Date	Location	RPAS System
	Glen View, Harare	
Task Description	Inspection of Glen View 1&2 132Kv feeders	
PIC	Second RP	Observer/Crew
Tafadzwa Chikurira	Tamuonaishe Gurupira	Tafadzwa Chikurira

Operation Details		
Local Area Frequency	Emergency Numbers	
Notes (special operation procedures, permissions, etc.)	FA Notes	

Flight Authorization		
Chief Remote Pilot	Tafadzwa Chikurira	PENDING
PIC	Tafadzwa Chikurira	PENDING

Job Safety Form

ZESA HOLDINGS PVT LTD		Date	2023-04-27
Task	Inspection of Glen View 1&2 132Kv feeders	Location	Glen View, Harare
Check the following and address as needed			
Sketch of an area (if necessary)	Maps and charts available and checked	PASS	
	Weather, within limits for RPA and operation	PASS	
	Airspace Classification and requirements	PASS	
	NOTAMs	PASS	
	Possibility of public moving into area	PASS	
	Footpath/right of way	PASS	
	Landing area including alternate	PASS	
	Ability to maintain 30m from public	PASS	
	Obstruction (buildings, trees) ('Return to Home', height settings)	PASS	
	Possible inteference (Powerlines/ antennas)		
	Ability to maintain visual line of sight	PASS	
	Remote Pilot's ability matches location/task	PASS	
	Permission of any landowners	PASS	
	Signage Placement	PASS	
	Permission from local authority	PASS	
RP	Tafadzwa Chikurira	Signature	--
Crew			
Comments			

Pre-Flight Checklist Form

Date	2023-04-27		
PIC	Tafadzwa Chikurira	Signature	
	ITEM	CHECK	
1	Fuselage/Frame is not damaged	PASS	
2	Propellers are good	PASS	
3	Gimbal is good and can move freely	PASS	
4	Motors are not damaged and can turn freely	PASS	
5	Obstacle Sensors are clean and free of obstructions	PASS	
6	Batteries are fully charged	PASS	
7	Micro SD card is inserted	PASS	
8	Remote Control Battery is fully charged	PASS	
9	Remote Control is not damaged	PASS	
10	Joysticks are fastened tightly	PASS	
11	Application is connected and showing status of the aircraft	PASS	
12	All necessary aircraft calibrations have been done	--	
13	Radios are functioning properly	PASS	
14	Accessories (if any) are functioning properly	PASS	
15	Home Point and RTH Height have been set	PASS	
16	Flight Conditions are safe (Check UAV Forecast Application)	PASS	
17	Identify landing site	PASS	
18	Identify alternative landing site	PASS	
19	Has the Job Safety Assessment been validated	PASS	
20	Check for other Aircraft, hazards and obstacles	PASS	

Arrival Checklist Form

Date	2023-04-27			
PIC	Tafadzwa Chikurira	Signature	PENDING	
	ITEM	QTY	CONDITION OUT	CONDITION IN
1	Full RPA with all components	1	Working	Working
2	Spare propellers	1	Working	Working
3	Gimbal Cover	1	Working	Working
4	Remote Control	1	Working	Working
5	Joysticks	1	Working	Working
6	USB Cable C-type	1	Working	Working
7	Connector cables	1	Working	Working
8	Rugged case	1	Working	Working
9	Batteries	1	Working	Working
10	Battery charger	1	Working	Working
11	Car battery charger	1	Working	Working
12	Explosive Proof Battery Bag	1	Working	Working
13	Two-way radios	1	Working	Working
14	Loudspeaker	1	Working	Working
15	Light Beacon	1	Working	Working
16	Flashlight	1	Working	Working
17	Landing pad	1	Working	Working
18	Cones	1	Working	Working
19	Cordoning Tape	1	Working	Working
20	Chairs	1	Working	Working
21	Tables	1	Working	Working
22	Tent	1	Working	Working
23	Fire Extinguisher	1	Working	Working

Departure Checklist Form

Date	2023-04-27			
Dispatched By	Janet Chiduwa	Signature	PENDING	
Dispatched To	Tafadzwa Chikurira	Signature	PENDING	
Destination				
	ITEM	QTY	CONDITION IN	CONDITION OUT
1	Full RPA with all components	1	Working	Working
2	Spare propellers	1	Working	Working
3	Gimbal Cover	1	Working	Working
4	Remote Control	1	Working	Working
5	Joysticks	1	Working	Working
6	USB Cable C-type	1	Working	Working
7	Connector cables	1	Working	Working
8	Rugged case	1	Working	Working
9	Batteries	1	Working	Working
10	Battery charger	1	Working	Working
11	Car battery charger	1	Working	Working
12	Explosive Proof Battery Bag	1	Working	Working
13	Two-way radios	1	Working	Working
14	Loudspeaker	1	Working	Working
15	Light Beacon	1	Working	Working
16	Flashlight	1	Working	Working
17	Landing pad	1	Working	Working
18	Cones	1	Working	Working
19	Cordoning Tape	1	Working	Working
20	Chairs	1	Working	Working
21	Tables	1	Working	Working
22	Tent			

23	Fire Extinguisher			
Notes	Departure Notes			

Post-Flight Checklist Form

Date	2023-04-27		
PIC	Tafadzwa Chikurira	Signature	PENDING
	ITEM	CHECK	
1	Fuselage/Frame is not damaged	PASS	
2	Propellers are good	PASS	
3	Gimbal is good and can move freely	PASS	
4	Motors are not damaged and can turn freely	PASS	
5	Obstacle Sensors are clean and free of obstructions	PASS	
6	Remote Control is not damaged		
7	Radios are functioning properly	PASS	
8	Accessories (if any) are functioning properly	PASS	
9	Captured data is satisfactory	PASS	