



Heritage Site Assessment Report

1. General Information

Date of Assessment:

2025-06-06

Assessor's Name:

Gorun Jinian

Supervisor:

Gorun Jinian

Organization:

DBST Group

Monument Reference:

BH2023

Monument Name:

BH Statue

Ownership:

Municipality

2. Location Information

Governorate:

Mount Lebanon

District:

Metn

City/Village:

Bourj Hammoud

Location:

GHSTEXT

3. Preliminary Conditions

Observed Structural Conditions:

Stable

Exterior Walls Condition:

Cracked

Roof Conditions:

Minor Damage

Major Architectural Failure:

No Failure

Location of Major Damage:

Foundation

4. Evidence of Conflict or Damage

Evidence of Armed Conflict:

No

Fire or Smoke Damage:

Yes

Looting or Vandalism:

No

Conflict-Specific Damage Indicator:

No

5. Visible Damage

Significant Cultural/Religious Symbol Damage:

No

Visible Damage to Sculptures/Carvings:

No

Damage to Decorative Elements:

Yes

6. Environmental Concerns

Water Infiltration and Weather Exposure:

Minor moisture damage

Secondary Hazards Present:

Yes

7. Documentation and Evidence

Satellite Imagery Observations:

Imagery Analyzed

Eyewitness Report:

Nothing much going on

Testimonials:

No one

7. Documentation and Evidence

(No images available)

8. Risk Assessment

Potential Hazards to Public and Site:

Minor hazards

Urgent Stabilization Required:

No

Security Measures Needed:

No

Likelihood of Continued Damage:

Moderate

9. Historical or Cultural Significance

Historical or Cultural Significance:

This is BH's main statue

Significance for Local Population:

They love it

Additional References:

Nothing much in here