

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

October 20, 2025

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
Kiame Mahaniah, MD, MBA, Secretary, Executive Office of Health and Human Services (electronic copy)
Clerk, Massachusetts House of Representatives (electronic copy)
Clerk, Massachusetts Senate (electronic copy)
Lieutenant Jason Graham, Compliance Officer (electronic copy)


Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Hampshire County Jail and House of Correction, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Thomas Murphy
Environmental Analyst, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)
Merridith O'Leary, Commissioner, Northampton Health and Human Services (electronic copy)
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
Glenn Sexton, Superintendent (electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100 Marlborough, MA 01752
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

October 10, 2025

Patrick J. Cahillane, Sheriff
Hampshire County Jail and House of Correction
205 Rocky Hill Road
Northampton, MA 01060 (electronic copy)

Re: Facility Inspection – Hampshire County Jail and House of Correction, Northampton

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Hampshire County Jail and House of Correction on October 8, 2025 accompanied by Lieutenant Jason Graham, Compliance Officer, Lieutenant Bryan Luszczki, and Lieutenant Jake McCormick, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 20 total deficiencies: 12 new deficiencies under the Required Standards (.100 and .200 series), 4 repeat deficiencies under the Required Standards, 3 new deficiencies under the Recommended Standards (.300 series), and 1 repeat deficiency under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Deficiencies under the Required Standards (.100 and .200 series)

12 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Special Management Unit	B Block	Lower Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged in shower
2. Housing Units	Unit – 3	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C14
3. Housing Units	Unit – 5	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C38
4. Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Soap scum on walls in shower
5. Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower
6. Housing Units	Unit – 5	Lower Shower	105 CMR 451.123	Maintenance: Mold observed on ceiling in shower
7. Housing Units	Unit - 5	Upper Shower	105 CMR 451.123*	Maintenance: Floor paint damaged in shower
8. Housing Units	Unit - 6	Upper Shower	105 CMR 451.123	Maintenance: Ceiling damaged in shower
9. Housing Units	Unit – 7	Upper Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged in shower
10. Kitchen	Walk-in Freezer # 1		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
11. Kitchen	Dishwashing Area		105 CMR 451.200	Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Wet cloth not stored in sanitizer solution. Standard found in 105 CMR 590; FC 3-304.14(B)(1). ** Corrected On-Site **
12. Kitchen	Walk-in Cooler # 2		105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C).
13. Kitchen	Pot Room		105 CMR 451.200	Protection of Clean Items, Storing: Pans not stored in a self-draining position, pans stacked wet. Standard found in 105 CMR 590; FC 4-903.11(B)(1).
14. Kitchen	Handwash Sink		105 CMR 451.126*	Hot Water for Bathing and Hygiene: Hot water temperature 140°F at handwash sink
15. Modular Units	Old Dining Area/Case Worker's Area	Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty

16. Modular Units	Culinary Arts Kitchen	Dishwashing Machine	105 CMR 451.200	Numbers and Capacities, Utensils, Temperature Measuring Devices, and Testing Devices: No irreversible registering temperature measuring device readily accessible to measure the surface temperature of the utensil (Pf). Standard found in 105 CMR 590; FC 4-302.13(B).
-------------------	-----------------------	---------------------	-----------------	--

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Administration	Lobby Control Area		105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged
2. Special Management Unit	A Block	Cells	105 CMR 451.353	Interior Maintenance: Floor damaged in cell # J12
3. Housing Units	Unit – 5	Cells	105 CMR 451.353	Interior Maintenance: Floor coving damaged in cell # C41
4. Laundry			105 CMR 451.353	Interior Maintenance: Dryer # 1 out-of-order

SECTION 2: Areas Found to be in Compliance

EHRS inspected 205 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 16 areas of the facility because they were either in use, locked, or under construction.

1. Administration	Male Staff Locker Area		Unable to Inspect – In Use
2. Special Management Unit	A Block	Cells	Unable to Inspect – Cell # J1 out-of-order
3. Special Management Unit	A Block	Cells	Unable to Inspect – Cell # J7 out-of-order
4. Special Management Unit	A Block	Storage Closet (upper)	Unable to Inspect – Not in Use
5. Special Management Unit	B Block	Storage Closet (upper)	Unable to Inspect – Not in Use
6. Housing Units	Unit – 1	Shower	Unable to Inspect – In Use
7. Housing Units	Unit – 3	Storage Closet (upper)	Unable to Inspect – Locked
8. Housing Units	Unit – 4	Storage Closet (upper)	Unable to Inspect – Locked
9. Housing Units	Unit – 5	Storage Closet (upper)	Unable to Inspect – Not in Use
10. Housing Units	Unit – 6	Storage Closet (upper)	Unable to Inspect – Not in Use
11. Main Building Gym	Female Staff Locker Room		Unable to Inspect – Locked
12. Main Building Gym	Bathroom (located within Female Staff Locker Room)		Unable to Inspect – Locked
13. Modular Units	Old Dining Area/Case Worker's Area	Dental Office	Unable to Inspect – Locked
14. Modular Units	Old Dining Area/Case Worker's Area	Office # 52	Unable to Inspect – Locked
15. Modular Units	South Housing Unit		Unable to Inspect – Not in Use

SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 129 at the time of inspection.
2. Housing Unit 2 was being used as the quarantine unit and was not inspected.
3. Housing Unit 4 was unoccupied at the time of the inspection.
4. At the time of inspection, the EHRS recommended numbering all showers throughout the institution. This will assist the EHRS and County Sheriff's employees to better recognize where issues exist.
5. Hot water temperature range for handwash sinks is 110°F - 130°F.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#) available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Thomas Murphy
Environmental Analyst, EHRS, BCEH



THE COMMONWEALTH OF MASSACHUSETTS

Hampshire Sheriff's Office Jail & House of Correction

P.O. Box 7000
205 Rocky Hill Road
Northampton, Massachusetts 01061-7000



Sheriff

PATRICK J. CAHILLANE

Superintendent

GLEN N. SEXTON

TELEPHONE

(413) 584-5911

FAX

(413)-584-2695

October 14th, 2025


Mr. Thomas Murphy
Environmental Analyst, CSP, BEH
Commonwealth of Massachusetts
Executive Office Health & Human Services
Department of Public Health
Bureau of Environmental Health
Community Sanitation Program
23 Service Center Road
Northampton, MA 01060

Re: Hampshire County Jail & HOC Inspection dated October 10th, 2025

Dear Mr. Murphy,

At your request the following items have been addressed, please refer to the enclosed documentation for the corrective actions that have been taken.

Sincerely yours,


Patrick J. Cahillane
Sheriff

SECTION 1: Health and Safety Deficiencies

Deficiencies under the Required Standards (.100 and .200 series)

12 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Special Management Unit	B Block	Lower Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged in Shower <u>Awaiting approval from DCAM for repairs to the shower floors, anticipation that moneys will be appropriated in fiscal year 2026</u>
2.	Housing Units	Unit – 3	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C14 <u>Mattress replaced as of 10/14/25</u>
3.	Housing Units	Unit – 5	Cells	105 CMR 451.103	Mattresses: Mattress damaged in cell # C38 <u>Mattress replaced as of 10/14/25</u>
4.	Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Soap scum on walls in Shower <u>Staff and inmates retrained on proper maintenance of showers</u>
5.	Housing Units	Unit – 5	Lower Shower	105 CMR 451.123*	Maintenance: Floor epoxy damaged in Shower <u>Awaiting approval from DCAM for repairs to the shower floors, anticipation that moneys will be appropriated in fiscal year 2026</u>
6.	Housing Units	Unit – 5	Lower Shower	105 CMR 451.123	Maintenance: Mold observed on ceiling in shower <u>Maintenance staff will paint shower ceiling to be painted by 11/14/25</u>
7.	Housing Units	Unit - 5	Upper Shower	105 CMR 451.123*	Maintenance: Floor paint damaged in Shower <u>Awaiting approval from DCAM for repairs to the shower floors, anticipation that moneys will be appropriated in fiscal year 2026</u>
8.	Housing Units	Unit - 6	Upper Shower	105 CMR 451.123	Maintenance: Ceiling damaged in shower <u>Maintenance staff will repair shower ceiling by 11/14/25</u>
9.	Housing Units	Unit – 7	Upper Shower	105 CMR 451.123	Maintenance: Floor epoxy damaged in Shower <u>Awaiting approval from DCAM for repairs to the shower floors, anticipation that moneys will be appropriated in fiscal year 2026</u>
10.	Kitchen	Walk-in Freezer # 1		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B). <u>Requesting quotes from outside bidder to replace walk-in-freezer #1, expected replacement within six months</u>


11. Kitchen	Dishwashing Area		105 CMR 451.200	Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Wet cloth not stored in sanitizer solution. Standard found in 105 CMR 590; FC 3-304.14(B)(1). ** Corrected On-Site ** <u>Inmates retrained on wet cloth storage</u>
12. Kitchen	Walk-in Cooler # 2		105 CMR 451.200	Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, gaskets dirty. Standard found in 105 CMR 590; FC 4-601.11(C). <u>Requesting quotes from outside bidder to replace walk-in-cooler #2, expected replacement within six months</u>
13. Kitchen	Pot Room		105 CMR 451.200	Protection of Clean Items, Storing: Pans not stored in a self-draining position, pans stacked wet. Standard found in 105 CMR 590; FC 4-903.11(B)(1). <u>Staff and inmates retrained on proper storage of pans.</u>
14. Kitchen	Handwash Sink		105 CMR 451.126*	Hot Water for Bathing and Hygiene: Hot water temperature 140°F at handwash sink <u>Maintenance staff to adjust water temperature 10/14/25</u>
15. Modular Units	Old Dining Area/Case Worker's Area	Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty <u>Vent cleaned 10/14/25</u>
16. Modular Units	Culinary Arts Kitchen	Dishwashing Machine	105 CMR 451.200	Numbers and Capacities, Utensils, Temperature Measuring Devices, and Testing Devices: No irreversible registering temperature measuring device readily accessible to measure the surface temperature of the utensil (Pf). Standard found in 105 CMR 590; FC 4-302.13(B). <u>Temperature measuring device ordered as of 10-14-25 for use in the culinary arts kitchen</u>

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Administration	Lobby Control Area		105 CMR 451.353*	Interior Maintenance: Ceiling tiles water Damaged <u>Ceiling tiles to be replace by 11/14/25</u>
2. Special Management Unit	A Block	Cells	105 CMR 451.353	Interior Maintenance: Floor damaged in cell # J12 <u>Request for services submitted and tiles to be replaced by 12-11-25</u>

3. Housing Units	Unit – 5	Cells	105 CMR 451.353	Interior Maintenance: Floor coving damaged in cell # C41 <u>Molding in cell to be fixed by 12-11-25</u>
4. Laundry			105 CMR 451.353	Interior Maintenance: Dryer # 1 out-of-order <u>Request for service was placed before DPH inspection control board parts were ordered and waiting for deliverer , expected repair date 11-11-25</u>



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

October 17, 2025

Patrick J. Cahillane, Sheriff
Hampshire County Jail and House of Correction
205 Rocky Hill Road
Northampton, MA 01060 (electronic copy)

Re: Plan of Correction - Hampshire County Jail and House of Correction, Northampton

Dear Sheriff Cahillane:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction in response to an inspection on October 8, 2025. After review, the EHRS finds the plan addresses all the deficiencies noted with the following exception:

1. Your Plan of Correction (POC) does not provide a date of completion for shower repair work which requires DCAMM funding. While the EHRS understands you do not have control over DCAMM's allotment of funds, we cannot approve any item that does not identify a reasonable time frame for repair. The EHRS remains concerned with the uncorrected deficiencies and asks you to provide a plan describing the interim measures you have implemented to ensure the health and safety of inmates and staff. In addition, we ask to be kept apprised of the DCAMM funding progress.


Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

Thomas Murphy
Environmental Analyst, EHRS, BCEH

cc: Glenn Sexton, Superintendent
Lieutenant Jason Graham, Compliance Officer

(electronic copy)
(electronic copy)



THE COMMONWEALTH OF MASSACHUSETTS

Hampshire Sheriff's Office Jail & House of Correction

P.O. Box 7000
205 Rocky Hill Road
Northampton, Massachusetts 01061-7000



Sheriff

PATRICK J. CAHILLANE

Superintendent

GLEN N. SEXTON

TELEPHONE

(413) 584-5911

FAX

(413)-584-2695

October 20th, 2025

Mr. Thomas Murphy
Environmental Analyst, CSP, BEH
Commonwealth of Massachusetts
Executive Office Health & Human Services
Department of Public Health
Bureau of Environmental Health
Community Sanitation Program
23 Service Center Road
Northampton, MA 01060

Re: Hampshire County Jail & HOC Inspection dated October 10th, 2025

Dear Mr. Murphy,

I am writing to update you on the ongoing efforts concerning the conditions of the showers in our facility. While we currently await the issuance of funds from DCAMM, the Hampshire Sheriff's Office maintenance department has been actively working to improve the conditions in the identified units.


As part of our proactive approach, we are in the process of epoxy coating the shower floors on a rotating basis in the affected units. This is an interim measure that aims to enhance safety and usability until the allocated DCAMM funds allow us to undertake more comprehensive renovations.

We anticipate that funds will be available to complete these projects by July of 2026, and we are committed to ensuring that all necessary improvements are made to maintain a safe and healthy environment for our patrons.

Thank you for your continued support and understanding as we work to resolve these issues. Should you have any questions or need further information, please feel free to reach out.

Sincerely yours,

Handwritten signature of Patrick J. Cahillane in cursive script.
Patrick J. Cahillane
Sheriff



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
67 Forest Street, Suite # 100
Marlborough, MA 01752
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

October 20, 2025

Patrick J. Cahillane, Sheriff
Hampshire County Jail and House of Correction
205 Rocky Hill Road
Northampton, MA 01060 (electronic copy)

Re: Plan of Correction - Hampshire County Jail and House of Correction, Northampton

Dear Sheriff Cahillane:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction dated October 20, 2025. After review, the EHRS finds the plan addresses all the deficiencies noted.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A handwritten signature in blue ink, appearing to read "Thomas Murphy".

Thomas Murphy
Environmental Analyst, EHRS, BCEH

cc: Glenn Sexton, Superintendent
Lieutenant Jason Graham, Compliance Officer

(electronic copy)
(electronic copy)