

UNIFORM TRAFFIC CRASH REPORT
Form eCrash (2024)Report #
AL-2026-411385
Complexity: HIGH

A. CRASH SCENE INFORMATION

Date of Crash	05/19/2026	Time	19:00 hrs	Day of Week	Tuesday
County / Parish	Madison	City / Town	Riverside	Reporting Agency Case #	AL-20260519-4931
Crash Location (Route/ Road)	Route 132 S (Interstate)	At Intersection With / Mile Marker	132.6	Latitude / Longitude	29.94769, -101.28037
Weather	Rain	Light Conditions	Dark - Lighted	Road Surface	Wet
Road Alignment	Curve & Grade	Traffic Control	No Controls	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2019	Make	Peterbilt	Model	379
Color	Red	License Plate	VBC8234	Plate State / Year	AL / 2026
VIN	64CJWG0CE8CT72UFV	Owner	Andrew Lee (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	Farmers Insurance Exchange	Policy #	FA-286545524	Damage Severity	Functional
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Andrew Lee	DOB	09/06/1972	Age / Sex	53 / M
Address	9807 Highland Hwy	City/State/Zip	Clinton, AL 68714	Phone	(848) 494-6234
DL #	AL76337052	DL State	AL	DL Class	CDL-A
Restraint Used	None Used	Airbag	Not Deployed	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: VC 21703 - Following Too Closely

C. UNIT / VEHICLE #2

Vehicle Details

Year	2023	Make	Ford	Model	Transit
Color	Green	License Plate	JBC1234	Plate State / Year	AL / 2026
VIN	TN0030P4R133JTRZD	Owner	Paul Thomas	Towed?	Yes - to Sec. Towing
Insurance Company	American Family Mutual Ins	Policy #	AM-126577337	Damage Severity	Minor
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Paul Thomas	DOB	07/21/1989	Age / Sex	36 / M
Address	2145 Market Dr	City/State/Zip	Springfield, AL 99463	Phone	(238) 667-4662
DL #	AL13119158	DL State	AL	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Not Deployed	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Madison Regional Medical Center	EMS Run #	EMS-1443

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Donald Evans	08/01/1947	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Madison Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2022	Make	Mercedes-Benz	Model	GLE
Color	Brown	License Plate	WBC8234	Plate State / Year	AL / 2026
VIN	5CWHGX5XPY99PEM2P	Owner	Nicholas Reyes	Towed?	No
Insurance Company	Travelers Indemnity Company	Policy #	TR-646910285	Damage Severity	Functional
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Nicholas Reyes	DOB	03/30/1981	Age / Sex	45 / M
Address	1469 Lincoln Rd	City/State/Zip	Franklin, AL 83318	Phone	(568) 234-5606
DL #	AL64502184	DL State	AL	DL Class	Class D
Restraint Used	None Used	Airbag	Not Deployed	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-3047

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 05/19/2026 at approximately 19:00 hrs, in rain conditions with wet roadway, Unit 1 (commercial: 2019 Peterbilt 379, operated by Andrew Lee) was traveling on I-393 S (Interstate) approaching Mile Marker 132.6. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2023 Ford Transit, driven by Paul Thomas), propelling Unit 2 into Unit 3 (2022 Mercedes-Benz GLE, operated by Nicholas Reyes). Driver of Unit 2 sustained suspected serious injury and was transported to Madison Regional Medical Center via EMS-1443. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-393 S (Interstate) at Mile Marker 132.6. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses

#	Name	Address	Phone	Statement Summary		
1	Angela Martin	1841 Spring Way, Bristol, AL	(240) 932-3549	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 60-65 mph.		
2	Jason Nelson	8041 Spring Rd, Springfield, AL	(376) 453-2406	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.		
Investigating Officer		Lisa Scott	Badge #	7278	Agency	Alabama Law Enforcement Agency
Reviewing Supervisor		Joseph Ortiz	Badge #	7341	Date Approved	05/21/2026
Report Status		Approved / Final	Date Filed (RMV/SAF)	05/24/2026	Distribution	Driver(s), Insurer(s), State Records