

A. CRASH SCENE INFORMATION

Date of Crash	03/22/2026	Time	20:45 hrs	Day of Week	Sunday
County / Parish	Washington	City / Town	Springfield	Reporting Agency Case #	AZ-20260322-9366
Crash Location (Route/Highway)	Route 100S (Interstate)	At Intersection With / Mile Marker	MI 100 / Mile Marker 72.1	Latitude / Longitude	46.54018, -108.61290
Weather	Rain	Light Conditions	Dark - Lighted	Road Surface	Wet
Road Alignment	Straight & Grade	Traffic Control	Traffic Signal	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2020	Make	Volvo Trucks	Model	VHD
Color	Brown	License Plate	TBC1234	Plate State / Year	AZ / 2026
VIN	70W97WT6GYW33LU9M	Owner	Angela Watson (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	American Family Mutual Ins	Policy #	AM-182518007	Damage Severity	Disabling
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Angela Watson	DOB	09/25/1996	Age / Sex	29 / F
Address	148 Main Ter	City/State/Zip	Georgetown, AZ 18056	Phone	(591) 781-3848
DL #	AZ83230082	DL State	AZ	DL Class	CDL-A
Restraint Used	None Used	Airbag	Deployed - Front	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: PL 1180(b) - Speed Not Reasonable & Prudent

C. UNIT / VEHICLE #2

Vehicle Details

Year	2020	Make	Tesla	Model	Model Y
Color	Gray	License Plate	JBC1234	Plate State / Year	AZ / 2026
VIN	B09W5PDF9RZFNM7XD	Owner	Deborah Howard	Towed?	Yes - to Sec. Towing
Insurance Company	Travelers Indemnity Company	Policy #	TR-827373167	Damage Severity	Minor
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Deborah Howard	DOB	10/29/1975	Age / Sex	50 / F
Address	5664 Sunset Ln	City/State/Zip	Madison, AZ 63478	Phone	(293) 702-1588
DL #	AZ31286457	DL State	AZ	DL Class	Class D
Restraint Used	None Used	Airbag	Not Deployed	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Washington Regional Medical Center	EMS Run #	EMS-9516

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Donald Cooper	09/28/1969	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Washington Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2023	Make	Mazda	Model	Mazda6
Color	Red	License Plate	CBC0234	Plate State / Year	AZ / 2026
VIN	VDR3GMGBT95KZZ2YL	Owner	Patricia Hernandez	Towed?	No
Insurance Company	Progressive Casualty Ins.	Policy #	PR-270635386	Damage Severity	Minor
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Patricia Hernandez	DOB	05/10/1997	Age / Sex	29 / F
Address	74 Lake Ct	City/State/Zip	Madison, AZ 68228	Phone	(713) 721-9037
DL #	AZ30457185	DL State	AZ	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Deployed - Front	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-4264

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 03/22/2026 at approximately 20:45 hrs, in rain conditions with wet roadway, Unit 1 (commercial: 2020 Volvo Trucks VHD, operated by Angela Watson) was traveling on I-343 S (Interstate) approaching Mile Marker 72.1. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2020 Tesla Model Y, driven by Deborah Howard), propelling Unit 2 into Unit 3 (2023 Mazda Mazda6, operated by Patricia Hernandez). Driver of Unit 2 sustained suspected serious injury and was transported to Washington Regional Medical Center via EMS-9516. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-343 S (Interstate) at Mile Marker 72.1. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses

#	Name	Address	Phone	Statement Summary		
1	Justin Ward	5225 Elm Pkwy, Greenville, AZ	(399) 416-7356	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 60-65 mph.		
2	Amanda Gonzalez	1092 Highland Ter, Bristol, AZ	(230) 527-9767	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.		
Investigating Officer		Joshua Gomez	Badge #	7736	Agency	Arizona Department of Public Safety
Reviewing Supervisor		Steven Morgan	Badge #	8535	Date Approved	03/24/2026
Report Status		Approved / Final	Date Filed (RMV)	03/27/2026	Distribution	Driver(s), Insurer(s), State Records