

TRAFFIC COLLISION REPORT
Form CHP 555 Page 1 (Rev. 7-22) OPI
062

Report #
CA-2026-424102
Complexity: MEDIUM

A. CRASH SCENE INFORMATION

Date of Crash	02/05/2026	Time	08:20 hrs	Day of Week	Thursday
County / Parish	Los Angeles	City / Town	Los Angeles	Reporting Agency Case #	CA-20260205-7233
Crash Location (Route / Road)	US-46 N	At Intersection With / Major Road	Washington Pkwy	Latitude / Longitude	29.89760, -119.01058
Weather	Clear	Light Conditions	Daylight	Road Surface	Dry
Road Alignment	Straight & Level	Traffic Control	Stop Sign	Direction of Crash	Same Direction (Rear End)
# Vehicles Involved	2	# Injured	0	# Fatalities	0

B. UNIT / VEHICLE #1

Vehicle Details

Year	2021	Make	BMW	Model	3 Series
Color	White	License Plate	BBC0234	Plate State / Year	CA / 2026
VIN	N5TGYKNFEFLH8SHYW	Owner	Matthew Scott (same as driver)	Towed?	No
Insurance Company	GEICO Indemnity Company	Policy #	GE-832777579	Damage Severity	Minor
Areas of Damage	Front	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Matthew Scott	DOB	09/05/1959	Age / Sex	66 / M
Address	6647 Washington Ln	City/State/Zip	Sacramento, CA 28091	Phone	(449) 577-1814
DL #	CA69267313	DL State	CA	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Front	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [16] Backing Unsafely

C. UNIT / VEHICLE #2

Vehicle Details

Year	2020	Make	Ram	Model	ProMaster
Color	Gray	License Plate	DBC2234	Plate State / Year	CA / 2026
VIN	AKTH5J92SKMU5WF5U	Owner	Jessica Mitchell	Towed?	No
Insurance Company	Allstate Insurance Company	Policy #	AL-449313366	Damage Severity	Minor
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Jessica Mitchell	DOB	02/26/1996	Age / Sex	30 / M
Address	5213 Washington Pkwy	City/State/Zip	Fresno, CA 35315	Phone	(843) 470-2493
DL #	CA28366338	DL State	CA	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Side	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 02/05/2026 at approximately 08:20 hrs, Unit 1 (2021 BMW 3 Series) was traveling on US-466 N approaching Washington Pkwy. Unit 2 (2020 Ram ProMaster) was stopped in the same lane awaiting a green light. Driver of Unit 1 failed to maintain safe following distance and struck the rear of Unit 2. No injuries reported. Both drivers exchanged information. Roadway dry, weather clear, daylight conditions. Property damage only. No citations issued at scene; driver of Unit 1 advised of contributing factor.

Diagram Description: Two-vehicle rear-end at signalized intersection. V1 northbound, V2 stopped at signal. Impact: V1 front to V2 rear.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Investigating Officer	Daniel Cook	Badge #	3801	Agency	California Highway Patrol
Reviewing Supervisor	Cynthia Hill	Badge #	6303	Date Approved	02/06/2026
Report Status	Approved / Final	Date Filed (RMV/CPD)	02/06/2026	Distribution	Driver(s), Insurer(s), State Records