

A. CRASH SCENE INFORMATION

Date of Crash	02/22/2026	Time	19:50 hrs	Day of Week	Sunday
County / Parish	Franklin	City / Town	Madison	Reporting Agency Case #	CO-20260222-7990
Crash Location (Route/County)	231 W (Interstate)	At Intersection With / Mile Marker	Mill/Marker 23.0	Latitude / Longitude	35.83204, -113.07141
Weather	Rain	Light Conditions	Dusk	Road Surface	Wet
Road Alignment	Curve & Grade	Traffic Control	Traffic Signal	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2015	Make	Volvo Trucks	Model	VNL 760
Color	Black	License Plate	CBC3234	Plate State / Year	CO / 2026
VIN	YAS9VX66TAG0R0F11	Owner	Patricia Garcia (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	Nationwide Mutual Insurance	Policy #	NW-240930095	Damage Severity	Disabling
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Patricia Garcia	DOB	03/15/1976	Age / Sex	50 / M
Address	3230 Mill Ct	City/State/Zip	Madison, CO 43925	Phone	(633) 315-4390
DL #	CO55756803	DL State	CO	DL Class	CDL-A
Restraint Used	Lap Belt Only	Airbag	Deployed - Front	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: MGL 90 §17 - Speeding

C. UNIT / VEHICLE #2

Vehicle Details

Year	2020	Make	GMC	Model	Acadia
Color	Blue	License Plate	JBC5234	Plate State / Year	CO / 2026
VIN	GY048V16P10PZEU61	Owner	Ronald Edwards	Towed?	Yes - to Sec. Towing
Insurance Company	Liberty Mutual Insurance	Policy #	LM-570284520	Damage Severity	Functional
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Ronald Edwards	DOB	08/26/1982	Age / Sex	43 / F
Address	4424 Birch Ln	City/State/Zip	Riverside, CO 91323	Phone	(863) 697-4087
DL #	CO66650767	DL State	CO	DL Class	Class D
Restraint Used	Lap Belt Only	Airbag	Not Deployed	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Franklin Regional Medical Center	EMS Run #	EMS-1847

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Michelle Hall	04/27/1971	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Franklin Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2021	Make	Subaru	Model	Impreza
Color	Green	License Plate	WBC7234	Plate State / Year	CO / 2026
VIN	LOFPVXJT55EP7ZALF	Owner	Paul Gonzalez	Towed?	No
Insurance Company	Travelers Indemnity Company	Policy #	TR-206955082	Damage Severity	Functional
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Paul Gonzalez	DOB	12/24/1963	Age / Sex	62 / F
Address	1991 Walnut Blvd	City/State/Zip	Madison, CO 47287	Phone	(560) 869-5564
DL #	CO84770027	DL State	CO	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Deployed - Front	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-6076

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 02/22/2026 at approximately 19:50 hrs, in rain conditions with wet roadway, Unit 1 (commercial: 2015 Volvo Trucks VNL 760, operated by Patricia Garcia) was traveling on I-231 W (Interstate) approaching Mile Marker 23.0. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2020 GMC Acadia, driven by Ronald Edwards), propelling Unit 2 into Unit 3 (2021 Subaru Impreza, operated by Paul Gonzalez). Driver of Unit 2 sustained suspected serious injury and was transported to Franklin Regional Medical Center via EMS-1847. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-231 W (Interstate) at Mile Marker 23.0. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.
[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses

#	Name	Address	Phone	Statement Summary		
1	Steven Lee	8422 Park Way, Greenville, CO	(578) 835-5011	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 60 mph.		
2	Stephanie Reed	6290 Highland Rd, Greenville, CO	(220) 496-8074	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.		
Investigating Officer		Justin Williams	Badge #	2688	Agency	Colorado State Patrol
Reviewing Supervisor		Eric Morris	Badge #	6815	Date Approved	02/24/2026
Report Status		Approved / Final	Date Filed (RMV)	02/27/2026	Distribution	Driver(s), Insurer(s), State Records