

A. CRASH SCENE INFORMATION

Date of Crash	04/25/2026	Time	09:55 hrs	Day of Week	Saturday
County / Parish	Washington	City / Town	Springfield	Reporting Agency Case #	IN-20260425-5123
Crash Location (Route / Road)	I-114 N	At Intersection With / Monument	Church Ter	Latitude / Longitude	30.21275, -105.34534
Weather	Clear	Light Conditions	Daylight	Road Surface	Dry
Road Alignment	Straight & Level	Traffic Control	Stop Sign	Direction of Crash	Same Direction (Rear End)
# Vehicles Involved	2	# Injured	0	# Fatalities	0

B. UNIT / VEHICLE #1

Vehicle Details

Year	2022	Make	Toyota	Model	Tundra
Color	Beige	License Plate	HBC3234	Plate State / Year	IN / 2026
VIN	SVB7EJ6K724XEYWE7	Owner	Ashley Nelson (same as driver)	Towed?	No
Insurance Company	Allstate Insurance Company	Policy #	AL-716872346	Damage Severity	Minor
Areas of Damage	Front	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Ashley Nelson	DOB	11/26/1989	Age / Sex	36 / F
Address	7483 Locust Ln	City/State/Zip	Franklin, IN 95019	Phone	(550) 586-4935
DL #	IN80823783	DL State	IN	DL Class	Class D
Restraint Used	Lap Belt Only	Airbag	Deployed - Side	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [15] Inattention

C. UNIT / VEHICLE #2

Vehicle Details

Year	2025	Make	Tesla	Model	Model Y
Color	Silver	License Plate	SBC2234	Plate State / Year	IN / 2026
VIN	JGXEZL7X4UBL43PDA	Owner	Joseph Walker	Towed?	No
Insurance Company	American Family Mutual Ins	Policy #	AM-191491997	Damage Severity	Disabling
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Joseph Walker	DOB	03/25/1969	Age / Sex	57 / M
Address	5143 River Dr	City/State/Zip	Bristol, IN 66421	Phone	(411) 565-6261
DL #	IN64717727	DL State	IN	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Side	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 04/25/2026 at approximately 09:55 hrs, Unit 1 (2022 Toyota Tundra) was traveling on I-114 N approaching Church Ter. Unit 2 (2025 Tesla Model Y) was stopped in the same lane awaiting a green light. Driver of Unit 1 failed to maintain safe following distance and struck the rear of Unit 2. No injuries reported. Both drivers exchanged information. Roadway dry, weather clear, daylight conditions. Property damage only. No citations issued at scene; driver of Unit 1 advised of contributing factor.

Diagram Description: Two-vehicle rear-end at signalized intersection. V1 northbound, V2 stopped at signal. Impact: V1 front to V2 rear.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Investigating Officer	Timothy Nelson	Badge #	3533	Agency	Indiana State Police
Reviewing Supervisor	Jeffrey Parker	Badge #	5166	Date Approved	04/26/2026
Report Status	Approved / Final	Date Filed (RMV)	04/26/2026	Distribution	Driver(s), Insurer(s), State Records