

A. CRASH SCENE INFORMATION

Date of Crash	04/14/2026	Time	17:55 hrs	Day of Week	Tuesday
County / Parish	Madison	City / Town	Riverside	Reporting Agency Case #	MI-20260414-5530
Crash Location (Route/County)	R452E (Interstate)	At Intersection With / Mile Marker	MI-100 / 33.9	Latitude / Longitude	28.02788, -98.38285
Weather	Rain	Light Conditions	Dark - Lighted	Road Surface	Wet
Road Alignment	Curve & Grade	Traffic Control	Traffic Signal	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2023	Make	Peterbilt	Model	389
Color	Green	License Plate	JBC6234	Plate State / Year	MI / 2026
VIN	X0N4G13ZLL1XH4Z94	Owner	Andrew Cox (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	State Farm Mutual Auto Ins.	Policy #	SF-285989248	Damage Severity	Disabling
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Andrew Cox	DOB	12/01/1974	Age / Sex	51 / F
Address	3647 Madison Dr	City/State/Zip	Springfield, MI 27328	Phone	(725) 476-8908
DL #	MI88141065	DL State	MI	DL Class	CDL-A
Restraint Used	Lap & Shoulder Belt	Airbag	Not Deployed	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: VC 21703 - Following Too Closely

C. UNIT / VEHICLE #2

Vehicle Details

Year	2019	Make	GMC	Model	Yukon
Color	Green	License Plate	UBC4234	Plate State / Year	MI / 2026
VIN	KRNM25WL32HWS033B	Owner	Cynthia Torres	Towed?	Yes - to Sec. Towing
Insurance Company	State Farm Mutual Auto Ins.	Policy #	SF-838665062	Damage Severity	Minor
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Cynthia Torres	DOB	11/23/1992	Age / Sex	33 / M
Address	8308 Main St	City/State/Zip	Madison, MI 74592	Phone	(790) 792-1502
DL #	MI97134696	DL State	MI	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Not Deployed	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Madison Regional Medical Center	EMS Run #	EMS-6823

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Justin Morris	09/10/2011	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Madison Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2025	Make	Hyundai	Model	Kona
Color	Gray	License Plate	TBC8234	Plate State / Year	MI / 2026
VIN	NX548Z8H7AVE1G8XA	Owner	Nancy Cox	Towed?	No
Insurance Company	Nationwide Mutual Insurance	Policy #	NW-635581068	Damage Severity	Functional
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Nancy Cox	DOB	01/11/1967	Age / Sex	59 / F
Address	6351 Broadway Hwy	City/State/Zip	Greenville, MI 72490	Phone	(212) 201-2826
DL #	MI31451575	DL State	MI	DL Class	Class D
Restraint Used	Lap Belt Only	Airbag	Not Deployed	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-6137

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 04/14/2026 at approximately 17:55 hrs, in rain conditions with wet roadway, Unit 1 (commercial: 2023 Peterbilt 389, operated by Andrew Cox) was traveling on I-452 E (Interstate) approaching Mile Marker 33.9. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2019 GMC Yukon, driven by Cynthia Torres), propelling Unit 2 into Unit 3 (2025 Hyundai Kona, operated by Nancy Cox). Driver of Unit 2 sustained suspected serious injury and was transported to Madison Regional Medical Center via EMS-6823. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-452 E (Interstate) at Mile Marker 33.9. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses

#	Name	Address	Phone	Statement Summary		
1	Ronald Taylor	4509 Highland Rd, Clinton, MI	(834) 387-7125	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 40-45 mph.		
2	Nancy Campbell	3112 Jefferson St, Madison, MI	(862) 917-7948	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.		
Investigating Officer		Stephanie Jackson	Badge #	5841	Agency	Michigan State Police
Reviewing Supervisor		Richard Rivera	Badge #	9614	Date Approved	04/16/2026
Report Status		Approved / Final	Date Filed (RMV/State)	04/16/2026	Distribution	Driver(s), Insurer(s), State Records