

A. CRASH SCENE INFORMATION

Date of Crash	03/12/2026	Time	09:00 hrs	Day of Week	Thursday
County / Parish	Jefferson	City / Town	Madison	Reporting Agency Case #	MI-20260312-8820
Crash Location (Route/Street)	SR-112 N	At Intersection With / Mile Marker	Lake Dr	Latitude / Longitude	26.05205, -113.94519
Weather	Clear	Light Conditions	Daylight	Road Surface	Dry
Road Alignment	Straight & Level	Traffic Control	No Controls	Direction of Crash	Same Direction (Rear End)
# Vehicles Involved	2	# Injured	0	# Fatalities	0

B. UNIT / VEHICLE #1

Vehicle Details

Year	2021	Make	BMW	Model	X3
Color	Green	License Plate	FBC2234	Plate State / Year	MI / 2026
VIN	G60TP24JF78PG6B9T	Owner	Michael Peterson (same as driver)	Towed?	No
Insurance Company	Progressive Casualty Ins. Co.	Policy #	PR-465459612	Damage Severity	Disabling
Areas of Damage	Front	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Michael Peterson	DOB	01/13/2008	Age / Sex	18 / F
Address	7750 Valley Way	City/State/Zip	Bristol, MI 24198	Phone	(617) 858-9905
DL #	MI63765554	DL State	MI	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Front	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [15] Inattention

C. UNIT / VEHICLE #2

Vehicle Details

Year	2024	Make	Honda	Model	Pilot
Color	Green	License Plate	FBC5234	Plate State / Year	MI / 2026
VIN	WRBCKAXAFE94VM7NN	Owner	Shirley Robinson	Towed?	No
Insurance Company	Allstate Insurance Company	Policy #	AL-126311926	Damage Severity	Minor
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Shirley Robinson	DOB	07/30/1985	Age / Sex	40 / F
Address	1877 River Pkwy	City/State/Zip	Franklin, MI 36715	Phone	(536) 670-2573
DL #	MI17187049	DL State	MI	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Side	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 03/12/2026 at approximately 09:00 hrs, Unit 1 (2021 BMW X3) was traveling on SR-112 N approaching Lake Dr. Unit 2 (2024 Honda Pilot) was stopped in the same lane awaiting a green light. Driver of Unit 1 failed to maintain safe following distance and struck the rear of Unit 2. No injuries reported. Both drivers exchanged information. Roadway dry, weather clear, daylight conditions. Property damage only. No citations issued at scene; driver of Unit 1 advised of contributing factor.

Diagram Description: Two-vehicle rear-end at signalized intersection. V1 northbound, V2 stopped at signal. Impact: V1 front to V2 rear.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Investigating Officer	Nicole Campbell	Badge #	4009	Agency	Michigan State Police
Reviewing Supervisor	Elizabeth Wilson	Badge #	1875	Date Approved	03/13/2026
Report Status	Approved / Final	Date Filed (RMV/State)	03/15/2026	Distribution	Driver(s), Insurer(s), State Records