

A. CRASH SCENE INFORMATION

Date of Crash	02/06/2026	Time	22:00 hrs	Day of Week	Friday
County / Parish	Washington	City / Town	Madison	Reporting Agency Case #	MO-20260206-4508
Crash Location (Route/Highway)	Route 5 (Interstate)	At Intersection With / Mile Marker	MoDOT 202.1	Latitude / Longitude	38.84839, -100.82494
Weather	Rain	Light Conditions	Dark - Lighted	Road Surface	Wet
Road Alignment	Curve & Level	Traffic Control	Traffic Signal	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2019	Make	Peterbilt	Model	389
Color	Silver	License Plate	PBC1234	Plate State / Year	MO / 2026
VIN	H2BD3CJFK58745MM7	Owner	Jeffrey Brown (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	Liberty Mutual Insurance	Policy #	LM-842225588	Damage Severity	Minor
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Jeffrey Brown	DOB	08/25/1984	Age / Sex	41 / F
Address	6989 Sunset Rd	City/State/Zip	Springfield, MO 66134	Phone	(251) 535-1423
DL #	MO28621030	DL State	MO	DL Class	CDL-A
Restraint Used	Lap & Shoulder Belt	Airbag	Deployed - Front	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: VC 22350 - Unsafe Speed for Conditions

C. UNIT / VEHICLE #2

Vehicle Details

Year	2019	Make	Nissan	Model	Versa
Color	Brown	License Plate	FBC7234	Plate State / Year	MO / 2026
VIN	FKC4CSW4MDWNUNTB1	Owner	Deborah Scott	Towed?	Yes - to Sec. Towing
Insurance Company	Allstate Insurance Company	Policy #	AL-566091126	Damage Severity	Functional
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Deborah Scott	DOB	02/21/1978	Age / Sex	48 / F
Address	2347 Main Dr	City/State/Zip	Bristol, MO 49159	Phone	(567) 716-6619
DL #	MO67529632	DL State	MO	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Side	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Washington Regional Medical Center	EMS Run #	EMS-3346

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Jacob Ramos	06/18/1985	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Washington Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2020	Make	Subaru	Model	Outback
Color	Beige	License Plate	FBC8234	Plate State / Year	MO / 2026
VIN	VXWNVENS1JN164GF	Owner	James Taylor	Towed?	No
Insurance Company	State Farm Mutual Auto Ins.	Policy #	SF-147373347	Damage Severity	Minor
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	James Taylor	DOB	05/16/2000	Age / Sex	26 / F
Address	3700 Cedar Ter	City/State/Zip	Clinton, MO 51112	Phone	(205) 226-6982
DL #	MO49343223	DL State	MO	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Front	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-6751

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 02/06/2026 at approximately 22:00 hrs, in rain conditions with wet roadway, Unit 1 (commercial: 2019 Peterbilt 389, operated by Jeffrey Brown) was traveling on I-95 S (Interstate) approaching Mile Marker 202.1. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2019 Nissan Versa, driven by Deborah Scott), propelling Unit 2 into Unit 3 (2020 Subaru Outback, operated by James Taylor). Driver of Unit 2 sustained suspected serious injury and was transported to Washington Regional Medical Center via EMS-3346. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-95 S (Interstate) at Mile Marker 202.1. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.
[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses

#	Name	Address	Phone	Statement Summary	
1	Kevin Phillips	2529 Church Hwy, Riverside, MO	(738) 321-7107	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 60-65 mph.	
2	Amy Anderson	8476 Jefferson Ct, Greenville, MO	(604) 509-7119	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.	
Investigating Officer	Matthew White	Badge #	4987	Agency	Missouri State Highway Patrol
Reviewing Supervisor	James Harris	Badge #	5801	Date Approved	02/08/2026
Report Status	Approved / Final	Date Filed (RMV/State)	02/11/2026	Distribution	Driver(s), Insurer(s), State Records