

A. CRASH SCENE INFORMATION

Date of Crash	04/02/2026	Time	18:10 hrs	Day of Week	Thursday
County / Parish	Madison	City / Town	Franklin	Reporting Agency Case #	MS-20260402-5474
Crash Location (Route/County)	Route 902 W (Interstate)	At Intersection With / Mile Marker	MS-902 / 29.5	Latitude / Longitude	30.07015, -71.15774
Weather	Rain	Light Conditions	Dusk	Road Surface	Wet
Road Alignment	Curve & Level	Traffic Control	Traffic Signal	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2019	Make	International	Model	LT
Color	Blue	License Plate	FBC7234	Plate State / Year	MS / 2026
VIN	0NKKBD3ZPJ01K20UV	Owner	Jonathan Stewart (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	Progressive Casualty Ins. Co.	Policy #	PR-573948962	Damage Severity	Functional
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Jonathan Stewart	DOB	12/27/1994	Age / Sex	31 / F
Address	389 Mill Way	City/State/Zip	Greenville, MS 88925	Phone	(614) 940-4359
DL #	MS40637199	DL State	MS	DL Class	CDL-A
Restraint Used	Unknown	Airbag	Deployed - Side	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: NJSA 39:4-89 - Following Too Closely

C. UNIT / VEHICLE #2

Vehicle Details

Year	2022	Make	Subaru	Model	Ascent
Color	Black	License Plate	ABC1234	Plate State / Year	MS / 2026
VIN	2RDXL9BJEYV3L3LUK	Owner	Nicole Jackson	Towed?	Yes - to Sec. Towing
Insurance Company	Travelers Indemnity Company	Policy #	TR-679897540	Damage Severity	Functional
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Nicole Jackson	DOB	10/24/1961	Age / Sex	64 / M
Address	5164 Lincoln Blvd	City/State/Zip	Madison, MS 55797	Phone	(248) 924-6764
DL #	MS23843312	DL State	MS	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Deployed - Front	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Madison Regional Medical Center	EMS Run #	EMS-3319

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Jonathan Lopez	05/21/2005	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Madison Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2016	Make	Tesla	Model	Model X
Color	Gold	License Plate	GBC2234	Plate State / Year	MS / 2026
VIN	7RPA10X4HH3BZ8CYE	Owner	Ronald Watson	Towed?	No
Insurance Company	USAA Casualty Insurance Co.	Policy #	US-254857146	Damage Severity	Disabling
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Ronald Watson	DOB	05/10/1976	Age / Sex	50 / F
Address	4369 Cedar St	City/State/Zip	Riverside, MS 66480	Phone	(709) 921-8510
DL #	MS37694632	DL State	MS	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Side	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-2532

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 04/02/2026 at approximately 18:10 hrs, in rain conditions with wet roadway, Unit 1 (commercial: 2019 International LT, operated by Jonathan Stewart) was traveling on I-192 W (Interstate) approaching Mile Marker 29.5. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2022 Subaru Ascent, driven by Nicole Jackson), propelling Unit 2 into Unit 3 (2016 Tesla Model X, operated by Ronald Watson). Driver of Unit 2 sustained suspected serious injury and was transported to Madison Regional Medical Center via EMS-3319. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-192 W (Interstate) at Mile Marker 29.5. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.
[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses					
#	Name	Address	Phone	Statement Summary	
1	Stephen Ortiz	5468 Cedar Dr, Riverside, MS	(511) 741-7532	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 60-65 mph.	
2	Matthew Cox	2963 Market Ter, Bristol, MS	(455) 720-3499	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.	
Investigating Officer		Jason Diaz	Badge # 3827	Agency	Mississippi Highway Patrol
Reviewing Supervisor		Jacob Parker	Badge # 3309	Date Approved	04/04/2026
Report Status		Approved / Final	Date Filed (RMV) 04/07/2026	Distribution	Driver(s), Insurer(s), State Records