

A. CRASH SCENE INFORMATION

Date of Crash	05/17/2026	Time	17:15 hrs	Day of Week	Sunday
County / Parish	Washington	City / Town	Riverside	Reporting Agency Case #	NC-20260517-4940
Crash Location (Route/Right of Way)	Route 141N (Interstate)	At Intersection With / Mile Marker	NC-141N / 93.4	Latitude / Longitude	39.19557, -111.22483
Weather	Snow	Light Conditions	Dark - Not Lighted	Road Surface	Snow
Road Alignment	Straight & Grade	Traffic Control	No Controls	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2015	Make	Kenworth	Model	W900
Color	Gray	License Plate	LBC8234	Plate State / Year	NC / 2026
VIN	CCBZPVF4WBZW1SXS	Owner	Justin Kim (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	Travelers Indemnity Company	Policy #	TR-437250534	Damage Severity	Minor
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Justin Kim	DOB	10/30/1996	Age / Sex	29 / M
Address	5158 Birch Dr	City/State/Zip	Clinton, NC 85971	Phone	(744) 916-6402
DL #	NC99907567	DL State	NC	DL Class	CDL-A
Restraint Used	Unknown	Airbag	Deployed - Side	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: VC 21703 - Following Too Closely

C. UNIT / VEHICLE #2

Vehicle Details

Year	2025	Make	Hyundai	Model	Santa Fe
Color	Silver	License Plate	RBC7234	Plate State / Year	NC / 2026
VIN	1PNGTMGETEKFLP20C	Owner	Samantha Cooper	Towed?	Yes - to Sec. Towing
Insurance Company	USAA Casualty Insurance	Policy #	US-271887959	Damage Severity	Functional
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Samantha Cooper	DOB	11/22/1982	Age / Sex	43 / F
Address	9947 Washington Hwy	City/State/Zip	Georgetown, NC 76155	Phone	(832) 579-3437
DL #	NC35095290	DL State	NC	DL Class	Class D
Restraint Used	Lap Belt Only	Airbag	Deployed - Front	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Washington Regional Medical Center	EMS Run #	EMS-7178

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Robert Anderson	04/18/2006	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Washington Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2023	Make	Mazda	Model	CX-30
Color	Gold	License Plate	WBC7234	Plate State / Year	NC / 2026
VIN	ETMUJK19071T05HCD	Owner	Katherine Ramirez	Towed?	No
Insurance Company	Liberty Mutual Insurance	Policy #	LM-410430195	Damage Severity	Minor
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Katherine Ramirez	DOB	02/18/1996	Age / Sex	30 / F
Address	1481 Court Blvd	City/State/Zip	Bristol, NC 98359	Phone	(887) 236-5010
DL #	NC86905610	DL State	NC	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Not Deployed	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-9093

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 05/17/2026 at approximately 17:15 hrs, in snow conditions with snow roadway, Unit 1 (commercial: 2015 Kenworth W900, operated by Justin Kim) was traveling on I-413 N (Interstate) approaching Mile Marker 93.4. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2025 Hyundai Santa Fe, driven by Samantha Cooper), propelling Unit 2 into Unit 3 (2023 Mazda CX-30, operated by Katherine Ramirez). Driver of Unit 2 sustained suspected serious injury and was transported to Washington Regional Medical Center via EMS-7178. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-413 N (Interstate) at Mile Marker 93.4. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses

#	Name	Address	Phone	Statement Summary		
1	Jessica Roberts	639 Jefferson Hwy, Greenville, NC	(781) 557-2566	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 45 mph.		
2	Ashley Taylor	1149 Market St, Greenville, NC	(813) 862-6017	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.		
Investigating Officer		Angela Hernandez	Badge #	6570	Agency	North Carolina Department of Motor Vehicles
Reviewing Supervisor		Richard Stewart	Badge #	4292	Date Approved	05/19/2026
Report Status		Approved / Final	Date Filed (RMV)	05/22/2026	Distribution	Driver(s), Insurer(s), State Records