

POLICE CRASH INVESTIGATION
REPORT
Form NJTR-1 (Rev. 06/2023)

Report #
NJ-2026-614155
Complexity: MEDIUM

A. CRASH SCENE INFORMATION

Date of Crash	04/22/2026	Time	06:45 hrs	Day of Week	Wednesday
County / Parish	Madison	City / Town	Madison	Reporting Agency Case #	NJ-20260422-3517
Crash Location (Route / Road)	I-139 E	At Intersection With / Mile Marker	Broadway Ct	Latitude / Longitude	35.15704, -83.56121
Weather	Clear	Light Conditions	Daylight	Road Surface	Dry
Road Alignment	Straight & Level	Traffic Control	Stop Sign	Direction of Crash	Same Direction (Rear End)
# Vehicles Involved	2	# Injured	0	# Fatalities	0

B. UNIT / VEHICLE #1

Vehicle Details

Year	2017	Make	Subaru	Model	Impreza
Color	Green	License Plate	CBC2234	Plate State / Year	NJ / 2026
VIN	X6WG8NDTC726S6ZC5	Owner	Jeffrey Collins (same as driver)	Towed?	No
Insurance Company	Nationwide Mutual Insurance	Policy #	NW-711490657	Damage Severity	Functional
Areas of Damage	Front	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Jeffrey Collins	DOB	01/11/1997	Age / Sex	29 / M
Address	2191 Hill Blvd	City/State/Zip	Riverside, NJ 41184	Phone	(519) 356-1186
DL #	NJ31058295	DL State	NJ	DL Class	Class D
Restraint Used	Lap Belt Only	Airbag	Not Deployed	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [15] Inattention

C. UNIT / VEHICLE #2

Vehicle Details

Year	2017	Make	Kia	Model	Telluride
Color	Blue	License Plate	WBC3234	Plate State / Year	NJ / 2026
VIN	A4LVT6JWKSAT0UY9H	Owner	David Williams	Towed?	No
Insurance Company	Progressive Casualty Ins.	Policy #	PR-286577049	Damage Severity	Minor
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	David Williams	DOB	08/23/1987	Age / Sex	38 / F
Address	1876 Court Hwy	City/State/Zip	Georgetown, NJ 14838	Phone	(568) 515-3531
DL #	NJ28390022	DL State	NJ	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Deployed - Front	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 04/22/2026 at approximately 06:45 hrs, Unit 1 (2017 Subaru Impreza) was traveling on I-139 E approaching Broadway Ct. Unit 2 (2017 Kia Telluride) was stopped in the same lane awaiting a green light. Driver of Unit 1 failed to maintain safe following distance and struck the rear of Unit 2. No injuries reported. Both drivers exchanged information. Roadway dry, weather clear, daylight conditions. Property damage only. No citations issued at scene; driver of Unit 1 advised of contributing factor.

Diagram Description: Two-vehicle rear-end at signalized intersection. V1 northbound, V2 stopped at signal. Impact: V1 front to V2 rear.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Investigating Officer	Christine Cox	Badge #	7464	Agency	New Jersey Division of State Police
Reviewing Supervisor	Matthew Murphy	Badge #	2781	Date Approved	04/23/2026
Report Status	Approved / Final	Date Filed (RMV/SALES)	04/25/2026	Distribution	Driver(s), Insurer(s), State Records