

A. CRASH SCENE INFORMATION

Date of Crash	05/09/2026	Time	20:10 hrs	Day of Week	Saturday
County / Parish	Albany	City / Town	Albany	Reporting Agency Case #	NY-20260509-9535
Crash Location (Route/County) (Interstate)	Rt 50N	At Intersection With / Mile Marker	NY 111.5	Latitude / Longitude	26.72144, -113.56070
Weather	Fog/Smog/Smoke	Light Conditions	Dark - Not Lighted	Road Surface	Dry
Road Alignment	Curve & Level	Traffic Control	Traffic Signal	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2023	Make	International	Model	LT
Color	Brown	License Plate	SBC3234	Plate State / Year	NY / 2026
VIN	ELSY3RAJLR5WJTRZ1	Owner	Deborah Jackson (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	Farmers Insurance Exchange	Policy #	FA-720920359	Damage Severity	Disabling
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Deborah Jackson	DOB	11/24/1981	Age / Sex	44 / M
Address	1595 Walnut Ln	City/State/Zip	Rochester, NY 59805	Phone	(479) 349-4724
DL #	NY36569126	DL State	NY	DL Class	CDL-A
Restraint Used	Lap & Shoulder Belt	Airbag	Deployed - Side	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: MGL 90 §17 - Speeding

C. UNIT / VEHICLE #2

Vehicle Details

Year	2018	Make	Kia	Model	Sorento
Color	Black	License Plate	VBC2234	Plate State / Year	NY / 2026
VIN	5P7ZHDBV1HHUL9AKP	Owner	Margaret Young	Towed?	Yes - to Sec. Towing
Insurance Company	Farmers Insurance Exchange	Policy #	FA-536853920	Damage Severity	Functional
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Margaret Young	DOB	09/27/2005	Age / Sex	20 / M
Address	7956 Pine Ave	City/State/Zip	Syracuse, NY 95471	Phone	(612) 427-1154
DL #	NY36625043	DL State	NY	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Deployed - Side	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Albany Regional Medical Center	EMS Run #	EMS-3555

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Steven Cook	04/06/1977	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Albany Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2022	Make	Nissan	Model	Altima
Color	Green	License Plate	BBC7234	Plate State / Year	NY / 2026
VIN	UD21M7YGD8TTBDAPK	Owner	Rebecca Baker	Towed?	No
Insurance Company	Allstate Insurance Company	Policy #	AL-343045104	Damage Severity	Minor
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Rebecca Baker	DOB	01/07/1995	Age / Sex	31 / M
Address	4161 Lake Pkwy	City/State/Zip	Rochester, NY 47280	Phone	(409) 442-6509
DL #	NY79997415	DL State	NY	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Not Deployed	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-1117

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 05/09/2026 at approximately 20:10 hrs, in fog/smog/smoke conditions with dry roadway, Unit 1 (commercial: 2023 International LT, operated by Deborah Jackson) was traveling on I-65 N (Interstate) approaching Mile Marker 111.5. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2018 Kia Sorento, driven by Margaret Young), propelling Unit 2 into Unit 3 (2022 Nissan Altima, operated by Rebecca Baker). Driver of Unit 2 sustained suspected serious injury and was transported to Albany Regional Medical Center via EMS-3555. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-65 N (Interstate) at Mile Marker 111.5. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.
[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses					
#	Name	Address	Phone	Statement Summary	
1	Stephen Taylor	1593 Forest Rd, Buffalo, NY	(774) 766-9320	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 70 mph.	
2	Scott Rodriguez	8748 Lake Hwy, Buffalo, NY	(253) 465-7579	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.	
Investigating Officer		Sandra Torres	Badge # 4326	Agency	New York State Department of Motor Vehicles
Reviewing Supervisor		Thomas Jackson	Badge # 7592	Date Approved	05/11/2026
Report Status		Approved / Final	Date Filed (RMV/State)	Distribution	Driver(s), Insurer(s), State Records