

A. CRASH SCENE INFORMATION

Date of Crash	03/17/2026	Time	19:05 hrs	Day of Week	Tuesday
County / Parish	Washington	City / Town	Riverside	Reporting Agency Case #	OH-20260317-6199
Crash Location (Route/County)	R250 S (Interstate)	At Intersection With / Mile Marker	128.4	Latitude / Longitude	35.55426, -96.52772
Weather	Snow	Light Conditions	Dusk	Road Surface	Snow
Road Alignment	Straight & Grade	Traffic Control	Traffic Signal	Direction of Crash	Same Direction (Chain Reaction)
# Vehicles Involved	3	# Injured	3	# Fatalities	0

B. UNIT / VEHICLE #1 (COMMERCIAL)

Vehicle Details

Year	2019	Make	International	Model	LT
Color	White	License Plate	TBC3234	Plate State / Year	OH / 2026
VIN	L48J2VUKV20BRYWRR	Owner	Kathleen Cruz (same as driver)	Towed?	Yes - to Sec. Towing
Insurance Company	Allstate Insurance Company	Policy #	AL-799299789	Damage Severity	Functional
Areas of Damage	Front	Vehicle Type	Commercial/Truck	Cargo (if commercial)	General Freight

Driver Information

Driver Name	Kathleen Cruz	DOB	05/17/1971	Age / Sex	55 / F
Address	5096 Broadway Ln	City/State/Zip	Clinton, OH 73339	Phone	(694) 473-7938
DL #	OH90549383	DL State	OH	DL Class	CDL-A
Restraint Used	Lap Belt Only	Airbag	Deployed - Side	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [06] Driving Too Fast for Conditions | [14] Fatigued/Asleep
Citations Issued: TC 545.062 - Following Distance (TX)

C. UNIT / VEHICLE #2

Vehicle Details

Year	2015	Make	Toyota	Model	Sienna
Color	Gold	License Plate	PBC1234	Plate State / Year	OH / 2026
VIN	7EAB11RMNYMNUBAGY	Owner	Shirley Hill	Towed?	Yes - to Sec. Towing
Insurance Company	State Farm Mutual Auto Ins.	Policy #	SF-302688999	Damage Severity	Minor
Areas of Damage	Front & Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Shirley Hill	DOB	01/18/1988	Age / Sex	38 / F
Address	442 Forest Dr	City/State/Zip	Greenville, OH 78421	Phone	(889) 596-7966
DL #	OH53028865	DL State	OH	DL Class	Class D
Restraint Used	Lap & Shoulder Belt	Airbag	Deployed - Side	Ejected	No
Injury Severity	Suspected Serious Injury (A)	Taken To	Washington Regional Medical Center	EMS Run #	EMS-2884

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

Other Occupants

#	Name	DOB	Position	Restraint	Injury Severity	Transported To
1	Jennifer King	12/18/1958	Right Front	Lap & Shoulder Belt	Suspected Minor Injury (B)	Washington Regional Medical Center

D. UNIT / VEHICLE #3

Vehicle Details

Year	2019	Make	Nissan	Model	Rogue
Color	Blue	License Plate	XBC2234	Plate State / Year	OH / 2026
VIN	J7BTW6N48DE3P9E1H	Owner	Nancy Lewis	Towed?	No
Insurance Company	Progressive Casualty Ins.	Policy #	PR-802636215	Damage Severity	Minor
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Nancy Lewis	DOB	01/27/2004	Age / Sex	22 / F
Address	8935 Hill Ct	City/State/Zip	Bristol, OH 71961	Phone	(832) 917-4233
DL #	OH17995700	DL State	OH	DL Class	Class D
Restraint Used	None Used	Airbag	Deployed - Front	Ejected	No
Injury Severity	Possible Injury (C)	Taken To	Treated at scene - declined transport	EMS Run #	EMS-5695

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 03/17/2026 at approximately 19:05 hrs, in snow conditions with snow roadway, Unit 1 (commercial: 2019 International LT, operated by Kathleen Cruz) was traveling on I-253 S (Interstate) approaching Mile Marker 128.4. Per witness statements, Unit 1 was traveling at a speed unsafe for conditions and failed to slow for slowing traffic ahead. Unit 1 struck the rear of Unit 2 (2015 Toyota Sienna, driven by Shirley Hill), propelling Unit 2 into Unit 3 (2019 Nissan Rogue, operated by Nancy Lewis). Driver of Unit 2 sustained suspected serious injury and was transported to Washington Regional Medical Center via EMS-2884. Passenger in Unit 2 sustained minor injuries. Driver of Unit 3 reported using cell phone at time of impact. Operator of Unit 1 admitted to extended driving hours; ELD records to be subpoenaed. Citations issued to Unit 1 driver (unsafe speed / following too closely) and Unit 3 driver (cell phone use). Roadway closed for 2.5 hours. DOT inspection of Unit 1 commercial vehicle requested.

Diagram Description: Three-vehicle chain-reaction collision on I-253 S (Interstate) at Mile Marker 128.4. V1 (commercial) rear-ended V2 from behind; V2 then struck V3 ahead. Impact angles: V1 front->V2 rear; V2 front->V3 rear. All vehicles came to rest in right travel lane and right shoulder.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Witnesses

#	Name	Address	Phone	Statement Summary		
1	Christopher Parker	3977 Cedar Ave, Springfield, OH	(250) 739-8218	Was traveling behind V1; observed V1 not braking as traffic slowed. Estimated V1 speed 45 mph.		
2	Kenneth Morales	701 Highland Ave, Franklin, OH	(416) 368-5027	Was in left lane parallel to scene. Saw V3 driver looking down at phone seconds before impact.		
Investigating Officer		Ronald Kelly	Badge #	8279	Agency	Ohio State Highway Patrol
Reviewing Supervisor		Donna Torres	Badge #	6004	Date Approved	03/19/2026
Report Status		Approved / Final	Date Filed (RMV)	03/22/2026	Distribution	Driver(s), Insurer(s), State Records