

OKLAHOMA OFFICIAL TRAFFIC
COLLISION REPORT
Form OCR (2024)

A. CRASH SCENE INFORMATION

Date of Crash	01/11/2026	Time	19:10 hrs	Day of Week	Sunday
County / Parish	Franklin	City / Town	Springfield	Reporting Agency Case #	OK-20260111-5597
Crash Location (Route / Road)	US-139 S	At Intersection With / Maple Ave	Maple Ave	Latitude / Longitude	27.79835, -106.88112
Weather	Clear	Light Conditions	Daylight	Road Surface	Dry
Road Alignment	Straight & Level	Traffic Control	Stop Sign	Direction of Crash	Same Direction (Rear End)
# Vehicles Involved	2	# Injured	0	# Fatalities	0

B. UNIT / VEHICLE #1

Vehicle Details

Year	2019	Make	BMW	Model	X1
Color	Blue	License Plate	BBC2234	Plate State / Year	OK / 2026
VIN	P6EW8XF39SCHH5MUV	Owner	Mary Walker (same as driver)	Towed?	No
Insurance Company	Liberty Mutual Insurance	Policy #	LM-577651145	Damage Severity	Minor
Areas of Damage	Front	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Mary Walker	DOB	08/06/1965	Age / Sex	60 / F
Address	5903 Birch Ter	City/State/Zip	Greenville, OK 31616	Phone	(987) 426-9429
DL #	OK11939690	DL State	OK	DL Class	Class D
Restraint Used	None Used	Airbag	Not Deployed	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #1): [16] Backing Unsafely

C. UNIT / VEHICLE #2

Vehicle Details

Year	2025	Make	BMW	Model	5 Series
Color	Brown	License Plate	VBC1234	Plate State / Year	OK / 2026
VIN	1XTW0F5SRH49YEGYK	Owner	Nicole Taylor	Towed?	No
Insurance Company	Progressive Casualty Ins. Co.	Policy #	PR-313131746	Damage Severity	Disabling
Areas of Damage	Rear	Vehicle Type	Passenger	Cargo (if commercial)	N/A

Driver Information

Driver Name	Nicole Taylor	DOB	02/11/1959	Age / Sex	67 / M
Address	1714 Washington Ter	City/State/Zip	Greenville, OK 97860	Phone	(246) 659-8860
DL #	OK18316587	DL State	OK	DL Class	Class D
Restraint Used	Lap Belt Only	Airbag	Not Deployed	Ejected	No
Injury Severity	No Apparent Injury	Taken To	N/A	EMS Run #	N/A

Contributing Factors (Driver/Vehicle #2): [99] None Apparent

E. OFFICER NARRATIVE & DIAGRAM DESCRIPTION

Narrative: On 01/11/2026 at approximately 19:10 hrs, Unit 1 (2019 BMW X1) was traveling on US-139 S approaching Maple Ave. Unit 2 (2025 BMW 5 Series) was stopped in the same lane awaiting a green light. Driver of Unit 1 failed to maintain safe following distance and struck the rear of Unit 2. No injuries reported. Both drivers exchanged information. Roadway dry, weather clear, daylight conditions. Property damage only. No citations issued at scene; driver of Unit 1 advised of contributing factor.

Diagram Description: Two-vehicle rear-end at signalized intersection. V1 northbound, V2 stopped at signal. Impact: V1 front to V2 rear.

[Diagram field on official form would contain hand-drawn or CAD-rendered crash scene reconstruction. Not rendered in this sample.]

F. WITNESSES & OFFICER SIGN-OFF

Investigating Officer	Kenneth Scott	Badge #	2855	Agency	Oklahoma Highway Patrol
Reviewing Supervisor	Daniel Jackson	Badge #	3363	Date Approved	01/12/2026
Report Status	Approved / Final	Date Filed (RMV/State)	01/14/2026	Distribution	Driver(s), Insurer(s), State Records