

# Accident Scene Damage Report

## Vehicle ID: Car A

Summary: Car A sustained damage to multiple areas including the front bumper and headlights.

## Detected Damaged Parts:

- Front bumper: crack (Severity: high)
- Left headlight: shattered (Severity: medium)