SYNTHETIC HOME INSPECTION REPORT

Property: 12 Example Lane, Testville
Inspection date: June 22, 2023
Inspector: Sample Inspections Co.

Summary: The roof covering is composition shingle in fair condition.
The water heater is a 50 gallon gas unit with a seismic strap.

D E S C R I P T I O N

The furnace is a forced-air gas unit located in the garage.
It was installed in 2009 and is near the end of its expected life.
A flexible gas connector is routed through the cabinet wall.
Recommend evaluation by a licensed HVAC contractor.

INVOICE 1001 - Brightline Pest Co.

Termite damage repair at the rear deck ledger.
Total due: $1,234.00
Completed July 14, 2023.