



DEFICIENCY REPORT

Customer Name: 25 The Esplanade
 Customer Site: Head Office
 Certificate #: 19-ESP1003
 Equipment Tag: 1003
 Inspection by: Ian Devlin

Date: Jun 05, 2019


Inspection Point	Deficiency	Hazard Class
------------------	------------	--------------

MOULD INSPECTION
 (OKAY)




ISOLATION VALVES TEST
 (NOT OKAY)

VALVES RUSTED;



CONDENSATION TRAY
 TEST - SPRING ONLY
 (OKAY)



HAZARD CLASS ICON LEGEND:



Bio Hazard



Electrical Hazard



Fire Hazard

Water Hazard