

INSPECTION REPORT

121+ Checkpoints Doorstep Inspection Service

Ordered By



Anant Goel



10 / 01 / 2021



Gurgaon

Inspected By



Inspection System



Verified Technician



36+ Vehicle Treated



4+ Years Experience

Audi A4 Premium Plus, 2019



₹ 34,07,519

Automobile from individual in
good condition is valued

Vehicle Information


Make	Audi	Transmission Type	Automatic
Model	A4	Registration No.	DL10CG3657
Year	2019	VIN/Chassis Number	16191
Trim	Premium Plus	Kms Run	25105
Color	Terra Gray	Insurance Expiry	2020-7-14
Body Type	Sedan	Location	Janak Puri
Fuel Type	Petrol	Engine Sound Link	Listen Engine Sound

Key Highlights

Flood Damage	No	Insurance Copy Available	No
Tyre Life Remaining (KM)	25,105	Service Logs Available	No
Dent	Yes	Bank Hypothecation	No
Major Accidents	No	Bank NOC	No
RC Copy Available	Yes (Original)		


Repair Estimate

Total Repair Estimate ₹ 10250



EXTERIOR


Vehicle Exterior View and Condition



Front License Plate is available?	<input checked="" type="checkbox"/>
License Plates are HSRP complaint?	<input type="checkbox"/>
Head Lights are working?	<input checked="" type="checkbox"/>
Turn Signal lamps are working?	<input type="checkbox"/>
Hazard Lamps are working?	<input checked="" type="checkbox"/>
License plate light is working?	<input checked="" type="checkbox"/>
Rear windshield wiper is working in good condition?	<input checked="" type="checkbox"/>

Rear License Plate is available?	<input checked="" type="checkbox"/>
HSRP colour sticker is available?	<input type="checkbox"/>
Tail Lights are working?	<input checked="" type="checkbox"/>
Fog Lamps are working?	<input type="checkbox"/>
Break lights are working?	<input checked="" type="checkbox"/>
Front windshield wiper is working in good condition?	<input checked="" type="checkbox"/>
Reverse parking lights are working?	<input checked="" type="checkbox"/>

Exterior Images

FRONT VIEW**REAR VIEW****LEFT SIDE VIEW****RIGHT SIDE VIEW****LEFT FRONT CORNER VIEW****LEFT REAR CORNER VIEW****RIGHT FRONT CORNER VIEW****RIGHT REAR CORNER VIEW**

INTERIOR

Vehicle Interior View and Condition




Music System is working properly?	<input checked="" type="checkbox"/>
Navigation System is working properly?	<input checked="" type="checkbox"/>
Horn is loud & clear?	<input checked="" type="checkbox"/>
Sun Visors are working properly?	<input checked="" type="checkbox"/>
Luggage Compartment light is working properly?	N/A
Power Windows are working?	<input checked="" type="checkbox"/>
Carpets are in good condition?	<input checked="" type="checkbox"/>
Seat Belts are working properly?	N/A
Boot Lever is working properly?	<input checked="" type="checkbox"/>
Front De-Fogger is available?	<input checked="" type="checkbox"/>
USB port is available?	<input checked="" type="checkbox"/>
Rear view mirror is functional?	<input checked="" type="checkbox"/>
Speakers are working properly?	<input checked="" type="checkbox"/>
Steering Mounted Controls are working properly?	N/A
Handbrake is working properly?	<input checked="" type="checkbox"/>
All Cabin lights are working properly?	N/A
Central Lock is working?	<input checked="" type="checkbox"/>
Floor Mats are available?	<input checked="" type="checkbox"/>
Seat Covers are in good condition?	<input checked="" type="checkbox"/>
Fuel Lid Lever is working properly?	<input checked="" type="checkbox"/>
Bonnet Lever is working properly?	<input checked="" type="checkbox"/>
Rear De-Fogger is available?	<input checked="" type="checkbox"/>
Glove box light is working?	<input checked="" type="checkbox"/>

Interior Images





DASHBOARD VIEW**CLUSTER METER VIEW****FRONT SEATS****REAR SEATS****GLOVE BOX****INTERIOR REAR VIEW****INTERIOR FRONT VIEW****INTERIOR DOOR PANEL**

WHEELS

Wheel View and Condition




Wheels Images




TEST DRIVE

Test Drive and Condition





HOOD

Vehicle Hood View and Condition




Hood Images



Miscellaneous

Service Required?	<input checked="" type="checkbox"/>
VIN/Chassis Number matching with document?	<input type="checkbox"/>
Vehicle jack and wrench available?	<input checked="" type="checkbox"/>
Cruise Control?	<input checked="" type="checkbox"/>
Medical Kit available?	<input type="checkbox"/>

Images



Hygiene & Cleanliness

Car odour?	<input checked="" type="checkbox"/>
Seat covers are clean & tidy?	<input type="checkbox"/>
Floor mats are clean?	<input checked="" type="checkbox"/>
Door panel, seat pockets and cup holders are clean?	<input checked="" type="checkbox"/>
Mirrors and windshield are clean?	<input type="checkbox"/>
Floor & underseats are clean?	<input checked="" type="checkbox"/>

Documents


REGISTRATION CERTIFICATE		INSURANCE COPY	

NEED ATTENTION

Interior

CENTRAL LOCKRemarks
Repair EstimateCentral Lock Not Working
₹ 600**POWER WINDOW**Remarks
Repair EstimateCentral Lock Not Working
₹ 600










Wheel

FRONT TYRESRemarks
Repair EstimateSpare tyres are not in a good condition
₹ 600**SPARE TYRES**Remarks
Repair EstimateSpare tyres are not in a good condition
₹ 600

Exterior

FOG LAMPSRemarks
Repair EstimateMajor cracks In Fog Lamps
₹ 900**LEFT FRONT DOOR**Remarks
Repair EstimateScratches/Dents In Front Door
₹ 900

All Images



All Images

RIGHT QUARTER PANEL



BOOT TRUNK LID



ROOF



FRONT LICENSE PLATE



REAR LICENSE PLATE



HSRP COLOUR STICKER



FRONT WINDSHIELD WIPER



REAR WINDSHIELD WIPER



ODOMETER



POWER WINDOWS



REAR VIEW MIRROR



ENGINE COMPARTMENT



UNDERCARRIAGE



BATTERY



TRUNK LID

