



# MAHARASHTRA POLLUTION CONTROL BOARD

SUB REGIONAL OFFICE,

Plot No. A 4/1, M.I.D.C. CHIKHALTHANA, AURANGABAD - II

Ph. No. ( 0240 ) 2473463.

## Inspection Report

Date : 11 / 08 / 2010

1. Name of the Factory , Address & Tel. No. :-

M/s Bhagyalaxmi Steel & Alloys  
Plot No. 4/1, Addl. MIDC Talna.

2. Factory Officer Contacted :-

Mr. Nitin Kabra (Director)

3. Scale & Category :-

Red

4. Validity of Consent

Valid Period / Applied / Not - Applied :-

31.08.2010

5. Industrial Effluent

	Treatment	Disposal
Not Provided		Nalla, on land for irrigation/ gardening
Primary		
Secondary		
Tertiary		

6. Spot Observations

Discharge	Spot I	Spot II
PH		
Smell		
Colour / Physical Appearance		

7. Operation & Maintenance

	OK	average	Poor
ETP			
Disposal			
Record Keeping			
House Keeping			
Mfg. Plant			
ETP			

10. Air Pollution

Problems	Control System	O & M
SPM	Cyclones	
SO2		
Nox		
Chimney	Cyclone	
Height	30mt	

8. Cess & Details

9. Solid Waste / Hazardous Waste Storage Arrangement

11. Tree Plantation done.....  
Proposed.....

12. Details of Sample Collected :-

3. Special Remarks if any:

① At the time of visit, the production activity found in operation ② Suction efficiency of APC system is very less and its require maintenance of hood & cyclone. ③ No smoke emissions from chimney is noticed ④ It is instructed to repair the hood, dusting and clean the cyclone immediately and to submit the compliance within week period ⑤ To carry out the tree plantation of trees having characteristic of control of air pollution in this rainy season.

Signature & Stamp of  
Factory Authority

(S.A. Kadam)

Signature & Name  
E.O./S.R.O.