

Interim	Start	End	Survey Summary for the Interim Report Period
1	21/02/2025	28/02/2025	
2	28/02/2025	07/03/2025	

Ref No.	Start Time	End Time	Duration (mins)
---------	------------	----------	-----------------

X

Not Working

V

Velocity Problem

D

Depth Problem

G

Dry Pipe

B

Blocked Filter RG

R

Ragging

L

Low Flow <10l/s

T

Sediment

S

Surcharged

P

Pluming

K

Monitor Submerged

W

Working

U

Dislodged Sensor

H

Standing Water

I

Installed

O

Taken Out

M

Monitor Changed

Week	1							2						
Day	F	S	S	M	T	W	T	F	S	S	M	T	W	T
Date	21/02/2025	22/02/2025	23/02/2025	24/02/2025	25/02/2025	26/02/2025	27/02/2025	28/02/2025	01/03/2025	02/03/2025	03/03/2025	04/03/2025	05/03/2025	06/03/2025
FM001	W	W	S	W	W	X	X	X	X	X	W	W		
FM002	W	W	W											
FM003	X	X	X	W	W	W	W	W	W	W	S	W		
FM004	R	R	W	W	R	W	W	W	W	W	W	W		
FM005	X	X	X	W	W	W	W	W	W	W	S	W		
FM006	X	X	X	W	W	W	W	W	W	W	W	W	W	
FM007	W	W	S	W	W	W	W	W	W	W	W	W		
FM008														
FM009				W	W	W	W	W	W	W	W	W		
FM010	X	X	X	X	X	X	X	W	W	W				
RG001	W	W	W	W	W	W	W	W	W	W	W	W	W	W
RG002														
RG003														
RG004														
RG005														

Monitor No.	Location	Pipe	Height (mm)	Width (mm)	Shape	Depth (mm)	Type	MH Ref.	Installed Date	Removed Date	Installed	
											Weeks	Days
FM001	Outside 19 Glengoyne Court (6391)	A	900	900	C	1000	D	NS59536122	18/02/2025		2	3
FM002	Path off Abernathy Park (6392)	A	825	825	C	1000	D	NS62546601	18/02/2025		2	3
FM003	On Footpath OS 17 Incholm Place (6393)	A	800	800	C	1000	D	NS62543801	24/02/2025		1	4
FM004	Corner of Rural Life Museum (6394)	A	850	850	C	1000	D	NS60557702	18/02/2025		2	3
FM005	In Field off Philipshill Road (6395)	A	900	900	C	1000	D	NS60556802	24/02/2025		1	4
FM006	Corner of Gardenia Grove & Philipshill Road (6396)	A	720	720	C	1000	D	NS60553501	24/02/2025		1	4
FM007	Eaglesham Road - South of Police Academy (6397)	A	450	450	C	1000	D	NS59534301	18/02/2025		2	3
FM008	On Grass at Entrance to Police Collage B764 (6398)	A	450	450	C	1000	D	NS59536501	18/02/2025		2	3
FM009	On Path by 42 Findhorn place (6399)	A	425	425	C	1000	D	NS59538501	24/02/2025		1	4
FM010	By Newlands Way (6400)	A	450	450	C	1000	D	NS60510628	28/02/2025		1	0

Monitor No.	Location	Posit'n	Type	Easting	Northing	Installed Date	Removed Date	Installed	
								Weeks	Days
RG001	Greenhills Dental Practice (6402)	G	D	0.0	0.0	18/02/2025		2	3
RG002	Kirriemuir Nursery (6403)	G	D	0.0	0.0	18/02/2025		2	3
RG003	On Substation, Newhouse Road (6404)	G	D	0.0	0.0	18/02/2025		2	3
RG004	Substation next to Cash For Clothes Off Glenburn Road (6405)	G	D	0.0	0.0	18/02/2025		2	3
RG005	USave, 4 Cullen Road (6406)	G	D	0.0	0.0	28/02/2025		1	0

Location	Outside 19 Glengoyne Court (6391)
Pipe	Circular 900 diameter
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		W	W	S	W	W	X	X
2	2025-02-28 00:00:00		X	X	X	W	W		
3	2025-03-07 00:00:00								

Location	Path off Abernathy Park (6392)
Pipe	Circular 825 diameter
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		W	W	W				
2	2025-02-28 00:00:00								
3	2025-03-07 00:00:00								

Location	On Footpath OS 17 Incholm Place (6393)
Pipe	Circular 800 diameter
Monitor Type	Detec
Installed	24/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		X	X	X	W	W	W	W
2	2025-02-28 00:00:00		W	W	W	W	S	W	
3	2025-03-07 00:00:00								

Location	Corner of Rural Life Museum (6394)
Pipe	Circular 850 diameter
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		R	R	W	W	R	W	W
2	2025-02-28 00:00:00		W	W	W	W	W		
3	2025-03-07 00:00:00								

Location	In Field off Philipshill Road (6395)
Pipe	Circular 900 diameter
Monitor Type	Detec
Installed	24/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		X	X	X	W	W	W	W
2	2025-02-28 00:00:00		W	W	W	W	S	W	
3	2025-03-07 00:00:00								

Location	Corner of Gardenia Grove & Philipshill Road (6396)
Pipe	Circular 720 diameter
Monitor Type	Detec
Installed	24/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		X	X	X	W	W	W	W
2	2025-02-28 00:00:00		W	W	W	W	W	W	
3	2025-03-07 00:00:00								

Location	Eaglesham Road - South of Police Academy (6397)
Pipe	Circular 450 diameter
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		W	W	S	W	W	W	W
2	2025-02-28 00:00:00		W	W	W	W	W		
3	2025-03-07 00:00:00								

Location	On Grass at Entrance to Police Collage B764 (6398)
Pipe	Circular 450 diameter
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00								
2	2025-02-28 00:00:00								
3	2025-03-07 00:00:00								

Location	On Path by 42 Findhorn place (6399)
Pipe	Circular 425 diameter
Monitor Type	Detec
Installed	24/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00					W	W	W	W
2	2025-02-28 00:00:00		W	W	W	W	W		
3	2025-03-07 00:00:00								

Location	By Newlands Way (6400)
Pipe	Circular 450 diameter
Monitor Type	Detec
Installed	28/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		X	X	X	X	X	X	X
2	2025-02-28 00:00:00		W	W	W				
3	2025-03-07 00:00:00								

Location	Greenhills Dental Practice (6402)
Position	Ground
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00		W	W	W	W	W	W	W
2	2025-02-28 00:00:00		W	W	W	W	W	W	W
3	2025-03-07 00:00:00		W						

Location	Kirriemuir Nursery (6403)
Position	Ground
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00								
2	2025-02-28 00:00:00								
3	2025-03-07 00:00:00								

Location	On Substation, Newhouse Road (6404)
Position	Ground
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00								
2	2025-02-28 00:00:00								
3	2025-03-07 00:00:00								

Location	Substation next to Cash For Clothes Off Glenburn Road (6405)
Position	Ground
Monitor Type	Detec
Installed	18/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00								
2	2025-02-28 00:00:00								
3	2025-03-07 00:00:00								

Location	USave, 4 Cullen Road (6406)
Position	Ground
Monitor Type	Detec
Installed	28/02/2025
Removed	
Comment	No data in interim period

Week	Date	Comments	F	S	S	M	T	W	T
1	2025-02-21 00:00:00								
2	2025-02-28 00:00:00								
3	2025-03-07 00:00:00								