# PW Run - HS Liability

Vehicle Damage Assessment Report

Report No. 30DB4B09
Date: 05.04.2026

## Vehicle Information

| | |
|---|---|
| **Manufacturer** | Volkswagen |
| **Type** | Golf |
| **Subtype** | Golf VII 2.0 TDI |
| **VIN** | WVWZZZ3CZWE999999 |
| **KBA Number** | 0603/BGH |
| **First Registration** | 15.01.2020 |
| **Power** | 110 kW / 150 PS |
| **Engine Design** | Inline |
| **Displacement** | 1.968 ccm |
| **Transmission** | Manual (6-speed) |
| **Vehicle Type** | compact |
| **Doors** | 4 |
| **Seats** | 5 |
| **Previous Owners** | 1 |

## Accident Information

### Claimant

| | |
|---|---|
| **Name** | Thomas Müller |
| **Address** | Friedrichstr. 100, 10117, Berlin |
| **Email** | thomas@test.de |
| **License Plate** | B TM 2026 |

## Vehicle Condition

| | |
|---|---|
| **General Condition** | Well maintained |
| **Body Condition** | Minor cosmetic |
| **Interior Condition** | Clean, no structural damage. |
| **Paint Type** | Metallic |
| **Paint Finish** | Original manufacturer paint |
| **Paint Condition** | Good |
| **Driving Ability** | Roadworthy |
| **Mileage** | 75.000 km |

| | |
|---|---|
| **Estimated Mileage** | 76.000 km |
| **Next MOT** | 01.06.2027 |
| **Special Features** | Klimaanlage, Navi |
| **Full Service History** | Yes |
| **Notes** | Fahrzeug in gutem Zustand. |
| **Previous Damage Reported** | Keine |
| **Existing Damage (Not Reported)** | Keine |
| **Subsequent Damage** | Keine |

## Valuation & Calculation

### Vehicle Value

| | |
|---|---|
| **Replacement Value** | 25.000,00 € |
| **Residual Value** | 18.000,00 € |
| **Diminution in Value** | 3.500,00 € |

### Repair

| | |
|---|---|
| **Repair Method** | Instandsetzung |
| **Damage Class** | III |

### Loss of Use

| | |
|---|---|
| **Cost per Day** | 35,00 € |
| **Repair Time** | 5 days |
| **Replacement Time** | 12 days |

### Additional Costs

| | |
|---|---|
| **Abschleppkosten** | 180,00 € |

# Invoice

| | |
|---|---|
| **Invoice Number** | PW-HS-001 |
| **Invoice Date** | 03.04.2026 |

| # | Description | Qty | Rate | Amount |
|---|---|---|---|---|
| 1 | Gutachten | LS | - | 362,00 € |
| 2 | Fotos | LS | - | 7,50 € |
| 3 | Fahrtkosten | LS | - | 40,00 € |

| | |
|---|---|
| Net Total | 409,50 € |
| VAT (19%) | 77,80 € |
| **Gross Total** | **487,30 €** |

## Photo Documentation

### Other Photos (5)



inigung Teil I
X/XX-XXXXX
Bundesrepublik Deutschland
XXX ***

| | | | |
|---|---|---|---|
| B | 04.06.2019 | 8212 | ADW00092 |
| I | M1 | AC | |
| E | UU1K6720463XXXXXX | 4 | |
| D.1 | DACIA | | |
| | SD | | |
| | 00EV | | |
| D.2 | NB5CA000M500 | | |
| D.3 | DOKKER | | |
| 2 | DACIA (RO) | | |
| | FZ.Z.PERS.BEF.B. 8 SPL. | | |
| 5 | KOMBILIMOUSINE | | |
| V.9 | 715/2007*2017/1347AD | | |
| 14 | EURO6;WLTP;AD;PI/CI; M, | | |
| P.3 | BENZIN | | |
| 10 | 0001 | 36AD | 01598 |
| 22 | DATUM ZUR EMISSIONSKLASSE: 04.06.2019* | | |

| | | | |
|---|---|---|---|
| L | 02 | 01 | 00 |
| 18 | 04390 - - | | |
| 20 | 1804 - 1846 | | |
| 12 | - | 13 | 00075 |
| G.7 | 0175 | F.1 | 00180 |
| G.1 | 00900 | J.2 | 01020 |
| G.1 | 00900 | J.2 | 01020 |
| M.1 | 77 | U.2 | 03750 |
| D.1 | 01200 | D.2 | 0635 |
| T5.1 | 195/55 R16 (91 | | |
| T5.2 | 195/55 R16 (91 | | |
| T5.3 | - | | |
| R | GRAU/GRAU | | |
| K | e2*2001/116*03 | | |
| 6 | 27.03.2019 | | |
| 21 | - | | |

MINDEN
26.11.2020