PW Final - HS

Vehicle Damage Assessment Report

Report No. F9863FA8
Date: 03.04.2026

Vehicle Information

Manufacturer	VW
Type	Golf
Subtype	Golf VII 2.0 TDI
VIN	WVWZZZ3CZWE999999
First Registration	15.01.2020
Power	110 kW / 150 PS
Displacement	1.968 ccm
Transmission	Manual (6-speed)
Vehicle Type	compact
Doors	4
Seats	5

Accident Information

Accident Date	15.03.2026
Accident Scene	Berlin Kreuzung

Claimant

Name	Thomas Müller
Address	Friedrichstr. 100, 10117, Berlin
Email	thomas@test.de
License Plate	B TM 2026

Opponent

Name	Stefan Braun
Insurance Company	HUK-COBURG
Insurance Number	HUK-123

Visits

Type	other
Address	Werkstatt Berlin, 10117, Berlin
Expert	Dr. Turnes

Expert Opinion

Expert Name	Dr. Turnes
File Number	HS-001

Vehicle Condition

General Condition	Well maintained
Body Condition	Minor cosmetic
Paint Type	Metallic
Driving Ability	Roadworthy
Mileage	75.000 km
Full Service History	Yes
Notes	Guter Zustand
Previous Damage Reported	Keine

Valuation & Calculation

Vehicle Value

Replacement Value	25.000,00 €
Residual Value	18.000,00 €
Diminution in Value	3.500,00 €

Repair

Repair Method	Instandsetzung
Damage Class	III

Loss of Use

Cost per Day	35,00 €
Repair Time	5 days

Additional Costs

Abschleppkosten	180,00 €

Invoice

Invoice Number	PW-HS-FINAL
Invoice Date	03.04.2026

#	Description	Qty	Rate	Amount
1	Gutachten	LS	-	362,00 €
2	Fotos	LS	-	7,50 €

3	Fahrtkosten	LS	-	40,00 €

Net Total	409,50 €
VAT (19%)	77,80 €
Gross Total	**487,30 €**

Photo Documentation

Other Photos (3)